

# MAINTENANCE REPORT

Propeller

A/C

Description of all operations pertaining to Airworthiness Directives

THUNDERBIRD AIRWAYS, INC.  
7930 AIRPORT BLVD.  
SUITE 201  
HOUSTON, TX, USA, 77061

HC-B4MP-3 HC-B4MP-3C S/N: FWA-4322

On Aircraft Reg: N109G Serial: FL-492


Work Order #: N/A

Date	A/C HRS	A/C AFL	ENG 1 HRS	ENG 1 ENC	ENG 2 HRS	ENG 2 ENC	PROP 1 HRS	PROP 2 HRS
03-Jun-2015	2603.1	1839	2603.1	1839	2505.2	1774	2603.1	2603.1

No.	Task No./Position	Description
1	HC-SB-61-356	NO. 2 PROPELLER - BLADE - SECONDARY WINDINGS ON ( )7690( ) AND ( )7890( ) COMPOSITE BLADES, SERVICE BULLETIN <b>Method Of Compliance:</b>  <b>Update Note:</b> NOT APPLICABLE
2	HC-SB-61-356	NO. 1 PROPELLER - BLADE - SECONDARY WINDINGS ON ( )7690( ) AND ( )7890( ) COMPOSITE BLADES, SERVICE BULLETIN <b>Method Of Compliance:</b>  <b>Update Note:</b> NOT APPLICABLE

I CERTIFY THAT THIS AIRCRAFT HAS BEEN INSPECTED OR REPAIRED IN ACCORDANCE WITH CURRENT FEDERAL AVIATION REGULATION 91.409 (F) (3) AND APPROVED FOR RETURN TO SERVICE

Work Performed By:

  
MICHALE CHALLENGER

Certificate #:

AP3644566

Work Inspected By:

AP3644566

Certificate #:

**TEXAS  
TURBINE &  
PROPELLER** LLC

9510 Max Conrad Dr, Spring, TX 7379 T: 281-376-1509  
CustomerService@TexasTurbineAndProp.com  
www.texas-turbineandprop.com

## LH Propeller Entry

Reg #: N726TT	Job #: N726TT-20160215	Model: King Air B300 (350)	Aircraft S/N: FL-492
Hobbs: 345.3	AFTT: 2659.3	Landings: 1894	
LH Prop Model #: HC-B4MP-3	LH Prop S/N: FWA-4322	LH Prop Time: 2659.3	


- # Description
- C/W Phase 1 & 2 inspection
  - C/W Task 610105 & 610605 Inspect / Lubricate No. 1 Propeller
  - Inspected, serviced and lubricated IAW Hartzell Propeller Owners Manual 139

The aircraft and/or component(s) identified above was repaired and inspected in accordance with Federal Aviation Administration Regulations and manufacturers maintenance manuals and Hartzell Propeller 139 owner's manual and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this agency under this job number.

Name: Luis F. Acosta

(For TT&P LLC)

Auth. Signature:

  
(For TT&P LLC)

License #:

2553437 A & P

Date:

3/8/2016

**MAINTENANCE**

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
------	----------------------	------------	---



MEXXAM AIRCRAFT MAINTENANCE  
20803 STUEBNER AIRLINE E-1  
KDWH HOOKS AIRPORT  
SPRING, TX, USA, 77379

HC-B4MP-3 HC-B4MP-3C S/N: FWA-4322

On Aircraft Reg : N726TT Serial : FL-492

Work Order #: MX-082916

Date	A/C HRS	A/C AFL	ENG 1 HRS	ENG 1 ENC	ENG 2 HRS	ENG 2 ENC	PROP 1 HRS	PROP 2 HRS
27-Jul-2016	2673.4	1902	2672.4	1902	2583.9	1837	2673.4	2673.4

No.	Task No./Position	Description
1	610010	NO. 1 PROPELLER - OVERHAUL <b>Update Note:</b> OVERHAUL OF NO. 1 PROPELLER WAS PERFORMED BY JORDAN PROPELLER PLEAS SEE ATTACHED 8130. PERFORMED R&R ONLY OF ORIGINAL UNITS RECEIVED FROM JORDAN PROPELLER.
2	P004-160801	NO. 1 PROPELLER - REVIEW HC-SL-61-61Y REV 10 <b>Update Note:</b> SENT OT PROP TO JORDAN PROPELLER FOR O/H.

I CERTIFY THAT THIS AIRCRAFT HAS BEEN INSPECTED OR REPAIRED IN ACCORDANCE WITH CURRENT FEDERAL AVIATION REGULATION 91.409 (F) (3) AND APPROVED FOR RETURN TO SERVICE

Work Performed By:

MARK A. CISNEROS

Certificate #: A&P 3285121



MEXXAM AIRCRAFT MAINTENANCE  
20803 STUEBNER AIRLINE E-1  
KDWH HOOKS AIRPORT  
SPRING, TX, USA, 77379

HC-B4MP-3 HC-B4MP-3C S/N: FWA-4322

On Aircraft Reg : N726TT Serial : FL-492

Work Order #: MX-082916

Date	A/C HRS	A/C AFL	ENG 1 HRS	ENG 1 ENC	ENG 2 HRS	ENG 2 ENC	PROP 1 HRS	PROP 2 HRS
27-Jul-2016	2673.4	1902	2672.4	1902	2583.9	1837	2673.4	2673.4

No.	Task No./Position	Description
1	HC-SL-61-348	NO. 1 PROPELLER - HUB CLAMPING BOLT INSPECTION, SERVICE LETTER <b>Method Of Compliance:</b> NOT APPLICABLE - DOSE NOT APPLY BY AC MODEL <b>Update Note:</b> DOSE NOT APPLY BY AC MODEL
2	HC-SL-61-351	NO. 1 PROPELLER - ALTERNATE BOLT (A-2051-1) FOR ATTACHING THE SPINNER MOUNTING PLATE, SERVICE LETTER <b>Method Of Compliance:</b> COMPLIED WITH - CW BY JORDAN PROPELLER <b>Update Note:</b> CW BY JORDAN PROPELLER
3	HC-SL-61-354	NO. 1 PROPELLER - LUBRICATION FITTINGS, SERVICE LETTER <b>Method Of Compliance:</b> NOT APPLICABLE - N/A BY PART MODEL NUMBER <b>Update Note:</b> N/A BY PART MODEL NUMBER

I CERTIFY THAT THIS AIRCRAFT HAS BEEN INSPECTED OR REPAIRED IN ACCORDANCE WITH CURRENT FEDERAL AVIATION REGULATION 91.409 (F) (3) AND APPROVED FOR RETURN TO SERVICE

Work Performed By:

MARK A. CISNEROS

Certificate #: A&P 3285121