



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Maintenance Inspections

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
052601	PORTABLE FIRE EXTINGUISHER WEIGHT CHK UNK		MTH 15-Feb-2016 HRS 1387.2 LDG 1122		12		28-Feb-2017	11 m 13 d
052602	30 DAY VISUAL INSPECTION OF FIRE EXTINGUISHER UNK		DAYS 15-Feb-2016 HRS 1387.2 LDG 1122		30		16-Mar-2016	1 d
0532001	PERFORM TIRE ROTATION KTMB		MTH 22-Oct-2013 HRS 1283 LDG 1058					61
053400	REPLACE PITOT AND STATIC HOSES *CF		MTH 18-Mar-2005		120		31-Mar-2015	-11 m 15 d Over Due
053700	REPLACE VACUUM HOSES *CF		MTH 18-Mar-2005		120		31-Mar-2015	-11 m 15 d Over Due
5-15-01	INSPECTION DOCUMENT 01 UNK		MTH 02-Feb-2016 HRS 1387.2 LDG 1122		12		28-Feb-2017	11 m 13 d
B262001	WEIGHT CHECK FIRE EXTINGUISHER PORTABLE UNK	A352TS W945382	MTH 02-Feb-2016		12		28-Feb-2017	11 m 13 d
5-15-02	INSPECTION DOCUMENT 02 UNK		MTH 02-Feb-2016 HRS 1387.2 LDG 1122	-182	24		31-Aug-2017	17 m 16 d
5-15-03	INSPECTION DOCUMENT 03 UNK		MTH 02-Feb-2016 HRS 1387.2 LDG 1122	-182	48		31-Aug-2019	41 m 16 d
5-15-04	INSPECTION DOCUMENT 04		MTH 04-Aug-2011 HRS 950.3 LDG 611		72		31-Aug-2017	17 m 16 d
B262005	RESTORATION FIRE EXTINGUISHER PORTABLE (INTERNAL INSPECTION)							
051226	SAT	A352TS W945382	MTH 04-Aug-2011 HRS 950.3 LDG 611		72		31-Aug-2017	17 m 16 d
5-15-05	INSPECTION DOCUMENT 05		MTH 18-Mar-2005		144			
B262003	HYDROSTATIC TEST FIRE EXTINGUISHER PORTABLE							
051227	*CF	A352TS W945382	MTH 01-Jan-2005		144		31-Jan-2017	10 m 16 d
5-15-06	INSPECTION DOCUMENT 06 UNK		MTH 02-Feb-2016 HRS 1387.2 LDG 1122		12	200	28-Feb-2017	11 m 13 d 1587.2 200
5-15-07	INSPECTION DOCUMENT 07 UNK		MTH 02-Feb-2016 HRS 1387.2 LDG 1122		12	400	28-Feb-2017	11 m 13 d 1787.2 400
5-15-08	INSPECTION DOCUMENT 08 KTMB		MTH 22-Oct-2013 HRS 1283 LDG 1058	-79	24	400	31-Aug-2015	-6 m 15 d 1683 295.8
5-15-09	INSPECTION DOCUMENT 09 UNK		MTH 02-Feb-2016 HRS 1387.2 LDG 1122		12	800	28-Feb-2017	11 m 13 d 2187.2 800
B243301	FUNCTIONAL CHECK BATTERY CONCORD SEALED LEAD ACID BATTERY (CAPACITY CHECK)							
	UNK	RG-38E/44 40774211	MTH 02-Feb-2016 HRS 1387.2 LDG 1122		3	200	31-May-2016	2 m 16 d 1587.2 200

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
5-15-0A	INSPECTION DOCUMENT 0A	UNK			MTH 02-Feb-2016 HRS 1387.2 LDG 1122		12 100		28-Feb-2017 1487.2	11 m 13 d 100
5-15-10	INSPECTION DOCUMENT 10	UNK			MTH 02-Feb-2016 HRS 1387.2 LDG 1122	-182	24 800		31-Aug-2017 2187.2	17 m 16 d 800
5-15-11	INSPECTION DOCUMENT 11	UNK			MTH 02-Feb-2016 HRS 1387.2 LDG 1122	-182	24 1600		31-Aug-2017 2987.2	17 m 16 d 1600
5-15-12	INSPECTION DOCUMENT 12				MTH 04-Aug-2011 HRS 950.3 LDG 611		60 1600		31-Aug-2016 2550.3	5 m 16 d 1163.1
5-15-13 <i>051331</i>	INSPECTION DOCUMENT 13	<i>*CF</i>			MTH 18-Mar-2005 HRS 0			20000	20000	18612.8
5-15-14 <i>051332</i>	INSPECTION DOCUMENT 14	<i>*CF</i>			MTH 18-Mar-2005 HRS 0		5000		5000	3612.8
5-15-15 <i>051333</i>	INSPECTION DOCUMENT 15	<i>*CF</i>			MTH 18-Mar-2005 HRS 0		7500		7500	6112.8
5-15-16 <i>051334</i>	INSPECTION DOCUMENT 16	<i>*CF</i>			MTH 18-Mar-2005 HRS 0		12500		12500	11112.8
5-15-17 <i>051335</i>	INSPECTION DOCUMENT 17	<i>*CF</i>			MTH 18-Mar-2005 HRS 0		16500		16500	15112.8
5-15-18 <i>051336</i>	INSPECTION DOCUMENT 18	<i>*CF</i>			MTH 18-Mar-2005 HRS 0		17500		17500	16112.8
5-15-19 <i>051337</i>	INSPECTION DOCUMENT 19	<i>*CF</i>			MTH 18-Mar-2005 LDG 0		25000		25000	23878
5-15-20	INSPECTION DOCUMENT 20	UNK			MTH 02-Feb-2016 HRS 1387.2 LDG 1122		12		28-Feb-2017	11 m 13 d
5-15-21	INSPECTION DOCUMENT 21				MTH 02-May-2012 HRS 1078.8 LDG		24			
B341103 LEFT HAND <i>051007 : L</i>	FUNCTION CHECK PITOT/STATIC SYSTEM (91.411)	KFMY			MTH 12-Jun-2014 HRS 1288 LDG 1062		24		30-Jun-2016	3 m 15 d
B341103 NO. 1 <i>051006 : L</i>	CALIBRATION TEST ENCODING ALTIMETER (FAR 91.411)	KFMY		066-03064-0005 34373	MTH 09-Jun-2014		24		30-Jun-2016	3 m 15 d
B341103 NO. 2 <i>051006 : R</i>	CALIBRATION TEST ENCODING ALTIMETER (FAR 91.411)	KFMY		C661014-0101 444838	MTH 09-Jun-2014		24		30-Jun-2016	3 m 15 d
B341103 RIGHT HAND <i>051007 : R</i>	FUNCTION CHECK PITOT/STATIC SYSTEM (91.411)	KFMY			MTH 12-Jun-2014 HRS 1288 LDG 1062		24		30-Jun-2016	3 m 15 d
5-15-22	INSPECTION DOCUMENT 22				MTH 02-May-2012 HRS 1078.8 LDG		24			
B345001 NO. 1 <i>051008 : 1</i>	CALIBRATION TEST TRANSPONDER (FAR 91.413)	KFMY		011-00455-00 84111504	MTH 09-Jun-2014		24		30-Jun-2016	3 m 15 d
B345001 NO. 2 <i>051008 : R</i>	CALIBRATION TEST TRANSPONDER (FAR 91.413)	KFMY		011-00455-00 84113529	MTH 09-Jun-2014		24		30-Jun-2016	3 m 15 d
5-15-25	INSPECTION DOCUMENT 25				MTH 18-Mar-2005 HRS 0		20000		20000	18612.8

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
5-15-MA <i>051321</i>	INSPECTION DOCUMENT MA				MTH 18-Mar-2005 HRS 0		10000		10000	8612.8
5-15-MB	INSPECTION DOCUMENT MB				MTH 18-Mar-2005 LDG 0		5000			
A321005 LEFT	SPECIAL DETAILED INSPECTION MAIN LANDING GEAR AXLE, PART NUMBERS 2641011-1, -3, -4 (SID 32-10-01)				MTH 18-Mar-2005 LDG 0		5000		5000	3878
A321005 RIGHT	SPECIAL DETAILED INSPECTION MAIN LANDING GEAR AXLE, PART NUMBERS 2641011-1, -3, -4 (SID 32-10-01)				MTH 18-Mar-2005 LDG 0		5000		5000	3878
5-15-MD <i>051350 : MD</i>	INSPECTION DOCUMENT MD				MTH 18-Mar-2005 LDG 0		15000		15000	13878
5-15-ME <i>051350 : ME</i>	INSPECTION DOCUMENT ME				MTH 18-Mar-2005 HRS 0		5000		5000	3612.8
5-15-MF <i>051350 : MF</i>	INSPECTION DOCUMENT MF				MTH 18-Mar-2005 HRS 0		20000		20000	18612.8
5-15-MG	INSPECTION DOCUMENT MG				MTH 18-Mar-2005 HRS 0		5000		5000	3612.8
5-15-MH <i>051350 : MH</i>	INSPECTION DOCUMENT MH				MTH 18-Mar-2005 HRS 0		2500		2500	1112.8
5-15-MI <i>051350 : MI</i>	INSPECTION DOCUMENT MI				MTH 18-Mar-2005 HRS 0		5000		5000	3612.8
5-15-MJ <i>051350 : MJ</i>	INSPECTION DOCUMENT MJ				MTH 18-Mar-2005 HRS 0		5000		5000	3612.8
5-15-MK <i>051350 : MK</i>	INSPECTION DOCUMENT MK				MTH 18-Mar-2005 HRS 0		20000		20000	18612.8
5-15-ML <i>051350 : ML</i>	INSPECTION DOCUMENT ML				MTH 18-Mar-2005 HRS 0		20000		20000	18612.8
057005 E1	MINOR INSPECTION	UNK			MTH 15-Feb-2016 HRS 1387.2 LDG 1122		200		1587.2	200
741025 E1 OUTBOARD	INSPECT/CLEAN SPARK IGNITER	UNK		CH34055 N/A	MTH 15-Feb-2016 HRS 1387.2 LDG 1122		200		1587.2	200
741035 E1 INBOARD	INSPECT/CLEAN SPARK IGNITER	UNK		CH34055 N/A	MTH 15-Feb-2016 HRS 1387.2 LDG 1122		200		1587.2	200
057900 E1	PERFORM ENGINE OIL SAMPLE	UNK			MTH 15-Feb-2016 HRS 1387.2 LDG 1122		100		1487.2	100
350005 CENTER	HYDROSTATIC TEST OXYGEN 50.67 CU FT AND 116.95 CU FT CYLINDER (DOT-SP 8162)	UNK		C166001-1102 522614665	MTH 02-Feb-2016		60		28-Feb-2021	59 m 13 d
610001 P1	OVERHAUL PROPELLER	SAT			MTH 04-Aug-2011 HRS 950.3		72 4000		31-Aug-2017 4950.3	17 m 16 d 3563.1
610040 P1	INSPECTION PROPELLER 100 HOUR AND ANNUAL	UNK			MTH 15-Feb-2016 HRS 1378.2		12 100		28-Feb-2017 1478.2	11 m 13 d 91
710010 E1	OVERHAUL ENGINE				MTH 18-Mar-2005 HRS 0		3600		3600	2212.8
710020 E1	INSPECT HOT SECTION	UNK			MTH 02-Feb-2016 HRS 1387.2 ENC 1122		1800		3187.2	1800

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Maintenance Inspections

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
710030 E1	BORESCOPE INSPECT HOT SECTION	KTMB	MTH 22-Oct-2013 HRS 1283 LDG 1058		200		1483	95.8
710050 E1	PERFORM DESALINATION WASH	UNK	MTH 07-Nov-2012 HRS 1168.4		A/R			
710055 E1	PERFORM PERFORMANCE RECOVERY WASH		MTH		A/R			
710060 E1	ADJUSTMENT/CHECK CONTROLS	UNK	MTH 15-Feb-2016 HRS 1387.2 LDG 1122		12		28-Feb-2017	11 m 13 d
710070 E1	CHECK OPERATION/CALIBRATION ALL ENGINE RELATED INSTRUMENTATION	KTMB	MTH 22-Oct-2013 HRS 1283 LDG 1058		12 1000		31-Oct-2014 2283	-16 m 15 d 895.8
								Over Due
720010 E1	PERFORM CORROSION INHIBITION PROCEDURE		MTH 18-Mar-2005		A/R			
725015 E1	INSPECT COMPRESSOR TURBINE DISC BLADES	*CF 3013411 A001M7A2	MTH 18-Mar-2005 HRS 0		5000	2	5000	3612.8
725017 E1	BORESCOPE INSPECTION OF COMPRESSOR TURBINE BLADE TRAILING EDGE	UNK	MTH 15-Feb-2016 HRS 1387.2 LDG 1122		400		1787.2	400
725025 E1	INSPECT COMPRESSOR FIRST STAGE BLADES FOR FOD	UNK	MTH 15-Feb-2016 HRS 1387.2 LDG 1122		12 1000		28-Feb-2017 2387.2	11 m 13 d 1000
725040 E1	INSPECT EXHAUST DUCT	KTMB	MTH 22-Oct-2013 HRS 1283 LDG 1058		A/R			
725050 E1	INSPECT EXHAUST DUCT WELDS	UNK	MTH 15-Feb-2016 HRS 1387.2 LDG 1122		150		1537.2	150
731025 E1	CLEAN/LEAK/FUNCTIONAL TEST FUEL MANIFOLD AND NOZZLES	UNK	MTH 02-Feb-2016 HRS 1387.2 LDG 1122		200		1587.2	200
731030 E1	REPLACE FUEL PUMP OUTLET FILTER	KTMB 702801-5 1020	MTH 22-Oct-2013 HRS 1283 LDG 1058		600		1883	495.8
731040 E1	CHECK/CLEAN/REPLACE FUEL PUMP INLET SCREEN	702801-5 1020	MTH 17-Sep-2012 HRS 1134.5 LDG 871		600		1734.5	347.3
731095 E1	INSPECT FUEL CONTROL UNIT BODY/BEARING	3122678-04 C65775	MTH 18-Mar-2005 HRS 0		3600		3600	2212.8
731100 E1	OPERATIONAL CHECK FUEL CONTROL UNIT MANUAL OVERRIDE STATIC SYSTEM	KTMB 3122678-04 C65775	MTH 22-Oct-2013 HRS 1283 LDG 1058		200		1483	95.8
731105 E1	PERFORM DECELERATION CHECK	UNK	MTH 15-Feb-2016 HRS 1387.2 LDG 1122		150		1537.2	150

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
733010 E1	CLEAN/REPLACE /INSPECT PNEUMATIC P3 FILTER/HOUSING	UNK			MTH 15-Feb-2016 HRS 1387.2 ENC 1122	-4.2	100		1483	95.8
733020 E1	REPLACE PNEUMATIC P3 FILTER	KTMB			MTH 22-Oct-2013 HRS 1283 ENC 1058	-283	1000		2000	612.8
750020 E1	INSPECT/CHECK BLEED VALVE				MTH 17-Sep-2012 HRS 1134.5 LDG 871		600		1734.5	347.3
760000 E1	DOWNLOAD ECTM	KFMY			DAYS 12-Jun-2014 HRS 1288 LDG 1062		7		19-Jun-2014	-20 m 25 d
										Over Due
790030 E1	CONTINUITY CHECK CHIP DETECTOR	UNK		PN SN-UNKNOWN	MTH 15-Feb-2016 HRS 1387.2 LDG 1122		200		1587.2	200
790040 E1	BRIDGE CHECK CHIP DETECTOR	UNK		PN SN-UNKNOWN	MTH 15-Feb-2016 HRS 1387.2 LDG 1122		12 600		28-Feb-2017 1987.2	11 m 13 d 600
790050 E1	CLEAN/REPLACE OIL FILTER	ORL			MTH 17-Sep-2012 HRS 1134.5 ENC 871	-134.5	1000		2000	612.8
790070 E1	CHECK SCAVENGE OIL PUMP INLET SCREEN	UNK			MTH 15-Feb-2016 HRS 1387.2 LDG 1122		6 200		31-Aug-2016 1587.2	5 m 16 d 200



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Components

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
210856	CABIN TEMP CONTROL	*CF		1H102-2 1BA6	MTH 18-Mar-2005		O/C			
210857	FLOW CONTROL VALVE	*CF		1H101-4 1BA6	MTH 18-Mar-2005		O/C			
210858	PRESSURE REGULATOR	*CF		1H75-21 1BA8	MTH 18-Mar-2005		O/C			
210860	MIXER MUFFLER ASSEMBLY	*CF		2613421-1 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
215001 AFT	EVAPORATOR 2601275	*CF		1134200-17 483	MTH 18-Mar-2005		O/C			
215001 LEFT	EVAPORATOR 2601275	*CF		1134380-1 279	MTH 18-Mar-2005		O/C			
215001 RIGHT	EVAPORATOR 2601275	*CF		1134380 276	MTH 18-Mar-2005		O/C			
215008 215005	COMPRESSOR	*CF		SD5H14C4527 6240105480	MTH 18-Mar-2005		O/C			
216001	TEMP PROBE	*CF		05257-SCD/508208 00550	MTH 18-Mar-2005		O/C			
220002	AUTOPILOT COMPUTER KFC225	*CF	7	065-00183-2901 2742	MTH 18-Mar-2005		O/C			
220004	TRIM SERVO KS272C	*CF	7	065-00180-0800 7580	MTH 18-Mar-2005		O/C			
220005 PITCH	SERVO KS270C	FTY		065-00178-2200 8100	MTH 15-Feb-2006 HRS 315		O/C	0		
220005 ROLL	SERVO KS271C	FTY		065-00179-0100 11046	MTH 28-Apr-2006 HRS 384		O/C	0		
220005 YAW	SERVO KS271C	*CF	9	065-00179-0600 10329	MTH 18-Mar-2005		O/C			
220006 PITCH	SERVO MOUNT KM275	*CF		065-0030-00 61496	MTH 18-Mar-2005		O/C			
220006 ROLL	SERVO MOUNT KM275	*CF		065-0030-00 61572	MTH 18-Mar-2005		O/C			
220006 YAW	SERVO MOUNT KSM375	*CF		065-0015-01 61443	MTH 18-Mar-2005		O/C			
220006	SERVO MOUNT TRIM KM-277	*CF		065-0041-00 5056	MTH 18-Mar-2005		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Components

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
220007	YAW INVERTER	*CF		MD26-28 M0410993	MTH 18-Mar-2005		O/C			
221010 YAW	REMOTE RATE GYRO KRG331	*CF	1	060-0024-00 8174	MTH 18-Mar-2005		O/C			
230008 230001	AUDIO PANEL GMA340	*CF	8	011-00401-20 97300253	MTH 18-Mar-2005		O/C			
230010 LEFT	VHF ANTENNA	*CF		CI268-60 5014268	MTH 18-Mar-2005		O/C			
230010 RIGHT	VHF ANTENNA	*CF		CI268-60 5014275	MTH 18-Mar-2005		O/C			
235002	AUDIO ADAPTER KK1210	*CF		200-4273-00 2367	MTH 18-Mar-2005		O/C			
240000 240002	GENERATOR CONTROL UNIT	*CF	A	51539-012N P111	MTH 18-Mar-2005		O/C			
240003	ALT DR PULLEY ASSEMBLY	*CF		2601271-15 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
240004	STATIC INVERTER	ICT		SS50 SN-UNKNOWN	MTH 13-Apr-2005 HRS 2		O/C	0		
240125	ALTERNATOR CONTROL ASSEMBLY	*CF		2618500-1 311	MTH 18-Mar-2005		O/C			
240220	OVERVOLTAGE SENSOR	*CF		C593005-0101 E112619	MTH 18-Mar-2005		O/C			
240301	STARTER GENERATOR	*CF	3	200SGL119Q-2 5407XL	MTH 18-Mar-2005 HRS 0		2000	0	2000	612.8
240401	ALTERNATOR 9910592-2	*CF		ASG12000-2 A176687	MTH 18-Mar-2005		O/C			
240501	BATTERY	UNK		RG-38E/44 40774211	MTH 15-Feb-2016 HRS 1387.2 LDG 1122		O/C	0		
BATTERY SHOULD BE REPLACED EVERY 60 MONTHS OR 5000 HOURS PER CONCORDE BATTERY MANUAL.										
256015	ELT BATTERY	UNK		452-0133 367483-005	MTH 15-Feb-2016 HRS 1387.2 LDG 1122		60	0	28-Feb-2021	59 m 13 d
256020	ARTEX ELT ANTENNA DORNE&MARGOLIAN	*CF		261C1385-001 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
256025 256005	ELT/NAV INTERFACE	*CF		453-6500 04490	MTH 18-Mar-2005		O/C			
260101	FIRE EXTINGUISHER	*CF		A352TS W945382	MTH 18-Mar-2005		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Components

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
260201 NO. 1	FIRE DETECTION CABLE			PN SN-UNKNOWN	MTH 18-Mar-2005		O/C	0		
260201 NO. 2	FIRE DETECTION CABLE			PN SN-UNKNOWN	MTH 18-Mar-2005		O/C	0		
260225	FIRE BOX	*CF		477-90008 0503306	MTH 18-Mar-2005		O/C			
270101 LEFT INBOARD FORWARD	FLAP BELLCRANK	*CF		2622311-16 164	MTH 18-Mar-2005 LDG 0		40000	0	40000	38878
270102 BOTTOM	FLAP BELLCRANK BEARING	*CF		MS27641-5 SN-UNKNOWN	MTH 18-Mar-2005 LDG 0		10000	0	10000	8878
270102 TOP	FLAP BELLCRANK BEARING	*CF		MS27641-5 SN-UNKNOWN	MTH 18-Mar-2005 LDG 0		10000	0	10000	8878
270103	FLAP BELLCRANK BOLT	*CF		AN5-77 SN-UNKNOWN	MTH 18-Mar-2005 LDG 0		10000	0	10000	8878
270601	AILERON TRIM ACTUATOR	*CF		2661615-1 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
271401 LEFT	ELEVATOR TRIM ACTUATOR	*CF		2661215-9 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
271401 RIGHT	ELEVATOR TRIM ACTUATOR	*CF		2661215-9 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
271502	FLAP ACTUATOR ASSEMBLY 9910586-3	*CF		D145-00-46-2 8988	MTH 18-Mar-2005		O/C			
271508 AFT	FLAP ACTUATOR MOTOR C145-250	*CF		C301002-0104 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
271508 FWD	FLAP ACTUATOR MOTOR	FMY		C145-450 NSN	MTH 26-Apr-2012 HRS 1076.2 LDG 787		O/C	0 0 0		
271700	FLAP ACT ASSY SWITCH	*CF		2662011-1 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
271903	STALL WARNING LIFT TRANSDUCER	*CF		799-1 1986	MTH 18-Mar-2005		O/C			
271904	FLAP TRANS GEARBOX	*CF		C145-00-46 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
273000 AFT 273001	ELEVATOR PUSHROD	*CF		2634027-1 NSN	MTH 18-Mar-2005 LDG 0		40000	0	40000	38878
273000 FORWARD 273001	ELEVATOR PUSHROD	*CF		2613440-3 NSN	MTH 18-Mar-2005 LDG 0		40000	0	40000	38878

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Components

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
277001	RUDDER GUST LOCK KIT	*CF		AT-RL-1001 1111	MTH 18-Mar-2005		O/C			
280001 LEFT	FUEL QUANTITY GAUGE	*CF		C662041-0102 3156	MTH 18-Mar-2005		O/C			
280001 RIGHT	FUEL QUANTITY GAUGE	*CF		C662041-0102 3289	MTH 18-Mar-2005		O/C			
280347	FUEL PRESSURE SWITCH	*CF		S2615-2 2305	MTH 18-Mar-2005		O/C			
280389	FUEL SHUTOFF VALVE	*CF		72D10C SN-UNKNOWN	MTH 18-Mar-2005		O/C			
280414	ELEC FUEL BOOST PUMP	*CF		2C6-8 12AY89	MTH 18-Mar-2005		O/C			
280418	PUMP EJECTOR	*CF		68E101-14 2332	MTH 18-Mar-2005		O/C			
280421	FUEL CHECK VALVE	*CF		6C172 5003	MTH 18-Mar-2005		O/C			
280433	LW FUEL WARN SWITCH	*CF		GF5500-82 0413807	MTH 18-Mar-2005		O/C			
280500	FUEL TO ENGINE HOSE S2808-8B0520	UNK		AE3663726H0520 SN-UNKNOWN	MTH 15-Feb-2016 HRS 1387.2 LDG 1122		120 3600	0 0	28-Feb-2026 4987.2	119 m 13 d 3600
280600	MOTIVE FLOW HOSE S2808-6-330	UNK		AE3663724G0330 SN-UNKNOWN	MTH 15-Feb-2016 HRS 1387.2 LDG 1122		120 3600	0 0	28-Feb-2026 4987.2	119 m 13 d 3600
280701 LEFT NO. 1	FUEL TRANSMITTER	*CF		C668050-1103 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
280701 LEFT NO. 2	FUEL TRANSMITTER	*CF		C668050-1107 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
280701 LEFT NO. 3	FUEL TRANSMITTER	*CF		C668050-1108 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
280701 LEFT NO. 4	FUEL TRANSMITTER	*CF		C668050-1104 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
280701 RIGHT NO. 1	FUEL TRANSMITTER	*CF		C668050-1103 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
280701 RIGHT NO. 2	FUEL TRANSMITTER	*CF		C668050-1107 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
280701 RIGHT NO. 3	FUEL TRANSMITTER	*CF		C668050-1106 SN-UNKNOWN	MTH 18-Mar-2005		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
280701 RIGHT NO. 4	FUEL TRANSMITTER	*CF		C668050-1104 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
280702 L1	FUEL LEVEL SENSOR			PN SN-UNKNOWN	MTH 18-Mar-2005		O/C	0		
280713 NO. 1	LOW FUEL LEVEL SWITCH	*CF		GF5500-81 417389	MTH 18-Mar-2005		O/C			
280713 NO. 2	LOW FUEL LEVEL SWITCH	*CF		GF5500-81 451523	MTH 18-Mar-2005		O/C			
280726	FUEL FLOW TRANSDUCER 9910338-6	*CF		TFF2905-13 2281	MTH 18-Mar-2005		O/C			
300015 RIGHT	TKS STRUT			PN SN-UNKNOWN	MTH 18-Mar-2005		O/C	0		
300206 AFT	DE-ICE PRESS SWITCH	*CF		1D1470-15 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
300206 CENTER	DE-ICE PRESS SWITCH	*CF		1D1470-15 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
300206 FORWARD	DE-ICE PRESS SWITCH	*CF		1D1470-15 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
300403	W/S ANTI-ICE CONTROL	*CF		C166065-0101 1767	MTH 18-Mar-2005		O/C			
300412	W/S ANTI-ICE PANEL 2601445-1	*CF		2601488-830 04357H5363	MTH 18-Mar-2005		O/C			
313104	FLIGHT DATA RECORDER			PN SN-UNKNOWN	MTH 18-Mar-2005		O/C	0		
313105	FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON			PN SN-UNKNOWN	MTH 18-Mar-2005		O/C	0		
320003 AFT	NOSE GEAR SPRING SUPPORT ASSEMBLY			PN SN-UNKNOWN	MTH 18-Mar-2005 LDG 0		40000	0	40000	38878
320003 FORWARD	NOSE GEAR SPRING SUPPORT ASSEMBLY	*CF		2643099-3 SN-UNKNOWN	MTH 18-Mar-2005 LDG 0		40000	0	40000	38878
320004	NOSE GEAR SPRING FORK ASSY	*CF		2643031-1 SN-UNKNOWN	MTH 18-Mar-2005 LDG 0		40000	0	40000	38878
320007	SHIMMY DAMPER	*CF		2643090-3 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
320008	NOSE GEAR DRAG LINK SPRING	*CF		2643062-3 NSN	MTH 18-Mar-2005 LDG 0		15000	0	15000	13878



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Components

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
320009	NOSE GEAR ASSEMBLY	*CF		2643100-12 369	MTH 18-Mar-2005 LDG 0		40000	0	40000	38878
320012 LEFT	MAIN GEAR SPRING	*CF		2641013-8 144	MTH 18-Mar-2005 LDG 0		31500	0	31500	30378
320012 RIGHT	MAIN GEAR SPRING	*CF		2641013-8 133	MTH 18-Mar-2005 LDG 0		31500	0	31500	30378
320013	MAIN LANDING GEAR CENTER SPRING	*CF		2641014-9 60	MTH 18-Mar-2005 LDG 0		31500	0	31500	30378
320014 LEFT	MLG TRUNNION ASSEMBLY	*CF		2641012-9R SN-UNKNOWN	MTH 18-Mar-2005 LDG 0		31500	0	31500	30378
320014 RIGHT	MLG TRUNNION ASSEMBLY	*CF		2641012-13 SN-UNKNOWN	MTH 18-Mar-2005 LDG 0		31500	0	31500	30378
320015 LEFT	MLG ATTACH PIN	KTMB		2641008-200 NSN	MTH 22-Oct-2013 HRS 1283 LDG 1058		31500	0	32558	31436
320015 RIGHT	MLG ATTACH PIN	KTMB		2641008-200 NSN	MTH 22-Oct-2013 HRS 1283 LDG 1058		31500	0	32558	31436
320016 LEFT	MLG AXLE FITTINGS	*CF		2641010-7 NSN	MTH 18-Mar-2005 LDG 0		31500	0	31500	30378
320016 RIGHT	MLG AXLE FITTINGS	*CF		2641010-7 NSN	MTH 18-Mar-2005 LDG 0		31500	0	31500	30378
320301 LEFT	MLG TIRE	FMY		078-446-1 SN-UNKNOWN	MTH 22-Aug-2014 HRS 1299.97 LDG 1078		O/C	0		
320301 RIGHT	MLG TIRE	FMY		078-446-1 SN-UNKNOWN	MTH 22-Aug-2014 HRS 1299.97 LDG 1078		O/C	0		
320302 LEFT	MAIN WHEEL ASSEMBLY C163001-1001	*CF		040-17900 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
320302 RIGHT	MAIN WHEEL ASSEMBLY C163001-1001	*CF		040-17900 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
320801	NOSE WHEEL ASSEMBLY	*CF		C163001-0901 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
320802	NLG TIRE	KTMB		024-560-0 221R00180	MTH 22-Oct-2013 HRS 1283 LDG 1058		O/C	0		
321000 LEFT	MSTR CYLINDER BRAKE	*CF		2682001-1 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
321000 RIGHT	MSTR CYLINDER BRAKE	*CF		2682001-1 SN-UNKNOWN	MTH 18-Mar-2005		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Components

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
321086 LEFT	MLG AXLE	*CF		2641011-5 1844	MTH 18-Mar-2005 LDG 0		31500	0	31500	30378
321086 RIGHT	MLG AXLE	*CF		2641011-5 1826	MTH 18-Mar-2005 LDG 0		31500	0	31500	30378
321101 LEFT	BRAKE ASSEMBLY	*CF		030-18200 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
321101 RIGHT	BRAKE ASSEMBLY	*CF		030-18200 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
321102 LEFT	BRAKE CYLINDER	*CF		061-11800 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
321102 RIGHT	BRAKE CYLINDER	*CF		061-11800 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
321106 LEFT	BRAKE PRESSURE PLATE	*CF		073-08500 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
321106 RIGHT	BRAKE PRESSURE PLATE	*CF		073-08500 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
321107 LEFT	MLG BRAKE LINING	KTMB		066-03300 NSN	MTH 22-Oct-2013 HRS 1283 LDG 1058		O/C	0		0
321107 RIGHT	MLG BRAKE LINING	KTMB		066-03300 NSN	MTH 22-Oct-2013 HRS 1283 LDG 1058		O/C	0		0
321108 LEFT	BRAKE DISC	KTMB		164-22201 NSN	MTH 22-Oct-2013 HRS 1283 LDG 1058		O/C	0		0
321108 RIGHT	BRAKE DISC	KTMB		164-22201 NSN	MTH 22-Oct-2013 HRS 1283 LDG 1058		O/C	0		0
321110 LEFT	BRAKE BACKING PLATE	*CF		074-06600 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
321110 RIGHT	BRAKE BACKING PLATE	*CF		074-06600 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
321118 LEFT	TORQUE PLATE	*CF		075-17100 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
321118 RIGHT	TORQUE PLATE	*CF		075-17100 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
321201	PARKING BRAKE CONTROL ASSEMBLY	*CF		S1779-3 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
330124	ANNUNCIATOR	*CF		2670104-2 1118	MTH 18-Mar-2005		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
330312	GRAPHIC SIGN	*CF		100-9042-03 04L296	MTH 18-Mar-2005		O/C			
330340	CRTSY LITE CNTL ASSY --	*CF		8810 724	MTH 18-Mar-2005		O/C			
330701 LEFT	LANDING LIGHT ASSEMBLY	*CF		4553 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
330701 RIGHT	LANDING LIGHT ASSEMBLY	*CF		4553 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
330702 LEFT	TAXI LIGHT ASSEMBLY	*CF		4626 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
330702 RIGHT	TAXI LIGHT ASSEMBLY	*CF		4626 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
330813	FLASHER ASSEMBLY BEACON	*CF		C594502-0102 C04092293	MTH 18-Mar-2005		O/C			
330901 LEFT	STROBE LIGHT ASSEMBLY	*CF		C622010-0101 H05021004	MTH 18-Mar-2005		O/C			
330901 RIGHT	STROBE LIGHT ASSEMBLY	*CF		C622010-0102 H05020975	MTH 18-Mar-2005		O/C			
340005 LEFT	TURN & BANK INDICATOR	*CF		1394T100-7A A0511158	MTH 18-Mar-2005		O/C			
340005 RIGHT	TURN & BANK INDICATOR	*CF		1394T100-7A L0410864	MTH 18-Mar-2005		O/C			
340006 NO. 1	ENCODING ALTIMETER KEA130A	*CF	3	066-03064-0005 34373	MTH 18-Mar-2005		O/C			
340006 NO. 2 <i>340003 : R</i>	ENCODING ALTIMETER 5934PAD-3	*CF		C661014-0101 444838	MTH 18-Mar-2005		O/C			
340007	ALTIMETER RADAR KRA10	*CF		066-1061-03 18700	MTH 18-Mar-2005		O/C			
340010M	MODE S ELT TRANSPONDER MODULE	*CF		9255017-4 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
340013 E1	EHSI-ELECTRONIC HSI INDICATOR --	KFT		80-5205-2-3 0471	MTH 05-Jun-2006 HRS 410		O/C	0		
340014	DIRECTIONAL GYRO KG102A	*CF	8	060-0015-00 51502	MTH 18-Mar-2005		O/C			
340015	SLAVING ACCESSORY KA51B	*CF		071-1242-06 36805	MTH 18-Mar-2005		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
340016	FLUX DETECTOR KMT112	*CF		071-1052-00 70222	MTH 18-Mar-2005		O/C			
340021 LEFT	AIRSPEED INDICATOR	*CF		C661065-0240 T46313	MTH 18-Mar-2005		O/C			
340021 RIGHT	AIRSPEED INDICATOR OPT	*CF		C661064-0237 T24988	MTH 18-Mar-2005		O/C			
340021	MULTI FUNCTION DISPLAY MX-20	ICT		430-0270-502 SN-UNKNOWN	MTH 13-Apr-2005 HRS 2		O/C	0		
340022 RIGHT	ATTITUDE GYRO	*CF	2	504-0111-906 25550	MTH 18-Mar-2005		O/C			
340022	RADAR ALT INDICATOR KMD550/850	*CF		071-00161-0101 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
340023 RIGHT	DIR GYRO INDICATOR	*CF		C661053-0103 45A0001G	MTH 18-Mar-2005		O/C			
340023	DATA LINK RECEIVER -- GDL69A	ICT		011-00987-00 SN-UNKNOWN	MTH 13-Apr-2005 HRS 2		O/C	0		
340024 NO. 1	ADF INDICATOR KI227-01	*CF	2	066-3063-01 61210	MTH 18-Mar-2005		O/C			
340025 NO. 1	ADF RECEIVER S3100-406	*CF	8	066-1072-04 78895	MTH 18-Mar-2005		O/C			
340028	DME RECEIVER KN-63	*CF	6	066-1070-01 28382	MTH 18-Mar-2005		O/C			
340029	DME INDICATOR KDI572	*CF	2	066-1069-00 29953	MTH 18-Mar-2005		O/C			
340032	NAV INDICATOR GI-106A	*CF	1	013-00049-11 M0411117	MTH 18-Mar-2005		O/C			
340033	RADAR ALT INDICATOR KI250	*CF	4	066-3054-01 12377	MTH 18-Mar-2005		O/C			
340035 NO. 1	TRANSPONDER GTX330	*CF		011-00455-00 84111504	MTH 18-Mar-2005		O/C			
340035 NO. 2	TRANSPONDER GTX330	*CF		011-00455-00 84113529	MTH 18-Mar-2005		O/C			
340037 LEFT	STORMSCOPE PROCESSOR -- LEFT	*CF		805-11500-001 86562	MTH 18-Mar-2005		O/C			
340040 LEFT	VERTICAL SPEED INDICATOR LEFT	*CF		C661035-0101 309695	MTH 18-Mar-2005		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Components

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
340040 RIGHT	VERTICAL SPEED INDICATOR	*CF		C661035-0101 309693	MTH 18-Mar-2005		O/C			
340050	REC/TRANSMITTER RADAR ART-2000	*CF	9	071-01519-0101 8999	MTH 18-Mar-2005		O/C			
340051	RDS ANTENNA AA-2012V	*CF		071-01549-0200 6093	MTH 18-Mar-2005		O/C			
340052	CARD ADAPTER GNS530	*CF		010-10201-01 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
340055 G	ADAPTER GROUND PROXIMIT BOARD KAC502	*CF	1	071-00158-0211 4213	MTH 18-Mar-2005		O/C			
340055 R	ADAPTER BOARD RADAR KAC501	*CF	1	071-00159-0111 4554	MTH 18-Mar-2005		O/C			
340055 T	ADAPTER TRAFFIC BOARD KAC504	*CF	1	071-00166-0411 4328	MTH 18-Mar-2005		O/C			
340058 BOTTOM	COUPLER	*CF		C598506-0101 3134	MTH 18-Mar-2005		O/C			
340058 TOP	COUPLER	*CF		C598506-0101 3143	MTH 18-Mar-2005		O/C			
340060	MARKER BEACON ANT	*CF		CI102 4100849	MTH 18-Mar-2005		O/C			
340062	ALTITUDE SERIALIZER --	ICT		3230015-3 SN-UNKNOWN	MTH 13-Apr-2005 HRS 2		O/C	0		
340063	REMOTE RELAY/COUPLER -- MD41	*CF	2	MD41-1208 A0511213	MTH 18-Mar-2005		O/C			
340066	GPS/ XM SAT ANTENNA GA-55 -- GA-55	ICT		011-01033-00 SN-UNKNOWN	MTH 13-Apr-2005 HRS 2		O/C	0		
340071 LEFT	NAV BAL LOOP ANT 22-37-101	*CF		C598505-0303 3805	MTH 18-Mar-2005		O/C			
340071 RIGHT	NAV BAL LOOP ANT	*CF		C598505-0303 3806	MTH 18-Mar-2005		O/C			
340080	FLT COMMAND INDICATOR KI256	*CF	11	060-0017-00 25143	MTH 18-Mar-2005		O/C			
340085	PHASING COUPLER	*CF		C598505-0304 2711	MTH 18-Mar-2005		O/C			
340100 NO. 1 <i>340049</i>	CONFIG MODULE RDR2000	*CF	1	071-00097-0100 13887	MTH 18-Mar-2005		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
340100 NO. 2 <i>340049 : 2</i>	CONFIG MODULE KCM805	*CF		071-00112-0200 1031	MTH 18-Mar-2005		O/C			
340107 <i>340100</i>	DATABASE KGP560/AMERICAS	*CF		071-00167-0101 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
340110	A/S WARNING PRESSURE SWITCH	*CF		251500-141-1 283131	MTH 18-Mar-2005		O/C			
340150	MULTI HAZARD AWARENESS UNIT IHAS	*CF		066-01175-2102 1045	MTH 18-Mar-2005		O/C			
340169 LEFT	MVNG MAP COM VOR LOC GS GPS GNS530	*CF	6	011-00550-10 78412769	MTH 18-Mar-2005		O/C			
340169	INTEGR VHF MVNG MAP GPS GNS430	*CF	5	011-00280-10 97124961	MTH 18-Mar-2005		O/C			
340308 LEFT	TUBE PITOT S2625-3			PST300-2SW SN-UNKNOWN	MTH 18-Mar-2005		O/C			
340308 RIGHT	TUBE PITOT S2625-3			PST300-2SW SN-UNKNOWN	MTH 18-Mar-2005		O/C			
340424	VACCUM REGULATOR	FTY		C482001-0402 S2BA13	MTH 13-May-2005 HRS 26		O/C	0		
340607	OAT GAGE	*CF		C668507-0105 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
340608	OAT PROBE --	*CF		TWIN-A052-2 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
345035 NO. 1	COMPENSATOR	*CF		172055 50720	MTH 18-Mar-2005		O/C			
345035 NO. 2	COMPENSATOR	*CF		172055 50698	MTH 18-Mar-2005		O/C			
345070	ALT ENC INTERFACE ADAPTER	*CF		RS232C 2933	MTH 18-Mar-2005		O/C			
350236	OXYGEN GAGE	*CF		C166010-0101 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
350301 CENTER	OXYGEN 50.67 CU FT AND 116.95 CU FT CYLINDER	UNK		C166001-1102 522614665	MTH 02-Feb-2016 HRS 1387.2 LDG 1122		180	0		?
350310 PORTABLE	OXYGEN BOTTLE	UNK		PN SN-UNKNOWN	MTH 02-Feb-2016 HRS 1387.2 LDG 1122		O/C	131 1387.2 1122		
351005	ASSEMBLY REGULATOR	UNK		172400-00 3549	MTH 02-Feb-2016 HRS 1387.2 LDG 1122		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
370102	VACUUM SYSTEM CENTRAL AIR FILTER DISCARD		MTH 22-Oct-2013		12	0	31-Oct-2014	-16 m 15 d
		PN	HRS 1283		400	0	1683	295.8
		SN-UNKNOWN	LDG 1058			0		
								Over Due
370103	VACUUM RELIEF VALVE FILTER DISCARD		MTH 22-Oct-2013		12	0	31-Oct-2014	-16 m 15 d
		PN	HRS 1283		400	0	1683	295.8
		SN-UNKNOWN	LDG 1058			0		
								Over Due
370110	AIR EJECTOR		MTH 13-May-2005		O/C			
		FTY	HRS 26			0		
		19E32-2A N05876						
390002	HOURMETER 85071	*CF	MTH 18-Mar-2005		O/C			
		C664503-0104 SN-UNKNOWN						
390101	GAGE-PROP AMMETER	*CF	MTH 18-Mar-2005		O/C			
		C662503-0109 SN-UNKNOWN						
390102	SUCTION GAGE	*CF	MTH 18-Mar-2005		O/C			
		C668540-0102 0851						
390103	CLOCK	*CF	MTH 18-Mar-2005		O/C			
		C664511-0102 21916						
390104	GAGE-VOLT AMMETER	*CF	MTH 18-Mar-2005		O/C			
		C662504-0101 SN-UNKNOWN						
550502	ASSEMBLY RUDDER	*CF	MTH 18-Mar-2005		O/C			
		2633000-40 SN-UNKNOWN						
560203 LEFT	WINDSHIELD	*CF	MTH 18-Mar-2005		O/C			
		2613088-1 SN-UNKNOWN						
560203 RIGHT	WINDSHIELD	*CF	MTH 18-Mar-2005		O/C			
		2613088-2 SN-UNKNOWN						
610002	PROPELLER GOVERNOR 3035926	FTY	MTH 18-Mar-2005					
			HRS 2		4100	2	4100	2712.8
		8210-002 1411097AE						
610005	PROPELLER OVERSPEED GOVERNOR	*CF	MTH 18-Mar-2005					
			HRS 0		6500	0	6500	5112.8
		D210507 14150465						
61PR1 NO. 1 <i>610001</i>	PROPELLER 3GFR34C703 OR 3GFR34C703-B	*CF	MTH 18-Mar-2005		PR/C	0		
					PR/C			
		P7036368-0154 050120						
610003A P1 NO. 1 <i>610003 : P1</i>	PROPELLER BLADE	*CF	MTH 18-Mar-2005		O/C			
		106GA-0 YF30046						
610003B P1 NO. 2 <i>610003 : P2</i>	PROPELLER BLADE	*CF	MTH 18-Mar-2005		O/C			
		106GA-0 YG30103						
610003C P1 NO. 3 <i>610003 : P3</i>	PROPELLER BLADE	*CF	MTH 18-Mar-2005		O/C			
		106GA-0 YH30096						
610006 P1	PROPELLER SLIPRING	*CF	MTH 18-Mar-2005		O/C			
		D40260 SN-UNKNOWN						

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
710002	ENGINE MOUNT ASSEMBLY	*CF		2651023-19 CES05001	MTH 18-Mar-2005		O/C			
712031 LEFT	ENGINE MOUNT 9910333-1	*CF		LM600-9 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
712031 RIGHT	ENGINE MOUNT 9910333-1	*CF		LM600-9 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
715001	ENGINE MONITORING PROCESSOR	*CF		EMU-A-010-3 0380	MTH 18-Mar-2005		O/C			
715002	ENGINE MONITORING PITOT P155-15A-E1A	*CF		P01001 H1104023	MTH 18-Mar-2005		O/C			
715003	ENGINE MONITORING TRANSDUCER P356-5000	*CF		P01002 G2404021	MTH 18-Mar-2005		O/C			
71EN1 NO. 1 <i>710001 : E1**L</i>	ENGINE 9910589-1	*CF		PT6A-114A PCE-1182	MTH 18-Mar-2005		E/C			
710033 E1	T5 TRIM STICK	*CF		3031417CL40 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
710512 E1	ENGINE COLLAR	*CF		2651022-15 102	MTH 18-Mar-2005		O/C			
723010 E1	COMPRESSOR 1ST STAGE HUB	*CF		3013111 RWA08A315	MTH 18-Mar-2005 ENC 0		19000	0	19000	17878
723030 E1	COMPRESSOR 2ND STAGE DISC	*CF		3013712 A001M69R	MTH 18-Mar-2005 ENC 0		24000	0	24000	22878
723040 E1	COMPRESSOR 3RD STAGE DISC	*CF		3011713 A001M8XB	MTH 18-Mar-2005 ENC 0		25000	0	25000	23878
723060 E1	IMPELLER	*CF		3027798 EAAA000H773	MTH 18-Mar-2005 ENC 0		19000	0	19000	17878
723080 E1	COMBUSTION CHAMBER LINER	*CF		3122633-01 RWA10A031	MTH 18-Mar-2005		O/C			
725010 E1	COMPRESSOR TURBINE DISC	*CF		3013411 A001M7A2	MTH 18-Mar-2005 ENC 0		16000	0	16000	14878
725030 E1	POWER TURBINE DISC	*CF		3026812 A001MTMR	MTH 18-Mar-2005 ENC 0		20000	0	20000	18878
725095 E1 NO. 2	FLANGE 1.5748 X2.6772 X.5906 ROLLER BEARING			PN SN-UNKNOWN	MTH 18-Mar-2005		O/C	0		
730001 E1	FUEL FLOW INDICATOR 9910338-8	*CF		DSFF1785-1 0502926	MTH 18-Mar-2005		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Components

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
731010 E1	FUEL PUMP 3034792	*CF		702801-5 1020	MTH 18-Mar-2005 HRS 0		4100	0	4100	2712.8
731060 E1	OIL TO FUEL HEATER	*CF		10552E WA21548	MTH 18-Mar-2005 HRS 0		4100	0	4100	2712.8
731070 E1	FLOW DIVIDER AND FUEL DUMP VALVE 25536	*CF		3019906 9959512243	MTH 18-Mar-2005		O/C			
731090 E1	FUEL CONTROL UNIT	*CF		3122678-04 C65775	MTH 18-Mar-2005 HRS 0		4100	0	4100	2712.8
740010 E1	IGNITION EXCITER	*CF		10-381550-4 NNA04505880	MTH 18-Mar-2005 HRS 0		4100	0	4100	2712.8
741020 E1 OUTBOARD	SPARK IGNITER 3027280	ORL		CH34055 N/A	MTH 17-Sep-2012 HRS 1134.5 ENC 871		O/C	0		
741030 E1 INBOARD	SPARK IGNITER 3027280	ORL		CH34055 N/A	MTH 17-Sep-2012 HRS 1134.5 ENC 871		O/C	0		
750010 E1	BLEED VALVE 540-1407-4	*CF		3049038-03 4419	MTH 18-Mar-2005 HRS 0		4100	0	4100	2712.8
760200	ENGINE CONTROL QUAD ASSEMBLY	*CF		C299514-0101 607	MTH 18-Mar-2005		O/C			
770010 NO. 1	TORQUE VENT & PRESSURE HOSE S2808-4-0113	UNK		AE3663161E0113 SN-UNKNOWN	MTH 15-Feb-2016 HRS 1387.2 LDG 1122		120 3600	0 0	28-Feb-2026 4987.2	119 m 13 d 3600
770011 NO. 2 <i>770010 : 2</i>	TORQUE VENT & PRESSURE HOSE S2808-4-0113	UNK		AE3663161E0113 SN-UNKNOWN	MTH 15-Feb-2016 HRS 1387.2 LDG 1122		120 3600	0 0	28-Feb-2026 4987.2	119 m 13 d 3600
770100	OIL PRESSURE HOSE	UNK		AE3663161E0230 SN-UNKNOWN	MTH 15-Feb-2016 HRS 1387.2 LDG 1122		120 3600	0 0	28-Feb-2026 4987.2	119 m 13 d 3600
773012	TRQ PRESSURE TRANSDUCER --	UNK		APTE51CF70D 7960-2-119	MTH 05-Oct-2012 HRS 1148.1 LDG 888		O/C			
770001 E1	TORQUE INDICATOR RCA70-2	*CF		2606011-3 A0510325	MTH 18-Mar-2005		O/C			
770002 E1	RPM PROP INDICATOR	*CF		2606014-2 04L395	MTH 18-Mar-2005		O/C			
770003 E1	ITT INDICATOR	*CF		2606012-1 05A501D	MTH 18-Mar-2005		O/C			
770004 E1	RPM INDICATOR RCA41-3	*CF		2606013-2 04E208	MTH 18-Mar-2005		O/C			
770010 E1 AFT	TACH GENERATOR OPT	*CF		22A703 92846	MTH 18-Mar-2005		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
770015 E1 FORWARD	TACH GENERATOR OPT	*CF		22A703 92913	MTH 18-Mar-2005		O/C			
780116	PRIMARY EXHAUST DUCT ASSEMBLY *CF			2654014-16 SN-UNKNOWN	MTH 18-Mar-2005		O/C			
780201	SECONDARY EXHAUST DUCT ASSEMBLY *CF			2654030-2 TRI04058	MTH 18-Mar-2005		O/C			
781100	EXHAUST DEFLECTOR/SA02080AK-D -- STC-SA02080AK-D			ED8-100 SN-UNKNOWN	MTH 21-Apr-2005 HRS 2		O/C	0		
791000	OIL COOLER RETURN HOSE UNK			AE3663163K0600 SN-UNKNOWN	MTH 15-Feb-2016 HRS 1387.2 LDG 1122		120 3600	0 0	28-Feb-2026 4987.2	119 m 13 d 3600
791020	ENGINE OIL BREATHER VENT HOSE			PN SN-UNKNOWN	MTH 18-Mar-2005 HRS 0		120 3600	0 0	31-Mar-2015 3600	-11 m 15 d 2212.8
792000	OIL COOLER SUPPLY HOSE S2808-12B0600 UNK			AE3663163K0600 SN-UNKNOWN	MTH 15-Feb-2016 HRS 1387.2 LDG 1122		120 3600	0 0	28-Feb-2026 4987.2	119 m 13 d 3600
792003	OIL PRESSURE SWITCH ASSEMBLY 9910287-16 *CF			1103P-65-16 4684	MTH 18-Mar-2005		O/C			
792005 790002	OIL TEMPERATURE/PRESSURE INDICATOR *CF			2606015-4 A0510172	MTH 18-Mar-2005		O/C			
790001 E1	OIL COOLER 9910085-2 *CF			10751B 1643	MTH 18-Mar-2005		O/C			
790020 E1	CHIP DETECTOR			PN SN-UNKNOWN	MTH 18-Mar-2005		O/C	0		

Over Due



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
<i>Position</i>	<i>Drawing # / Task #</i>	<i>City Mod Lvl Part Serial No</i>	<i>C/W Time 2</i>	<i>+ or -</i>	<i>TBO 2</i>	<i>TSO 2</i>	<i>DUE 2</i>	<i>Remains</i>
<i>SB CAB02-3 02SB03</i>	PLYWOOD FLOORBOARD INSTALL-5/8 INCH *CF	OPTIONAL	MTH		A/R			
MOC :								
<i>SB CAB05-10 05SB10</i>	ALTAIR ADAS+ PROCESSOR SOFTWARE MODIFICATION	OPTIONAL	MTH		A/R			
MOC :								
<i>SB CAB05-14 05SB14</i>	POH HANDBOOK S1 REVISION FTY	MANDATORY	MTH 29-Mar-2006 HRS 346		A/R			Complete
MOC : COMPLIED WITH								
<i>SB CAB05-8 05SB08</i>	POH TEMP REV/SUPPLEMENT FTY	MANDATORY	MTH 13-Dec-2005 HRS 280		A/R			Complete
MOC : COMPLIED WITH								
<i>SB CAB06-10 06SB10</i>	ELECTRICAL GROUND STRAP INSPECTION IWS	MANDATORY	MTH 25-Feb-2008 HRS 712		A/R			Complete
MOC : COMPLIED WITH								
<i>SB CAB06-3 06SB03</i>	CONTROL QUADRANT MOD HOU	RECOMMENDED	MTH 28-Jan-2011 HRS 944.1 LDG 595		A/R			Complete
MOC : COMPLIED WITH - COMMENTS: COMPLIED WITH SERVICE BULLETIN BY REPLACEMENT OF EMERGENCY POWER LEVER, FUEL CONDITION LEVER, QUADRANT COVER, AND INSTALLATION OF SK208-166. GROUND RUN UP AND OPERATIONAL CHECK WAS NORMAL. NO FURTHER ACTION REQUIRED.								
<i>SB CAB07-4 07SB04</i>	12 VOLT DIRECT CURRENT POWER OUTLETS INSTALLATION OPTIONAL		MTH		A/R			
MOC :								
<i>SB CAB07-5 07SB05</i>	POH REVISION HOU	MANDATORY	MTH 28-Jan-2011 HRS 944.1 LDG 595		A/R			Complete
MOC : COMPLIED WITH - COMMENTS: VERIFIED THAT PILOT'S OPERATING HANDBOOK PART NUMBER D1329R23-13PH WAS PREVIOUSLY INCORPORATED. INSTALLED LOG OF APPROVED SUPPLEMENTS PART NUMBER D1329-47-13SL, AND SUPPLEMENTS 60 THROUGH 64. NO FURTHER ACTION REQUIRED.								
<i>SNL 11-10</i>	GARMIN G1000 AOPA DATABASE	INFORMATIONAL			A/R			
MOC :								
<i>SNL 11-22</i>	SUBSCRIPTION TO AND USE OF PRATT & WHITNEY CANADA INTERNET-BASED ENGINE CONDITION TREND MONITORING WEBECTM® SERVICES	INFORMATIONAL			A/R			
MOC :								
<i>SNL 11-23</i>	P&WC PROPELLER-SHAFT OIL SEAL MODIFICATION	INFORMATIONAL			A/R			
MOC :								
<i>SNL 11-2</i>	REMOVAL OF AFFECTED APPROACHES IN DATABASE CYCLE 1013 FOR AIRPLANES WITH GARMIN G1000 AND WAAS	INFORMATIONAL			A/R			
MOC :								
<i>SNL 11-3</i>	2010 IGRF (INTERNATIONAL GEOMAGNETIC REFERENCE FIELD) MAGNETIC FIELD MODEL	INFORMATIONAL			A/R			
MOC :								

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB CAB07-3 <i>07SB03</i>	PILOTS OPERATING HANDBOOK SUPPLEMENT S1 REVISION AND OPERATION LIMITATION PLACARD INSTALLATION			MANDATORY	MTH 25-Mar-2008 HRS 722		A/R			Complete
MOC : COMPLIED WITH										
SB CAB08-5 <i>08SB05</i>	PILOTS ABBREVIATED CHECKLIST REVISION	HOU		RECOMMENDED	MTH 28-Jan-2011 HRS 944.1 LDG 595		A/R			Complete
MOC : COMPLIED WITH - COMMENTS: COMPLIED WITH SERVICE BULLETIN BY INCORPORATING PILOT'S ABBREVIATED CHECKLIST PART NUMBER D6177-23-13, REVISION 23. NO FURTHER ACTION REQUIRED.										
SL CAL-99-01	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			INFORMATIONAL			-			
MOC :										
SNL 11-29	CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION			INFORMATIONAL			-			
MOC :										
SL 2014-1C <i>P1</i>	PUBLICATION OF REVISED MCCAULEY MANUALS						-			
MOC :										
SL 2014-1D <i>P1</i>	PUBLICATION OF REVISED MCCAULEY MANUALS						-			
MOC :										
SB CAB11-5 R1	TIME LIMITS/MAINTENANCE CHECKS - NEW 208/208B TASK-BASED INSPECTION PROGRAM			OPTIONAL	MTH		-			
MOC :										
SB CAB11-5	TIME LIMITS/MAINTENANCE CHECKS - NEW 208/208B TASK-BASED INSPECTION PROGRAM	ORL			MTH 17-Sep-2012 HRS 1134.5 LDG 871		-			Complete
MOC : COMPLIED WITH										
SL CAL-05-01	TASK-BASED INSPECTION PROGRAM - TASK 0A FOR 14CFR PART 91.409 (A) AND (B)			INFORMATIONAL			-			
MOC :										
SB CAB11-7	ENGINE MOUNT INSPECTION FOR SUFFICIENT PAINT COVERAGE	UNK		RECOMMENDED	MTH 07-Nov-2012 HRS 1168.4		-			Complete
MOC : COMPLIED WITH										
SL CAL-20-01	LISTING OF NONDESTRUCTIVE TESTING FACILITIES			INFORMATIONAL			-			
MOC :										
SL CAL-51-01	STANDARD PRACTICES - STRUCTURES - USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL			-			
MOC :										
SL SEL-20-01 R1	LISTING OF NONDESTRUCTIVE TESTING FACILITIES			INFORMATIONAL			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL SEL-20-01	LISTING OF NONDESTRUCTIVE TESTING FACILITIES			INFORMATIONAL			-			
	MOC :									
SB CAB04-8 R1 <i>04SB08R1</i>	AIR CONDITIONER COMPRESSOR DRIVE INSPECTION	IWS		MANDATORY	MTH 07-Apr-2009 HRS 854		A/R			Complete
	MOC : COMPLIED WITH									
SB CAB05-11 R1	R134A AIR CONDITIONER SYSTEM INSTALLATION			OPTIONAL			A/R			
	MOC :									
SB CAB06-5 <i>06SB05</i>	HONEYWELL KS270C PITCH SERVO AND KS271C ROLL SERVO TACH GENERATOR MODIFICATION			OPTIONAL	MTH		A/R			
	MOC :									
SB CAB05-15 R1	CARAVAN SERVICE BULLETIN CAB05-15 REVISION 1: 300 AMPERE STARTER GENERATOR INSTALLATION			OPTIONAL			A/R			
	MOC :									
SB CAB08-2 <i>08SB02</i>	WING ELECTRICAL WIRING HARNESS INSPECTION	UNK		MANDATORY	MTH 17-Sep-2012 HRS 1134.5 LDG 871		A/R			N/A
	MOC : NOT APPLICABLE - BY A/C SERIAL NUMBER									
SL CAL-24-01	ALTERNATOR CONTROL UNIT INSPECTION			RECOMMENDED	MTH 12-Jun-2014 HRS 1288 LDG 1062		-			N/A
	MOC : NOT APPLICABLE - N/A DUE TO PART NOT BEING CHANGED IN PAST									
SL CAL-24-02	TRANSMITTAL OF HET SERVICE BULLETIN NO. 053			RECOMMENDED	MTH HRS		12 200		12-Sep-2014 1492.97	-18 m 3 d 105.77 Over Due
	MOC :									
SL CAL-24-03	ELECTRICAL POWER - SUPPLEMENTS TO ADDRESS ELECTRICAL REQUIREMENTS FOR OPERATION OF SINGLE-ENGINE PASSENGER-CARRYING AIRCRAFT FOR COMPENSATION OR HIRE			INFORMATIONAL			-			
	MOC :									
SK 208-165A	300 AMPERE STARTER-GENERATOR INSTALLATION			OPTIONAL			A/R			
	MOC :									
SB CAB-25-01	CARGO BARRIER MODIFICATION			OPTIONAL			-			
	MOC :									
SB CAB04-5 <i>04SB05</i>	SECURITY LOCK INSTALL	*CF		OPTIONAL	MTH		A/R			
	MOC :									
SB CAB06-6 <i>06SB06</i>	BEVERAGE CUP HOLDER INSTALL			OPTIONAL	MTH		A/R			
	MOC :									
SB CAB06-8 <i>06SB08</i>	POH SUP S1 REV & OP LMT PLACARD			MANDATORY	MTH 25-Mar-2008 HRS 722		A/R			Complete
	MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
SB CAB06-12 <i>06SB12</i>	ENGINE FIRE DETECTOR CABLE INSPECTION	MANDATORY	MTH 25-Mar-2008 HRS 722		A/R			N/A
	MOC : NOT APPLICABLE							
SB CAB06-9 <i>06SB09</i>	RUDDER SPAR INSPECTION	MANDATORY	MTH 25-Mar-2008 HRS 722		A/R			N/A
	MOC : NOT APPLICABLE							
SB CAB08-6 <i>08SB06</i>	AILERON CONTROL CABLE ATIACHMENT TO QUADRANT MODIFICATION	MANDATORY	MTH 17-Sep-2012 HRS 1134.5 LDG 871		-			N/A
	MOC : NOT APPLICABLE - BY A/C SERIAL NUMBER							
SB CAB09-2 <i>09SB02</i>	ELEVATOR PUSHROD PLACARDS INSTALLATION	MANDATORY	MTH 28-May-2010 HRS 939		A/R			Complete
	MOC : COMPLIED WITH							
SB CAB10-2 <i>10SB02</i>	INSTRUMENT PANEL CONTROL COLUMN CUTOUT MODIFICATION	MANDATORY	MTH 04-Aug-2011 HRS 950.3 LDG 611		A/R			Complete
	MOC : COMPLIED WITH							
SB CAB10-3 <i>10SB03</i>	WING AILERON CABLE AND PULLEY INSPECTION	MANDATORY	MTH 04-Aug-2011 HRS 950.3 LDG 611		A/R			Complete
	MOC : COMPLIED WITH							
SB CAB10-5 R1	FLAP PUSHROD ROD END INSPECTION	MANDATORY	MTH 04-Aug-2011 HRS 950.3 LDG 611		A/R			Complete
	MOC : COMPLIED WITH							
SB CAB10-5 <i>10SB05</i>	FLAP PUSH ROD ROD END INSPECTION	MANDATORY	MTH	3	A/R			
	MOC :							
SB CAB10-6	RIGHT INBOARD FLAP BELL CRANK BEARING INSPECTION / REPLACEMENT	MANDATORY	MTH 04-Aug-2011 HRS 950.3 LDG 611		A/R			Complete
	MOC : COMPLIED WITH							
SB CAB10-7	ELEVATOR HINGE BRACKET INSPECTION	MANDATORY	MTH 13-Oct-2011 HRS 988.5 LDG 658		A/R			Complete
	MOC : COMPLIED WITH							
SL CAL-27-04	RUDDER PEDAL RIVET INSPECTION	MANDATORY	MTH 12-Jun-2013 HRS 1280.7 LDG 1054		-			N/A
	MOC : NOT APPLICABLE - SL DOES NOT APPLY DUE TO S/N AND THE FACT THAT THE RUDDER PEDALS HAVE NEVER BEEN CHANGED. ALSO INSP PEDALS TO VERIFY THAT THE CORRECT RIVETS WERE INSTALLED							
SB CAB07-6 <i>07SB06</i>	FUEL CAPACITY PLACARD REPLACEMENT	MANDATORY	MTH 25-Feb-2008 HRS 712		A/R			Complete
	MOC : COMPLIED WITH							



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL CAL-28-02	FUEL - FUEL LINE COVER ASSEMBLIES SEALANT INSPECTION			MANDATORY			-			
	MOC :									
SB CAB-30-03	TKS FILL CAP PLACARD REPLACEMENT	UNK		RECOMMENDED	MTH 15-Feb-2016 HRS 1387.2 LDG 1122		-			N/A
	MOC :									
SB CAB-30-05 R1	SINGLE FILTER ELEMENT FOR TKS AIRCRAFT			OPTIONAL			-			
	MOC :									
SB CAB-30-05	SINGLE FILTER ELEMENT FOR TKS AIRCRAFT			OPTIONAL			-			
	MOC :									
SB CAB-30-07	TKS ICE WARNING PLACARD REPLACEMENT	UNK		MANDATORY	MTH 15-Feb-2016 HRS 1387.2 LDG 1122		-			N/A
	MOC :									
SB CAB09-9 09SB09	TKS ICE PROTECTION SYSTEM INSTALLATION			OPTIONAL	MTH		A/R			
	MOC :									
SL CAL-30-01 R1	TRANSMITTAL OF CAV AEROSPACE SERVICE LETTER SL 13120-10-30-001 CESSNA 208B CARAVAN TKS ICE PROTECTION SYSTEM FILTER ELEMENT REPLACEMENT			INFORMATIONAL			-			
	MOC :									
SL CAL-30-01 R2	ICE AND RAIN PROTECTION - TRANSMITTAL OF CAV AEROSPACE SERVICE LETTER SL 13120-10-30-001 CESSNA 208B CARAVAN TKS ICE PROTECTION SYSTEM FILTER ELEMENT REPLACEMENT			INFORMATIONAL			-			
	MOC :									
SL CAL-30-01	TRANSMITTAL OF CAV AEROSPACE SERVICE LETTER SL 13120-10-30-001 CESSNA 208B CARAVAN TKS ICE PROTECTION SYSTEM FILTER ELEMENT REPLACEMENT			INFORMATIONAL			-			
	MOC :									
SK 208-174D	TKS ICE PROTECTION SYSTEM INSTALLATION						-			
	MOC :									
SNL 11-30	FAA APPROVED DEICING PROGRAM UPDATE WINTER 2011-2012			INFORMATIONAL			A/R			
	MOC :									
SL HC--30-308 P1	DE-ICE: HARTZELL PMA DE-ICE COMPONENTS						-			
	MOC :									
SB CAB06-11 R1 06SB11 : 208R1	LOW A/S AWARENESS SYSTEM INSTALL			MANDATORY	MTH 25-Mar-2008 HRS 722		A/R			N/A
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB CAB-32-01 R1	BRAKE SYSTEM MODIFICATION AND CLEANSING PROCEDURE			MANDATORY	MTH HRS		18 400		14-Sep-2015 1713.43	-6 m 1 d 326.23
	MOC : DEFERRED									Over Due
SB CAB-32-01	BRAKE SYSTEM MODIFICATION AND CLEANSING PROCEDURE			MANDATORY			-			
	MOC :									
SB CAB-32-02	NLG SPRING FORWARD SUPPORT ASSEMBLY MODIFICATION			OPTIONAL	MTH		-			
	MOC :									
SB CAB-32-04	LANDING GEAR - MAIN LANDING GEAR TRUNNION AND FAIRING INSPECTION			MANDATORY			-			
	MOC :									
SB CAB05-16 05SB16	NLG LORD SHIMMY DAMPENER INSTALL			OPTIONAL			A/R			
	MOC :									
SB CAB05-17 05SB17	MLG TRUNNION & FAIRING INSP.			MANDATORY	MTH 25-Mar-2008 HRS 722		A/R			Complete
	MOC : COMPLIED WITH									
SB CAB06-7 06SB07	CARGO POD MLG OPENING MOD	SAT		OPTIONAL	MTH 04-Aug-2011 HRS 950.3 LDG 611		A/R			Complete
	MOC : COMPLIED WITH									
SB CAB07-1 07SB01	NOSE LANDING GEAR OVER TRAVEL INDICATOR/LORD SHIMMY DAMPENER INSTALLATION	IWS		RECOMMENDED	MTH 25-Feb-2008 HRS 712		A/R			Complete
	MOC : COMPLIED WITH									
SL CAL-32-02	TRANSMITTAL OF PARKER SERVICE BULLETIN SB7105			INFORMATIONAL			-			
	MOC :									
SSP 05-2 05SSP2	LANDING LIGHT LAMP INSPECTION	FTY		MANDATORY	MTH 30-Jun-2005 HRS 143		A/R			Complete
	MOC : COMPLIED WITH									
SB CAB05-11 05SB11	R134A A/C SYSTEM INSTALL			OPTIONAL	MTH		A/R			
	MOC :									
SB CAB05-15 05SB15	300 AMP STARTER-GENERATOR INSTALL			OPTIONAL	MTH		A/R			
	MOC :									
SB CAB05-2 05SB02	ARTEX ELT XSMTR INSTALL	*CF		OPTIONAL	MTH		A/R			
	MOC :									
SB CAB08-4 08SB04	ALTERNATE STATIC SOURCE SELECTOR VALVE INSPECTION	IWS		MANDATORY	MTH 07-Apr-2009 HRS 854		A/R			Complete
	MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB CAB08-7 R1	LOW AIRSPEED AWARENESS SYSTEM INSTALLATION	ORL		MANDATORY	MTH 17-Sep-2012 HRS 1134.5 LDG 871		A/R			N/A
MOC : NOT APPLICABLE - NOT FACTORY TKS AND SK208-174 NOT INSTALLED										
SNL 11-16	GARMIN SA1129A GRS77 LOSS OF FUNCTION			INFORMATIONAL			A/R			
MOC :										
SL CAL-51-03 R1	STANDARD PRACTICES - STRUCTURES - DRAIN HOLE INSPECTION			RECOMMENDED	MTH		-			
MOC :										
SL CAL-51-03	STANDARD PRACTICES - STRUCTURES - DRAIN HOLE INSPECTION	ORL		RECOMMENDED	MTH 17-Sep-2012 HRS 1134.5 LDG 871		-			N/A
MOC : NOT APPLICABLE - CARGO POD INSTALLED										
SL CAL-53-01	MAIN LANDING GEAR FITTING ATTACHMENT INSPECTION	ORL		MANDATORY	MTH 17-Sep-2012 HRS 1134.5 LDG 871		-			N/A
MOC : NOT APPLICABLE - DETERMINED CAL53-01 BY INSPECTION OF MLG FITTING ATTACHMENTS, OK FOR SERVICE										
SL CAL-53-02	FUSELAGE - ELEVATOR STOP BRACKET INSPECTION FOR RIVETS	FMY		MANDATORY	MTH 27-Nov-2012 HRS 1183.2 LDG 940		-			Complete
MOC : COMPLIED WITH										
SL CAL-53-04	AFT ELEVATOR BELLCRANK MOUNT BRACKET AND SUPPORT DOUBLER INSPECTION	UNK		MANDATORY	MTH 15-Feb-2016 HRS 1387.2 LDG 1122		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH BY VARIFICATION OF CORRECT DOUBLER INSTALLED IN AIRCRAFT										
SB CAB08-3 08SB03	WINDSHIELD ANTI-ICE PANEL SEAL MODIFICATION			RECOMMENDED	MTH 07-Apr-2009 HRS 854		A/R			N/A
MOC : NOT APPLICABLE										
SB CAB08-8 08SB08	STALL WARNING MARGIN ADJUSTMENT/RESET	HOU		MANDATORY	MTH 28-Jan-2011 HRS 944.1 LDG 595		A/R			Complete
MOC : COMPLIED WITH - COMMENTS: COMPLIED WITH SERVICE BULLETIN BY ADJUSTING STALL WARNING DETECTOR TO OPERATE AT 3.0 GRAMS, AS PER ACCOMPLISHMENT INSTRUCTIONS. STALL DETECTOR WAS FOUND TO BE PREVIOUSLY SET AT 4.2 GRAMS. NO FURTHER ACTION REQUIRED										
SB CAB09-4 R1 09SB04 : 208R1	AFT WING SPAR ATTACH BOLT RETAINING NUT TORQUE	DWH		MANDATORY	MTH 28-May-2010 HRS 939		A/R			Complete
MOC : COMPLIED WITH										
SL CAL-57-02	WINGS - AILERON TAB HINGE PIN INSPECTION			RECOMMENDED	MTH		-			
MOC :										
SB 267 P1	PROPELLER HUB SOCKET INSPECTION AND REPAIR			RECOMMENDED	MTH HRS		DUE DUE DUE		31-Aug-2017 4950.3	17 m 16 d 3563.1
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 2013-1 P1	SERVICE INFORMATION FOR MCCAULEY PRODUCTS						-			
	MOC :									
SL 2014-1E P1	PUBLICATION OF REVISED MCCAULEY MANUALS						-			
	MOC :									
SL 2014-2 P1	PROPELLER HUB STUD PLATING CHANGE						-			
	MOC :									
SB CAB-71-01	COWL LOCK MODIFICATION UNK			RECOMMENDED	MTH 15-Feb-2016 HRS 1387.2 LDG 1122		-			Complete
	MOC : COMPLIED WITH									
SB CAB09-1 09SB01	ENGINE INLET INERTIAL SEPARATOR DRAIN HOLE INSPECTION DWH			MANDATORY	MTH 28-May-2010 HRS 939		A/R			Complete
	MOC : COMPLIED WITH									
SL CAL-71-01	POWER PLANT - TRANSMITTAL OF PRATT & WHITNEY CANADA S.I.L. NO. GEN-119 INFORMATIONAL						-			
	MOC :									
SL CAL-71-03	POWER PLANT - TRANSMITTAL OF PRATT & WHITNEY CANADA S.B. NO. A1427R3 RECOMMENDED						-			
	MOC :									
SL CAL-71-08	TRANSMITTAL OF P&WC S.I.L NO. PT6A-204, S.I.L NO. GEN-125, PT6A SPB NO. 34R1, S.I.L NO GEN-116R1, AND S.I.L NO. GEN-123 INFORMATIONAL						-			
	MOC :									
SL CAL-71-09	TRANSMITTAL OF P&WC S.B. NO. 1669R9 RECOMMENDED				MTH HRS		12 200		01-Aug-2014 1504.7	-19 m 14 d 117.5 Over Due
	MOC :									
SL CAL-71-10	POWER PLANT - TRANSMITTAL OF P&WC S.B. NO. 1638R2, S.B. NO. 1714, S.I.L NO. PT6A-041R6, S.I.L NO. PT6A-107R1, S.I.L NO. PT6A-149R4, S.I.L NO. PT6A-201, S.I.L NO. PT6A-208 INFORMATIONAL						-			
	MOC :									
SL CAL-71-11	TRANSMITTAL OF P&WC S.B. NO. 1703R9, S.B. NO. 1717, S.B. NO. 1381R5, S.B. NO. 1721, S.B. NO. 1722, S.B. NO. 1002R28, S.B. NO. 1244R26, S.B. NO. 1727, S.I.L NO. PT6A-211, S.I.L NO. PT6A-208R1, S.I.L NO. PT6A-160R2, S.I.L NO. PT6A-146R1, S.I.L NO. PT6A-116R3, S.I.L NO. GEN-123R1, S.I.L NO. GEN-127, S.I.L GEN-027R4 INFORMATIONAL						-			
	MOC :									
SL CAL-71-12	TRANSMITTAL OF P&WC S.I.L. NO. PT6A-196R1, S.I.L. NO. GEN-123R2, S.I.L. NO. GEN-134, PT6A SPB NO. 185, PT6A SPB NO. 186, S.B. NO. 1002R29, S.B. NO. 1455R3, S.B. NO. 1521R5, S.B. NO. 1568R7, S.B. NO. 1588R2, S.B. NO. 1731, S.B. NO. 1733 INFORMATIONAL						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL CAL-71-13	TRANSMITTAL OF P&WC S.I.L. NO. GEN-PT6-034, S.B. NO. 1447R4, S.B. NO. 1703R10, S.B. NO. 1705R1, S.B. NO. 1722R1, S.B. NO. 1729, S.B. NO. 1737			INFORMATIONAL			-			
	MOC :									
SNL 11-25	P&WC ENGINE OPERATION IN VOLCANIC ASH CONDITIONS			INFORMATIONAL			A/R			
	MOC :									
SNL 11-26	P&WC OPERATION INTO RADIOACTIVE ENVIRONMENTS			INFORMATIONAL			A/R			
	MOC :									
SNL 11-27	P&WC PROPER POSITIONING OF LOCKING DEVICES AT ASSEMBLY			INFORMATIONAL			A/R			
	MOC :									
SB CAB05-7 <i>05SB07</i>	ENGINE SHROUD SEGMENT INSP. FTY			MANDATORY	MTH 13-Dec-2005 HRS 280		A/R			Complete
	MOC : COMPLIED WITH									
SB CAB09-5 <i>09SB05</i>	ENGINE COMPRESSOR TURBINE BLADES REPLACEMENT			RECOMMENDED	MTH		-			
	MOC :									
SB CAB10-1 R1 <i>10SB01 : 208R1</i>	PRATT & WHITNEY ENGINE SERVICES ADAS+ ETM TORQUE TRANSDUCER REPLACEMENT AND SOFTWARE UPDATE			OPTIONAL	MTH 05-Oct-2012 HRS 1148.1 LDG 888		-			Complete
	MOC : COMPLIED WITH									
SL CAL-12-02	SERVICING - TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN P&WC S.B. NO. 1001R29			INFORMATIONAL			-			
	MOC :									
SL CAL-72-03	ENGINE - TRANSMITTAL OF P&WC S.B. NO. 1703R7			INFORMATIONAL			-			
	MOC :									
SL CAL-72-04	TRANSMITTAL OF P&WC S.B. NO. 1657R1			INFORMATIONAL			-			
	MOC :									
SNL 11-20	ENGINE PERFORMANCE CHECKING CURVES			INFORMATIONAL			A/R			
	MOC :									
SB 1445 R3 E1	REPLACEMENT OF GAS GENERATOR CASE ASSEMBLIES CATEGORY 7						-			
	MOC :									
SB 72-1706 E1	PT6A-135A BUILD SPEC 1282 CONVERSION TO BUILD SPEC 1200						-			
	MOC :									
SB 72-1712 E1	REPLACEMENT OF POWER TURBINE STATOR ASSEMBLY						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 72-1803 R3 E1	OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY									
	MOC :									
SB 72-A1427 R3 E1	MODIFICATION OF POWER TURBINE CONTAINMENT RING			CATEGORY 4						
	MOC :									
SB PT6A-72-1001 R25 E1	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS									
	MOC :									
SB PT6A-72-1001 R26 E1	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS									
	MOC :									
SB PT6A-72-1001 R27 E1	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS									
	MOC :									
SB PT6A-72-1001 R28 E1	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS									
	MOC :									
SB PT6A-72-1001 R29 E1	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS				MTH					
	MOC :									
SB PT6A-72-1001 R30 E1	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS			RECOMMENDED						
	MOC :									
SB PT6A-72-1001 R31 E1	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS			RECOMMENDED						
	MOC :									
SB PT6A-72-1001 R32 E1	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS			RECOMMENDED						
	MOC :									
SB PT6A-72-1002 R26 E1	SERVICE LIFE ROTOR COMPONENTS									
	MOC :									
SB PT6A-72-1002 R27 E1	SERVICE LIFE ROTOR COMPONENTS									
	MOC :									
SB PT6A-72-1002 R28 E1	SERVICE LIFE ROTOR COMPONENTS									
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PT6A-72-1002 R29 E1	SERVICE LIFE ROTOR COMPONENTS									
	MOC :									
SB PT6A-72-1244 R23 E1	REQUIREMENTS AND APPROVED LISTING ENGINE FUELS AND ADDITIVES									
	MOC :									
SB PT6A-72-1244 R24 E1	REQUIREMENTS AND APPROVED LISTING ENGINE FUELS AND ADDITIVES									
	MOC :									
SB PT6A-72-1244 R25 E1	REQUIREMENTS AND APPROVED LISTING ENGINE FUELS AND ADDITIVES									
	MOC :									
SB PT6A-72-1244 R26 E1	ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING									
	MOC :									
SB PT6A-72-1381 R5 PART A E1	INSTALL REPLACEMENT OF PROPELLER SHAFT OIL SEAL DUST SEAL - INTRODUCTION OF PROPELLER SHAFT OIL SEAL RUNNER NEW PROPELLER SHAFT OIL SEAL RETAINING RING HALF ASSEMBLIES P/N 3114352-01 AND 3114353-01 AT FIELD MAINTENANCE OR REDUCTION GEARBOX OVERHAUL CATEGORY 7									
	MOC :									
SB PT6A-72-1381 R5 PART B E1	INSTALL REPLACEMENT OF PROPELLER SHAFT OIL SEAL DUST SEAL - INTRODUCTION OF PROPELLER SHAFT OIL SEAL RUNNER NEW PROPELLER SHAFT OIL SEAL RETAINING RING HALF ASSEMBLIES P/N 3114662-01 AT REDUCTION GEARBOX OVERHAUL CATEGORY 7									
	MOC :									
SB PT6A-72-1381 R5 E1	REPLACEMENT OF PROPELLER SHAFT OIL SEAL DUST SEAL - INTRODUCTION OF PROPELLER SHAFT OIL SEAL RUNNER CATEGORY 7									
	MOC :									
SB PT6A-72-1381 R6 PART A E1	INSTALL REPLACEMENT OF PROPELLER SHAFT OIL SEAL DUST SEAL - INTRODUCTION OF PROPELLER SHAFT OIL SEAL RUNNER NEW PROPELLER SHAFT OIL SEAL RETAINING RING HALF ASSEMBLIES P/N 3114352-01 AND 3114353-01 AT FIELD MAINTENANCE OR REDUCTION GEARBOX OVERHAUL CATEGORY 7									
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PT6A-72-1381 R6 PART B	INSTALL REPLACEMENT OF PROPELLER SHAFT OIL SEAL DUST SEAL - INTRODUCTION OF PROPELLER SHAFT OIL SEAL RUNNER NEW PROPELLER SHAFT OIL SEAL RUNNER P/N 3114662-01 AT REDUCTION GEARBOX OVERHAUL			CATEGORY 7						
E1	MOC :									
SB PT6A-72-1381 R6	REPLACEMENT OF PROPELLER SHAFT OIL SEAL DUST SEAL - INTRODUCTION OF PROPELLER SHAFT OIL SEAL RUNNER			CATEGORY 7						
E1	MOC :									
SB PT6A-72-1381 R7 PART A	ACCOMPLISH INSTALL NEW PROPELLER SHAFT OIL SEAL RETAINING RING HALF ASSEMBLIES P/N 3114352-01 AND 3114353-01			CATEGORY 7						
E1	MOC :									
SB PT6A-72-1381 R7 PART B	ACCOMPLISH INSTALL NEW PROPELLER SHAFT OIL SEAL RUNNER P/N 3114662-01			CATEGORY 7						
E1	MOC :									
SB PT6A-72-1381 R7	REPLACEMENT OF PROPELLER SHAFT OIL SEAL DUST SEAL - INTRODUCTION OF PROPELLER SHAFT OIL SEAL RUNNER			CATEGORY 7						
E1	MOC :									
SB PT6A-72-1386 R4	STARTER GENERATOR GEARSHAFT WET SPLINE DRIVE - INTRODUCTION OF			CATEGORY 8						
E1	MOC :									
SB PT6A-72-1404 R10 E1	INTRODUCTION OF BRONZE PLANET GEAR BEARINGS			CATEGORY 8						
E1	MOC :									
SB PT6A-72-1404 R9 E1	BRONZE PLANET GEAR BEARINGS - INTRODUCTION OF			CATEGORY 8						
E1	MOC :									
SB PT6A-72-1422 R5	IGNITION EXCITER BRACKET ASSEMBLY - REPLACEMENT/MODIFICATION OF			CATEGORY 8						
E1	MOC :									
SB PT6A-72-1439 R3 E1	REPLACEMENT OF NEW COMPRESSOR TURBINE BOLT			CATEGORY 6						
E1	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PT6A-72-1447 R4 E1	MODIFICATION OF TACHOMETER DRIVE BEVEL GEARSHAFT						-			
	MOC :									
SB PT6A-72-1447 R5 E1	MODIFICATION OF TACHOMETER DRIVE BEVEL GEARSHAFT						-			
	MOC :									
SB PT6A-72-1451 R4 E1	INTRODUCTION OF IMPROVED OIL FILLER TUBE WITH BALL VALVE ASSEMBLY			CATEGORY 3	MTH		36		20-Jul-2018	28 m 5 d
	MOC :									
SB PT6A-72-1455 R3 E1	REPLACEMENT OF COMPRESSOR TURBINE BLADE (SUPERSEDED BY SB PT6A-72-1669 R9)			CATEGORY 10			-			
	MOC :									
SB PT6A-72-1465 R2 E1	REPLACEMENT OF PROPELLER SHAFT OIL SEAL			CATEGORY 8			-			
	MOC :									
SB PT6A-72-1472 R5 E1	REPLACEMENT / MODIFICATION OF MANUAL OVERRIDE FUEL CONTROL UNIT			CATEGORY 5			-			
	MOC :									
SB PT6A-72-1510 R6 E1	MODIFICATION/REPLACEMENT OF THIRD-STAGE COMPRESSOR-STATOR ASSEMBLY - REPLACEMENT OF; IMPELLER HOUSING, COMPRESSOR BLEED-VALVE ASSEMBLY			CATEGORY 5			-			
	MOC :									
SB PT6A-72-1521 R4 E1	REPLACEMENT/MODIFICATION OF COMPRESSOR TURBINE DISK BALANCING ASSEMBLY AND BLADES (SUPERSEDED BY SB PT6A-72-1669 R9)			CATEGORY 8			-			
	MOC :									
SB PT6A-72-1521 R5 E1	REPLACEMENT/MODIFICATION OF COMPRESSOR TURBINE DISK BALANCING ASSEMBLY AND BLADES (SUPERSEDED BY SB PT6A-72-1669 R9)			CATEGORY 8			-			
	MOC :									
SB PT6A-72-1537 R3 E1	GAS GENERATOR CASE ASSEMBLY - REPLACEMENT/MODIFICATION OF			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PT6A-72-1537 R4 E1	REPLACEMENT / MODIFICATION OF GAS GENERATOR CASE ASSEMBLY			CATEGORY 7						
MOC :										
SB PT6A-72-1538 R4 E1	INSPECTION / REPLACEMENT OF BLEED OFF VALVE (BOV) COVER			CATEGORY 10						
MOC :										
SB PT6A-72-1560 R4 E1	ACCESSORY GEARBOX DIAPHRAGM ASSEMBLY - REPLACEMENT/MODIFICATION OF			CATEGORY 8						
MOC :										
SB PT6A-72-1561 R4 E1	MODIFICATION / REPLACEMENT OF FUEL CONTROL UNIT			CATEGORY 6						
MOC :										
SB PT6A-72-1568 R8 E1	MODIFICATION / REPLACEMENT OF FUEL CONTROL UNIT			CATEGORY 7						
MOC :										
SB PT6A-72-1570 R2 E1	INSPECTION OF NO. 1 BEARING OUTER HOUSING			CATEGORY 10						
MOC :										
SB PT6A-72-1578 R4 E1	MODIFICATION / REPLACEMENT OF FUEL CONTROL UNIT			CATEGORY 5						
MOC :										
SB PT6A-72-1591 R3 E1	REPLACEMENT/MODIFICATION OF COMPRESSOR STATORS			CATEGORY 7						
MOC :										
SB PT6A-72-1614 R2 E1	REPLACEMENT/MODIFICATION OF SHIPPING CONTAINER SKID BASE			CATEGORY 9						
MOC :										
SB PT6A-72-1625 R1 E1	CONVERSION OF PT6A-114 (BS642) MODEL TO PT6A-114A (BS750) CONFIGURATION			CATEGORY 8						
MOC :										
SB PT6A-72-1638 R2 E1	REPLACEMENT OF SEAL, PLAIN			CATEGORY 6						
MOC :										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PT6A-72-1647 R1 E1	REPLACEMENT OF ACCESSORY GEARBOX KEY WASHERS AND OIL TRAY			CATEGORY 7			-			
MOC :										
SB PT6A-72-1652 R1 E1	REPLACEMENT / MODIFICATION OF PROPELLER-SHAFT OIL SEAL RETAINING-RING-HALVES			CATEGORY 7			-			
MOC :										
SB PT6A-72-1654 R2 E1	REPLACEMENT OF OIL FILTER ELEMENT			CATEGORY 8			A/R			
MOC :										
SB PT6A-72-1655 R2 E1	REPLACEMENT OF P3 AIR-PRESSURE-TUBE ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PT6A-72-1657 R1 E1	REPLACEMENT OF NEW OIL TANK FILLER CAP AND GAGE ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PT6A-72-1657 R2 E1	REPLACEMENT OF NEW OIL TANK FILLER CAP AND GAGE ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PT6A-72-1657 R3 E1	REPLACEMENT OF NEW OIL TANK FILLER CAP AND GAGE ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PT6A-72-1659 R1 E1	REPLACEMENT OF OIL FILLER-TUBE-VALVE ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PT6A-72-1660 E1	TURBOPROP ENGINE - LOCK PLATE - REPLACEMENT OF			CATEGORY 7			-			
MOC :										
SB PT6A-72-1669 R7 E1	REPLACEMENT OF COMPRESSOR TURBINE BLADES			CATEGORY 6			-			
MOC :										
SB PT6A-72-1669 R8 E1	REPLACEMENT OF COMPRESSOR TURBINE BLADES			CATEGORY 6			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
SB PT6A-72-1669 R9 PART A	BORESCOPE INSPECTION INSPECTION/REPLACEMENT OF COMPRESSOR TURBINE BLADES OF CT BLADE TRAILING EDGE							
E1		UNK CATEGORY 3	MTH 15-Feb-2016 HRS 1387.2 LDG 1122		400		1787.2	400 Complete
	MOC : COMPLIED WITH - COMPLIED WITH BORESCOPE INSPECTION BORESCOPE DONE BY TSI, TURIN SOURCE INTERNATIONAL UNDER THEIR WORK ORDER NUMBER 2898 SEE BORESCOPE REPORT DATED JAN 7,2016							
SB PT6A-72-1669 R9 PART B	ACCOMPLISH INSPECTION/REPLACEMENT OF COMPRESSOR TURBINE BLADES FOR ENGINES AT HSI(SUBMIT A TWO-CT BLADE SAMPLE FOR METALLURGICAL EVALUATION)							
E1		CATEGORY 3			-			
	MOC :							
SB PT6A-72-1669 R9 PART C	REPLACEMENT INSPECTION/REPLACEMENT OF COMPRESSOR TURBINE BLADES OF CT BLADES							
E1		CATEGORY 3 MTH			36		28-Jun-2016	3 m 13 d
	MOC :							
SB PT6A-72-1669 R9	INSPECTION/REPLACEMENT OF COMPRESSOR TURBINE BLADES							
E1		CATEGORY 3			-			
	MOC :							
SB PT6A-72-1670 R1	REPLACEMENT/MODIFICATION OF PROPELLER-SHAFT OIL SEAL RETAINING-RING-HALVES							
E1		CATEGORY 7			-			
	MOC :							
SB PT6A-72-1670 E1	PROPELLER-SHAFT OIL SEAL RETAINING-RING-HALVES - REPLACEMENT/MODIFICATION OF							
E1		CATEGORY 7			-			
	MOC :							
SB PT6A-72-1678 R1	REPLACEMENT/MODIFICATION OF COMPRESSOR BLADES							
E1		CATEGORY 7			-			
	MOC :							
SB PT6A-72-1678 R2	REPLACEMENT/MODIFICATION OF COMPRESSOR BLADES							
E1		CATEGORY 7			-			
	MOC :							
SB PT6A-72-1680 R1	REPLACEMENT OF IGNITION EXCITER							
E1		CATEGORY 10			A/R			
	MOC :							
SB PT6A-72-1681 R1	REPLACEMENT/MODIFICATION OF COMPRESSOR BLEED VALVE							
E1		CATEGORY 7			-			
	MOC :							



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PT6A-72-1681 R2	REPLACEMENT/MODIFICATION OF COMPRESSOR BLEED VALVE			CATEGORY 7			-			
E1	MOC :									
SB PT6A-72-1681 R3	REPLACEMENT / MODIFICATION OF COMPRESSOR BLEED VALVE			CATEGORY 7			-			
E1	MOC :									
SB PT6A-72-1688 E1	PT6A-135A CONVERSION FROM BUILD SPEC 1200 TO BUILD SPEC 1248			CATEGORY 8			-			
E1	MOC :									
SB PT6A-72-1689 E1	REPLACEMENT OF FRONT PUSH/PULL CONTROL SWIVEL JOINT CASING			CATEGORY 7			-			
E1	MOC :									
SB PT6A-72-1692 R1 E1	INSPECTION OF OIL SCAVENGE HOSE			CATEGORY 5			-			
E1	MOC :									
SB PT6A-72-1693 E1	REPLACEMENT OF NO.2 BEARING OIL PACKING			CATEGORY 6			-			
E1	MOC :									
SB PT6A-72-1703 R10	OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY						-			
E1	MOC :									
SB PT6A-72-1703 R11	OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY						-			
E1	MOC :									
SB PT6A-72-1703 R7	OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY						-			
E1	MOC :									
SB PT6A-72-1703 R8	OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY						-			
E1	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PT6A-72-1703 R9	OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY									
E1	MOC :									
SB PT6A-72-1705 R1	INSPECTION OF TURBOPROP ENGINE WITH HAMILTON SUNSTRAND FUEL PUMP, COUPLING SHAFT SPLINE									
E1	CATEGORY 3									
E1	MOC : NOT APPLICABLE									
SB PT6A-72-1705 E1	INSPECTION OF TURBOPROP ENGINE WITH HAMILTON SUNSTRAND FUEL PUMP COUPLING SHAFT SPLINE									
E1	KFMY			CATEGORY 3	MTH 12-Nov-2012					Complete
E1	MOC : COMPLIED WITH									
SB PT6A-72-1711 R1	DELETION OF VANERING DAMPING STRAP									
E1	CATEGORY 6									
E1	MOC :									
SB PT6A-72-1714 R1	REVERSED POSITION ADJUSTER BOLT INSTALLATION									
E1	CATEGORY 8									
E1	MOC :									
SB PT6A-72-1714 E1	REVERSED POSITION ADJUSTER BOLT INSTALLATION									
E1	CATEGORY 8									
E1	MOC :									
SB PT6A-72-1727 E1	REPLACEMENT OF COMPRESSOR TURBINE BLADES									
E1	CATEGORY 7									
E1	MOC :									
SB PT6A-72-1732 R1	REPLACEMENT OF ENGINE IDENTIFICATION AND TRIM SPEED INSTRUCTION PLATE									
E1	CATEGORY 10									
E1	MOC :									
SB PT6A-72-1738 E1	REPLACEMENT OF PROPELLER CONTROL CAM									
E1	CATEGORY 8									
E1	MOC :									
SB PT6A-72-1739 E1	REPLACEMENT OF COMPRESSOR DELIVERY AIR LINES GROUP WITH P3 AIR FILTER									
E1	CATEGORY 8									
E1	MOC :									
SB PT6A-72-1741 E1	REPLACEMENT OF SHIPPING CAPS FOR SHIPPING CONTAINERS									
E1	CATEGORY 3									
E1	MOC :									
SB PT6A-72-1744 E1	REPLACEMENT OF OIL-FILLER-TUBE, OIL-FILLER-CAP AND GAGE ASSEMBLY									
E1	CATEGORY 6									
E1	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PT6A-72-1746 E1	REPLACEMENT OF ENGINE SHIPPING CONTAINER ASSEMBLY MOC :			CATEGORY 7			-			
SB PT6A-72-1747 E1	REPLACEMENT OF SAFETY CABLE MOC :			CATEGORY 7			-			
SB PT6A-72-1748 R1 E1	INSPECTION OF FUEL CONTROL UNIT MOC :			CATEGORY 5			-			
SB PT6A-72-1748 E1	INSPECTION OF FUEL CONTROL UNIT MOC :			CATEGORY 4			-			
SB PT6A-72-1749 E1	REPLACEMENT OF COMPRESSOR TURBINE BLADES MOC :			CATEGORY 7			-			
SB PT6A-72-1754 R1 E1	INSPECTION/REPLACEMENT OF FUEL PUMP MOC :			CATEGORY 5	MTH HRS		DUE DUE DUE		01-Jan-2020 1800	45 m 17 d 412.8
SB PT6A-72-1754 E1	INSPECTION/REPLACEMENT OF FUEL PUMP MOC :			CATEGORY 6			-			
SB PT6A-72-1759 R1 E1	INSPECTION OF COMPRESSOR TURBINE DISK ASSEMBLY INTERPLATFORM GAP MOC :			CATEGORY 5			-			
SB PT6A-72-1759 E1	INSPECTION OF COMPRESSOR TURBINE DISK ASSEMBLY INTERPLATFORM GAP MOC :			CATEGORY 5			-			
SB PT6A-72-1761 R1 E1	INTRODUCTION OF IMPROVED OIL FILLER TUBE WITH BALL VALVE ASSEMBLY MOC :			CATEGORY 3			-			
SB PT6A-72-1761 R2 E1	INTRODUCTION OF IMPROVED OIL FILLER TUBE WITH BALL VALVE ASSEMBLY MOC :			CATEGORY 3			-			
SB PT6A-72-1761 R3 E1	INTRODUCTION OF IMPROVED OIL FILLER TUBE WITH BALL VALVE ASSEMBLY MOC :			CATEGORY 3	MTH		36		16-Sep-2018	30 m 1 d



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
SB PT6A-72-1761 E1	INTRODUCTION OF IMPROVED OIL FILLER TUBE WITH BALL VALVE ASSEMBLY	CATEGORY 5			-			
MOC :								
SB PT6A-72-1762 R1 E1	INSPECTION OF COMPRESSOR TURBINE BLADES	CATEGORY 6			-			
MOC :								
SB PT6A-72-1762 E1	INSPECTION OF COMPRESSOR TURBINE BLADES	CATEGORY 6			-			
MOC :								
SB PT6A-72-1764 R1 E1	REPLACEMENT / MODIFICATION OF ACCESSORY GEARBOX HOUSING ASSEMBLY	CATEGORY 6			-			
MOC :								
SB PT6A-72-1764 R2 E1	REPLACEMENT / MODIFICATION OF ACCESSORY GEARBOX HOUSING ASSEMBLY	CATEGORY 6			-			
MOC :								
SB PT6A-72-1764 E1	REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX HOUSING ASSEMBLY	CATEGORY 6			-			
MOC :								
SB PT6A-72-1766 E1	INSPECTION OF INTERCONNECT ROD	CATEGORY 3	MTH HRS		12 150		13-Jul-2016 1593	3 m 28 d 205.8
MOC :								
SB PT6A-72-1768 R1 E1	REPLACEMENT / MODIFICATION OF COMPRESSOR TURBINE VANE RING AND NO. 2 BEARING HOUSING ASSEMBLY COVER	CATEGORY 6			-			
MOC :								
SB PT6A-72-1768 R2 E1	REPLACEMENT / MODIFICATION OF COMPRESSOR TURBINE VANE RING AND NO. 2 BEARING HOUSING ASSEMBLY COVER	CATEGORY 6			-			
MOC :								
SB PT6A-72-1768 R3 E1	REPLACEMENT / MODIFICATION OF COMPRESSOR TURBINE VANE RING AND NO. 2 BEARING HOUSING ASSEMBLY COVER	CATEGORY 6			-			
MOC :								
SB PT6A-72-1768 E1	REPLACEMENT / MODIFICATION OF COMPRESSOR TURBINE VANE RING AND NO. 2 BEARING HOUSING ASSEMBLY COVER	CATEGORY 6			-			
MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PT6A-72-1769 E1	REPLACEMENT/MODIFICATION OF COMPRESSOR DISK BALANCING ASSEMBLY			CATEGORY 6			-			
MOC :										
SB PT6A-72-1773 E1	REPLACEMENT OF OVERSPEED GOVERNOR WASHER			CATEGORY 5			-			
MOC :										
SB PT6A-72-1780 E1	CONVERSION OF PT6A-135 (BS529) TO PT6A-135A (BS1282)			CATEGORY 8			-			
MOC :										
SB PT6A-72-1784 E1	REIDENTIFICATION OF SPECIFIC FUEL CONTROL UNIT	UNK		CATEGORY 3	MTH 15-Feb-2016 HRS 1387.2 LDG 1122				DUE DUE DUE DUE	N/A
MOC : NOT APPLICABLE - DOES NOT APPLY PER FCU SERIAL NUMBER										
SB PT6A-72-1786 E1	REPLACEMENT OF FUEL CONTROL UNIT SAFETY CABLE			CATEGORY 7			-			
MOC :										
ASB PT6A-72-A1774 R1 E1	INSPECTION OF FUEL CONTROL UNIT						-			
MOC :										
ASB PT6A-72-A1774 R2 E1	INSPECTION OF FUEL CONTROL UNIT.	UNK		CATEGORY 3	MTH 15-Feb-2016 HRS 1387.2 LDG 1122		25		1412.2	N/A 25 N/A
MOC : NOT APPLICABLE - DOES NOT APPLY PER FCU SERIAL NUMBER										
ASB PT6A-72-A1774 E1	INSPECTION OF FUEL CONTROL UNIT			CATEGORY 3	MTH		-			
MOC :										
SB CAB05-18 05SB18	ENGINE FUEL PUMP COUPLING INSP.			MANDATORY	MTH HRS		-239	3600	3600	2212.8
MOC :										
SB CAB08-1 08SB01	FUEL CONTROL UNIT ROD END HARDWARE REPLACEMENT	HOU		RECOMMENDED	MTH 28-Jan-2011 HRS 944.1 LDG 595			A/R		Complete
MOC : COMPLIED WITH - COMMENTS: VERIFIED THROUGH VISUAL INSPECTION THAT CAB08-1 WAS PREVIOUSLY ACCOMPLISHED BY COMPLIANCE WITH P&WC SERVICE BULLETIN NO. 1658R3 AND P&WC SERVICE BULLETIN NO. 1666R1. NO FURTHER ACTION REQUIRED										
SL CAL-73-01	ENGINE FUEL AND CONTROL - TRANSMITTAL OF P&WC S.B. NO. 1705	KTMB		MANDATORY	MTH 22-Oct-2013 HRS 1283 LDG 1058		-			N/A
MOC : NOT APPLICABLE										
SL CAL-73-05	TRANSMITTAL OF P&WC S.B. NO. 1748			INFORMATIONAL			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PT6A-72-1687 E1	INSPECTION/REPLACEMENT OF PY AND P3 INSULATED AIR PRESSURE TUBES			CATEGORY 5			A/R			
MOC :										
SB CAB07-7 07SB07	ENGINE SPARK IGNITERS INSPECTION			MANDATORY	MTH 25-Feb-2008 HRS 712		A/R			N/A
MOC : NOT APPLICABLE										
SB CAB-77-02	ENGINE INDICATING - NEW CONFIGURATION FILE FOR ADAS SYSTEMS			OPTIONAL			-			
MOC :										
SB CAB07-2 07SB02	ENGINE PRIMARY EXHAUST DUCT INSPECTION	IWS		MANDATORY	MTH 25-Feb-2008 HRS 712		A/R			Complete
MOC : COMPLIED WITH										
SB CAB05-9 05SB09	ENGINE OIL FILLER CAP INSP.	FTY		MANDATORY	MTH 30-Jun-2005 HRS 143		A/R			Complete
MOC : COMPLIED WITH										
SB CAB09-3 09SB03	LINE AND TUBE ASSEMBLIES INSPECTION	DWH		MANDATORY	MTH 28-May-2010 HRS 939		-			Complete
MOC : COMPLIED WITH										
SB CAB11-6	OIL SCAVENGE HOSE INSPECTION	UNK		RECOMMENDED	MTH 07-Nov-2012 HRS 1168.4		A/R			N/A
MOC : NOT APPLICABLE - BY INSTALLED HOSE P/N										
SB PT6A-72-1692 E1	INSPECTION OF OIL SCAVENGE HOSE			CATEGORY 5			-			
MOC :										
SL CAL-80-01	STARTING - 200-AMP STARTER GENERATOR MODIFICATION AT OVERHAUL			INFORMATIONAL			-			
MOC :										
SL CAL-80-02	TRANSMITTAL OF SKURKA AEROSPACE INC. SERVICE LETTER # 231 REV. A			INFORMATIONAL			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 1997-25-04	POWER LEVER POSITIONING UNK			MANDATORY	MTH 17-Sep-2012 HRS 1134.5 LDG 871		A/R			Complete
MOC : COMPLIED WITH - PCW										
FAA 2004-17-01	INSP FLAP BELLCRANK WELD UNK			MANDATORY	MTH 17-Sep-2012 HRS 1134.5 LDG 871		A/R			N/A
MOC : NOT APPLICABLE - BY A/C SERIAL NUMBER										
FAA 2006-01-11 <i>03AD-04</i>	DEICE BOOT/POH REV/AST HANDLE UNK			MANDATORY	MTH 17-Sep-2012 HRS 1134.5 LDG 871		A/R			Complete
MOC : COMPLIED WITH - PCW										
FAA 2006-06-06 <i>03AD-05</i>	AFM REVISION-ICING CONDITIONS FTY			MANDATORY	MTH 29-Mar-2006 HRS 346		A/R			Complete
MOC : COMPLIED WITH										
FAA 2006-01-11 REV1	DEICE BOOT/ASSIST HANDLE UNK			MANDATORY	MTH 17-Sep-2012 HRS 1134.5 LDG 871		A/R			Complete
MOC : COMPLIED WITH - PCW										
FAA 2008-13-06 <i>13AD-06</i>	DETECT AND CORRECT DAMAGED WIRING OF THE AUTO-CONTROL WING DE-ICE SYSTEM, FUEL QUANTITY INDICATION, AND LOW FUEL ANNUNCIATION SYSTEMS UNK			MANDATORY	MTH 17-Sep-2012 HRS 1134.5 LDG 871		-			Complete
MOC : COMPLIED WITH - PCW										
FAA 2015-10-02 (G)	GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2 MANDATORY						-			
MOC :										
FAA 2015-10-02 (H)	CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK MANDATORY						-			
MOC :										
FAA 2015-10-02 (I)	REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS MANDATORY						-			
MOC :										
FAA 2015-10-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT MANDATORY				MTH		-			
MOC :										
FAA 1988-19-06	PREVENT POSSIBLE ELEVATOR FLUTTER UNK			MANDATORY	MTH 17-Sep-2012 HRS 1134.5 LDG 871		A/R			N/A
MOC : NOT APPLICABLE - BY A/C SERIAL NUMBER										



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 1990-05-01	TO PREVENT FAILURE OF THE PART NUMBER (P/N) 2622083-18 BELLCRANK ASSEMBLY AND THE RESULTING UNEXPECTED RETRACTION OF THE FLAPS	UNK		MANDATORY	MTH 17-Sep-2012 HRS 1134.5 LDG 871		A/R			N/A
MOC : NOT APPLICABLE - BY A/C SERIAL NUMBER										
FAA 2009-05-12 27AD-07	MODIFY THE AILERON CARRY-THROUGH CABLE ATTACHMENT TO THE AILERON UPPER QUADRANT WITH PARTS OF IMPROVED DESIGN	UNK		MANDATORY	MTH 17-Sep-2012 HRS 1134.5 LDG 871		-			Complete
MOC : COMPLIED WITH - PCW										
FAA 2009-15-05	MEASURE AND ADJUST AS NECESSARY, THE ROLL BRIDLE CABLE TENSION AND YAW BRIDLE CABLE TENSION, AND TORQUE THE 12 BRIDLE CABLE CLAMP SCREWS	UNK		MANDATORY	MTH 17-Sep-2012 HRS 1134.5 LDG 871		-			N/A
MOC : NOT APPLICABLE - BY A/C SERIAL NUMBER										
FAA 1997-01-13	TO PREVENT FUEL, OIL, OR HYDRAULIC SYSTEMS FAILURE CAUSED BY A COLLAPSED HOSE	UNK		MANDATORY	MTH 17-Sep-2012 HRS 1134.5 LDG 871		A/R			N/A
MOC : NOT APPLICABLE - NOT INSTALLED										
FAA 1996-09-15	TO MINIMIZE THE POTENTIAL HAZARDS ASSOCIATED WITH OPERATING THE AIRPLANE IN SEVERE ICING CONDITIONS	UNK		MANDATORY	MTH 17-Sep-2012 HRS 1134.5 LDG 871		A/R			Complete
MOC : COMPLIED WITH - PCW										
FAA 2005-07-01 03AD-03	PILOT INFORMATION ON ICING CONDITIONS	FTY		MANDATORY	MTH 29-Sep-2005 HRS 236		A/R			Complete
MOC : COMPLIED WITH - SUPERSEDED BY AD2006-06-06.										
FAA 2007-10-15 07AD-10	KNOWN ICING EQUIPMENT AFM SUPPLEMENT	UNK		MANDATORY	MTH 17-Sep-2012 HRS 1134.5 LDG 871		A/R			Complete
MOC : COMPLIED WITH - PCW										
FAA 1990-05-04	TO PREVENT NOSE LANDING GEAR SHIMMY AND FAILURE OF THE ENGINE MOUNT RING	UNK		MANDATORY	MTH 17-Sep-2012 HRS 1134.5 LDG 871		A/R			N/A
MOC : NOT APPLICABLE - BY A/C SERIAL NUMBER										
FAA 1993-12-04	APPLICABILITY: PRECISE FLIGHT, INC., PULSELITE UNITS, MODEL 1210-2405-2; SERIAL NUMBERS X00150 THROUGH X01371, INCLUSIVE; AS INSTALLED IN VARIOUS SMALL AIRPLANES IN ACCORDANCE WITH SUPPLEMENTAL TYPE CERTIFICATE (STC) SA4005NM; CERTIFICATED IN ANY CATEGORY.				MTH 17-Sep-2012		A/R			N/A
MOC : NOT APPLICABLE - BY DATE.										
FAA 2001-23-17	APPLIANCE AD - TO PREVENT INACCURATE COURSE DEVIATION DISPLAYS IN THE GNS 430 UNIT	UNK		MANDATORY	MTH 17-Sep-2012 HRS 1134.5 LDG 871		A/R			N/A
MOC : NOT APPLICABLE - BY DATE										



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2005-01-19	APPLIANCE AD - GTX 33/33D/330/330D SOFTWARE UPGRADE	UNK		MANDATORY	MTH 17-Sep-2012 HRS 1134.5 LDG 871		A/R			Complete
	MOC : COMPLIED WITH - PCW									
FAA 2006-16-18 34AD-06	APPLIANCE AD - SANDEL ST3400 TAWS/RMI PLACARD			MANDATORY	MTH 09-Oct-2006 HRS 522		A/R			Complete
	MOC : COMPLIED WITH									
FAA 2008-10-02 08AD-10	INSPECT THE ALTERNATE STATIC AIR SOURCE SELECTOR VALVE TO ASSURE THAT THE PART NUMBER IDENTIFICATION PLACARD IS NOT OBSTRUCTING THE PORT	UNK		MANDATORY	MTH 17-Sep-2012 HRS 1134.5 LDG 871		-			Complete
	MOC : COMPLIED WITH - PCW									
FAA 2008-26-10 08AD-26	INSPECT ALTERNATE STATIC AIR SOURCE SELECTOR VALVE FOR OBSTRUCTION BY PLACARD.	UNK		MANDATORY	MTH 17-Sep-2012 HRS 1134.5 LDG 871		A/R			Complete
	MOC : COMPLIED WITH - PCW									
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION			MANDATORY	MTH		-			
	MOC :									
FAA 2015-10-51-E	APPLIANCE/EMERGENCY AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.			MANDATORY			-			
	MOC :									
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS	UNK		MANDATORY	MTH 15-Feb-2016 HRS 1387.2 LDG 1122		-			N/A
	MOC : NOT APPLICABLE - DOES NOT APPLY PER AVIONICS INSTALLED									
FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011			MANDATORY	MTH		24		16-Jun-2017	15 m 1 d
	MOC :									
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PAPERGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSES			MANDATORY	MTH		24		16-Jun-2017	15 m 1 d
	MOC :									
FAA 2015-08-07	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSES			MANDATORY			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2015-23-09 PARA (G)	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER	UNK		MANDATORY	MTH HRS 1387.2 LDG 1122		-			Complete
MOC : COMPLIED WITH - ON DEMAND OXYGEN MASK INSTALLED IN AIRCRAFT WITH NO REGULATOR INSTALLED										
FAA 2015-23-09 PARA (H)(1)	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).	UNK		MANDATORY	MTH HRS 1387.2 LDG 1122		-			N/A
MOC : NOT APPLICABLE - DOES NOT APPLY PER OXYGEN MASK PART NUMBERS										
FAA 2015-23-09 PARA (H)(2)(I)	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1			MANDATORY	DAYS		30		27-Jan-2016	-1 m 17 d Over Due
MOC :										
FAA 2015-23-09 PARA (H)(2)(II)	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."	UNK		MANDATORY	MTH HRS 1387.2 LDG 1122		-			N/A
MOC : NOT APPLICABLE - DOES NOT APPLY, PLACARD PREVIOUSLY INSTALLED IN AIRCRAFT										
FAA 2015-23-09 PARA (I)	REGULATOR REPLACEMENT			MANDATORY	MTH		12		28-Dec-2016	9 m 13 d
MOC :										
FAA 2015-23-09	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS			MANDATORY	MTH		-			
MOC :										
FAA 2004-08-17	TO DETECT AND CORRECT LOOSE AND IMPROPERLY TIED NUTS ON THE WING STRUTS	UNK		MANDATORY	MTH 17-Sep-2012 HRS 1134.5 LDG 871		A/R			N/A
MOC : NOT APPLICABLE - BY A/C SERIAL NUMBER										
FAA 2005-14-11	PREVENT BLADE FAILURE	UNK		MANDATORY	MTH 17-Sep-2012 HRS 1134.5 LDG 871		A/R			N/A
MOC : NOT APPLICABLE - N/A BY NOT RETURNED TO SERVICE BY NAMED REPAIR STATION										
AD 61-04 P1	HARTZELL PROP SLUG ATTACH BOLT				MTH 28-May-2010 HRS 939		-			N/A
MOC : NOT APPLICABLE										
FAA 1997-04-12 E1	PERFORM A VISUAL INSPECTION OF COMPRESSOR BOV'S	UNK		MANDATORY	MTH 17-Sep-2012 HRS 1134.5 ENC 871		-			N/A
MOC : NOT APPLICABLE - BY NOT INSTALLED										



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2001-20-01 E1	TO DETECT WEAR IN THE COMPRESSOR BLEED VALVE ASSEMBLY WHICH MAY CAUSE VALVE ORIFICE BLOCKAGE	UNK		MANDATORY	MTH 17-Sep-2012 HRS 1134.5 ENC 871		-			N/A
	MOC : NOT APPLICABLE - BY DATE									
FAA 1990-12-05	APPLICABILITY: PRATT & WHITNEY CANADA (PWC) PT6A SERIES TURBOPROPELLER ENGINES REPAIRED BY GREGORY FLYING SERVICE/AIRFORCE TURBINE SERVICE (HEREAFTER IDENTIFIED AS GREGORY FLYING SERVICE), LOCATED IN TYNAN, TEXAS.				MTH 17-Sep-2012		A/R			N/A
	MOC : NOT APPLICABLE - N/A. NOT RETURNED TO SERVICE BY NAMED REPAIR STATION.									
FAA 2012-09-10 E1	REMOVE FROM SERVICE PMA REPLACEMENT TAATI FIRST STAGE SUN GEAR AND THE PLANET GEARS FROM THE PROPELLERREDUCTION GEARBOX ASSEMBLY	ORL		MANDATORY	MTH 17-Sep-2012 HRS 1134.5 LDG 871		-			N/A
	MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED									
FAA 2014-11-05 E1	MODIFY THE EXISTING POWER TURBINE CONTAINMENT RING			MANDATORY	MTH		48		05-Aug-2018	28 m 21 d
	MOC :									
FAA 2014-17-08 (BSI) E1	PERFORM BORESCOPE INSPECTION			MANDATORY			-			
	MOC :									
FAA 2014-17-08 (HSI) E1	REPLACE CT BLADES AT HSI			MANDATORY			-			
	MOC :									
FAA 2014-17-08 (REPLACE) E1	MANDATORY TERMINATING ACTION			MANDATORY			-			
	MOC :									
FAA 2014-17-08 R1 PARA (E)(1)(I) E1	ACCOMPLISH BORESCOPE INSPECTION OF CT BLADE LEADING AND TRAILING EDGES (FOR ENGINES INSTALLED WITH CT BLADES OTHER THAN P&WC SINGLE CRYSTAL CT BLADES, PART NUMBERS (P/NS) 3072791-01, 3072791-02, OR 3079351-01)			MANDATORY	MTH HRS		150		1472.53	85.33
	MOC :									
FAA 2014-17-08 R1 PARA (E)(1)(III) E1	REPLACE THE COMPLETE SET OF CT BLADES			MANDATORY	MTH HRS		DUE DUE DUE		1800	412.8
	MOC :									
FAA 2014-17-08 R1 PARA (E)(2) E1	TERMINATION ACION - REPLACEMENT OF THE COMPLETE SET OF CT BLADES WITH SINGLE CRYSTAL CT BLADES, P/N 3072791-01, 3072791-02, OR 3079351-01 IS TERMINATING ACTION FOR THE REQUIREMENTS OF PARAGRAPH (E)(1) OF THIS AD			MANDATORY			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **TMI SOLUTIONS, LLC**
 Aircraft Model: **208B - CARAVAN (MSG)**
 Aircraft Serial: **208B-1118** Unit: **1118** Reg No: **N937CK**
 Airworthiness: **18-Mar-2005**
 Print Date: **15-Mar-2016 2:54PM**
 MSG-3 Program Applied Date: **04-Aug-2011**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1387.2	1122	15-Mar-2016	.9
ENG	1387.2	1122	15-Mar-2016	.9
PROP 1	1387.2		15-Mar-2016	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2014-17-08 R1 PARA (E)(3)	REPLACE THE COMPLETE SET OF CT BLADES WITH P&WC SINGLE CRYSTAL CT BLADES, P/N 3072791-01, 3072791-02, OR 3079351-01.			MANDATORY	MTH		DUE DUE		08-Oct-2017	18 m 23 d
E1	MOC :									
FAA 2014-17-08 R1 E1	ACCOMPLISH INITIAL AND REPETITIVE BORESCOPE INSPECTIONS (BSIS) OF COMPRESSOR TURBINE (CT) BLADES, AND THE REMOVAL FROM SERVICE OF BLADES THAT FAIL INSPECTION.			MANDATORY			-			
E1	MOC :									
FAA 2014-17-08 E1	CT BLADES - INSPECTION/REPLACE			MANDATORY			-			
E1	MOC :									
FAA 2002-23-13 E1	TO PREVENT FAILURE OF THE EXHAUST TURBINE DUCT	UNK		MANDATORY	MTH 17-Sep-2012 HRS 1134.5 ENC 871		-			N/A
E1	MOC : NOT APPLICABLE - BY MODEL									