

OWNER: CDJ ASSETS, LLC
ADDRESS: 950 CORBINDALE RD STE 300
 HOUSTON TX 77024-2849
PHONE:
FAX:

OPERATOR: CHAMPAIR AVIATION, LLC
ADDRESS: C/O JET AVIATION HOUSTON
 HOUSTON TX 77061
PHONE: 713-851-7816
FAX:

ANALYST: SEAN WELLS
EMAIL: SWELLS@CAMPSYSTEMS.COM

+1-316-928-7895 (DIRECT)
 1-866-581-2267 (OFFICE)
 WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
 631-980-4222 (EFAX-CARDS)

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

AIRCRAFT SERIAL/REGNO: 45-267/N219JL **MODEL:** LEARJET 45 **MANUFACTURER:** BOMBARDIER INCORPORATED

DATES	LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE: 03-APR-2005	4932.3 A/C HRS	as of 17-JUL-2020	A/C HRS	as of ___/___/___
	3714 AFL	as of 17-JUL-2020	AFL	as of ___/___/___
	1497.37 APH	as of 11-OCT-2019	APH	as of ___/___/___

APU SERIAL/PART: P-297/3800726-1 **MODEL:** RE100 (CIMMS) **MANUFACTURER:** HONEYWELL

INSTALLED ON 01-MAY-2005	LAST ACTUALS		CURRENT ACTUAL	
0 APU HRS	1497.37 APU HRS	as of 11-OCT-2019	APU HRS	as of ___/___/___
0 APUS	3338 APUS	as of 11-OCT-2019	APUS	as of ___/___/___

ENGINE NO. 1 SERIAL/PART: P-116593/3060084-2 **MODEL:** TFE731-20BR-1B **MANUFACTURER:** HONEYWELL

INSTALLED ON 03-APR-2005		LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	0 A/C HRS	4857.5 ENG. HRS	as of 17-JUL-2020	ENG. HRS	as of ___/___/___
0 ENC		3654 ENC	as of 17-JUL-2020	ENC	as of ___/___/___

ENGINE NO. 2 SERIAL/PART: P-116590/3060084-2 **MODEL:** TFE731-20BR-1B **MANUFACTURER:** HONEYWELL

INSTALLED ON 10-OCT-2014		LAST ACTUALS		CURRENT ACTUAL	
4048.88 ENG. HRS	4118 A/C HRS	4862.9 ENG. HRS	as of 17-JUL-2020	ENG. HRS	as of ___/___/___
2866 ENC		3646 ENC	as of 17-JUL-2020	ENC	as of ___/___/___



Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05	TIME LIMITS/MAINTENANCE CHECKS							
051101	PHASE A1-300 HOUR CHECKS							
	PKG 1	MOS	12			17-JUL-2020	17-JUL-2021	31-JUL-2021
		HRS/MSC	300	+14d/-14d		4932.3	5232.3	5257.3
	REF: See Workcard	AFL		+25/-25				
051102	PHASE A2-300 HOUR CHECKS							
	PKG 2	MOS	12			17-JUL-2020	17-JUL-2021	31-JUL-2021
		HRS/MSC	300	+14d/-14d		4932.3	5232.3	5257.3
	REF: See Workcard	AFL		+25/-25				
051103	PHASE A3-300 HOUR CHECKS							
	PKG 3	MOS	12			17-JUL-2020	17-JUL-2021	31-JUL-2021
		HRS/MSC	300	+14d/-14d		4932.3	5232.3	5257.3
	REF: See Workcard	AFL		+25/-25				
051104	PHASE A4-300 HOUR CHECKS							
	PKG 4	MOS	12			17-JUL-2020	17-JUL-2021	31-JUL-2021
		HRS/MSC	300	+14d/-14d		4932.3	5232.3	5257.3
	REF: See Workcard	AFL		+25/-25				
051105	PHASE A5-300 HOUR CHECKS							
	PKG 5	MOS	12			17-JUL-2020	17-JUL-2021	31-JUL-2021
		HRS/MSC	300	+14d/-14d		4932.3	5232.3	5257.3
	REF: See Workcard	AFL		+25/-25				



Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
051106	PHASE A6-300 HOUR CHECKS								
	PKG 6	MOS	12				17-JUL-2020	17-JUL-2021	31-JUL-2021
		HRS/MSC	300				4932.3	5232.3	5257.3
	REF: See Workcard	AFL							
051201	PHASE B1 600 HOUR CHECKS								
	PKG 7	MOS	24				17-JUL-2020	17-JUL-2022	31-JUL-2022
		HRS/MSC	600				4932.3	5532.3	5557.3
	REF: See Workcard	AFL							
051202	PHASE B2 600 HOUR CHECKS								
	PKG 8	MOS	24				17-JUL-2020	17-JUL-2022	31-JUL-2022
		HRS/MSC	600				4932.3	5532.3	5557.3
	REF: See Workcard	AFL							
051203	PHASE B3 600 HOUR CHECKS								
	PKG 9	MOS	24				17-JUL-2020	17-JUL-2022	31-JUL-2022
		HRS/MSC	600				4932.3	5532.3	5557.3
	REF: See Workcard	AFL							
051204	PHASE B4 600 HOUR CHECKS								
	PKG 10	MOS	24				17-JUL-2020	17-JUL-2022	31-JUL-2022
		HRS/MSC	600				4932.3	5532.3	5557.3
	REF: See Workcard	AFL							



Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
051205	PHASE B5 600 HOUR CHECKS								
	PKG 11	MOS	24				17-JUL-2020	17-JUL-2022	31-JUL-2022
		HRS/MSC	600	+14d/-14d			4932.3	5532.3	5557.3
	REF: See Workcard	AFL		+25/-25					
051206	PHASE B6 600 HOUR CHECKS								
	PKG 12	MOS	24				17-JUL-2020	17-JUL-2022	31-JUL-2022
		HRS/MSC	600	+14d/-14d			4932.3	5532.3	5557.3
	REF: See Workcard	AFL		+25/-25					
051301	PHASE C1 1200 HOUR CHECKS								
	PKG 13	MOS	48				23-NOV-2016	23-NOV-2020	07-DEC-2020
		HRS/MSC	1200	+14d/-14d			4476	5676	5701
	REF: See Workcard	AFL		+25/-25			3270		
051302	PHASE C2 1200 HOUR CHECKS								
	PKG 14	MOS	48				23-NOV-2016	23-NOV-2020	07-DEC-2020
		HRS/MSC	1200	+14d/-14d			4476	5676	5701
	REF: See Workcard	AFL		+25/-25			3270		
051303	PHASE C3 1200 HOUR CHECKS								
	PKG 15	MOS	48				23-NOV-2016	23-NOV-2020	07-DEC-2020
		HRS/MSC	1200	+14d/-14d			4476	5676	5701
	REF: See Workcard	AFL		+25/-25			3270		



Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
051304	PHASE C4 1200 HOUR CHECKS							
	PKG 16	MOS	48			23-NOV-2016	23-NOV-2020	07-DEC-2020
		HRS/MSC	1200	+14d/-14d		4476	5676	5701
	REF: See Workcard	AFL		+25/-25		3270		
051305	PHASE C5 1200 HOUR CHECKS							
	PKG 17	MOS	48			23-NOV-2016	23-NOV-2020	07-DEC-2020
		HRS/MSC	1200	+14d/-14d		4476	5676	5701
	REF: See Workcard	AFL		+25/-25		3270		
051306	PHASE C6 1200 HOUR CHECKS							
	PKG 18	MOS	48			23-NOV-2016	23-NOV-2020	07-DEC-2020
		HRS/MSC	1200	+14d/-14d		4476	5676	5701
	REF: See Workcard	AFL		+25/-25		3270		
051401	PHASE D1 2400 HOUR CHECKS							
	PKG 19	MOS	96			23-NOV-2016	23-NOV-2024	07-DEC-2024
		HRS/MSC	2400	+14d/-14d		4476	6876	6901
	REF: See Workcard	AFL		+25/-25		3270		
051402	PHASE D2 2400 HOUR CHECKS							
	PKG 20	MOS	96			23-NOV-2016	23-NOV-2024	07-DEC-2024
		HRS/MSC	2400	+14d/-14d		4476	6876	6901
	REF: See Workcard	AFL		+25/-25		3270		



Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
051403	PHASE D3 2400 HOUR CHECKS							
	PKG 21	MOS	96			23-NOV-2016	23-NOV-2024	07-DEC-2024
		HRS/MSC	2400	+14d/-14d		4476	6876	6901
	REF: See Workcard	AFL		+25/-25		3270		
051404	PHASE D4 2400 HOUR CHECKS							
	PKG 22	MOS	96			23-NOV-2016	23-NOV-2024	07-DEC-2024
		HRS/MSC	2400	+14d/-14d		4476	6876	6901
	REF: See Workcard	AFL		+25/-25		3270		
051405	PHASE D5 2400 HOUR CHECKS							
	PKG 23	MOS	96			23-NOV-2016	23-NOV-2024	07-DEC-2024
		HRS/MSC	2400	+14d/-14d		4476	6876	6901
	REF: See Workcard	AFL		+25/-25		3270		
051406	PHASE D6 2400 HOUR CHECKS							
	PKG 24	MOS	96			23-NOV-2016	23-NOV-2024	07-DEC-2024
		HRS/MSC	2400	+14d/-14d		4476	6876	6901
	REF: See Workcard	AFL		+25/-25		3270		
051500	4800 HOUR CHECKS							
	PKG 25	MOS				25-JUL-2018		
		HRS/MSC	4800	+25/-25		4687.6	9487.6	9512.6
	REF: See Workcard	AFL				3479		



Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
051600	9600 HOUR CHECKS							
	PKG 26	MOS				03-APR-2005		
	REF: See Workcard	HRS/MSC AFL	9600	+25/-25		0	9600	9625
						0		
051700	MAJOR LANDING GEAR INSPECTION							
	PKG 27	MOS				03-APR-2005		
	REF: See Workcard	HRS/MSC AFL	10000	+25/-25		0	10000	10025
						0		
ENGINE NO. 1 Model : TFE731-20/-40/-60 (CIMMS) Serial # P-116593 Part # 3060084-2								
057110	NO. 1 ENGINE - 150 TO 250 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							
	PKG 0	MOS				21-NOV-2019		
	REF: LMM 72-00-00	HRS/MSC ENC	150	+100		4790.6	(4940.6) 5015.4	5040.6
						3589		
057120	NO. 1 ENGINE - 300 TO 440 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							
	PKG 0	MOS				08-JAN-2007		
	REF: LMM 72-00-00	HRS/MSC ENC	N/A			1197		
						816		
057130	NO. 1 ENGINE - 500 TO 650 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							
	PKG 0	MOS				11-OCT-2019		
	REF: LMM 72-00-00	HRS/MSC ENC	600			4766.2	(5366.2) 5441	
						3564		



Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
057140	NO. 1 ENGINE - 500 TO 850 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							
	PKG 0	MOS				09-MAY-2017		
		HRS/MSC	800	+50/-300	10.73	4456.5	(5267.23) 5342.03	5317.23
	REF: LMM 72-00-00	ENC				3267		
057150	NO. 1 ENGINE - 1000 TO 1300 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							
	PKG 0	MOS				21-NOV-2019		
		HRS/MSC	1200			4790.6	(5990.6) 6065.4	
	REF: LMM 72-00-00	ENC				3589		
057160	NO. 1 ENGINE - 1500 TO 1650 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							
	PKG 0	MOS				09-MAY-2017		
		HRS/MSC	1600	+50/-100	11.1	4456.5	(6067.6) 6142.4	6117.6
	REF: LMM 72-00-00	ENC				3267		
ENGINE NO. 2 Model : TFE731-20/-40/-60 (CIMMS) Serial # P-116590 Part # 3060084-2								
057110	NO. 2 ENGINE - 150 TO 250 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							
	PKG 0	MOS				21-NOV-2019		
		HRS/MSC	150	+100		4796	(4946) 5015.4	5046
	REF: LMM 72-00-00	ENC				3581		
057120	NO. 2 ENGINE - 300 TO 440 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							
	PKG 0	MOS				29-JUN-2009		
		HRS/MSC	N/A			2398.4		
	REF: LMM 72-00-00	ENC				1655		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE <small>(ENG/APU) A/C</small>	MAX LIMIT
057130	NO. 2 ENGINE - 500 TO 650 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							
	PKG 0	MOS				17-JUL-2020		
		HRS/MSC	600			4862.9	(5462.9)	5532.3
	REF: LMM 72-00-00	ENC				3646		
<hr/>								
057140	NO. 2 ENGINE - 500 TO 850 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							
	PKG 0	MOS				21-NOV-2019		
		HRS/MSC	800	+50/-300		4796	(5596)	5665.4
	REF: LMM 72-00-00	ENC				3581		5646
<hr/>								
057150	NO. 2 ENGINE - 1000 TO 1300 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							
	PKG 0	MOS				17-JUL-2020		
		HRS/MSC	1200			4862.9	(6062.9)	6132.3
	REF: LMM 72-00-00	ENC				3646		
<hr/>								
057160	NO. 2 ENGINE - 1500 TO 1650 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							
	PKG 0	MOS				07-OCT-2014		
		HRS/MSC	1600	+50/-100		4048.8	(5648.8)	5718.2
	REF: LMM 72-00-00	ENC				2866		5698.8



Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 00	INFORMATION								
CI45-150721	REVIEW CONCORDE EMERGENCY BATTERY CMM 5-0167 REV E								
		MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF CI45	HRS/MSC -							
		AFL							
CI45-160527	REVIEW LEARJET AMM REVISION 66								
		MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF CI45	HRS/MSC -							
		AFL							
CI45-160603	REVIEW LEARJET 45 AMM TR 4-40								
		MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF CI45	HRS/MSC -							
		AFL							
CI45-160613	REVIEW LEARJET 45 AMM TR 5-110								
		MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF CI45	HRS/MSC -							
		AFL							
CI45-161207B	REVIEW LEARJET 45 AMM REVISION 67								
		MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF CI45	HRS/MSC -							
		AFL							
CI45-181109B	REVIEW LEARJET 45/45XR AMM REVISION 71								
		MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF CI45	HRS/MSC -							
		AFL							

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CI45-190429A	REVIEW LEARJET 45/45XR AMM REV 72	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF CI45	HRS/MSC - AFL							
+ CI45-200529	REVIEW AUDIT SUMMARY CHANGE FORM	MOS					13-JUL-2020		
AUDIT SUMMARY CHANGE FORM	REF: RCF CI45	HRS/MSC - AFL							
ENGINE NO. 1 Model : TFE731-20BR-1B Serial # P-116593 Part # 3060084-2									
EC04-180802	NO. 1 ENGINE - REVIEW TFE731-20/-40/-60 (CIMMS) LMM TR 5-17	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EC04-180802	HRS/MSC - ENC							
ENGINE NO. 2 Model : TFE731-20BR-1B Serial # P-116590 Part # 3060084-2									
EC04-180802	NO. 2 ENGINE - REVIEW TFE731-20/-40/-60 (CIMMS) LMM TR 5-17	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EC04-180802	HRS/MSC - ENC							
CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS									
5-50-00-EV	PERFORM ENGINE VIBRATION TEST AND INSPECTION	MOS							
	REF: AMM 05-50-00	HRS/MSC A/R AFL							
CHAPTER 05-50 TIME LIMITS/MAINTENANCE CHECKS									
5-50-00-FD	INSPECTION FOREIGN OBJECT DAMAGE	MOS							
	REF: AMM 05-50-00	HRS/MSC O/C AFL							

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 08 LEVELING AND WEIGHING									
082000	REWEIGH AIRCRAFT							08-FEB-2016	
		MOS						4383.7	
	REF: See Workcard	HRS/MSC	A/R					3170	
		AFL							
CHAPTER 11 PLACARDS AND MARKINGS									
G1130000 (s)	CHECK CHECK BRIGHTNESS LEVEL OF ALL SELF-LUMINOUS PLACARDS						PKG		
	PKG 13	MOS	48	+14d/-14d				23-NOV-2016	
		HRS/MSC	1200	+25/-25				4476	
	REF: AMM 11-30-00	AFL						3270	
CHAPTER 12 SERVICING									
5-19-00-Q1221064	FLAP ACTUATOR JOINT (P/N 145673-1) - APPLY CORROSION PREVENTIVE COMPOUND (CPC). (REFER TO 12-21-03.)								
		MOS	3	+14d/-14d				17-JUL-2020	17-OCT-2020 31-OCT-2020
		HRS/MSC						4932.3	
	REF: AMM 12-21-03	AFL							
5-19-00-U1210004	LUBRICATE FLAP FLEXIBLE TRANSMISSION SHAFTS - BY HAND (U1210004)								
		MOS						05-MAY-2019	
		HRS/MSC	4800	+25/-25	10.4			4789.6	9600 9625
	REF: GENERIC NO REF	AFL						3579	
+ AB1210060 (s)	MAIN LANDING GEAR UP-LOCK ACTUATOR - LUBRICATE						PKG		
	PKG 5	MOS	12	+14d/-14d				17-JUL-2020	
		HRS/MSC	300	+25/-25				4932.3	
	REF: AMM 12-21-01	AFL							
O1210002 (s)	FLAP ACTUATORS - CHECK OIL LEVEL.						PKG		
	PKG 10	MOS	24	+14d/-14d				17-JUL-2020	
		HRS/MSC	600	+25/-25				4932.3	
	REF: AMM 12-21-03	AFL							

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y1210000 (s)	NOSE LANDING GEAR SHOCK STRUT - CHECK FOR PROPER FLUID LEVEL AND INFLATION PRESSURE. PKG 5 REF: AMM 12-10-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
Y1210001 (s)	MAIN LANDING GEAR SHOCK STRUTS - CHECK FOR PROPER FLUID LEVEL AND INFLATION PRESSURE. PKG 5 REF: AMM 12-10-03	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
Y1210003 (s)	FLAP ACTUATOR BALLNUT - LUBRICATE. PKG 4 REF: AMM 12-21-03	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
Y1210005 (s)	NOSE LANDING GEAR TRUNNION PIN - LUBRICATE. PKG 5 REF: AMM 12-21-01	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
Y1210006 (s)	NOSE LANDING GEAR ACTUATOR ATTACH FITTING - LUBRICATE. PKG 5 REF: AMM 12-21-01	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
Y1210007 (s)	NOSE AND MAIN TIRES - CHECK FOR PROPER INFLATION. PKG 5 REF: AMM 12-10-04	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
Y1210009 (s)	NOSE GEAR DOOR HINGE - LUBRICATE. PKG 1 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y1210011 (s)	MAIN LANDING GEAR ACTUATOR JOINTS - LUBRICATE. PKG 5	MOS	12	+14d/-14d			PKG	17-JUL-2020	
	REF: AMM 12-21-01	HRS/MSC	300	+25/-25			4932.3		
		AFL							
Y1210012 (s)	MAIN LANDING GEAR AXLE BEAM/PISTON JOINTS - LUBRICATE. PKG 5	MOS	12	+14d/-14d			PKG	17-JUL-2020	
	REF: AMM 12-21-01	HRS/MSC	300	+25/-25			4932.3		
		AFL							
Y1210013 (s)	MAIN LANDING GEAR TORQUE LINKS - LUBRICATE. PKG 5	MOS	12	+14d/-14d			PKG	17-JUL-2020	
	REF: AMM 12-21-01	HRS/MSC	300	+25/-25			4932.3		
		AFL							
Y1210014 (s)	MAIN GEAR DOOR HINGE - LUBRICATE PKG 5	MOS	12	+14d/-14d			PKG	17-JUL-2020	
	REF: AMM 12-21-02	HRS/MSC	300	+25/-25			4932.3		
		AFL							
Y1210016 (s)	PASSENGER/CREW DOOR HINGE - LUBRICATE PKG 6	MOS	12	+14d/-14d			PKG	17-JUL-2020	
	REF: AMM 12-21-02	HRS/MSC	300	+25/-25			4932.3		
		AFL							
Y1210017 (s)	PASSENGER/CREW DOOR PINS - LUBRICATE PKG 6	MOS	12	+14d/-14d			PKG	17-JUL-2020	
	REF: AMM 12-21-02	HRS/MSC	300	+25/-25			4932.3		
		AFL							
Y1210018 (s)	PASSENGER/CREW DOOR TENSION BOLTS - LUBRICATE. PKG 6	MOS	12	+14d/-14d			PKG	17-JUL-2020	
	REF: AMM 12-21-02	HRS/MSC	300	+25/-25			4932.3		
		AFL							

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y1210019 (s)	EMERGENCY EXIT DOOR LATCHING MECHANISM - LUBRICATE. PKG 6 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
Y1210020 (s)	EMERGENCY EXIT DOOR PINS - LUBRICATE. PKG 6 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
Y1210021 (s)	BAGGAGE COMPARTMENT DOOR LATCH PINS - LUBRICATE. PKG 6 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
Y1210022 (s)	BAGGAGE COMPARTMENT DOOR HINGE - LUBRICATE PKG 6 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
Y1210023 (s)	OXYGEN SYSTEM SERVICING DOOR HINGE - LUBRICATE PKG 1 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
Y1210024 (s)	TOILET SERVICING DOOR HINGE - LUBRICATE. PKG 4 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
Y1210025 (s)	PRESSURE REFUELING DOOR HINGE - LUBRICATE. PKG 2 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y1210026 (s)	FUSELAGE FUEL FILLER DOOR HINGE - LUBRICATE PKG 2 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
Y1210027 (s)	TAILCONE ACCESS DOOR PINS - LUBRICATE PKG 6 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
Y1210028 (s)	TAILCONE ACCESS DOOR HINGE - LUBRICATE. PKG 6 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
Y1210029 (s)	MAIN LANDING GEAR TRUNNION PIN - LUBRICATE PKG 5 REF: AMM 12-21-01	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
Y1221037 (s)	FLAPS - LUBRICATE ROLLING SURFACES OF MAIN AND NOSE ROLLER TRACKS PKG 4 REF: AMM 12-21-03	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
Y1221042 (s)	HORIZONTAL STABILIZER UPPER AND LOWER TORQUE LINKS - LUBRICATE PKG 9 REF: AMM 12-21-03	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
Y1227000 (s)	EMERGENCY PARK BRAKE HANDLE SHAFT - LUBRICATE PKG 1 REF: AMM 12-27-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		

CHAPTER 21 AIR CONDITIONING

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
211001	SERVO AIR PRESSURE REGULATING VALVE 3213982-2 1020 REF: AMM 36-15-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
211011	LEFT PLENUM CHECK VALVE PN SN-UNKNOWN REF: AMM 21-20-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
211012	RIGHT PLENUM CHECK VALVE 6621000000-037 3394 REF: AMM 21-20-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2007 1214.2 827		
211017	LEFT EMERGENCY PRESSURIZATION ISOLATION CHECK VALVE 6621000000-043 2577 REF: AMM 21-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
211018	RIGHT EMERGENCY PRESSURIZATION ISOLATION CHECK VALVE 6621000000-043 2579 REF: AMM 21-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
212001	COCKPIT AIR CHECK VALVE PN SN-UNKNOWN REF: AMM 21-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
212041	LEFT ENGINE OZONE CONVERTER 53A405-4 0393/0827 REF: AMM 21-20-12	MOS HRS/MSC AFL	O/C	N:3600			11-DEC-2012 3615.55 2542		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212041A	TEST LEFT ENGINE OZONE CONVERTER EFFICIENCY. (Y2140001) 53A405-4 0393/0827 REF: AMM 21-20-12	MOS HRS/MSC AFL	3600	+25/-25			11-DEC-2012 3615.55 2542	7215.55	7240.55
212042	RIGHT ENGINE OZONE CONVERTER 53A405-4 0398/0832 REF: AMM 21-20-12	MOS HRS/MSC AFL	O/C	N:3600			11-DEC-2012 3615.55 2542		
212042A	TEST RIGHT ENGINE OZONE CONVERTER EFFICIENCY (Y2140001) 53A405-4 0398/0832 REF: AMM 21-20-12	MOS HRS/MSC AFL	3600	+25/-25			11-DEC-2012 3615.55 2542	7215.55	7240.55
212213	LEFT CABIN AIR CHECK VALVE PN SN-UNKNOWN REF: AMM 21-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
212214	RIGHT CABIN AIR CHECK VALVE PN SN-UNKNOWN REF: AMM 21-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
212801	AVIONICS COOLING B13 FAN 4521208521-009 A00318352A REF: AMM 21-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
213000	CABIN PRESSURE CONTROLLER 6621300000-027 65-J0085 REF: AMM 21-30-03	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			01-OCT-2017 4589.5 3375		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
213001	LEFT EMERGENCY PRESSURE SHUTOFF VALVE 3291224-1 706 REF: AMM 21-31-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
213002	RIGHT EMERGENCY PRESSURE SHUTOFF VALVE 3291224-1 707 REF: AMM 21-31-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
213031	PRIMARY OUTFLOW VALVE 103858-1 18-A0098 REF: AMM 21-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
213032	SECONDARY OUTFLOW VALVE 103858-2 104-C0134 REF: AMM 21-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
213056	ABSOLUTE PRESSURE SWITCH E45C-47 4981 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
213110	CABIN PRESSURIZATION CHECK VALVE 130158-3-1 94-A0630 REF: AMM 21-30-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
214301	FOOT WARMER (S167) THERMOSTAT PN SN-UNKNOWN REF: AMM 21-41-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
215001	WATER SEPARATOR ASSEMBLY 2341168-1 416 REF: AMM 21-50-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
215013	BI-LEVEL PRESSURE REGULATING & SHUTOFF (L19) VALVE PN SN-UNKNOWN REF: AMM 21-50-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
215030	ENVIRONMENTAL CONTROL UNIT 6621000000-083 405 REF: AMM 21-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
215033	AIR CYCLE MACHINE 2205580-2 325 REF: AMM 21-50-04	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			26-MAY-2011 2935 2041		
215036	HEAT, PRIMARY, SECONDARY EXCHANGER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
216001	INTEGRATED ECS TEMPERATURE CONTROLLER 1151830-3 032C-0622 REF: AMM 21-60-10	MOS HRS/MSC AFL	O/C				09-JUN-2010 2638.43 1843		
216013	COCKPIT TEMPERATURE CONTROL VALVE 6621000000-047 739 REF: AMM 21-60-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216014	CABIN TEMPERATURE CONTROL VALVE 6621000000-047 740 REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
5-19-00-L2150054	WEAR INSPECTION - AIR CONDITIONING COMPRESSOR DRIVE MOTOR BRUSHES - PERFORM WEAR INSPECTION (RETURN DRIVE MOTOR TO AUTHORIZED SERVICE FACILITY FOR OVERHAUL) REF: GENERIC NO REF	MOS HRS/MSC AFL	-				03-APR-2005 0 0		
5-19-00-L2150055	OVERHAUL - AIR CONDITIONING COMPRESSOR MOTOR - PERFORM OVERHAUL (RETURN DRIVE MOTOR TO AUTHORIZED SERVICE FACILITY FOR OVERHAUL) REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				03-APR-2005 0 0		
5-19-00-Y2130065	LEAK TEST CABIN PRESSURIZATION SYSTEM. (IRN # Y2130065). REF: AMM 21-30-00	MOS HRS/MSC AFL	1200	+25/-25		-47.92	14-AUG-2019 4829.3 3616	5981.38	6006.38
5-19-01-Y2141002	REPLACE WATER SEPARATOR COALESCER BAG. (ZONE/ACCESS 310HL, 310RR IRN # W2141002) REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				01-MAY-2005 10.4 9		
J2160007 (s)	TEMPERATURE CONTROL SYSTEM - INSPECT AND CLEAN CABIN AND COCKPIT TEMPERATURE CONTROL VALVE SERVO AIR FILTERS. (EFFECTIVE ON AIRCRAFT 45-005 THRU 45-232 POST SB 45-21-16, AND AIRCRAFT 45-233 THRU 45-2000.) PKG 8 REF: AMM 21-60-11	MOS HRS/MSC AFL	24	+14d/-14d			17-JUL-2020 4932.3		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
L2150056 (s)	** AUXILIARY HEAT SYSTEM - PERFORM FUNCTIONAL TEST. (EFFECTIVE ON AIRCRAFT 45-250 AND SUBSEQUENT EQUIPPED WITH KEITH PRODUCTS VAPOR CYCLE AIR CONDITIONING SYSTEM USING REFRIGERANT R-134.)						PKG		
	PKG 8	MOS	24	+14d/-14d				17-JUL-2020	
AIRWORTHINESS	REF: AMM 21-51-00	HRS/MSC	600	+25/-25				4932.3	
		AFL							
L2150057 (s)	PERFORM ** AUXILIARY HEAT SYSTEM - AUXILIARY HEATER ELECTRICAL AND TEMPERATURE SWITCH TEST. (EFFECTIVE ON AIRCRAFT 45-250 AND SUBSEQUENT EQUIPPED WITH KEITH PRODUCTS VAPOR CYCLE AIR CONDITIONING SYSTEM USING REFRIGERANT R-134.)						PKG		
	PKG 14	MOS	48	+14d/-14d				23-NOV-2016	
AIRWORTHINESS	REF: AMM 21-51-00	HRS/MSC	1200	+25/-25				4476	
		AFL						3270	
O2130000 (s)	PERFORM PRIMARY AND SECONDARY OUTFLOW VALVES - INSPECTION.						PKG		
	PKG 13	MOS	48	+14d/-14d				23-NOV-2016	
	REF: See Workcard	HRS/MSC	1200	+25/-25				4476	
		AFL						3270	
O2130001 (s)	REPLACE OUTFLOW VALVE AIR FILTER - REMOVE AND REPLACE.						PKG		
	PKG 19	MOS	96	+14d/-14d				23-NOV-2016	
AIRWORTHINESS	REF: AMM 21-30-04	HRS/MSC	2400	+25/-25				4476	
		AFL						3270	
O2130002 (s)	PERFORM ** PRESSURIZATION CONTROL SYSTEM - FUNCTIONAL TEST.						PKG		
	PKG 13	MOS	48	+14d/-14d				23-NOV-2016	
AIRWORTHINESS	REF: AMM 21-30-00	HRS/MSC	1200	+25/-25				4476	
		AFL						3270	
Y2130003 (s)	PRESSURIZATION CONTROL SYSTEM - PERFORM OPERATIONAL CHECK						PKG		
	PKG 7	MOS	24	+14d/-14d				17-JUL-2020	
	REF: AMM 21-30-00	HRS/MSC	600	+25/-25				4932.3	
		AFL							

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y2140000 (s)	PERFORM AIR CYCLE MACHINE HEAT EXCHANGER INLET - VISUAL INSPECTION PKG 14 REF: AMM 05-10-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 23-NOV-2016 4476 3270		
Y2141000 (s)	PERFORM ENVIRONMENTAL CONTROL UNIT - VISUAL INSPECTION PKG 14 REF: AMM 05-10-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 23-NOV-2016 4476 3270		
Y2141001 (s)	WATER SEPARATOR COALESCER BAG - PERFORM VISUAL INSPECTION. CLEAN IF NECESSARY. (NOTE: THE SERVICING ACTIVITY MAY REQUIRE A MORE FREQUENT INTERVAL, DEPENDING ON ENVIRONMENTAL AND OPERATIONAL REQUIREMENTS, AND SHOULD BE ADJUSTED BY INDIVIDUAL OPERATORS) PKG 2 REF: AMM 05-10-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
Y2142000 (s)	PERFORM BAGGAGE COMPARTMENT HEATING SYSTEM - FUNCTIONAL TEST PKG 20 REF: AMM 21-40-00	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 23-NOV-2016 4476 3270		
Y2145000 (s)	PERFORM ECS PLENUM ASSEMBLY CHECK VALVES - VISUAL INSPECTION. VERIFY FREEDOM OF MOVEMENT OF BUTTERFLY ASSEMBLY PKG 14 REF: See Workcard	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 23-NOV-2016 4476 3270		
Y2150058 (s)	PERFORM VISUAL INSPECTION OF THE AIR CONDITIONING SYSTEM COMPONENTS, INCLUDING COMPRESSOR MOTORBELT FOR WEAR AND PROPER V-BELT TENSION, CONDENSER COILS FOR CLEANLINESS AND HOSES FOR CHAFING AND WEAR. IF OIL LEAKS ARE VISIBLE AND/OR REFRIGERANT DUMPED, CHECK COMPRESSOR OIL LEVEL (SOME LEAKAGE IS ALLOWABLE AROUND THE SHAFT.) PKG 14 REF: AMM 05-10-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 23-NOV-2016 4476 3270		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y2150059 (s)	PERFORM AIR CONDITIONING SYSTEM - LOAD SHED ASSEMBLY CHECK PKG 14	MOS	48	+14d/-14d			PKG	23-NOV-2016	
	REF: AMM 21-51-00	HRS/MSC AFL	1200	+25/-25			4476 3270		
CHAPTER 22 AUTO FLIGHT									
221001	FLIGHT GUIDANCE, AUTOPILOT CONTROLLER								
	7021170-901	MOS					R:0	02-FEB-2010	
	00110787	HRS/MSC	O/C				R:0	2591.43	
	REF: AMM 22-10-01	AFL					R:0	1807	
221041	AUTOPILOT, ROLL SERVO								
	4006719-948	MOS					N:0	03-APR-2005	
	04118962	HRS/MSC	O/C				N:0	0	
	REF: AMM 22-10-04	AFL					N:0	0	
221045	SERVO, ROLL BRACKET								
	4005842	MOS					N:0	03-APR-2005	
	01095060	HRS/MSC	O/C				N:0	0	
	REF: AMM 22-10-05	AFL					N:0	0	
221051	AUTOPILOT, PITCH SERVO								
	4006719-923	MOS						01-NOV-2007	
	06019842	HRS/MSC	O/C					1785	
	REF: AMM 22-10-02	AFL						1240	
221055	SERVO, PITCH BRACKET								
	4005842	MOS					N:0	03-APR-2005	
	04067162	HRS/MSC	O/C				N:0	0	
	REF: AMM 22-10-03	AFL					N:0	0	
221061	AUTOPILOT, YAW SERVO								
	7012919-904	MOS					R:0	25-NOV-2019	
	02060554	HRS/MSC	O/C				R:0		
	REF: AMM 22-10-06	AFL					R:0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
221065	SERVO, YAW BRACKET 7012098-902 04080539 REF: AMM 22-10-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
225001	YAW INTERFACE UNIT 4522108501-013 A00014585-01 REF: AMM 22-50-01	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			09-JUN-2010 2644.08 1845		
225031	PILOT YAW FORCE, RUDDER BOOST SYSTEM SENSOR 6622500001-003 1225506 REF: AMM 22-50-02	MOS HRS/MSC AFL	O/C				21-NOV-2008 2304 1593		
225032	COPILOT YAW FORCE, RUDDER BOOST SYSTEM. SENSOR 6622500001-003 1227787 REF: AMM 22-50-02	MOS HRS/MSC AFL	O/C				21-NOV-2008 2304 1593		
A2210033 (s)	** AUTOPILOT SYSTEM - PERFORM AUTOPILOT DISCONNECT TONE TEST PKG 7 REF: AMM 22-10-00	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
G2210030 (s)	PERFORM PITCH SERVO CABLES - CABLE TENSION CHECK PKG 14 REF: AMM 22-10-03	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 23-NOV-2016 4476 3270		
G2210031 (s)	PERFORM ROLL SERVO CABLES - CABLE TENSION CHECK PKG 13 REF: AMM 22-10-05	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 23-NOV-2016 4476 3270		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
G2210032 (s)	PERFORM YAW SERVO CABLES - CABLE TENSION CHECK. PKG 14 REF: AMM 22-10-07	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 23-NOV-2016 4476 3270		
CHAPTER 23 COMMUNICATIONS									
231011	NO. 1 POWER AMPLIFIER/HF ANTENNA COUPLER 064-1017-01 19129 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		03-APR-2005 0 0		
231021	NO. 1 VHF COMMUNICATIONS TRANSCEIVER UNIT 7510700-655 01312D213 REF: AMM 23-11-01	MOS HRS/MSC AFL	O/C				10-MAY-2019 4774.6 3558		
231021A	TEST/INSPECT NO. 1 VHF COMMUNICATIONS TRANSCEIVER UNIT ATC TRANSPONDER 7510700-655 01312D213 REF: See Workcard	MOS HRS/MSC AFL	24	+14d/-14d			06-MAY-2019 06-MAY-2021 20-MAY-2021		
231022	NO. 2 VHF COMMUNICATIONS TRANSCEIVER UNIT 7510700-655 04108913 REF: See Workcard	MOS HRS/MSC AFL	O/C				10-MAY-2019 4774.6 3558		
231022A	TEST/INSPECT NO. 2 VHF COMMUNICATIONS TRANSCEIVER UNIT ATC TRANSPONDER 7510700-655 04108913 REF: See Workcard	MOS HRS/MSC AFL	24	+14d/-14d			06-MAY-2019 06-MAY-2021 20-MAY-2021		
231030	NO. 1 HF SELCAL RECEIVER/EXCITER 064-1015-01 34065 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		03-APR-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231033	UPPER VHF ANTENNA DMC60-17-1 15109 REF: AMM 23-11-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			02-APR-2009 2381.38 1642		
231034	LOWER VHF ANTENNA DMC60-17-1 14002 REF: AMM 23-11-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
231045	NO. 1 HF (KCU-951) CONTROL 064-1016-03 12412 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
231300	PHONE MAGNASTAR TRANSCEIVER 500617 5210 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
231301	ANTENNA 500644-1/C1490-1 5015575 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
231308	CABIN ASSEMBLY PHONE 500092-230 2409106 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
233001	FORWARD CABIN VIDEO MONITOR- AI-LCD104-04-1 040400650 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				29-APR-2015 4258 3059		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
233002	AFT CABIN VIDEO MONITOR- AI-LCD104-04-1 110400411 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
233003	AUDIO DISTRIBUTION MODULE AV-4589-01-1 060400879 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			03-JUL-2012 3445.3 2422		
233005	PA SYSTEM AMPLIFER PA-7501-01-1 110400031 REF: AMM 23-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
233054-1	CD PLAYER CHANGER MCD-102-RU-3 010500995 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-APR-2005 0 0		
233101	LEFT FORWARD CABIN SPEAKER 6623308507-001/30700011 020500279 REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
233102	RIGHT FORWARD CABIN SPEAKER 6623308507-001/30700011 020500280 REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
233103	LEFT AFT CABIN SPEAKER 6623308507-001/30700011 020500269 REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
233104	RIGHT AFT CABIN SPEAKER 6623308507-001/30700011 020500271 REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
233105	SUBWOOFER SPEAKER EN-646-W/6623308507-003 120400694 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
233201	PASSENGER INTERFACE UNIT PIU-45-02-1 010500977 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
235001	#1 AUDIO CONTROL UNIT 7511001-937 05019889 REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
235002	#2 AUDIO CONTROL UNIT 7511001-937 05019904 REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
237001	COCKPIT VOICE (CVR) RECORDER 980-6020-011 CVR120-63874 REF: AMM 23-70-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
237005	CVR UNDERWATER LOCATOR (ULB) BEACON DK120 SC65449 REF: AMM 25-61-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			03-OCT-2018		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
237005A	FUNCTIONAL TEST CVR UNDERWATER LOCATOR (ULB) BEACON / CLEAN BEACON SWITCH AND PERFORM TEST OF ULB BATTERY (IRN AA2560000) DK120 SC65449 REF: GENERIC CUSTOM	MOS HRS/MSC AFL	24	+14d/-14d			03-OCT-2018	03-OCT-2020	17-OCT-2020
237005B	REPLACE CVR UNDERWATER LOCATOR (ULB) BEACON BATTERY ON OR BEFORE ULB BATTERY REPLACEMENT DATE. (ZONE/ACCESS 300 IRN # D2566001) DK120 SC65449 REF: AMM NO REF	MOS HRS/MSC AFL	DUE				03-OCT-2018	01-DEC-2024 M	
237018	CVR INERTIA SWITCH 3L0-871/8 79275 REF: AMM 23-70-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
237019	COCKPIT AREA MICROPHONE 980-6113-001 03351 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
237031	COCKPIT VOICE RECORDER PRE-AMPLIFIER 980-6118-001 CAMPRAMP-00555 REF: AMM 23-70-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
238001	NO. 1 RADIO MANAGEMENT (RMU) UNIT 7013270-975 04124475 REF: AMM 23-80-01	MOS HRS/MSC AFL	O/C				23-AUG-2017 4571.9 3365		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
238002	NO. 2 RADIO MANAGEMENT (RMU) UNIT 7013270-975 04094486 REF: AMM 23-80-01	MOS HRS/MSC AFL	O/C				23-AUG-2017 4571.9 3365		
238025	CLEARANCE DELIVERY UNIT 7513000-835 04062696 REF: AMM 23-82-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
A2300000 (s)	** COMMUNICATIONS SYSTEMS - PERFORM OPERATIONAL CHECK PKG 7 REF: AMM 23-00-00	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
Y2312003 (s)	HF ANTENNA- PERFORM VISUAL INSPECTION. CHECK FOR PROPER TENSION ON HF ANTENNA WIRE PKG 14 REF: AMM 23-12-04	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 23-NOV-2016 4476 3270		
Y2360020 (s)	PERFORM AIRCRAFT STATIC DISCHARGERS - FUNCTIONAL TEST PKG 20 REF: AMM 23-60-00	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 23-NOV-2016 4476 3270		
Y2360023 (s)	PERFORM AIRCRAFT STATIC DISCHARGERS - FUNCTIONAL TEST PKG 22 REF: AMM 23-60-00	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 23-NOV-2016 4476 3270		
CHAPTER 24 ELECTRICAL POWER									
240109	AFT CIRCUIT BREAKER PANEL ASSY 4524088502-029 A00608512-01 REF: AMM 24-60-04	MOS HRS/MSC AFL	O/C				01-MAY-2005 10.4 9		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
242001	NO. 1 AC 5KVA ALTERNATOR 90278-2 811 REF: AMM 24-20-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			28-FEB-2018 4664.5 3452		
242001A	REPLACE NO. 1 AC 5KVA ALTERNATOR ** BEARING. (F2420000) 90278-2 811 REF: GENERIC NO REF	MOS HRS/MSC AFL	1200	+25/-25			28-FEB-2018 4664.5 3452	5864.5	5889.5
AIRWORTHINESS									
242002	NO. 2 AC 5KVA ALTERNATOR 90278-2 365 REF: AMM 24-20-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			23-MAR-2019 4774.6 3558		
242002A	REPLACE NO. 2 AC 5KVA ALTERNATOR ** BEARING. (F2420000) 90278-2 365 REF: GENERIC NO REF	MOS HRS/MSC AFL	1200	+25/-25			23-MAR-2019 4774.6 3558	5974.6	5999.6
AIRWORTHINESS									
242050	REMOTE CONTROL CIRCUIT BREAKER SM600BA25N1/N536-9077 52359 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
242052	REMOTE CONTROL CIRCUIT BREAKER SM600BA25N1/N536-9077 90186 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
242081	CABIN AC INVERTER 2D1200-1A-011 GB001057 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				08-AUG-2008 2256.57 1566		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243001	NO. 1 STARTER/GENERATOR 23280-067 P1173 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			30-MAR-2020 4909.4 3693		
243001A	OVERHAUL NO. 1 STARTER/GENERATOR IRN P2430003. (ZONE/ACCESS 410) 23280-067 P1173 REF: AMM 24-30-01	MOS HRS/MSC AFL	1200	+25/-25			30-MAR-2020 4909.4 3693	6109.4	6134.4
243001B	REPLACE NO. 1 STARTER/GENERATOR BEARING 23280-067 P1173 REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				30-MAR-2020 4909.4 3693		
243002	NO. 2 STARTER/GENERATOR 232080-067 P1107/CA REF: AMM 24-30-01	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			03-AUG-2014 4066.5 2880		
243002A	OVERHAUL NO. 2 STARTER/GENERATOR IRN P2430003. (ZONE/ACCESS 410) 232080-067 P1107/CA REF: AMM 24-30-01	MOS HRS/MSC AFL	1200	+25/-25			03-AUG-2014 4066.5 2880	5266.5	5291.5
243002B	REPLACE NO. 2 STARTER/GENERATOR BEARING 232080-067 P1107/CA REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				09-JUL-2012 3445.3 2422		
243003	APU STARTER/GENERATOR 23080-023B Y01200 REF: AMM 49-40-01	MOS HRS/MSC AFL	O/C	N:125 O:0 N:4346 O:0 N:3131 O:0			18-SEP-2015 4346 3131		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243003A	OVERHAUL APU STARTER/GENERATOR AND BRUSH REPLACEMENT. (IRN # V4900021, V4900003)								
OVERHAUL	23080-023B Y01200 REF: AMM 49-40-01	MOS HRS/MSC AFL APH					18-SEP-2015 4346 3131 1204.75	1800	1825
			600	+25/-25		-4.75			
243003B	VISUALLY INSPECT APU STARTER/GENERATOR GEAR BOX DRIVE SPLINE. (IRN # O4900006)								
	23080-023B Y01200 REF: AMM 05-10-00	MOS HRS/MSC AFL APH					18-SEP-2015 4346 3131 1204.75	1800	1825
			600	+25/-25		-4.75			
243019	NO. 1 MAIN SHIP BATTERY								
	RG380E/40L 41070223 REF: See Workcard	MOS HRS/MSC AFL					01-MAR-2020 4900.9 3686		
			O/C						
				N:0 N:0 N:0					
243019A	CHECK/SERVICE NO. 1 MAIN SHIP BATTERY (IRN O1222000 NI-CAD) - CAPACITY CHECK (IRN T1222004 38 AMP HOUR LEAD- ACID) - CAPACITY CHECK (IRN T1222007 28 AMP HOUR LEAD ACID)								
	RG380E/40L 41070223 REF: See Workcard	MOS HRS/MSC AFL	12 1000	+1m/-1m +100/-100			01-MAR-2020 4900.9 3686	01-MAR-2021 5900.9	01-APR-2021 6000.9
243020	NO. 2 MAIN SHIP BATTERY								
	RG380E/40L 41075528 REF: See Workcard	MOS HRS/MSC AFL					01-MAR-2020 4900.9 3686		
			O/C						
				N:0 N:0 N:0					
243020A	CHECK/SERVICE NO. 2 MAIN SHIP BATTERY (IRN O1222000 NI-CAD) - CAPACITY CHECK (IRN T1222004 38 AMP HOUR LEAD- ACID) - CAPACITY CHECK (IRN T1222007 28 AMP HOUR LEAD ACID)								
	RG380E/40L 41075528 REF: See Workcard	MOS HRS/MSC AFL	6 500	+1m/-1m +100/-100			01-MAR-2020 4900.9 3686	01-SEP-2020 5400.9	01-OCT-2020 5500.9

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243037	EMERGENCY (IRN AB2431063 FOR RG-443) BATTERY RG443 40944150 REF: See Workcard	MOS HRS/MSC AFL	60 5000	+14d/-14d +25/-25 N:24 N:226.1 N:224			01-MAR-2020 4900.9 3686	01-MAR-2023 9674.8	15-MAR-2023 9699.8
243037A	PERFORM EMERGENCY (IRN AB2431063 FOR RG-443) BATTERY CAPACITY CHECK (P/N 7624308001, IRN O2431002), (P/N RG-443, IRN AB2431062) RG443 40944150 REF: CMM 24-30-67	MOS HRS/MSC AFL	6 500	+14d/-14d +25/-25			01-MAR-2020 4900.9 3686	01-SEP-2020 5400.9	15-SEP-2020 5425.9
246001	LEFT FORWARD POWER DISTRIBUTION PANEL 650GC02Y03 362 REF: AMM 24-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
246002	RIGHT FORWARD POWER DISTRIBUTION PANEL 655GC02Y03 356 REF: AMM 24-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
246003	LEFT AFT POWER DISTRIBUTION PANEL 660GC02Y07 237 REF: AMM 24-60-03	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			31-JAN-2007 1214.2 827		
246004	RIGHT AFT POWER DISTRIBUTION PANEL 665GC02Y07 337 REF: AMM 24-60-03	MOS HRS/MSC AFL	O/C				01-JAN-2009 2348 1620		
246106	APU GENERATOR CONTROL UNIT PRINTED CIRCUIT BOARD 790CE01Y04 1904 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				25-JAN-2012 3229.48 2261		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-Y2431005	BATTERY CABLES AND RECEPTACLES - PERFORM BATTERY CONNECTOR TOLERANCE CHECK. (REFER TO 24-31-00.). IRN Y2431005	MOS					17-JUL-2020		
	REF: AMM 24-31-00	HRS/MSC AFL	300	+25/-25			4932.3	5232.3	5257.3
+ AC2460002 (s)	REMOVE ATTACHING PARTS SECURING CIRCUIT BREAKER PANEL TO STRUCTURE. CHECK FOR LOOSE CIRCUIT BREAKER TERMINALS, LOOSE WIRE TERMINALS, CORRODED TERMINALS OR BUSS BARS, AND EVIDENCE OF WIRE INSULATION DAMAGE.						PKG		
	PKG 19	MOS	96	+14d/-14d			03-APR-2005		
	REF: AMM NO REF	HRS/MSC AFL	2400	+25/-25			0		0
B2450002 (s)	PERFORM ** ELECTRICAL SYSTEM CONTROL - OPERATIONAL CHECK						PKG		
	PKG 13	MOS	48	+14d/-14d			23-NOV-2016		
AIRWORTHINESS	REF: AMM 24-00-00	HRS/MSC AFL	1200	+25/-25			4476		3270
H2450001 (s)	** AUXILIARY POWER SUPPLIES - PERFORM FUNCTIONAL TEST						PKG		
	PKG 7	MOS	24	+14d/-14d			17-JUL-2020		
AIRWORTHINESS	REF: AMM 24-00-00	HRS/MSC AFL	600	+25/-25			4932.3		
H2450023 (s)	** EMER BATT LOW AND GEN AMPS HIGH INDICATION - PERFORM OPERATIONAL CHECK.						PKG		
	PKG 7	MOS	24	+14d/-14d			17-JUL-2020		
AIRWORTHINESS	REF: AMM 24-00-00	HRS/MSC AFL	600	+25/-25			4932.3		
Q2460001 (s)	PERFORM ** POWER DISTRIBUTION SYSTEM - SQUAT SWITCH CHECK.						PKG		
	PKG 17	MOS	48	+14d/-14d			23-NOV-2016		
AIRWORTHINESS	REF: AMM 24-60-00	HRS/MSC AFL	1200	+25/-25			4476		3270

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
R2431003 (s)	PERFORM ** BATTERY WARNING SYSTEM - FUNCTIONAL TEST. (EFFECTIVE ON AIRCRAFT WITH NI-CAD BATTERIES INSTALLED)						PKG		
	PKG 19	MOS	96	+14d/-14d				23-NOV-2016	
AIRWORTHINESS	REF: AMM 24-31-00	HRS/MSC	2400	+25/-25				4476	
		AFL						3270	
W2450000 (s)	** GENERATOR FAIL INDICATION - PERFORM OPERATIONAL CHECK						PKG		
	PKG 7	MOS	24	+14d/-14d				17-JUL-2020	
AIRWORTHINESS	REF: AMM 24-00-00	HRS/MSC	600	+25/-25				4932.3	
		AFL							
Y2400001 (s)	PERFORM SWITCH AND CIRCUIT BREAKER PANELS - VISUAL INSPECTION						PKG		
	PKG 13	MOS	48	+14d/-14d				23-NOV-2016	
		HRS/MSC	1200	+25/-25				4476	
	REF: AMM 05-10-00	AFL						3270	
Y2400002 (s)	ELECTRICAL WIRING - PERFORM VISUAL INSPECTION FOR ROUTING, SECURITY, CLEARANCES, CHAFING, AND ELECTRICAL COMPONENTS FOR SECURITY AND GENERAL CONDITION						PKG		
	PKG 7	MOS	24	+14d/-14d				17-JUL-2020	
		HRS/MSC	600	+25/-25				4932.3	
	REF: AMM 05-10-00	AFL							
Y2400025 (s)	ELECTRICAL WIRING - PERFORM VISUAL INSPECTION FOR ROUTING, SECURITY, CLEARANCES, CHAFING, AND ELECTRICAL COMPONENTS FOR SECURITY AND GENERAL CONDITION						PKG		
	PKG 8	MOS	24	+14d/-14d				17-JUL-2020	
		HRS/MSC	600	+25/-25				4932.3	
	REF: AMM 05-10-00	AFL							
Y2430005 (s)	STARTER/GENERATOR - PERFORM GROUNDING LUG BONDING CHECK						PKG		
	PKG 9	MOS	24	+14d/-14d				17-JUL-2020	
		HRS/MSC	600	+25/-25				4932.3	
	REF: AMM 24-30-01	AFL							

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y2430006 (s)	STARTER/GENERATOR - PERFORM VISUAL INSPECTION OF GROUNDING LUGS PKG 9	MOS	24	+14d/-14d			PKG	17-JUL-2020	
	REF: AMM 05-10-00	HRS/MSC AFL	600	+25/-25			4932.3		
Y2431000 (s)	PERFORM BATTERY, GENERATOR, AND BUS-TIE CABLES - VISUAL INSPECTION. PKG 20	MOS	96	+14d/-14d			PKG	23-NOV-2016	
	REF: AMM 05-10-00	HRS/MSC AFL	2400	+25/-25			4476		3270
Y2431001 (s)	EMERGENCY BATTERY CABLES - PERFORM VISUAL INSPECTION PKG 7	MOS	24	+14d/-14d			PKG	17-JUL-2020	
	REF: AMM 05-10-00	HRS/MSC AFL	600	+25/-25			4932.3		
Y2460000 (s)	PERFORM DC BUS ISOLATION - OPERATIONAL CHECK PKG 13	MOS	48	+14d/-14d			PKG	23-NOV-2016	
	REF: AMM 24-60-00	HRS/MSC AFL	1200	+25/-25			4476		3270
CHAPTER 25	EQUIPMENT/FURNISHINGS								
252000-1	#1 PASSENGER SEAT								
	M6613100-001-TD	MOS						03-APR-2005	
	050215-7	HRS/MSC	O/C					0	
	REF: AMM 25-20-45	AFL						0	
252000-2	#2 PASSENGER SEAT								
	M6613100-002-TD	MOS						03-APR-2005	
	050215-1	HRS/MSC	O/C					0	
	REF: AMM 25-20-45	AFL						0	
252000-3	#3 PASSENGER SEAT								
	M6613100-001-TD	MOS						03-APR-2005	
	050215-5	HRS/MSC	O/C					0	
	REF: AMM 25-20-45	AFL						0	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
252000-4	#4 PASSENGER SEAT M6613100-002-D 050215-2 REF: AMM 25-20-45	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
252000-5	#5 PASSENGER SEAT M6613100-001-D 050215-6 REF: AMM 25-20-45	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
252000-6	#6 PASSENGER SEAT M6613100-002-TD 050215-3 REF: AMM 25-20-45	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
252000-7	#7 PASSENGER SEAT M6613100-001-TD 050215-8 REF: AMM 25-20-45	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
252000-8	#8 PASSENGER SEAT M6613100-002-TD 050215-4 REF: AMM 25-20-45	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
252001-1	#1 PASSENGER SEAT PCU SP-45-34/30600558 030500328 REF: AMM 25-20-45	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
252005	AIRSHOW FLIGHT DECK CONTROLLER 922000-2/C233800-001 G00154594 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256001	PILOT CREW SEAT 4525103038-007 650 REF: AMM 25-10-50	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
256002	COPILOT CREW SEAT 4525103038-008 653 REF: AMM 25-10-50	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
256030	PILOT PROTECTIVE BREATHING (PBE), (IRN A3510008) EQUIPMENT UNIT PN NOT INSTALLED REF: AMM 25-60-00	MOS HRS/MSC AFL	N/A	N:0			01-APR-2005		
256061	PILOT LIFE VEST D21343-153 L849249 REF: See Workcard	MOS HRS/MSC AFL	O/C				23-NOV-2016 4476 3270		
256061A	INSPECT PILOT LIFE VEST (IRN # E2561002) D21343-153 L849249 REF: See Workcard	MOS HRS/MSC AFL	60		-33		23-NOV-2016	21-OCT-2021	
256062	COPILOT LIFE VEST D21343-153 L807615 REF: See Workcard	MOS HRS/MSC AFL	O/C				23-NOV-2016 4476 3270		
256062A	INSPECT COPILOT LIFE VEST (IRN # E2561002) D21343-153 L807615 REF: See Workcard	MOS HRS/MSC AFL	60		-33		23-NOV-2016	21-OCT-2021	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256063	NO. 1 LIFE VEST D21343-153 L815901 REF: See Workcard	MOS HRS/MSC AFL	O/C				23-NOV-2016 4476 3270		
256063A	INSPECT NO. 1 LIFE VEST (IRN # E2561002) D21343-153 L815901 REF: See Workcard	MOS HRS/MSC AFL	60		-33		23-NOV-2016	21-OCT-2021	
256064	NO. 2 LIFE VEST D21343-153 L899935 REF: See Workcard	MOS HRS/MSC AFL	O/C				23-NOV-2016 4476 3270		
256064A	INSPECT NO. 2 LIFE VEST (IRN # E2561002) D21343-153 L899935 REF: See Workcard	MOS HRS/MSC AFL	60		-33		23-NOV-2016	21-OCT-2021	
256065	NO. 3 LIFE VEST D21343-153 L839064 REF: See Workcard	MOS HRS/MSC AFL	O/C				23-NOV-2016 4476 3270		
256065A	INSPECT NO. 3 LIFE VEST (IRN # E2561002) D21343-153 L839064 REF: See Workcard	MOS HRS/MSC AFL	60		-33		23-NOV-2016	21-OCT-2021	
256066	NO. 4 LIFE VEST D21343-153 L899882 REF: See Workcard	MOS HRS/MSC AFL	O/C				23-NOV-2016 4476 3270		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256066A	INSPECT NO. 4 LIFE VEST (IRN # E2561002) D21343-153 L899882 REF: See Workcard	MOS HRS/MSC AFL	60			-33	23-NOV-2016	21-OCT-2021	
256067	NO. 5 LIFE VEST D21343-153 L829067 REF: See Workcard	MOS HRS/MSC AFL	O/C				23-NOV-2016 4476 3270		
256067A	INSPECT NO. 5 LIFE VEST (IRN # E2561002) D21343-153 L829067 REF: See Workcard	MOS HRS/MSC AFL	60			-33	23-NOV-2016	21-OCT-2021	
256068	NO. 6 LIFE VEST D21343-153 L899884 REF: See Workcard	MOS HRS/MSC AFL	O/C				23-NOV-2016 4476 3270		
256068A	INSPECT NO. 6 LIFE VEST (IRN # E2561002) D21343-153 L899884 REF: See Workcard	MOS HRS/MSC AFL	60			-33	23-NOV-2016	21-OCT-2021	
256069	NO. 7 LIFE VEST D21343-153 L904824 REF: See Workcard	MOS HRS/MSC AFL	O/C				23-NOV-2016 4476 3270		
256069A	INSPECT NO. 7 LIFE VEST (IRN # E2561002) D21343-153 L904824 REF: See Workcard	MOS HRS/MSC AFL	60			-33	23-NOV-2016	21-OCT-2021	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256070	NO. 8 LIFE VEST D21343-153 L785810 REF: See Workcard	MOS HRS/MSC AFL	O/C				23-NOV-2016 4476 3270		
256070A	INSPECT NO. 8 LIFE VEST (IRN # E2561002) D21343-153 L785810 REF: See Workcard	MOS HRS/MSC AFL	60		-33		23-NOV-2016	21-OCT-2021	
256071	LAVATORY LIFE VEST D21343-153 L835549 REF: CMM 25-60-05	MOS HRS/MSC AFL	O/C				23-NOV-2016 4476 3270		
256071A	INSPECT LAVATORY LIFE VEST (IRN # E2561002) D21343-153 L835549 REF: See Workcard	MOS HRS/MSC AFL	60		-33		23-NOV-2016	21-OCT-2021	
256076	FIRST AID KIT IFAK 022306040 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				03-APR-2008 2109 1464		
256076A	VISUALLY INSPECT FIRST AID KIT PER MANUFACTURER INSTRUCTIONS IFAK 022306040 REF: GENERIC CUSTOM	MOS HRS/MSC AFL	12				01-MAR-2020 4900.9 3686	01-MAR-2021	
256109	(ELT) EMERGENCY LOCATOR TRANSMITTER 453-5000-366 210-07096 REF: AMM 25-62-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			08-FEB-2016 4383.7 3170		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256109A	FUNCTIONAL TEST (ELT) EMERGENCY LOCATOR TRANSMITTER 453-5000-366 210-07096 REF: See Workcard	MOS HRS/MSC AFL	12	+14d/-14d			01-MAR-2020 4900.9 3686	01-MAR-2021	15-MAR-2021
256109B	INSPECT ELT BATTERIES (IF INSTALLED) 453-5000-366 210-07096 REF: See Workcard	MOS HRS/MSC AFL	12	+14d/-14d			01-MAR-2020 4900.9 3686	01-MAR-2021	15-MAR-2021
256109C	REPLACE (ELT) EMERGENCY LOCATOR TRANSMITTER ELT BATTERY 453-5000-366 210-07096 REF: See Workcard	MOS HRS/MSC AFL	DUE				08-FEB-2016 4383.7 3170	30-APR-2021 M	
256109D	REPLACE (ELT) EMERGENCY LOCATOR TRANSMITTER REMOTE SWITCH BATTERY ARTEX 110 SYSTEMS WITHOUT 406 MHZ CAPABILITIES. 453-5000-366 210-07096 REF: See Workcard	MOS HRS/MSC AFL	N/A						
	N/A EQUIPMENT NOT INSTALLED								
256109E	REPLACE (ELT) EMERGENCY LOCATOR TRANSMITTER REMOTE SWITCH BATTERY (DORNE AND MARGOLIN ELT REMOTE CONTROL BATTERY (P/N U264-1). (ZONE/ACCESS 200 IRN # N2561004) 453-5000-366 210-07096 REF: AMM 25-62-04	MOS HRS/MSC AFL	N/A						
	NOT INSTALLED								
256115	ELT ANTENNA 110-337 4054043 REF: AMM 25-62-03	MOS HRS/MSC AFL	O/C				03-APR-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
258001	CABIN AIRSHOW DISPLAY COMPUTER UNIT 920040 D01655730 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
ST01677WI-A	INSPECT AIRCELL WIRELESS LOCAL AREA NETWORK (WLAN) COMPONENTS FOR SECURITY REF:	MOS HRS/MSC AFL	72				05-FEB-2016 4383.7 3170	05-FEB-2022	
ST01677WI-B	INSPECT AIRCELL WIRELESS LOCAL AREA NETWORK (WLAN) CONNECTING CABLES AND/OR ASSOCIATED WIRING IS NOT FRAYED, CUT, OR PINCHED REF:	MOS HRS/MSC AFL	72				05-FEB-2016 4383.7 3170	05-FEB-2022	
ST01677WI-C	INSPECT AIRCELL WIRELESS LOCAL AREA NETWORK (WLAN) FWD ATG ANTENNA REF:	MOS HRS/MSC AFL	12500				05-FEB-2016 4383.7 3170	15670	
ST01677WI-D	INSPECT AIRCELL WIRELESS LOCAL AREA NETWORK (WLAN) AFT BULKHEAD FEED THROUGH REF:	MOS HRS/MSC AFL	12500				05-FEB-2016 4383.7 3170	15670	
Y2510000 (s)	GLARESHIELD, HEADLINER, AND TRIM STRIPS - PERFORM VISUAL INSPECTION PKG 1 REF: AMM 05-10-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
Y2510001 (s)	CREW SEATS AND SEAT BELTS - PERFORM VISUAL INSPECTION PKG 1 REF: AMM 05-10-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y2520000 (s)	CABIN - PERFORM VISUAL INSPECTION OF THE FOLLOWING: A. CABIN SEATS AND SEAT BELTS. ENSURE THAT THE SEATS FUNCTION CORRECTLY AND LOCK IN PLACE. B. STOWAGE CABINETS. C. HEADLINER. D. SIDE PANELS. E. RUG. PKG 1 REF: AMM 05-10-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25				17-JUL-2020 4932.3	
Y2540000 (s)	ALL LAVATORY PAPER AND LINEN WASTE RECEPTACLE ACCESS DOORS AND DISPOSAL DOORS FOR PROPER OPERATION, FIT, SEALING, LATCHING, AND LEGIBILITY OF PLACARD. PKG 7 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25				17-JUL-2020 4932.3	
Y2540009 (s)	PERFORM AVIONICS EQUIPMENT AND WIRING LOCATED IN LAVATORY AREA - GENERAL VISUAL INSPECTION PKG 25 REF: AMM 05-10-00	MOS HRS/MSC AFL	4800	+25/-25				25-JUL-2018 4687.6 3479	
CHAPTER 26	FIRE PROTECTION								
261057	NO. 1 FIRE DETECT CONTROL UNIT 877-01032 0445-247 REF: AMM 26-11-01	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0			03-APR-2005 0 0	
261058	NO. 2 FIRE DETECT CONTROL UNIT 877-01032 0445-250 REF: AMM 26-11-01	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0			03-APR-2005 0 0	
261069	NO. 1 BLEED AIR LEAK(A76) DETECTION UNIT 6626100000-003 1625 REF: AMM NO REF	MOS HRS/MSC AFL	O/C					29-APR-2007 1505.3 1028	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
261070	NO. 2 BLEED AIR LEAK(A78) DETECTION UNIT 6626100000-003 1021 REF: AMM 26-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
261071	ANTI-ICE BLEED AIR LEAK(A77) DETECTION UNIT 6626100000-003 1028 REF: AMM 26-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
261075	APU FIRE/OVERHEAT DETECTOR 10-1093 00-0202 REF: AMM 26-13-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
262001	NO. 1/LEFT/LOWER FIRE EXTINGUISHER BOTTLE 33100021-1 44186B1 REF: AMM 26-21-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			01-MAR-2020 4900.9 3686		
262001A	NO. 1/LEFT/LOWER FIRE EXTINGUISHER BOTTLE - HYDROSTATIC TEST (Q2620006) 33100021-1 44186B1 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+14d/-14d				01-MAR-2025 M 15-MAR-2025	
SCHEDULED MAINTENANCE TASKS AND INTERVALS									
262002	NO. 2/RIGHT/UPPER FIRE EXTINGUISHER BOTTLE 33100021-1 62751B1 REF: AMM 26-21-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			01-MAR-2020 4900.9 3686		
262002A	NO. 2/RIGHT/UPPER FIRE EXTINGUISHER BOTTLE - HYDROSTATIC TEST (Q2620006) 33100021-1 62751B1 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+14d/-14d				01-MAR-2025 M 15-MAR-2025	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262013	LEFT NO. 1 ENGINE FIRE EXTINGUISHER SQUIB 30903859 3019AA	MOS HRS/MSC AFL	180	N:1 N:0 N:0			01-MAR-2020 4900.9 3686	01-FEB-2030 M	
LIFE LIMIT	REF: Manufacture Date: 01-FEB-2020								
262013A	REPLACE LEFT NO. 1 ENGINE FIRE EXTINGUISHER SQUIB (SERVICE LIFE IRN # D2620007 AND D2620008). 30903859 3019AA	MOS HRS/MSC AFL	120				01-MAR-2020	01-MAR-2030	
LIFE LIMIT	REF:								
262014	RIGHT NO. 1 ENGINE FIRE EXTINGUISHER SQUIB 30903859 3031AA	MOS HRS/MSC AFL	180	N:1 N:0 N:0			01-MAR-2020 4900.9 3686	01-FEB-2030 M	
LIFE LIMIT	REF: Manufacture Date: 01-FEB-2020								
262014A	REPLACE RIGHT NO. 1 ENGINE FIRE EXTINGUISHER SQUIB (SERVICE LIFE IRN # D2620007 AND D2620008). 30903859 3031AA	MOS HRS/MSC AFL	120				01-MAR-2020	01-MAR-2030	
LIFE LIMIT	REF:								
262015	LEFT NO. 2 ENGINE FIRE EXTINGUISHER SQUIB 30903856 02469	MOS HRS/MSC AFL	180	N:8 N:0 N:0			01-MAR-2020 4900.9 3686	01-JUL-2029 M	
LIFE LIMIT	REF: Manufacture Date: 01-JUL-2019								
262015A	REPLACE LEFT NO. 2 ENGINE FIRE EXTINGUISHER SQUIB (SERVICE LIFE IRN # D2620007 AND D2620008). 30903856 02469	MOS HRS/MSC AFL	120				01-MAR-2020	01-MAR-2030	
LIFE LIMIT	REF:								
262016	RIGHT NO. 2 ENGINE FIRE EXTINGUISHER SQUIB 30903856 02482	MOS HRS/MSC AFL	180	N:8 N:0 N:0			01-MAR-2020 4900.9 3686	01-JUL-2029 M	
LIFE LIMIT	REF: Manufacture Date: 01-JUL-2019								

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262016A	REPLACE RIGHT NO. 2 ENGINE FIRE EXTINGUISHER SQUIB (SERVICE LIFE IRN # D2620007 AND D2620008). 30903856 02482 REF:	MOS HRS/MSC AFL	120				01-MAR-2020	01-MAR-2030	
LIFE LIMIT									
262040	APU FIRE WARNING HORN 430M1 19686 REF: AMM 26-13-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
262041	PILOT PORTABLE FIRE EXTINGUISHER A344T Y-648044 REF: GENERIC CUSTOM	MOS HRS/MSC AFL	O/C	N:53 N:0 N:0			27-MAY-2014 4022.13 2841		
262041A (s)	VISUAL INSPECTION AND WEIGHT CHECK PILOT PORTABLE FIRE EXTINGUISHER PILOTS PORTABLE FIRE EXTINGUISHER IRN (Y2620009) A344T PKG 1 Y-648044 REF: AMM NO REF	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			17-JUL-2020 4932.3	PKG	
262041B	HYDROSTATIC TEST PILOT PORTABLE FIRE EXTINGUISHER (IRN # Q2510003). A344T Y-648044 REF: AMM 26-23-00	MOS HRS/MSC AFL	144	+14d/-14d			27-MAY-2014	27-MAY-2026	10-JUN-2026
262042	COPILOT PORTABLE FIRE EXTINGUISHER A344T B-65822716 REF: GENERIC CUSTOM	MOS HRS/MSC AFL	O/C	N:3 N:0 N:0			20-MAY-2016 4415.8 3209		
262042A (s)	VISUAL INSPECTION AND WEIGHT CHECK COPILOT PORTABLE FIRE EXTINGUISHER CO-PILOT'S PORTABLE FIRE EXTINGUISHER (IRN Y2620009) A344T PKG 1 B-65822716 REF: AMM NO REF	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			17-JUL-2020 4932.3	PKG	



Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262042B	HYDROSTATIC TEST COPILOT PORTABLE FIRE EXTINGUISHER (IRN # Q2510003). A344T B-65822716 REF: AMM 26-23-00	MOS HRS/MSC AFL	144	+14d/-14d			01-FEB-2016	01-FEB-2028	15-FEB-2028
262051	CABIN PORTABLE FIRE EXTINGUISHER C352TS Y690586 REF: GENERIC CUSTOM	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-MAY-2014 4022.13 2841		
262051A (s)	VISUAL INSPECTION AND WEIGHT CHECK CABIN PORTABLE FIRE EXTINGUISHER (IRN Y2620009) C352TS PKG 1 Y690586 REF: AMM 26-23-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
262051B	HYDROSTATIC TEST CABIN PORTABLE FIRE EXTINGUISHER (IRN # Q2510003). C352TS Y690586 REF: AMM 26-23-00	MOS HRS/MSC AFL	144	+14d/-14d			01-JAN-2014	01-JAN-2026	15-JAN-2026
262075	APU FIRE EXTINGUISHER 51600-2 0291 REF: AMM 26-22-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			01-FEB-2019 4742.5 3528		
262075A	PERFORM APU FIRE EXTINGUISHER CONTAINER - ICC HYDROSTATIC TEST. (ZONE/ACCESS 310JL, 310QR) (IRN # Q4900014) 51600-2 0291 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+14d/-14d			01-JAN-2019	01-JAN-2024 M	15-JAN-2024
262076	REPLACE APU ENGINE FIRE EXTINGUISHER CONTAINER CARTRIDGE PN-UNKNOWN SN-UNKNOWN REF: AMM 26-21-02	MOS HRS/MSC AFL	180	+14d/-14d			01-FEB-2019 4742.5 3528	01-OCT-2030 M	15-OCT-2030
LIFE LIMIT	Manufacture Date: 01-OCT-2015								

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262076A	REPLACE REPLACE APU ENGINE FIRE EXTINGUISHER CONTAINER CARTRIDGE SERVICE LIFE (IRN # L4900015) PN-UNKNOWN SN-UNKNOWN REF:	MOS HRS/MSC AFL	144				01-FEB-2019 4742.5 3528	01-FEB-2031	
5-19-00-O2610001-LEFT	VISUALLY INSPECT NO. 1 ENGINE HOT SECTION FIRE DETECTOR ELEMENT. (ZONE/ACCESS 410 IRN O2610001) DURING MAJOR ENGINE INSPECTION/UNSCHEDULED ENGINE CHANGE REF: AMM 05-10-00	MOS HRS/MSC AFL	3000	+100/-100			02-JUN-2011 2942.4 2046	5942.4	6042.4
5-19-00-O2610001-RIGHT	VISUALLY INSPECT NO. 2 ENGINE HOT SECTION FIRE DETECTOR ELEMENT. (ZONE/ACCESS 410 IRN O2610001) DURING MAJOR ENGINE INSPECTION/UNSCHEDULED ENGINE CHANGE REF: AMM 05-10-00	MOS HRS/MSC AFL	3000	+100/-100			24-JUL-2009 2416.1 1669	5416.1	5516.1
J2620000 (s)	PERFORM ** ENGINE FIRE EXTINGUISHING SYSTEM FIRE SWITCH - FUNCTIONAL TEST PKG 25 REF: AMM 26-21-00	MOS HRS/MSC AFL	4800	+25/-25			PKG 25-JUL-2018 4687.6 3479		
T2620001 (s)	PERFORM ** FIREWALL SHUTOFF VALVES - OPERATIONAL CHECK. PKG 13 REF: AMM 26-21-00	MOS HRS/MSC AFL	48	+14d/-14d +25/-25			PKG 23-NOV-2016 4476 3270		
Y2610000 (s)	FIREWALL AND ACCESSORY COMPARTMENT FIRE DETECTOR ELEMENTS - PERFORM VISUAL INSPECTION PKG 9 REF: AMM 05-10-00	MOS HRS/MSC AFL	24	+14d/-14d +14/-14			PKG 17-JUL-2020 4932.3		
Y2620002 (s)	ENGINE FIRE EXTINGUISHER CONTAINERS - PERFORM VISUAL INSPECTION. CHECK CONTAINERS FOR CONDITION, CARTRIDGES AND CARTRIDGE WIRING FOR SECURITY AND CONDITION, CONTAINER PRESSURE GAUGE FOR PROPER PRESSURES, AND PLUMBING FOR SECURITY AND CONDITION PKG 2 REF: AMM 05-10-00	MOS HRS/MSC AFL	12	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y2620005 (s)	PERFORM ENGINE FIRE EXTINGUISHING SYSTEM - OPERATIONAL CHECK PKG 19 REF: AMM 26-21-00	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 23-NOV-2016 4476 3270		
Y2620009 (s)	INSPECT PORTABLE HAND HELD FIRE EXTINGUISHERS FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE. PKG 1 REF:	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
Z2620021 (s)	NO. 1 ENGINE FIRE EXTINGUISHER CONTAINER PLUMBING - PERFORM DETAILED INSPECTION PKG 2 REF: AMM 26-21-00	MOS HRS/MSC AFL	12 300				PKG 17-JUL-2020 4932.3		
Z2620021 (s)	NO. 2 ENGINE FIRE EXTINGUISHER CONTAINER PLUMBING - PERFORM DETAILED INSPECTION PKG 2 REF: AMM 26-21-00	MOS HRS/MSC AFL	12 300				PKG 17-JUL-2020 4932.3		
CHAPTER 27 FLIGHT CONTROLS									
271045	ASSEMBLY, AILERON CONTROL INBOARD LEFT CABLE 4527103079-009 1002797/1-10 REF: AMM 27-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
271046	ASSEMBLY, AILERON CONTROL INBOARD RIGHT CABLE 4527103078-009 1015927/1-16 REF: AMM 27-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
271051	LEFT AILERON FORWARD OUTBOARD CONTROL CABLE 4527103077-011 1013099/1-2 REF: AMM 27-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
271052	RIGHT AILERON FORWARD OUTBOARD CONTROL CABLE 4527103076-015 1013098/1-6 REF: AMM 27-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
271053	LEFT AILERON OUTBOARD AFT CONTROL CABLE 4527103078-009 1015927/1-18 REF: AMM 27-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
271054	RIGHT AILERON AFT OUTBOARD CONTROL CABLE 4527103079-009 1004783/1-5 REF: AMM 27-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
271083	AILERON TRIM TAB ACTUATOR 4323338 552 REF: AMM 27-10-09	MOS HRS/MSC AFL	O/C	R:22 R:0 R:0			11-DEC-2012 3615.55 2542		
271095	PILOT ANGLE OF ATTACK (AOA) INDICATOR C-38805-1 83046 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
271096	COPILOT ANGLE OF ATTACK (AOA) INDICATOR C-38805-1 83049 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
272021	RUDDER TRIM TAB ACTUATOR 4323322 0413 REF: AMM 27-20-03	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			01-FEB-2019 4742.5 3528		
272031	PILOT RUDDER PEDAL ADJUST ACTUATOR 6627208001-001 0786 REF: AMM 27-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
272032	COPILOT RUDDER PEDAL ADJUST ACTUATOR 6627208001-001 0787 REF: AMM 27-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
273005	LEFT AFT LOWER ELEVATOR CONTROL SYSTEM CABLE 7627302026-005 SN-UNKNOWN REF: AMM 27-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-MAY-2014 4022.13 2841		
273006	RIGHT AFT LOWER ELEVATOR CONTROL SYSTEM CABLE 7627302025-005 SN-UNKNOWN REF: AMM 27-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-MAY-2014 4022.13 2841		
273015	LEFT ANGLE OF ATTACK (AOA) VANE 6627308500-803 4700 REF: AMM 27-31-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			08-FEB-2012 3247.28 2274		
273016	RIGHT ANGLE OF ATTACK (AOA) VANE 6627308500-803 4724 REF: AMM 27-31-04	MOS HRS/MSC AFL	O/C	N:10 N:0 N:0			27-JUN-2012 3433.4 2416		
273063	PILOT STICK SHAKER 6627308500-009 1427 REF: AMM 27-31-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
273064	COPILOT STICK SHAKER 6627308500-009 1420 REF: AMM 27-31-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
273075	LEFT ANGLE OF ATTACK (AOA) TRANSMITTER 6627308500-001 883 REF: AMM 27-31-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
273076	RIGHT ANGLE OF ATTACK (AOA) TRANSMITTER 6627308500-001 877 REF: AMM 27-31-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
273087	STALL WARNING COMPUTER 6627308500-013 444 REF: AMM 27-31-02	MOS HRS/MSC AFL	O/C				08-SEP-2012 3510.28 2467		
274011	HORIZONTAL STABILIZER ACTUATOR 6627401000-009 B0337 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 N:4063.8 O:609.4 R:0 R:0			20-MAY-2016 4415.8 3209		
274011A	INSPECT HORIZONTAL STABILIZER ACTUATOR * (6627401000-009 - IRN P2740032). (6627401000-007 - IRN T2740002) 6627401000-009 B0337 REF: AMM 27-40-00	MOS HRS/MSC AFL	1200				20-MAY-2016 4415.8 3209	5615.8	
274011B	* HORIZONTAL STABILIZER ACTUATOR - PERFORM DETAILED STRUCTURAL INSPECTION (6627401000-009 - IRN P2740033). (6627401000-007 - IRN N2740025) 6627401000-009 B0337 REF: GENERIC NO REF	MOS HRS/MSC AFL	2400	I:1714.8			20-MAY-2016 4415.8 3209	5101	
274011C	REPLACE HORIZONTAL STABILIZER ACTUATOR * ACME SCREW (P/N 2A94568008). EFFECTIVE ON AIRCRAFT EQUIPPED WITH (6627401000-007 - IRN N2740023) 6627401000-009 B0337 REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A						
274011D	REPLACE HORIZONTAL STABILIZER ACTUATOR * ACME NUT (P/N 2A94567005). (EFFECTIVE ON AIRCRAFT EQUIPPED WITH (6627401000-007 - IRN N2740024) 6627401000-009 B0337 REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A						

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
274031	TRIM-IN-MOTION DETECTOR 1625-1-1 0412023 REF: AMM 27-41-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
274041	FORWARD INTERFACE UNIT 4527408503-027 MRP642857 REF: AMM 27-40-04	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			07-MAR-2012 3285.12 2304		
274051	HORIZONTAL STABILIZER ACTUATOR CONTROL BOX ASSEMBLY 6627401000-003 D0470 REF: See Workcard	MOS HRS/MSC AFL	O/C				28-SEP-2012 3541.32 2491		
275020	LEFT FLAP, OUTBOARD ACTUATOR 6627503000-011(C144488-1) 1608 REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
275021	LEFT FLAP, INBOARD ACTUATOR 6627503000-009(C144487-1) 1605 REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
275022	RIGHT FLAP, INBOARD ACTUATOR 6627503000-009(C144487-1) 1604 REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
275023	RIGHT FLAP, OUTBOARD ACTUATOR 6627503000-011(C144488-1) 1609 REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
275030	LEFT * INBOARD FLAP ACTUATOR JOINT REPLACE 145673-1 SN-UNKNOWN REF: AMM 27-50-06	MOS HRS/MSC AFL	24	N:0 N:0 N:0			30-MAR-2020 4909.4 3693	30-MAR-2022	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275031	LEFT * OUTBOARD FLAP ACTUATOR JOINT REPLACE 145673-1 SN-UNKNOWN REF: AMM 27-50-06	MOS HRS/MSC AFL	24	N:0 N:0 N:0			30-MAR-2020 4909.4 3693	30-MAR-2022	
275032	RIGHT * INBOARD FLAP ACTUATOR JOINT REPLACE 145673-1 SN-UNKNOWN REF: AMM 27-50-06	MOS HRS/MSC AFL	24	N:0 N:0 N:0			30-MAR-2020 4909.4 3693	30-MAR-2022	
275033	RIGHT * OUTBOARD FLAP ACTUATOR JOINT REPLACE 145673-1 SN-UNKNOWN REF: AMM 27-50-06	MOS HRS/MSC AFL	24	N:0 N:0 N:0			30-MAR-2020 4909.4 3693	30-MAR-2022	
275057	FLAP DRIVE POWER UNIT 6627503000-001 1341 REF: AMM 27-50-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
275058	FLAP CONTROL UNIT C144486-3-003 1215 REF: AMM 27-50-05	MOS HRS/MSC AFL	O/C				09-DEC-2005 484 339		
275069	FLAP POSITION INDICATOR C145159-1 432 REF: AMM 27-50-07	MOS HRS/MSC AFL	O/C				16-FEB-2007 1254 859		
275080	FLAP CONTROL MODULE 144486-3-0003 1215 REF: AMM 27-50-02	MOS HRS/MSC AFL	O/C				09-DEC-2005 484 339		
275081	LEFT FLAP DRIVE RVDT 6627503000-019(C144489-2) AO389 REF: AMM 27-50-03	MOS HRS/MSC AFL	O/C				03-JAN-2008 1908 1337		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275082	RIGHT FLAP DRIVE RVDT 6627503000-019(C144489-2) A0660 REF: AMM 27-50-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
276001	LEFT SPOILER ACTUATOR 6627602001-005 DAW714-04 REF: AMM 27-60-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
276002	RIGHT SPOILER ACTUATOR 6627602001-005 DAW700-04 REF: AMM 27-60-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
276005	SPOILER CONTROL MODULE 69014-7 338 REF: AMM 27-60-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
276013	SPOILER SHUTOFF VALVE 6627602002-005 0051T REF: AMM 27-60-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
276031	LEFT SPOILER RVDT 4527603007-001/3A2-249A A0643 REF: AMM 27-60-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
276032	RIGHT SPOILER RVDT 4527603007-001/3A2-249A A0644 REF: AMM 27-60-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
276073	SPOILERON COMPUTER 402800-06-01 00314 REF: AMM 27-60-02	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			14-AUG-2019 4829.3 3616		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
276076	CONTROL WHEEL RVDT 3G4-211A 3380442 REF: AMM 27-60-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
5-19-00-D2740003	** HORIZONTAL STABILIZER ACTUATOR SECONDARY TRIM - PERFORM FUNCTIONAL TEST (IRN D2740003) REF: AMM 27-40-02	MOS HRS/MSC AFL	600	+25/-25			20-MAY-2016 4415.8 3209	5015.8	5040.8
5-19-00-D2740004	** HORIZONTAL STABILIZER ACTUATOR PRIMARY TRIM - PERFORM FUNCTIONAL TEST (IRN D2740004) REF: AMM 27-40-02	MOS HRS/MSC AFL	600	+25/-25			20-MAY-2016 4415.8 3209	5015.8	5040.8
5-19-00-K2700007	* AILERON CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (IRN K2700007) REF: AMM 27-00-00	MOS HRS/MSC AFL	4800				25-JUL-2018 4687.6 3479	9487.6	
AIRWORTHINESS									
5-19-00-K2700008	* ELEVATOR CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (IRN K2700008) REF: AMM 27-00-00	MOS HRS/MSC AFL	4800				25-JUL-2018 4687.6 3479	9487.6	
AIRWORTHINESS									
5-19-00-K2700009	* RUDDER CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (IRN K2700009) REF: AMM 27-00-00	MOS HRS/MSC AFL	4800				25-JUL-2018 4687.6 3479	9487.6	
AIRWORTHINESS									
5-19-00-K2700010	* ELEVATOR CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (IRN K2700010) REF: AMM 27-00-00	MOS HRS/MSC AFL	4800				25-JUL-2018 4687.6 3479	9487.6	
AIRWORTHINESS									

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-K2700012	* RUDDER CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (IRN K2700012)	MOS					25-JUL-2018		
AIRWORTHINESS	REF: AMM 27-00-00	HRS/MSC AFL	4800				4687.6 3479	9487.6	
5-19-00-K2700014	DETAILED VISUAL INSPECTION *AILERON CONTROL SYSTEM PRIMARY CABLES (IRN K2700014)	MOS					25-JUL-2018		
AIRWORTHINESS	REF: AMM 27-00-00	HRS/MSC AFL	4800				4687.6 3479	9487.6	
5-19-00-M5540022	RUDDER TORQUE TUBE - PERFORM BORESCOPE INSPECTION	MOS							
	REF: AMM 55-40-00	HRS/MSC AFL	N/A						
5-19-00-N2720030	RUDDER TORQUE TUBE AND SPINDLE - PERFORM DETAILED VISUAL INSPECTION	MOS	72	+14d/-14d		-16	30-MAR-2020	14-MAR-2026	28-MAR-2026
AIRWORTHINESS	REF: AMM 27-20-01	HRS/MSC AFL					4909.4 3693		
5-19-00-S2750057	* FLAP ACTUATOR BALLNUT SLEEVE (FLAP ACTUATOR ASSEMBLY LEARJET P/N 6627503000-009, 6627503000-011, 6627503000-021, 6627503000-023, 6627503000-025, AND 6627503000-027, FLAP ACTUATOR ASSEMBLY MICROTECNICA P/N C144487-1, C144488-1, C144487-2, C144488-2, C144487-3, AND C144488-3) - PERFORM FLUORESCENT PENETRANT INSPECTION	MOS					10-SEP-2018		
NOT APPLICABLE	REF: See Workcard	HRS/MSC AFL	N/A				4717.7 3498		
5-19-00-W2750056	PERFORM * FLAP ACTUATOR JOINT (P/N 145673-1) - PERFORM DETAILED VISUAL INSPECTION. (REFER TO 27-50-06.) APPLY CORROSION PREVENTIVE COMPOUND (CPC) TO JOINT. (REFER TO 12-21-03.) IRN W2750056	MOS	12				01-MAR-2020	01-MAR-2021	
	REF: See Workcard	HRS/MSC AFL					4900.9 3686		
+ 5-19-01-AA2760021-LEFT	LEFT SPOILER HYDRAULIC PRESSURE SWIVEL - REPLACE	MOS					01-OCT-2018		
	REF: AMM NO REF	HRS/MSC AFL	1200	+25/-25			4717.7 3498	5917.7	5942.7

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 5-19-01-AA2760021-LEFT	LEFT SPOILER HYDRAULIC RETURN SWIVEL - REPLACE	MOS					01-OCT-2018		
	REF: AMM NO REF	HRS/MSC	1200	+25/-25			4717.7	5917.7	5942.7
		AFL					3498		
+ 5-19-01-AA2760021-RIGHT	RIGHT SPOILER HYDRAULIC PRESSURE SWIVEL - REPLACE	MOS					01-OCT-2018		
	REF: AMM NO REF	HRS/MSC	1200	+25/-25			4717.7	5917.7	5942.7
		AFL					3498		
+ 5-19-01-AA2760021-RIGHT	RIGHT SPOILER HYDRAULIC RETURN SWIVEL - REPLACE	MOS					01-OCT-2018		
	REF: AMM NO REF	HRS/MSC	1200	+25/-25			4717.7	5917.7	5942.7
		AFL					3498		
5-19-01-R2710041	REPLACE * AILERON SPINDLE (P/N 4527102103-001). (IRN R2710041)	MOS	120				29-APR-2015	29-APR-2025	
	REF: AMM 27-10-07	HRS/MSC					4258		
		AFL					3059		
5-19-01-W2750055	* FLAP ACTUATOR JOINT (P/N 145673-1) (IRN W2750055) REPLACEMENT	MOS	24	N:0			30-MAR-2020	30-MAR-2022	
	145673-1	HRS/MSC		N:0			4909.4		
	SN-UNKNOWN	AFL		N:0			3693		
	REF: AMM 27-50-06								
A2711001 (s)	** AILERON TRIM TAB CONTROL SYSTEM - PERFORM OPERATIONAL CHECK						PKG		
	PKG 7	MOS	24	+14d/-14d			17-JUL-2020		
	AIRWORTHINESS	HRS/MSC	600	+25/-25			4932.3		
	REF: AMM 27-10-04	AFL							
A2721001 (s)	** RUDDER TRIM SYSTEM - PERFORM OPERATIONAL CHECK						PKG		
	PKG 7	MOS	24	+14d/-14d			17-JUL-2020		
	AIRWORTHINESS	HRS/MSC	600	+25/-25			4932.3		
	REF: AMM 27-20-00	AFL							
A2731002 (s)	** ELEVATOR DISCONNECT SYSTEM - PERFORM OPERATIONAL CHECK						PKG		
	PKG 8	MOS	24	+14d/-14d			17-JUL-2020		
	AIRWORTHINESS	HRS/MSC	600	+25/-25			4932.3		
	REF: AMM 27-30-00	AFL							

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A2760001 (s)	** SPOILER ACTUATOR CHECK VALVE - PERFORM OPERATIONAL CHECK PKG 10	MOS	24	+14d/-14d			PKG	17-JUL-2020	
AIRWORTHINESS	REF: AMM 27-60-04	HRS/MSC AFL	600	+25/-25			4932.3		
A2760002 (s)	** SPOILER SYSTEM - PERFORM SPOILER AUTHORITY WITH FLAPS CHECK PKG 10	MOS	24	+14d/-14d			PKG	17-JUL-2020	
AIRWORTHINESS	REF: AMM 27-60-00	HRS/MSC AFL	600	+25/-25			4932.3		
AA2700000 (s)	AILERON CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF ACCESSIBLE CABLES PKG 7	MOS	24	+14d/-14d			PKG	17-JUL-2020	
	REF: AMM 27-00-00	HRS/MSC AFL	600	+25/-25			4932.3		
AA2700001 (s)	RUDDER CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF ACCESSIBLE CABLES PKG 7	MOS	24	+14d/-14d			PKG	17-JUL-2020	
	REF: AMM 27-00-00	HRS/MSC AFL	600	+25/-25			4932.3		
AA2700002 (s)	ELEVATOR CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF ACCESSIBLE CABLES PKG 7	MOS	24	+14d/-14d			PKG	17-JUL-2020	
	REF: AMM 27-00-00	HRS/MSC AFL	600	+25/-25			4932.3		
G2710003 (s)	PERFORM AILERON CONTROL SYSTEM CABLES (LOCATED IN WING AREA) - CABLE TENSION CHECK. PKG 16	MOS	48	+14d/-14d			PKG	23-NOV-2016	
	REF: AMM 27-10-00	HRS/MSC AFL	1200	+25/-25			4476 3270		
G2710004 (s)	PERFORM AILERON CONTROL SYSTEM CABLES (LOCATED IN FUSELAGE AREA) - CABLE TENSION CHECK. PKG 13	MOS	48	+14d/-14d			PKG	23-NOV-2016	
	REF: AMM 27-10-00	HRS/MSC AFL	1200	+25/-25			4476 3270		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
G2720003 (s)	PERFORM RUDDER CONTROL CABLES - TENSION CHECK. PKG 14 REF: AMM 27-20-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 23-NOV-2016 4476 3270		
G2720004 (s)	PERFORM RUDDER PEDALS, PEDAL PUSHRODS, ADJUSTMENT ACTUATOR, AND SECTORS - VISUAL INSPECTION. CHECK DURING FULL TRAVEL OF RUDDER. PKG 13 REF: AMM 05-10-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 23-NOV-2016 4476 3270		
G2730003 (s)	PERFORM ELEVATOR CONTROL CABLES - TENSION CHECK. PKG 14 REF: AMM 27-30-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 23-NOV-2016 4476 3270		
V2712000 (s)	** ROLL DISCONNECT SWITCHES - PERFORM OPERATIONAL CHECK. PKG 7 REF: AMM 27-60-09	MOS HRS/MSC AFL	24 600	+25d/-25d +14/-14			PKG 17-JUL-2020 4932.3		
W2731001 (s)	** PITCH TRIM - PERFORM OPERATIONAL CHECK OF ELEVATOR OVERRIDE ACTUATOR PKG 8 REF: AMM 27-30-14	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
Y2700003 (s)	AILERON CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF CABLES WITHIN WING PKG 10 REF: AMM 27-00-00	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
Y2700004 (s)	RUDDER CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF ACCESSIBLE UPPER AND LOWER CABLES PKG 8 REF: AMM 27-00-00	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y2700005 (s)	ELEVATOR CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF ACCESSIBLE UPPER AND LOWER CABLES PKG 8 REF: AMM 27-00-00	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
Y2700006 (s)	RUDDER AND ELEVATOR CONTROL CABLES AND ASSOCIATED PULLEYS, LOCATED IN AFT PRESSURE BULKHEAD SUPPORT CHANNEL - PERFORM VISUAL INSPECTION PKG 9 REF: AMM 27-00-00	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
Y2710000 (s)	AILERONS, AILERON TRIM TAB AND VISIBLE PORTION OF RODS - PERFORM VISUAL INSPECTION PKG 10 REF: AMM 05-10-00	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
Y2710001 (s)	PERFORM AILERON BALANCE WEIGHT INSTALLATION AND SUPPORTING STRUCTURE - VISUAL INSPECTION PKG 16 REF: AMM 05-10-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 23-NOV-2016 4476 3270		
Y2710002 (s)	PERFORM AILERON CONTROL SYSTEM - OPERATIONAL CHECK PKG 16 REF: AMM 27-10-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 23-NOV-2016 4476 3270		
Y2710048 (s)	AILERON TRIM TAB INSTALLATION - PERFORM FREE PLAY CHECK PKG 22 REF: See Workcard	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 23-NOV-2016 4476 3270		
Y2720000 (s)	RUDDER - PERFORM VISUAL INSPECTION PKG 2 REF: AMM 05-10-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y2720001 (s)	PERFORM RUDDER BALANCE WEIGHT INSTALLATION AND SUPPORTING STRUCTURE - VISUAL INSPECTION PKG 14 REF: AMM 05-10-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 23-NOV-2016 4476 3270		
Y2720002 (s)	PERFORM RUDDER CONTROL SYSTEM - OPERATIONAL CHECK PKG 14 REF: AMM 27-20-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 23-NOV-2016 4476 3270		
Y2721000 (s)	RUDDER TRIM TAB AND VISIBLE RODS - PERFORM VISUAL INSPECTION. NOTE: ON AIRCRAFT 45-005 THRU 45-364 NOT MODIFIED BY SB 45-27-34 AND AIRCRAFT 45-005 THRU 45-428 NOT MODIFIED PER SB 45-27-37, REPLACE THE RUDDER TRIM TAB HINGE LOWER COTTER PIN DURING THIS INSPECTION. PKG 2 REF: AMM 05-10-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
Y2730000 (s)	PERFORM CONTROL COLUMNS - VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO AILERON CONTROL WHEEL CABLE DRUM AND BOTTOM CROSSOVER PULLEYS PKG 13 REF: AMM 05-10-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 23-NOV-2016 4476 3270		
Y2730001 (s)	ELEVATORS - PERFORM VISUAL INSPECTION PKG 2 REF: AMM 05-10-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
Y2730002 (s)	PERFORM ELEVATOR CONTROL SYSTEM - OPERATIONAL CHECK PKG 14 REF: AMM 27-30-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 23-NOV-2016 4476 3270		
Y2730004 (s)	PERFORM CONTROL COLUMNS - INSPECTION. INSPECT CABLE, PULLEYS, BEARINGS, AND ELECTRICAL WIRING PKG 19 REF: AMM 27-00-00	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 23-NOV-2016 4476 3270		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y2730007 (s)	PERFORM AFT ELEVATOR DISCONNECT - DETAILED VISUAL INSPECTION PKG 20	MOS	96	+14d/-14d			PKG	23-NOV-2016	
	REF: AMM 05-10-00	HRS/MSC AFL	2400	+25/-25			4476 3270		
Y2740000 (s)	PERFORM PRIMARY PITCH TRIM SYSTEM - OPERATIONAL CHECK PKG 14	MOS	48	+14d/-14d			PKG	23-NOV-2016	
	REF: AMM 27-40-00	HRS/MSC AFL	1200	+25/-25			4476 3270		
Y2740001 (s)	PERFORM SECONDARY PITCH TRIM SYSTEM - OPERATIONAL CHECK PKG 14	MOS	48	+14d/-14d			PKG	23-NOV-2016	
	REF: AMM 27-40-00	HRS/MSC AFL	1200	+25/-25			4476 3270		
Y2750000 (s)	FLAP DRIVE INSTALLATION - PERFORM VISUAL INSPECTION WITH FLAPS LOWERED PKG 10	MOS	24	+14d/-14d			PKG	17-JUL-2020	
	REF: AMM 05-10-00	HRS/MSC AFL	600	+25/-25			4932.3		
Y2750001 (s)	FLAPS - PERFORM VISUAL INSPECTION PKG 4	MOS	12	+14d/-14d			PKG	17-JUL-2020	
	REF: AMM 05-10-00	HRS/MSC AFL	300	+25/-25			4932.3		
Y2750053 (s)	FLAP DRIVE ACTUATORS - PERFORM A VISUAL INSPECTION OF THE ACTUATOR ATTACHMENT, PAYING PARTICULAR ATTENTION TO THE GIMBAL PIN RETAINING RINGS PKG 10	MOS	24	+14d/-14d			PKG	17-JUL-2020	
	REF: AMM 05-10-00	HRS/MSC AFL	600	+25/-25			4932.3		
Y2760000 (s)	SPOILER AND SPOILER ACTUATOR - PERFORM VISUAL INSPECTION WITH FLAPS LOWERED AND ACCESS PANELS OPENED PKG 10	MOS	24	+14d/-14d			PKG	17-JUL-2020	
	REF: AMM 05-10-00	HRS/MSC AFL	600	+25/-25			4932.3		

CHAPTER 28 FUEL

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281001	LEFT NO. 1 FUEL, EJECTOR SCAVENGE PUMP 6628200302-001V0685/HTE230008 42040973 REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
281002	RIGHT NO. 1 FUEL, EJECTOR SCAVENGE PUMP 6628200302-001V0685/HTE230008 42040964 REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
281003	LEFT NO. 2 FUEL, EJECTOR SCAVENGE PUMP 6628200302-001V0685/HTE230008 42040994 REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
281004	RIGHT NO. 2 FUEL, EJECTOR SCAVENGE PUMP 6628200302-001V0685/HTE230008 42041012 REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
281005	LEFT NO. 3 FUEL, EJECTOR SCAVENGE PUMP 6628200302-001V0685/HTE230008 42040977 REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
281006	RIGHT NO. 3 FUEL, EJECTOR SCAVENGE PUMP 6628200302-001V0685/HTE230008 42041011 REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
281007	LEFT NO. 4 FUEL, EJECTOR SCAVENGE PUMP 6628200302-001V0685/HTE230008 42040968 REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
281008	RIGHT NO. 4 FUEL, EJECTOR SCAVENGE PUMP 6628200302-001V0685/HTE230008 42041000 REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281009	LEFT NO. 5 FUEL, EJECTOR SCAVENGE PUMP 6628200302-001V0685/HTE230008 42040978 REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
281010	RIGHT NO. 5 FUEL, EJECTOR SCAVENGE PUMP 6628200302-001V0685/HTE230008 42041006 REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
281031	FUEL, FUSELAGE CELL 6628100103-003 236 REF: AMM 28-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
281521	LEFT FUEL TRANSFER CHECK VALVE 7628200104-001/HTE460072 M0147CV1004 REF: AMM 28-12-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
281522	RIGHT FUEL TRANSFER CHECK VALVE 7628200104-001/HTE460072 M0138CV1104 REF: AMM 28-12-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
282011	SHUTOFF - REFUEL VALVE 6628200102-003 4604/02 REF: AMM 28-20-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
282031	LEFT NO. 1 FUEL SUPPLY CHECK VALVE 7628200101-001 M0160CV1004 REF: AMM 28-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
282032	LEFT NO. 2 FUEL SUPPLY CHECK VALVE 7628200101-001 M0162CV1004 REF: AMM 28-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282033	RIGHT NO. 1 FUEL SUPPLY CHECK VALVE 7628200101-001 M0157CV1004 REF: AMM 28-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
282034	RIGHT NO. 2 FUEL SUPPLY CHECK VALVE 7628200101-001 M0123CV1004 REF: AMM 28-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
282037	RIGHT FUEL SUPPLY SHUT-OFF (L10) VALVE ASSEMBLY 6628200101-003 1069 REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			01-OCT-2004 0 0		
282038	LEFT FUEL SUPPLY SHUT-OFF (L11) VALVE ASSEMBLY 6628200101-003 1091 REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			01-OCT-2004 0 0		
282041	CONTROL - REFUELING PANEL 10550P04Y00 04120823BA REF: AMM 28-20-14	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
282051	LEFT CHECK, MOTIVE FLOW VALVE 6628200106-003 33040923 REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
282052	RIGHT CHECK, MOTIVE FLOW VALVE 6628200106-003 FR016BM REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
282063	PRE-CHECK, SPPR VALVE HTE940032-1 30040604 REF: AMM 28-20-12	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282064	PILOT, SPPR VALVE 61087-2 324 REF: AMM 28-20-11	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
282075	LEFT ASSEMBLY, FUEL MAIN EJECTOR PUMP 6628200301-001/HTE230009 4404235 REF: AMM 28-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
282076	RIGHT ASSEMBLY, FUEL MAIN EJECTOR PUMP 6628200301-001/HTE230009 44040237 REF: AMM 28-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
282087	LEFT FUEL, STANDBY PUMP 6628200303-003 9AY46 REF: AMM 28-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
282088	RIGHT FUEL, STANDBY PUMP 6628200303-003 9AY45 REF: AMM 28-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
282601	DEFUEL (B24) SHUTOFF VALVE 91816-EM9102-2 1077 REF: AMM 28-20-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
282815	APU FUEL SHUTOFF VALVE 04320-8122-1 0251 REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
284001	ASSEMBLY, FUEL C1 PROBE 6628408000-001/10552T01Y00 0714 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284002	FUEL C2 PROBE 6628408000-027/10665T03Y 7456 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C					03-MAR-2008 2034 1415	
284003	ASSEMBLY, FUEL C3 PROBE 6628408000-005/10552T03Y00 0722 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				03-APR-2005 0 0	
284004	ASSEMBLY, FUEL C4 PROBE 6628408000-007/10552T04Y00 0767 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				03-APR-2005 0 0	
284005	ASSEMBLY, FUEL C5 PROBE 6628408000-021 0687 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				03-APR-2005 0 0	
284006	ASSEMBLY, FUEL C6 PROBE 6628408000-009 1044 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				03-APR-2005 0 0	
284008	FUEL C8 PROBE 6628408000-001/10552T01Y00 0726 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				03-APR-2005 0 0	
284009	ASSEMBLY, FUEL C9 PROBE 6628408000-003/10552T02Y00 0730 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				03-APR-2005 0 0	
284010	ASSEMBLY, FUEL C10 PROBE 6628408000-005/10552T03Y00 0681 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				03-APR-2005 0 0	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284011	ASSEMBLY, FUEL C11 PROBE 6628408000-007/10552T04Y00 0794 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
284012	ASSEMBLY, FUEL C12 PROBE 6628408000-021 0684 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
284013	ASSEMBLY, FUEL C13 PROBE 6628408000-009 1045 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
284014	ASSEMBLY, FUEL C14 PROBE 6628408000-011 1373 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
284015	FUEL C15 PROBE 6628408000-011 1370 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
284016	ASSEMBLY, FUEL C16 PROBE 6628408000-011 1243 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
284017	FUEL C17 PROBE 6628408000-011 1374 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
284033	FUSELAGE FUEL PROBE 6628408000-019 819 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284045	FUEL QUANTITY SIGNAL CONDITIONER 10551B08Y09 0926 REF: AMM 28-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				03-APR-2005 0 0	
5-19-00-D2820013	PERFORM INITIAL CLEANING AND LEAK CHECK OF LOW PRESSURE FUEL FILTERS. (NEW AIRCRAFT 50-FLIGHT HOUR CHECK) (ZONE/ACCESS 510AL IRN # D2820013) REF: AMM 28-20-15	MOS HRS/MSC AFL	A/R					18-MAY-2005 54 35	
5-19-00-H2840001	* DUAL FUEL FLOW CONVERTOR (DFFC) (P/N 10540B06F07) - PERFORM ACCEPTANCE TEST AND LOW TEMPERATURE SCREENING (IRN H2840001) REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A					09-JUL-2008 2215 1537	
F2840003 (s)	PERFORM ** FUEL QUANTITY SIGNAL CONDITIONER - FUNCTIONAL TEST TO VERIFY WEIGHT-ON-WHEELS (WOW) INPUTS. (EFFECTIVE ON AIRCRAFT 45-005 THRU 45-194 POST SB 45-28-5 AND 45-195 AND SUBSEQUENT.) PKG 14 REF: AMM 28-40-00	MOS HRS/MSC AFL	48	+14d/-14d +25/-25				23-NOV-2016 4476 3270	
Y2810001 (s)	WING TANKS - REMOVE FUEL TANK ACCESS PANELS AND PERFORM VISUAL INSPECTION PKG 10 REF: AMM 05-10-00	MOS HRS/MSC AFL	24	+14d/-14d +25/-25				17-JUL-2020 4932.3	
Y2810002 (s)	PERFORM WING TANKS - REMOVE FUEL TANK ACCESS PANELS AND PERFORM VISUAL INSPECTION PKG 22 REF: AMM 05-10-00	MOS HRS/MSC AFL	96	+14d/-14d +25/-25				23-NOV-2016 4476 3270	
Y2820000 (s)	LOW PRESSURE FUEL FILTER - REMOVE AND INSPECT FOR CONTAMINATION. CLEAN IF NECESSARY PKG 10 REF: AMM 28-20-15	MOS HRS/MSC AFL	24	+14d/-14d +25/-25				17-JUL-2020 4932.3	

CHAPTER 29 HYDRAULIC POWER

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291013	L9 HYDRAULIC SHUTOFF VALVE P40-791 20703387 REF: AMM 29-10-05	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			27-MAY-2014 4022.13 2841		
291033	RESERVOIR PRESSURIZATION CONTROL MODULE ZVM11-2 04-080661 REF: AMM 29-10-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
291034	RESERVOIR FLUID LEVEL SENSOR 3L14F-17 521 REF: AMM 29-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
291045	NO. 1 HYDRAULIC, ENGINE DRIVEN PUMP 6629101000-001 MX681128A REF: AMM 29-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
291046	NO. 2 HYDRAULIC, ENGINE DRIVEN PUMP 6629101000-001 MX687029A REF: AMM 29-10-01	MOS HRS/MSC AFL	O/C				01-MAY-2005 10.4 9		
291051	NO. 1 PRESSURE, MAIN HYDRAULIC SYSTEM SWITCH 7629001004-001 1131 REF: AMM 29-30-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
291057	MAIN HYDRAULIC SYSTEM ACCUMULATOR 88746-1 308 REF: AMM 29-10-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
291059	MAIN HYDRAULIC FILTER MANIFOLD 6629101001-005 1307 REF: AMM 29-10-03	MOS HRS/MSC AFL	O/C				01-MAY-2005 10.4 9		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291069	THERMAL SHUTOFF VALVE 98050 0518 REF: AMM 29-10-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
292011	AUXILIARY HYDRAULIC PUMP ASSEMBLY 266157-02 K0364 REF: AMM 29-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
292012	AUXILIARY HYDRAULIC PUMP PN SN-UNKNOWN REF: AMM 29-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
292013	AUXILIARY HYDRAULIC PUMP ELECTRIC MOTOR 6629201000-011 263A REF: AMM 29-20-04	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			02-APR-2009 2381.38 1642		
293001	GROUND SERVICE CONTROL BOX 4529308000V9-001 A5049 REF: AMM 29-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
293011	HYDRAULIC PRESSURE TRANSDUCER 7629301001-001 6821-2-249 REF: AMM 29-30-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
5-19-01-D2910017	REPLACE MAIN HYDRAULIC FILTER MANIFOLD ELEMENTS (D2910017) REF: AMM 29-10-03	MOS HRS/MSC AFL	-				03-APR-2005 0 0		
5-19-01-D2910018	REPLACE MAIN HYDRAULIC FILTER MANIFOLD ELEMENTS (D2910018) REF: AMM 29-10-03	MOS HRS/MSC AFL	300	+25/-25			17-JUL-2020 4932.3	5232.3	5257.3

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-01-O2910005	REPLACE AUXILIARY HYDRAULIC FILTER MANIFOLD ELEMENTS. (REFER TO 29-20-02.) (IRN # O2910005)	MOS						11-APR-2011	
	REF: AMM 29-20-02	HRS/MSC AFL	2400	+25/-25			2872.08 1990	5272.08	5297.08
H2920002 (s)	PERFORM HYDRAULIC SYSTEM GROUND SERVICE LEDS - FUNCTIONAL TEST. (EFFECTIVE ON AIRCRAFT 45-005 THRU 45-194 PRE SB 45-29-6.)	MOS	48	+14d/-14d			23-NOV-2016		
	PKG 13	HRS/MSC AFL	1200	+25/-25			4476 3270		
	REF: AMM 29-30-00								
T2910026 (s)	PERFORM RELIEF FUNCTION OF THE HYDRAULIC RESERVOIR PRESSURIZATION CONTROL MODULE - FUNCTIONAL TEST.	MOS	48	+14d/-14d			23-NOV-2016		
	PKG 14	HRS/MSC AFL	1200	+25/-25			4476 3270		
	REF: AMM 29-10-06								
Y2910001 (s)	PERFORM HYDRAULIC COMPONENTS AND ASSOCIATED PLUMBING (AFT OF FUSELAGE FUEL CELL, FS 495 TO FS 512) - VISUAL INSPECTION.	MOS	48	+14d/-14d			23-NOV-2016		
	PKG 14	HRS/MSC AFL	1200	+25/-25			4476 3270		
	REF: AMM 05-10-00								
Y2910002 (s)	PERFORM HYDRAULIC COMPONENTS AND ASSOCIATED PLUMBING (WHEEL WELL AND FORWARD AREA OF REAR SPAR) - VISUAL INSPECTION	MOS	48	+14d/-14d			23-NOV-2016		
	PKG 17	HRS/MSC AFL	1200	+25/-25			4476 3270		
	REF: AMM 05-10-00								
Y2910003 (s)	PERFORM HYDRAULIC COMPONENTS AND ASSOCIATED PLUMBING (AFT AREA OF REAR SPAR) - VISUAL INSPECTION	MOS	96	+14d/-14d			23-NOV-2016		
	PKG 19	HRS/MSC AFL	2400	+25/-25			4476 3270		
	REF: AMM 05-10-00								
Y2920001 (s)	PERFORM AUXILIARY HYDRAULIC SYSTEM - OPERATIONAL CHECK	MOS	48	+14d/-14d			23-NOV-2016		
	PKG 13	HRS/MSC AFL	1200	+25/-25			4476 3270		
	REF: AMM 29-20-00								

CHAPTER 30 ICE AND RAIN PROTECTION

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
301063	LEFT ANTI-ICE PRESSURE REGULATING SHUTOFF (PRSOV L12) VALVE 6621000000-087 843 REF: AMM 30-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
301064	RIGHT ANTI-ICE PRESSURE REGULATING SHUTOFF (PRSOV L13) VALVE 6621000000-087 844 REF: AMM 30-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
304021	WINDSHIELD ANTI-ICE CONTROLLER 90825-7 353 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
304060	NO. 1 WING SURFACE TEMPERATURE (MT42) SENSOR PN SN-UNKNOWN REF: AMM 30-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
304061	NO. 2 WING SURFACE TEMPERATURE (MT43) SENSOR PN SN-UNKNOWN REF: AMM 30-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
304062	NO. 3 WING SURFACE TEMPERATURE (MT44) SENSOR PN SN-UNKNOWN REF: AMM 30-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
304063	NO. 4 WING SURFACE TEMPERATURE (MT45) SENSOR PN SN-UNKNOWN REF: AMM 30-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
308005	ICE DETECTION PROBE 0871HN2 0185 REF: AMM 30-80-01	MOS HRS/MSC AFL	O/C				01-JUN-2020 4914.4 3699		



Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-Q3010006	BORESCOPE INSPECTION ANTI-ICE MANIFOLD ASSEMBLY. (ZONE/ACCESS 300 **IRN # Q3010006). REFER TO 30-10-07.	MOS					01-MAR-2020		
	REF: AMM 30-10-07	HRS/MSC	1200	+25/-25	-85.35		4900.9	6015.55	6040.55
		AFL					3686		
5-19-00-Z3020005-LEFT	LEFT * ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS.	MOS					30-AUG-2019		
AIRWORTHINESS	REF: AMM 30-20-00	HRS/MSC	250				4832.2	5082.2	
		AFL					3618		
5-19-00-Z3020005-RIGHT	RIGHT * ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS.	MOS					30-AUG-2019		
AIRWORTHINESS	REF: AMM 30-20-00	HRS/MSC	250				4832.2	5082.2	
		AFL					3618		
+ 5-19-00-Z3020006-LEFT	LEFT ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS	MOS					03-APR-2005		
	REF: GENERIC NO REF	HRS/MSC	N/A				0		
		AFL					0		
+ 5-19-00-Z3020006-RIGHT	RIGHT ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS	MOS					03-APR-2005		
	REF: GENERIC NO REF	HRS/MSC	N/A				0		
		AFL					0		
A3020000 (s)	PERFORM ** NACELLE ANTI-ICE SYSTEM - FUNCTIONAL TEST						PKG		
	PKG 15	MOS	48	+14d/-14d			23-NOV-2016		
AIRWORTHINESS	REF: AMM 30-20-00	HRS/MSC	1200	+25/-25			4476		
		AFL					3270		
A3030000 (s)	PERFORM ** PITOT/STATIC HEAT SYSTEM - OPERATIONAL CHECK						PKG		
	PKG 19	MOS	96	+14d/-14d			23-NOV-2016		
AIRWORTHINESS	REF: AMM 30-30-00	HRS/MSC	2400	+25/-25			4476		
		AFL					3270		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
H3010000 (s)	** WING/STAB ANTI-ICE SWITCH - PERFORM OPERATIONAL CHECK PKG 7	MOS	24	+14d/-14d			PKG	17-JUL-2020	
AIRWORTHINESS	REF: AMM 30-10-00	HRS/MSC AFL	600	+25/-25			4932.3		
T3040000 (s)	** PERFORM FUNCTIONAL TEST OF THE WINDSHIELD ANTI-ICE SYSTEM PKG 7	MOS	24	+14d/-14d			PKG	17-JUL-2020	
AIRWORTHINESS	REF: AMM 30-40-00	HRS/MSC AFL	600	+25/-25			4932.3		
Y3010007 (s)	WING ANTI-ICE PICCOLO TUBE - PERFORM DETAILED VISUAL INSPECTION FOR CRACKS AT W.S. 43 AND W.S. 176. PKG 10	MOS	24	+14d/-14d			PKG	17-JUL-2020	
	REF: GENERIC NO REF	HRS/MSC AFL	600	+25/-25			4932.3		
Y3080000 (s)	PERFORM ICE DETECTION SYSTEM - FUNCTIONAL TEST PKG 13	MOS	48	+14d/-14d			PKG	23-NOV-2016	
	REF: AMM 30-80-00	HRS/MSC AFL	1200	+25/-25			4476 3270		

CHAPTER 31 INDICATING/RECORDING SYSTEMS

311001	PILOT CIRCUIT BREAKER PANEL ASSY 4531180817-267-001 MAN147670 REF: AMM 24-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
311005	COPILOT CIRCUIT BREAKER PANEL ASSY 4531180818-264-001 A00591213-01 REF: AMM 24-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
311805	ENGINE FUEL CONTROL (P7) PANEL ASSY 4576108500-025 A00381788-01 REF: AMM 31-11-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
312001	PILOT CLOCK M850-5V-LA A2849 REF: AMM 31-21-01	MOS HRS/MSC AFL	O/C	N:106 N:3952.23 N:2783			06-FEB-2014 3952.23 2783		
312002	COPILOT CLOCK M850-5V-LA A4854 REF: AMM 31-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			08-FEB-2016 4383.7 3170		
312011	PILOTS DIGITAL CLOCK BATTERY TYPE N SN-UNKNOWN REF: AMM 31-21-02	MOS HRS/MSC AFL	12	+14d/-14d N:0 N:0 N:0			01-MAR-2020 4900.9 3686	01-MAR-2021	15-MAR-2021
312012	COPILOTS DIGITAL CLOCK BATTERY TYPE N SN-UNKNOWN REF: AMM 31-21-02	MOS HRS/MSC AFL	12	+14d/-14d N:0 N:0 N:0			01-MAR-2020 4900.9 3686	01-MAR-2021	15-MAR-2021
313001	FLIGHT DATA RECORDER 2100-2042-00 000387615 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				07-NOV-2011 3136.35 2189		
313003	FDR ACCELEROMETER 3001-01-111 0904-7088 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
313005	FDR UNDERWATER LOCATOR BEACON DK120 SD67045 REF: AMM 25-61-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			03-OCT-2008		
313005A	PERFORM FDR UNDERWATER LOCATOR BEACON FUNCTIONAL TEST OF BEACON, CLEAN BEACON SWITCH AND PERFORM TEST OF ULB BATTERY. (IRN AA2560000) DK120 SD67045 REF: AMM 25-61-01	MOS HRS/MSC AFL	24	+14d/-14d			03-OCT-2018 4717.7 3498	03-OCT-2020	17-OCT-2020

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
313005B	REPLACE FDR UNDERWATER LOCATOR BEACON BATTERY ON OR BEFORE ULB BATTERY REPLACEMENT DATE. (ZONE/ACCESS 300 IRN # D2566001)								
	DK120	MOS					03-OCT-2018	01-DEC-2024	M
	SD67045	HRS/MSC	DUE				4717.7		
	REF: AMM NO REF	AFL					3498		
313010	HOBBS METER								
	4531288503	MOS		N:0			03-APR-2005		
	A0052075-01	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
314001	SELCAL DECODER								
	920040	MOS					01-MAY-2005		
	1654	HRS/MSC	O/C				10.4		
	REF: GENERIC NO REF	AFL					9		
314011	NO. 1 DATA ACQUISITION (DAU) UNIT								
	7013348-938(C3140002-009)	MOS		N:0			03-APR-2005		
	04125850	HRS/MSC	O/C	N:0			0		
	REF: AMM 31-42-01	AFL		N:0			0		
314012	NO. 2 DATA ACQUISITION (DAU) UNIT								
	7013348-938(C3140002-009)	MOS		N:0			03-APR-2005		
	04125849	HRS/MSC	O/C	N:0			0		
	REF: AMM 31-42-01	AFL		N:0			0		
314023	NO. 1 INTEGRATED AVIONICS (IC-600) COMPUTER								
	7017000-82224	MOS					16-MAY-2018		
	01064564	HRS/MSC	O/C						
	REF: AMM 31-41-01	AFL							
314024	NO. 2 INTEGRATED AVIONICS (IC-600) COMPUTER								
	7017000-82224	MOS					06-MAR-2015		
	06077658	HRS/MSC	O/C						
	REF: AMM 31-41-01	AFL							
314051	NO. 1 CENTRAL COMPUTING IM-600 MEMORY MODULE								
	7025973-04216	MOS					01-MAY-2005		
	04073197	HRS/MSC	O/C				10.4		
	REF: AMM 31-41-02	AFL					9		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
314052	NO. 2 CENTRAL COMPUTING IM-600 MEMORY MODULE 7025973-04216 04073196 REF: AMM 31-41-02	MOS HRS/MSC AFL	O/C					01-MAY-2005 10.4 9	
315001	CREW WARNING PANEL ASSEMBLY 90-42801-8 381 REF: AMM 31-51-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				03-APR-2005 0 0	
316001	NO. 1 DU870 DISPLAY UNIT K9321060A14 2890020033 REF: AMM 31-60-01	MOS HRS/MSC AFL	O/C					29-MAR-2019	
316002	NO. 2 DU870 DISPLAY UNIT K9321060A14 2890020180 REF: AMM 31-60-01	MOS HRS/MSC AFL	O/C					29-MAR-2019	
316003	NO. 3 DU870 DISPLAY UNIT K9321060A14 2890020282 REF: AMM 31-60-01	MOS HRS/MSC AFL	O/C					29-MAR-2019	
316004	NO. 4 DU870 DISPLAY UNIT K9321060A14 2890020284 REF: AMM 31-60-01	MOS HRS/MSC AFL	O/C					29-MAR-2019	
316005	PILOT EFIS DISPLAY CONTROLLER 7016986-733 04125749 REF: AMM 31-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				03-APR-2005 0 0	
316006	COPILOT EFIS DISPLAY CONTROLLER 7016986-733 04125750 REF: AMM 31-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				03-APR-2005 0 0	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B3100000 (s)	** INDICATING/RECORDING SYSTEM - PERFORM OPERATIONAL CHECK						PKG		
	PKG 7	MOS	24	+14d/-14d			17-JUL-2020		
		HRS/MSC	600	+25/-25			4932.3		
AIRWORTHINESS	REF: AMM 31-00-00	AFL							
CHAPTER 32 LANDING GEAR									
320041	* REPLACE LEFT UPPER MAIN LANDING GEAR LINK PIN (P/N 200-0214) IRN N3220101								
	PN	MOS		N:0			03-APR-2005		
	SN-UNKNOWN	HRS/MSC		N:0			0		
LIFE LIMIT	REF: AMM 32-10-01	AFL	10000	N:0			0		10000
320042	* REPLACE RIGHT UPPER MAIN LANDING GEAR LINK PIN (P/N 200-0214) (IRN N3220101)								
	PN	MOS		N:0			03-APR-2005		
	SN-UNKNOWN	HRS/MSC		N:0			0		
LIFE LIMIT	REF: AMM 32-10-01	AFL	10000	N:0			0		10000
320043	* REPLACE LEFT LOWER MAIN LANDING GEAR LINK PIN (P/N 200-0214) (IRN N3220101)								
	PN	MOS		N:0			03-APR-2005		
	SN-UNKNOWN	HRS/MSC		N:0			0		
AIRWORTHINESS	REF: AMM 32-10-01	AFL	10000	N:0			0		10000
320044	* REPLACE RIGHT LOWER MAIN LANDING GEAR LINK PIN (P/N 200-0214) (IRN N3220101)								
	PN	MOS		N:0			03-APR-2005		
	SN-UNKNOWN	HRS/MSC		N:0			0		
AIRWORTHINESS	REF: AMM 32-10-01	AFL	10000	N:0			0		10000
320051	* REPLACE LEFT MAIN LANDING GEAR PISTON PIN (P/N 200-0215). (IRN N3220102)								
	PN	MOS		N:0			03-APR-2005		
	SN-UNKNOWN	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	10000	N:0			0		10000
320052	* REPLACE RIGHT MAIN LANDING GEAR PISTON PIN (P/N 200-0215) (IRN N3220102) ASSEMBLY								
	PN	MOS		N:0			03-APR-2005		
	SN-UNKNOWN	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	10000	N:0			0		10000

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320061	* REPLACE LEFT MAIN LANDING GEAR ACTUATOR PISTON (P/N 200-0301) (IRN N3220103) (JAA IRN Q3220065)								
	PN	MOS		N:0			03-APR-2005		
	SN-UNKNOWN	HRS/MSC		N:0			0		
LIFE LIMIT	REF: AMM 32-31-01	AFL	17000	N:0			0		17000
320062	* REPLACE RIGHT MAIN LANDING GEAR ACTUATOR PISTON (P/N 200-0301) (IRN N3220103) (JAA IRN Q3220065)								
	200-0301-103	MOS		N:0			03-APR-2013		
	H2309	HRS/MSC		N:0			3715.78		
LIFE LIMIT	REF: AMM 32-31-01	AFL	17000	N:0			2610		19610
320071	* REPLACE LEFT MAIN LANDING GEAR ACTUATOR CYLINDER (IRN N3220104) (JAA IRN Q3220066)								
	PN	MOS		N:0			03-APR-2005		
	SN-UNKNOWN	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	17000	N:0			0		17000
320072	* REPLACE RIGHT MAIN LANDING GEAR ACTUATOR CYLINDER (IRN N3220104) (JAA IRN Q3220066)								
	PN	MOS		N:0			03-APR-2005		
	SN-UNKNOWN	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	17000	N:0			0		17000
320081	* REPLACE LEFT MAIN LANDING GEAR END CAP (P/N 200-0303) (IRN T3220105) (JAA IRN T3220067)								
	200-0303-001	MOS		N:0			06-MAR-2012		
	H2191	HRS/MSC		N:0			3285.12		
LIFE LIMIT	REF: AMM 32-31-01	AFL	2387	N:0			2304		4691
320082	* REPLACE RIGHT MAIN LANDING GEAR END CAP (P/N 200-0303) (IRN T3220105) (JAA IRN T3220067)								
	200-0303-001	MOS		N:0			06-MAR-2012		
	H2196	HRS/MSC		N:0			3285.12		
LIFE LIMIT	REF: AMM 32-31-01	AFL	2387	N:0			2304		4691
320091	* REPLACE LEFT MAIN LANDING GEAR ACTUATOR HOUSING (P/N 200-0304) (IRN N3220106) (JAA IRN Q3220068)								
	PN	MOS		N:0			03-APR-2005		
	SN-UNKNOWN	HRS/MSC		N:0			0		
LIFE LIMIT	REF: AMM 32-31-01	AFL	17000	N:0			0		17000
320092	* REPLACE RIGHT MAIN LANDING GEAR ACTUATOR HOUSING (P/N 200-0304) (IRN N3220106) (JAA IRN Q3220068)								
	PN	MOS		N:0			03-APR-2005		
	SN-UNKNOWN	HRS/MSC		N:0			0		
LIFE LIMIT	REF: AMM 32-31-01	AFL	17000	N:0			0		17000

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321001	* LEFT MAIN LANDING GEAR STRUT (P/N 6632101000, 200-0200) (IRN N3220012) ASSEMBLY 200-0200-011 H0304	MOS HRS/MSC		N:96 N:3715.78			03-APR-2013 3715.78		
LIFE LIMIT	REF: AMM 32-10-01	AFL	10000	N:2610			2610	10000	
321001A	PERFORM SPECIAL DETAILED INSPECTION ON LEFT MAIN LANDING GEAR SHOCK STRUTS (IRN AA3220018)	MOS HRS/MSC	96 +14d/-14d				03-APR-2013 3715.78	03-APR-2021	17-APR-2021
	REF: See Workcard	AFL	6600 +25/-25				2610	9210	9235
321002	* RIGHT MAIN LANDING GEAR STRUT (P/N 6632101000, 200-0200) (IRN N3220012) ASSEMBLY 200-0200-012 H1321	MOS HRS/MSC		N:96 N:3715.78			03-APR-2013 3715.78		
LIFE LIMIT	REF: AMM 32-10-01	AFL	10000	N:2610			2610	10000	
321002A	PERFORM SPECIAL DETAILED INSPECTION ON RIGHT MAIN LANDING GEAR SHOCK STRUTS (IRN AA3220018)	MOS HRS/MSC	96 +14d/-14d				03-APR-2013 3715.78	03-APR-2021	17-APR-2021
	REF: See Workcard	AFL	6600 +25/-25				2610	9210	9235
321011	* LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER (IRN'S N3220116, Q3220137, Q3220128) 200-0200-109 H0399	MOS HRS/MSC		N:2610			11-APR-2013 3715.78		
LIFE LIMIT	REF: AMM 32-10-01	AFL	10000	N:2610			2610	10000	
321011A	ULTRASONIC-INSPECTION * LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER (IRN'S N3220116, Q3220137, Q3220128) * MLG SHOCK STRUT CYLINDER. PERFORM ULTRASONIC INSPECTION OF THE LOWER SERVICE PORT AND FORGING PARTING LINE. IRN L3220118, M3220136, P3220146, (JAA IRN L3220122) 200-0200-109 H0399	MOS HRS/MSC					11-APR-2013 3715.78		
	REF: See Workcard	AFL	4800				2610	7410	
321012	* RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER (IRN'S N3220116, Q3220137, Q3220128) 200-0201-110 H0404	MOS HRS/MSC		N:2610			11-APR-2013 3715.78		
LIFE LIMIT	REF: AMM 32-10-01	AFL	10000	N:2610			2610	10000	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321012A	ULTRASONIC-INSPECTION * RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER (IRN'S N3220116, Q3220137, Q3220128) * MLG SHOCK STRUT CYLINDER. PERFORM ULTRASONIC INSPECTION OF THE LOWER SERVICE PORT AND FORGING PARTING LINE. IRN L3220118, M3220136, P3220146, (JAA IRN L3220122)	200-0201-110 H0404 REF: See Workcard	MOS HRS/MSC AFL	4800			11-APR-2013 3715.78 2610	7410	
321025	* LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR UPPER PIN (P/N 200-0325) ASSEMBLY	200-0325-101 H3047 REF: AMM 32-31-01	MOS HRS/MSC AFL	96	N:0 N:0 N:0		25-JUL-2018 4687.6 3479	25-JUL-2026	
321025A	MAGNETIC PARTICLE INSPECT * LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR UPPER PIN (P/N 200-0325) ASSEMBLY * (IRN T3220024)	REF: See Workcard	MOS HRS/MSC AFL	48			25-JUL-2018 4687.6 3479	25-JUL-2022	
321025B	DETAILED VISUAL INSPECTION * LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR UPPER PIN (P/N 200-0325) ASSEMBLY * (IRN T3220135)	REF: AMM 05-10-00	MOS HRS/MSC AFL	48			25-JUL-2018 4687.6 3479	25-JUL-2022	
321026	* RIGHT MAIN LANDING GEAR SIDE STAY ACTUATOR UPPER PIN (P/N 200-0325) ASSEMBLY	200-0325-101 H3040 REF: AMM 32-31-01	MOS HRS/MSC AFL	96	N:0 N:0 N:0		25-JUL-2018 4687.6 3479	25-JUL-2026	
321026A	MAGNETIC PARTICLE INSPECT * RIGHT MAIN LANDING GEAR SIDE STAY ACTUATOR UPPER PIN (P/N 200-0325) ASSEMBLY * (IRN T3220024)	REF: See Workcard	MOS HRS/MSC AFL	48			25-JUL-2018 4687.6 3479	25-JUL-2022	
321026B	DETAILED VISUAL INSPECTION * RIGHT MAIN LANDING GEAR SIDE STAY ACTUATOR UPPER PIN (P/N 200-0325) ASSEMBLY * (IRN T3220135)	REF: AMM 05-10-00	MOS HRS/MSC AFL	48			25-JUL-2018 4687.6 3479	25-JUL-2022	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321037	* LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR LOWER PIN (P/N 200-0217) ASSEMBLY 200-0217-101 H2798	MOS HRS/MSC	96	N:0 N:0			25-JUL-2018 4687.6	25-JUL-2026	
LIFE LIMIT	REF: GENERIC NO REF	AFL		N:0			3479		
321037A	MAGNETIC PARTICLE INSPECT * LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR LOWER PIN (P/N 200-0217) ASSEMBLY * (IRN T3220024)	MOS HRS/MSC	48				25-JUL-2018 4687.6	25-JUL-2022	
AIRWORTHINESS	REF: See Workcard	AFL					3479		
321037B	DETAILED VISUAL INSPECTION * LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR LOWER PIN (P/N 200-0217) ASSEMBLY * (IRN T3220135)	MOS HRS/MSC	48				25-JUL-2018 4687.6	25-JUL-2022	
AIRWORTHINESS	REF: AMM 05-10-00	AFL					3479		
321038	* RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR LOWER PIN (P/N 200-0217) ASSEMBLY 200-0217-101 H2788	MOS HRS/MSC	96	N:0 N:0			25-JUL-2018 4687.6	25-JUL-2026	
LIFE LIMIT	REF: GENERIC NO REF	AFL		N:0			3479		
321038A	MAGNETIC PARTICLE INSPECT * RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR LOWER PIN (P/N 200-0217) ASSEMBLY * (IRN T3220024)	MOS HRS/MSC	48				25-JUL-2018 4687.6	25-JUL-2022	
AIRWORTHINESS	REF: See Workcard	AFL					3479		
321038B	DETAILED VISUAL INSPECTION * RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR LOWER PIN (P/N 200-0217) ASSEMBLY * (IRN T3220135)	MOS HRS/MSC	48				25-JUL-2018 4687.6	25-JUL-2022	
AIRWORTHINESS	REF: AMM 05-10-00	AFL					3479		
321049	* LEFT MAIN LANDING GEAR AXLE BEAM (P/N 200-0203) (N3220036) ASSEMBLY PN SN-UNKNOWN	MOS HRS/MSC		N:0 N:0			03-APR-2005 0		
LIFE LIMIT	REF: AMM 32-10-01	AFL	10000	N:0			0	10000	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321049A	INSPECTION * LEFT MAIN LANDING GEAR AXLES - PERFORM MAIN LANDING GEAR AXLE BEAM ASSEMBLY BORESCOPE INSPECTION (IRN T3220007)	MOS	48				01-FEB-2019 4742.5 3528	01-FEB-2023	
	REF: AMM 32-10-01	HRS/MSC AFL							
321050	* RIGHT MAIN LANDING GEAR AXLE BEAM (P/N 200-0203) (N3220036) ASSEMBLY	PN		N:0			03-APR-2005 0		
	SN-UNKNOWN	HRS/MSC		N:0					
LIFE LIMIT	REF: AMM 32-10-01	AFL	10000	N:0			0	10000	
321050A	INSPECTION * RIGHT MAIN LANDING GEAR AXLES - PERFORM MAIN LANDING GEAR AXLE BEAM ASSEMBLY BORESCOPE INSPECTION (IRN T3220007)	MOS	48				01-FEB-2019 4742.5 3528	01-FEB-2023	
	REF: AMM 32-10-01	HRS/MSC AFL							
321061	LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR PIN	PN		N:0			03-APR-2005 0		
	SN-UNKNOWN	HRS/MSC	O/C	N:0					
	REF: GENERIC NO REF	AFL		N:0			0		
321062	RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR PIN	PN		N:0			03-APR-2005 0		
	SN-UNKNOWN	HRS/MSC	O/C	N:0					
	REF: GENERIC NO REF	AFL		N:0			0		
321085	LEFT FORWARD TRUNNION ASSEMBLY	4532103011-009		N:0			03-APR-2005 0		
	CYC066	HRS/MSC	O/C	N:0					
	REF: GENERIC NO REF	AFL		N:0			0		
321086	RIGHT FORWARD TRUNNION ASSEMBLY	4532103011-010		N:0			03-APR-2005 0		
	CYC058	HRS/MSC	O/C	N:0					
	REF: GENERIC NO REF	AFL		N:0			0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321087	LEFT AFT TRUNNION ASSEMBLY 4532103021-007 CYC049 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
321088	RIGHT AFT TRUNNION ASSEMBLY 4532103021-008 CYC061 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
321101	* REPLACE LEFT MAIN LANDING GEAR TRUNNION FORWARD PIN (P/N 200-0212, 200-0213). (IRN N3220023) ASSEMBLY 200-0212-103 H0904 REF: See Workcard	MOS HRS/MSC AFL	10000	N:96 N:3715.78 N:2610			03-APR-2013 3715.78 2610		10000
321101A	MAGNETIC PARTICLE INSPECT LEFT MAIN LANDING GEAR TRUNNION FORWARD PIN - (IRN V3220022) REF: See Workcard	MOS HRS/MSC AFL	96	+14d/-14d			03-APR-2013 3715.78 2610	03-APR-2021	17-APR-2021
321102	* REPLACE RIGHT MAIN LANDING GEAR TRUNNION FORWARD PIN (P/N 200-0212, 200-0213) (IRN N3220023) ASSEMBLY 200-0212-103 H0896 REF: See Workcard	MOS HRS/MSC AFL	10000	N:96 N:3715.78 N:2610			03-APR-2013 3715.78 2610		10000
321102A	MAGNETIC PARTICLE INSPECT RIGHT MAIN LANDING GEAR TRUNNION FORWARD PIN (IRN V3220022) REF: See Workcard	MOS HRS/MSC AFL	96	+14d/-14d			03-APR-2013 3715.78 2610	03-APR-2021	17-APR-2021
321103	* REPLACE LEFT MAIN LANDING GEAR TRUNNION AFT PIN (P/N 200-0212, 200-0213) (IRN N3220023) ASSEMBLY 200-0213-103 H0687 REF: See Workcard	MOS HRS/MSC AFL	10000	N:96 N:3715.78 N:2610			03-APR-2013 3715.78 2610		10000

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321103A	MAGNETIC PARTICLE INSPECT LEFT MAIN LANDING GEAR TRUNNION AFT PIN (IRN V3220022)	MOS	96	+14d/-14d			03-APR-2013 3715.78 2610	03-APR-2021	17-APR-2021
	REF: See Workcard	HRS/MSC AFL							
321104	* REPLACE RIGHT MAIN LANDING GEAR AFT TRUNNION PIN (P/N 200-0212, 200-0213) (IRN N3220023) ASSEMBLY	MOS		N:96			03-APR-2013 3715.78 2610		
	200-0213-103	HRS/MSC		N:3715.78					
	H0696	AFL	10000	N:2610				10000	
LIFE LIMIT	REF: See Workcard								
321104A	MAGNETIC PARTICLE INSPECT RIGHT MAIN LANDING GEAR AFT TRUNNION PIN (IRN V3220022)	MOS	96	+14d/-14d			03-APR-2013 3715.78 2610	03-APR-2021	17-APR-2021
	REF: See Workcard	HRS/MSC AFL							
321111	LEFT FORWARD LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN	MOS		N:0			15-APR-2010 2631.17 1838		
	4532103201-001	HRS/MSC		N:0					
	CMI1382	AFL	5000	N:0				6838	
LIFE LIMIT	REF: AMM 57-10-05								
321111A	LEFT FORWARD LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION	MOS					24-MAR-2016 4406.7 3195		
	REF: AMM 57-10-05	HRS/MSC AFL	600					3795	
321112	RIGHT FORWARD LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN	MOS		N:0			15-APR-2010 2631.17 1838		
	4532103201-001	HRS/MSC		N:0					
	CMI1221	AFL	5000	N:0				6838	
LIFE LIMIT	REF: AMM 57-10-05								
321112A	RIGHT FORWARD LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION	MOS					24-MAR-2016 4406.7 3195		
	REF: AMM 57-10-05	HRS/MSC AFL	600					3795	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321113	LEFT FORWARD UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN 4532103201-001 CMI1226	MOS HRS/MSC		N:0 N:0			27-APR-2010 2631.17		
LIFE LIMIT	REF: AMM 57-10-05	AFL	5000	N:0			1838	6838	
321113A	LEFT FORWARD UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION	MOS HRS/MSC					24-MAR-2016 4406.7		
	REF: AMM 57-10-05	AFL	600				3195	3795	
321114	RIGHT FORWARD UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN 4532103201-001 CMI1226	MOS HRS/MSC		N:0 N:0			27-APR-2010 2631.17		
LIFE LIMIT	REF: AMM 57-10-05	AFL	5000	N:0			1838	6838	
321114A	RIGHT FORWARD UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION	MOS HRS/MSC					24-MAR-2016 4406.7		
	REF: AMM 57-10-05	AFL	600				3195	3795	
321117	LEFT AFT UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN 4532103202-001 CMI209	MOS HRS/MSC		N:0 N:0			27-APR-2010 2631.17		
LIFE LIMIT	REF: AMM 57-10-05	AFL	5000	N:0			1838	6838	
321117A	LEFT AFT UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION	MOS HRS/MSC					24-MAR-2016 4406.7		
	REF: AMM 57-10-05	AFL	600				3195	3795	
321118	RIGHT AFT UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN 4532103202-001 CMI699	MOS HRS/MSC		N:0 N:0			27-APR-2010 2631.17		
LIFE LIMIT	REF: AMM 57-10-05	AFL	5000	N:0			1838	6838	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321118A	RIGHT AFT UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION	MOS HRS/MSC REF: AMM 57-10-05	AFL 600				24-MAR-2016 4406.7 3195	3795	
321119	LEFT AFT LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN 4532103203-001 CMI580	MOS HRS/MSC REF: AMM 57-10-05	AFL 5000	N:0 N:0 N:0			27-APR-2010 2631.17 1838	6838	
321119A	LEFT AFT LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION	MOS HRS/MSC REF: AMM 57-10-05	AFL 600				24-MAR-2016 4406.7 3195	3795	
321120	RIGHT AFT LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN 4532103203-001 CMI662	MOS HRS/MSC REF: AMM 57-10-05	AFL 5000	N:0 N:0 N:0			15-APR-2010 2631.17 1838	6838	
321120A	RIGHT AFT LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION	MOS HRS/MSC REF: AMM 57-10-05	AFL 600				24-MAR-2016 4406.7 3195	3795	
321215	* REPLACE LEFT MAIN LANDING GEAR SHOCK STRUT PISTON (P/N 200-0202) (IRN N3220035) ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	10000	N:0 N:0 N:0			03-APR-2005 0 0	10000	
321216	* REPLACE RIGHT MAIN LANDING GEAR SHOCK STRUT PISTON (P/N 200-0202) (IRN N3220035) ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	10000	N:0 N:0 N:0			03-APR-2005 0 0	10000	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321227	* REPLACE LEFT MAIN LANDING GEAR SHOCK STRUT LINK (P/N 200-0204) (IRN N3220037) ASSEMBLY								
	PN	MOS		N:0			03-APR-2005		
	SN-UNKNOWN	HRS/MSC		N:0			0		
LIFE LIMIT	REF: AMM 32-10-01	AFL	10000	N:0			0		10000
321228	* REPLACE RIGHT MAIN LANDING GEAR SHOCK STRUT LINK (P/N 200-0204) (IRN N3220037) ASSEMBLY								
	PN	MOS		N:0			03-APR-2005		
	SN-UNKNOWN	HRS/MSC		N:0			0		
LIFE LIMIT	REF: AMM 32-10-01	AFL	10000	N:0			0		10000
321301	LEFT MAIN LANDING GEAR OUTBOARD DOOR								
	4552803003-003	MOS		N:0			03-APR-2005		
	223524200293	HRS/MSC	O/C	N:0			0		
	REF: AMM 52-80-01	AFL		N:0			0		
321302	LEFT MAIN LANDING GEAR INBOARD DOOR								
	4552803004-003	MOS		N:0			03-APR-2005		
	665478700293	HRS/MSC	O/C	N:0			0		
	REF: AMM 52-80-01	AFL		N:0			0		
321303	RIGHT MAIN LANDING GEAR INBOARD DOOR								
	4552803004-004	MOS		N:0			03-APR-2005		
	665481100298	HRS/MSC	O/C	N:0			0		
	REF: AMM 52-80-01	AFL		N:0			0		
321304	RIGHT MAIN LANDING GEAR OUTBOARD DOOR								
	4552803003-004	MOS		N:0			03-APR-2005		
	219789500293	HRS/MSC	O/C	N:0			0		
	REF: AMM 52-80-01	AFL		N:0			0		
322001	* REPLACE NOSE LANDING GEAR STRUT ASSEMBLY (O3220009) (JAA E3220069)								
	4532201000V16-005	MOS					17-MAR-2012		
	485	HRS/MSC					3315.13		
LIFE LIMIT	REF: AMM 32-20-01	AFL	20000	N:750			2328		21578
322002	NOSE LANDING GEAR CYLINDER								
	2342102-003	MOS		N:0			03-APR-2005		
	T357	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
322003	NOSE LANDING GEAR PISTON 2342104 F096 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
322004	NOSE LANDING GEAR ACTUATOR BRACKET 2342111 R239 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
322005	NOSE LANDING GEAR FORK 2342116 R377 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
322011	* REPLACE NOSE LANDING GEAR ACTUATOR (P/N 6632201000) (O3220010) (JAA IRN E3220073) ASSEMBLY 6632201000-005 EFS-623 REF: AMM 32-32-01	MOS HRS/MSC AFL	20000	N:0			03-OCT-2008 2280 1578		21578
322061	* REPLACE NOSE LANDING GEAR TRUNNION AXLE (P/N 2342110) (IRN O3220029 JAA IRN E3220072) ASSEMBLY 2342110-003 R382 REF: AMM 32-20-01	MOS HRS/MSC AFL	20000	N:0 N:0 N:0			03-APR-2005 0 0		20000
322071	* REPLACE LEFT NOSE GEAR TRUNNION PIN (P/N 2342108) (IRN O3220028 JAA IRN E3220071) ASSEMBLY 2342108-003 E023 REF: AMM 32-20-01	MOS HRS/MSC AFL	20000	N:0 N:0 N:0			03-APR-2005 0 0		20000
322072	* REPLACE RIGHT NOSE GEAR TRUNNION PIN (P/N 2342108) (IRN O3220028 JAA IRN E3220071) ASSEMBLY 2342108-003 E012 REF: AMM 32-20-01	MOS HRS/MSC AFL	20000	N:0 N:0 N:0			03-APR-2005 0 0		20000
322095	LEFT NOSE LANDING GEAR DOOR 4552800001-007 0313 REF: AMM 52-81-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
322096	RIGHT NOSE LANDING GEAR DOOR 455280002-007 0308 REF: AMM 52-81-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
322121	NOSE LANDING GEAR UPLOCK MECHANISM 6632302003-005 1322 REF: AMM 32-32-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
323001	LEFT * MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY REPLACE 200-0300-003 H0359 REF: AMM 32-31-01	MOS HRS/MSC AFL	17000	R:1 R:0 N:2610 R:0			03-APR-2013 3715.78 2610	17000	
323001A	INSPECT LH MAIN LANDING GEAR SIDE-STAY ACTUATOR - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION. (IRN AA3220111) REF: GENERIC NO REF	MOS HRS/MSC AFL	96 10000	+14d/-14d +25/-25			03-APR-2013 3715.78 2610	03-APR-2021 17-APR-2021 12610	12635
323002	RIGHT * MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY REPLACE 200-0300-004 H1351 REF: AMM 32-31-01	MOS HRS/MSC AFL	17000	R:1 R:0 N:2610 R:0			03-APR-2013 3715.78 2610	17000	
323002A	INSPECT RH MAIN LANDING GEAR SIDE-STAY ACTUATOR - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION. (IRN AA3220111) REF: GENERIC NO REF	MOS HRS/MSC AFL	96 10000	+14d/-14d +25/-25			03-APR-2013 3715.78 2610	03-APR-2021 17-APR-2021 12610	12635
323037	MAIN LANDING GEAR UPLOCK INBD DOOR, LEFT MECHANISM 6632303004-005 1632 REF: AMM 32-31-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323038	MAIN LANDING GEAR UPLOCK INBD DOOR, RIGHT MECHANISM 6632303004-006 1642 REF: AMM 32-31-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
323301	* REPLACE LEFT MAIN LANDING GEAR INBOARD DOOR ACTUATOR (P/N 7469-1) CAP SCREWS (IRN L3231024) ASSEMBLY NAS1352-3H1 SN-UNKNOWN REF: AMM 32-31-02	MOS HRS/MSC AFL	2400	N:0 N:0 N:0			14-AUG-2019 4829.3 3616	7229.3	
323302	* REPLACE RIGHT MAIN LANDING GEAR INBOARD DOOR ACTUATOR (P/N 7469-1) CAP SCREWS (IRN L3231024) ASSEMBLY NAS1352-3H12P SN-UNKNOWN REF: AMM 32-31-02	MOS HRS/MSC AFL	2400	N:0 N:0 N:0			29-DEC-2017 4626 3414	7026	
323305	LEFT MLG ACTUATOR GIMBAL ASSEMBLY 4532103050-003 SN-UNKNOWN REF: AMM 32-31-06	MOS HRS/MSC AFL	O/C				23-FEB-2008 2011 1404		
323306	RIGHT MLG ACTUATOR GIMBAL ASSEMBLY PN SN-UNKNOWN REF: AMM 32-31-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
323307	LEFT MLG SHAFT GIMBAL ASSEMBLY 4532103054-007 CM10080 REF: AMM 32-31-06	MOS HRS/MSC AFL	O/C				23-FEB-2008 2011 1404		
323308	RIGHT MLG SHAFT GIMBAL ASSEMBLY PN SN-UNKNOWN REF: AMM 32-31-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323309	LEFT MLG INBOARD DOOR GIMBAL BRACKET ASSEMBLY PN SN-UNKNOWN REF: AMM 32-31-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
323310	RIGHT MLG INBOARD DOOR GIMBAL BRACKET ASSEMBLY PN SN-UNKNOWN REF: AMM 32-31-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
323311	LEFT HAND MAIN GEAR DOOR INBD ACTUATOR 7469-1 0575 REF: AMM 32-31-02	MOS HRS/MSC AFL	O/C				01-MAY-2005 10.4 9		
323312	RIGHT HAND MAIN GEAR DOOR, INBD ACTUATOR 6632303003-003 (7469-1) 0767 REF: AMM 32-31-02	MOS HRS/MSC AFL	O/C	N:1262			24-JUL-2012 3466.7 2435		
323735	CONTROL VALVE 6632302001-003/2245H000-002 0223 REF: AMM 32-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
324001	NO. 1 MAIN LANDING GEAR WHEEL 3-1545-1 1818 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C				30-MAR-2020 4909.4 3693		
324001A	NON DESTRUCTIVE TEST NO. 1 MAIN LANDING GEAR WHEEL 3-1545-1 1818 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				30-MAR-2020 4909.4 3693		
324002	NO. 2 MAIN LANDING GEAR WHEEL 3-1545-1 1275 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C				30-MAR-2020 4909.4 3693		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324002A	NON DESTRUCTIVE TEST NO. 2 MAIN LANDING GEAR WHEEL 3-1545-1 1275 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				30-MAR-2020 4909.4 3693		
324003	NO. 3 MAIN LANDING GEAR WHEEL 3-1545-1 2599 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			17-JUL-2020 4932.3		
324003A	NON DESTRUCTIVE TEST NO. 3 MAIN LANDING GEAR WHEEL 3-1545-1 2599 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				01-JUL-2019 4824.5 3613		
324004	NO. 4 MAIN LANDING GEAR WHEEL 3-1545-1 0396 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			17-JUL-2020 4932.3		
324004A	NON DESTRUCTIVE TEST NO. 4 MAIN LANDING GEAR WHEEL 3-1545-1 0396 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				30-MAR-2020 4909.4 3693		
324005	NOSE GEAR WHEEL ASSEMBLY 5010694 APR06-10121 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			17-JUL-2020 4932.3		
324021	NO. 1 MAIN LANDING GEAR TIRE 226K08-4 82082693 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-MAR-2020 4909.4 3693		
324022	NO. 2 MAIN LANDING GEAR TIRE 226K08-4 93102887 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-MAR-2020 4909.4 3693		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324023	NO. 3 MAIN LANDING GEAR TIRE PN-UNKNOWN SN-UNKNOWN REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C					17-JUL-2020 4932.3	
324024	NO. 4 MAIN LANDING GEAR TIRE PN-UNKNOWN SN-UNKNOWN REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C					17-JUL-2020 4932.3	
324025	NOSE LANDING GEAR TIRE PN-UNKNOWN SN-UNKNOWN REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C					17-JUL-2020 4932.3	
324061	LEFT ANTI-SKID CONTROL VALVE 6632401001-009/39-787 800 REF: AMM 32-41-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				03-APR-2005 0 0	
324062	RIGHT ANTI-SKID CONTROL VALVE 39-787 600 REF: AMM 32-41-07	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0				08-SEP-2006 980 673	
324097	BRAKE CONTROL UNIT 42-933-3 331A REF: AMM 32-41-02	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0				01-JUN-2020 4914.4 3699	
324108	EMERGENCY PARKING BRAKE CHECK VALVE PN SN-UNKNOWN REF: AMM 32-42-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				03-APR-2005 0 0	
324109	EMERGENCY/PARK BRAKE VALVE 6632401002-011 045 REF: AMM 32-42-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0				17-JUL-2020 4932.3	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324110	PRESSURE, EMERGENCY/PARK BRAKE TRANSDUCER 7629301001-001 6821-2-251 REF: AMM 32-42-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
324111	NO. 1 ASSEMBLY, MAIN LANDING GEAR BRAKE 2-1579-2 0195 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C				11-APR-2013 3715.78 2610		
324112	NO. 2 ASSEMBLY, MAIN LANDING GEAR BRAKE 2-1579-2 1547 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C				11-APR-2013 3715.78 2610		
324113	NO. 3 ASSEMBLY, MAIN LANDING GEAR BRAKE 2-1579-2 1616 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C				11-APR-2013 3715.78 2610		
324114	NO. 4 ASSEMBLY, MAIN LANDING GEAR BRAKE 2-1579-2 1643 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C				11-APR-2013 3715.78 2610		
324201	NO. 1 BRAKE SHUTTLE VALVE 7632401002-003 1262 REF: AMM 32-42-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
324202	NO. 2 BRAKE SHUTTLE VALVE 7632401002-003 1282 REF: AMM 32-42-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
324203	NO. 3 BRAKE SHUTTLE VALVE 7632401002-003 1277 REF: AMM 32-42-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324204	NO. 4 BRAKE SHUTTLE VALVE 7632401002-003 1261 REF: AMM 32-42-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
324805	EMER/PARK BRAKE ACCUMULATOR 4532403040-005/88744-1 350 REF: AMM 32-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
325011	NOSE WHEEL STEERING SERVO ACTUATOR JR5208C A0133 REF: AMM 32-50-02	MOS HRS/MSC AFL	O/C				17-FEB-2012 3315.13 2328		
325021	NOSE WHEEL STEERING GEARBOX 2W3201D C0562 REF: AMM 32-50-03	MOS HRS/MSC AFL	O/C				03-OCT-2008 2280 1578		
325031	NOSE WHEEL STEERING COMPUTER 498000-03-03 00665 REF: AMM 32-50-01	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			01-MAR-2020 4900.9 3686		
325041	LEFT NOSE WHEEL STEERING TRANSDUCER 19710/3A1279A 0678 REF: AMM 32-50-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
325042	RIGHT NOSE WHEEL STEERING TRANSDUCER 19710/3A1279A 0680 REF: AMM 32-50-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
325051	* NOSE LANDING GEAR ACTUATOR UPPER PIN (IRN O3220011 OR JAA IRN E3220070) 4532302043-007 490 REF: AMM 32-32-01	MOS HRS/MSC AFL		N:0 N:0 N:0			03-APR-2005 0 0		
LIFE LIMIT			20000	N:0			0		20000

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-D3260006	LUBRICATE NOSE LANDING GEAR SQUAT SWITCH ROTATING DISK ASSEMBLY. EFFECTIVE ON AIRCRAFT 45-001 THRU 45-071 MODIFIED PER SB 45-32-3 AND AIRCRAFT 45-072 THROUGH 45-114 NOT MODIFIED PER SB 45-32-8. (ZONE/ACCESS 700 IRN # D3260006)	MOS					03-APR-2005		
	REF: AMM 12-21-01	HRS/MSC	N/A				0		
		AFL					0		
5-19-00-J3220120	* MLG TRUNNION SHEAR PIN BUSHING - PERFORM VISUAL INSPECTION FOR BUSHING MIGRATION (IRN J3220120)	MOS					03-APR-2005		
	REF: AMM 57-10-05	HRS/MSC	O/C				0		
		AFL					0		
5-19-00-L3220020	* MAIN LANDING GEAR TRUNNION FITTINGS ON MID AND REAR SPAR - PERFORM EDDY CURRENT INSPECTION. (REFER TO NDI MANUAL [NDI-104]. PART 6, 32-11-00 (L3220020)	MOS					03-APR-2005		
AIRWORTHINESS	REF: NDT PART 6/32-11-00	HRS/MSC					0		
		AFL	10000				0		10000
5-19-00-P3231020	MAIN LANDING GEAR DOOR ACTUATOR GIMBAL ASSEMBLY - PERFORM EDDY CURRENT INSPECTION	MOS					23-FEB-2008		
32.101	REF: NDT PART 6/32-13-00	HRS/MSC	N/A				2011		
		AFL					1404		
5-19-00-P3231021	MAIN LANDING GEAR DOOR ACTUATOR GIMBAL SHAFT - PERFORM FLUORESCENT PENETRANT INSPECTION	MOS					23-FEB-2008		
32.102	REF: NDT PART 8/32-13-02	HRS/MSC	N/A				2011		
		AFL					1404		
5-19-00-W3231022	MAIN LANDING GEAR INBOARD DOOR GIMBAL BRACKET - PERFORM EDDY CURRENT INSPECTION	MOS					23-FEB-2008		
32.103	REF: NDT PART 6/32-13-01	HRS/MSC	N/A				2011		
		AFL					1404		
5-19-01-F3220045	REPLACE NOSE LANDING GEAR ACTUATOR ATTACHMENT FITTING (ZINC COATED)	MOS					03-APR-2005		
NOT INSTALLED	REF: AMM 32-32-01	HRS/MSC	N/A				0		
		AFL					0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
571010	* REPLACE LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR FITTING								
	PN	MOS		N:0			03-APR-2005		
57.010	SN-UNKNOWN	HRS/MSC		N:0			0		
LIFE LIMIT	REF: AMM 32-31-01	AFL	20000	N:0			0		20000
571011	* REPLACE RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR FITTING								
	PN	MOS		N:0			03-APR-2005		
57.011	SN-UNKNOWN	HRS/MSC		N:0			0		
LIFE LIMIT	REF: AMM 32-31-01	AFL	20000	N:0			0		20000
A3230001 (s)	** LANDING GEAR - PERFORM EMERGENCY GEAR EXTENSION FUNCTIONAL TEST						PKG		
	PKG 11	MOS	24	+14d/-14d			17-JUL-2020		
		HRS/MSC	600	+25/-25			4932.3		
AIRWORTHINESS	REF: AMM 32-33-00	AFL							
A3240005 (s)	PERFORM ** BRAKE HYDRAULIC FUSES - FUNCTIONAL TEST						PKG		
	PKG 17	MOS	48	+14d/-14d			23-NOV-2016		
		HRS/MSC	1200	+25/-25			4476		
AIRWORTHINESS	REF: AMM 32-41-09	AFL					3270		
A3240006 (s)	PERFORM ** BRAKE SHUTTLE MODULE - FUNCTIONAL TEST						PKG		
	PKG 17	MOS	48	+14d/-14d			23-NOV-2016		
		HRS/MSC	1200	+25/-25			4476		
AIRWORTHINESS	REF: AMM 32-41-04	AFL					3270		
A3240007 (s)	PERFORM **BRAKE SHUTTLE VALVES - FUNCTIONAL TEST						PKG		
	PKG 23	MOS	96	+14d/-14d			23-NOV-2016		
		HRS/MSC	2400	+25/-25			4476		
AIRWORTHINESS	REF: AMM 32-42-04	AFL					3270		
A3240009 (s)	PERFORM ** BRAKE PRESSURE TRANSDUCERS - FUNCTIONAL TEST						PKG		
	PKG 25	MOS					25-JUL-2018		
		HRS/MSC	4800	+25/-25			4687.6		
AIRWORTHINESS	REF: AMM 32-41-08	AFL					3479		
AB3220016 (s)	PERFORM NOSE LANDING GEAR STRUT ASSEMBLY - SPECIAL DETAILED INSPECTION.						PKG		
	PKG 27	MOS					03-APR-2005		
		HRS/MSC					0		
	REF: See Workcard	AFL	10000	+25/-25			0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
H3220017 (s)	PERFORM NOSE LANDING GEAR TRUNNION AXLE - VISUAL INSPECTION. IF CORROSION IS FOUND, REMOVE AXLE FROM CYLINDER AND PERFORM FLUORESCENT PENETRANT INSPECTION OF LUG AREA AND MAGNETIC PARTICLE INSPECTION OF AXLE. IF CORROSION IS NOT FOUND, CONDUCT FLUORESCENT PENETRANT INSPECTION OF AXLE PORTION THAT IS EXPOSED FROM CYLINDER. PKG 27	MOS HRS/MSC					03-APR-2005 0		
	REF: AMM 05-10-00	AFL	10000	+25/-25			0		
L3220019 (s)	PERFORM NOSE LANDING GEAR ACTUATOR ATTACHMENT PIN - REMOVE PIN AND PERFORM MAGNETIC PARTICLE INSPECTION. PKG 27	MOS HRS/MSC					03-APR-2005 0		
	REF: NDT PART 7/32-30-02	AFL	10000	+25/-25			0		
L3220109 (s)	PERFORM NOSE LANDING GEAR ACTUATOR ASSEMBLY - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION. PKG 27	MOS HRS/MSC					03-APR-2005 0		
	REF: GENERIC NO REF	AFL	10000	+25/-25			0		
V3240004 (s)	** EMERGENCY/PARKING BRAKE SWITCH - VERIFY THAT "EMERGENCY/PARKING BRAKE" MESSAGE ILLUMINATES ON EICAS WHEN PARKING BRAKE IS SET AND THROTTLES ARE MOVED ABOVE MCR DETENT. PKG 11	MOS HRS/MSC	24	+14d/-14d			17-JUL-2020 4932.3		
AIRWORTHINESS	REF: AMM 32-42-01	AFL	600	+25/-25					
V3240008 (s)	** EMERGENCY/PARKING BRAKE CONTROL SYSTEM - PERFORM FUNCTIONAL TEST PKG 11	MOS HRS/MSC	24	+14d/-14d			17-JUL-2020 4932.3		
AIRWORTHINESS	REF: AMM 32-42-02	AFL	600	+25/-25					
Y3220000 (s)	NOSE LANDING GEAR ASSEMBLY - PERFORM VISUAL INSPECTION PKG 11	MOS HRS/MSC	24	+14d/-14d			17-JUL-2020 4932.3		
	REF: AMM 05-10-00	AFL	600	+25/-25					
Y3220001 (s)	MAIN LANDING GEAR ASSEMBLY - PERFORM VISUAL INSPECTION. INSPECTION TO INCLUDE ACTUATOR, FASTENERS, SUPPORT STRUCTURE, AND SQUAT SWITCHES PKG 11	MOS HRS/MSC	24	+14d/-14d			17-JUL-2020 4932.3		
	REF: AMM 05-10-00	AFL	600	+25/-25					

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y3220002 (s)	NOSE LANDING GEAR ACTUATOR PRESSURE AND RETURN LINES - PERFORM VISUAL INSPECTION. LOWER ACTUATOR DUST BOOT TO INSPECT LINES						PKG		
	PKG 11	MOS	24	+14d/-14d				17-JUL-2020	
		HRS/MSC	600	+25/-25			4932.3		
	REF: AMM 05-10-00	AFL							
Y3220003 (s)	NOSE GEAR SHOCK STRUT - REMOVE AND REPLACE RETAINER RING LOCKSCREW						PKG		
	PKG 11	MOS	24	+14d/-14d				17-JUL-2020	
		HRS/MSC	600	+25/-25			4932.3		
	REF: GENERIC NO REF	AFL							
Y3220004 (s)	MAIN LANDING GEAR ACTUATOR AND GEAR INBOARD DOOR ACTUATOR ATTACH POINTS - PERFORM VISUAL INSPECTION						PKG		
	PKG 11	MOS	24	+14d/-14d				17-JUL-2020	
		HRS/MSC	600	+25/-25			4932.3		
	REF: AMM 05-10-00	AFL							
Y3220006 (s)	LANDING GEAR ELECTRICAL WIRING - PERFORM VISUAL INSPECTION (THAT PORTION VISIBLE INSIDE WHEEL WELL)						PKG		
	PKG 11	MOS	24	+14d/-14d				17-JUL-2020	
		HRS/MSC	600	+25/-25			4932.3		
	REF: AMM 05-10-00	AFL							
Y3220008 (s)	PERFORM NOSE LANDING GEAR AXLE - REMOVE NOSE LANDING GEAR WHEEL AND PERFORM INSPECTION. INSPECT BOTH INSIDE AND OUTSIDE OF AXLE.						PKG		
	PKG 17	MOS	48	+14d/-14d				23-NOV-2016	
		HRS/MSC	1200	+25/-25			4476		
	REF: AMM 32-40-01	AFL					3270		
Y3220124 (s)	NOSE LANDING GEAR - PERFORM DETAILED VISUAL INSPECTION OF THE NOSE LANDING GEAR UPLOCK ROLLER BRACKET						PKG		
	PKG 11	MOS	24	+14d/-14d				17-JUL-2020	
		HRS/MSC	600	+25/-25			4932.3		
	REF: AMM 05-10-00	AFL							
Y3230002 (s)	MAIN LANDING GEAR FREE FALL ROLLER - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO BINDING OF ROLLERS						PKG		
	PKG 5	MOS	12	+14d/-14d				17-JUL-2020	
		HRS/MSC	300	+25/-25			4932.3		
	REF: AMM 05-10-00	AFL							

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y3231023 (s)	MAIN LANDING GEAR INBOARD DOOR ACTUATOR (P/N 7469) END CAP SCREWS - PERFORM DETAILED INSPECTION. (EFFECTIVE ON AIRCRAFT 45-005 THRU 45-276 PRE SB 45-32-19)						PKG		
	PKG 5	MOS	12	+14d/-14d				17-JUL-2020	
		HRS/MSC	300	+25/-25			4932.3		
	REF: AMM 32-31-02	AFL							
Y3240000 (s)	NOSE AND MAIN TIRES - PERFORM VISUAL INSPECTION						PKG		
	PKG 5	MOS	12	+14d/-14d				17-JUL-2020	
		HRS/MSC	300	+25/-25			4932.3		
	REF: AMM 12-10-04	AFL							
Y3240001 (s)	BRAKE LINES - PERFORM VISUAL INSPECTION. INSPECT ALL BRAKE LINES VISIBLE IN WHEEL WELLS AND ON STRUTS						PKG		
	PKG 11	MOS	24	+14d/-14d				17-JUL-2020	
		HRS/MSC	600	+25/-25			4932.3		
	REF: AMM 05-10-00	AFL							
Y3240002 (s)	BRAKE ASSEMBLIES - PERFORM VISUAL INSPECTION WITH PARKING BRAKE SET. WORN BRAKES ARE VISUALLY INDICATED WHEN THE WEAR INDICATOR PINS BECOME EVEN WITH THE OUTER SURFACE OF THE WEAR INDICATOR SLEEVE						PKG		
	PKG 5	MOS	12	+14d/-14d				17-JUL-2020	
		HRS/MSC	300	+25/-25			4932.3		
	REF: AMM 32-41-01	AFL							
Y3240003 (s)	PERFORM BRAKE CONTROL SYSTEM LINEAR VARIABLE DIFFERENTIAL TRANSFORMER (LVDT) - VISUAL INSPECTION						PKG		
	PKG 13	MOS	48	+14d/-14d				23-NOV-2016	
		HRS/MSC	1200	+25/-25			4476		
	REF: AMM 05-10-00	AFL					3270		
Y3260005 (s)	NOSE LANDING GEAR SQUAT SWITCH ROTATING DISK ASSEMBLY - LUBRICATE. (EFFECTIVE ON AIRCRAFT 45-001 THRU 45-114 POST SB 45-32-8 AND AIRCRAFT 45-115 AND SUBSEQUENT)						PKG		
	PKG 5	MOS	12	+14d/-14d				17-JUL-2020	
		HRS/MSC	300	+25/-25			4932.3		
	REF: AMM 12-21-01	AFL							

CHAPTER	33	LIGHTS							
	330000	MODIFIED PULSE CONTROLLER							
		2401S	MOS					03-APR-2005	
		AR00774	HRS/MSC	O/C				0	
		REF: GENERIC NO REF	AFL					0	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
331001	NO. 1 LIGHTING CONTROL UNIT RDC4-1 0376 REF: AMM 33-10-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
331002	NO. 2 LIGHTING CONTROL UNIT RDC4-1 0640 REF: AMM 33-10-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
331011	PILOT SWITCH PANEL ASSY M4523188545-013-613 A00587744-01 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
331015	CENTER SWITCH (P5) PANEL ASSEMBLY M4525188576-631-631 A00591213-01 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			12-JUL-2011 3004.22 2096		
331020	DIMMER CONTROL BOX LT-48(G) 1661 REF: AMM 33-10-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
331033	GLARESHIELD FLOODLIGHT POWER SUPPLY 6900135-001 475 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
332068	COPILOT LIGHTING CONTROL MODULE 6633208503-001/SP-45-01-676 010500443 REF: AMM 33-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
334023	TAIL NAVIGATION (DS39) LIGHT 30-2382-5 0707 REF: AMM 33-40-02	MOS HRS/MSC AFL	O/C				26-SEP-2011 3077.25 2145		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
334175	RELAY OPTIONS PANEL ASSY 4533488524-017 A00525992-01 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
334332	UPPER ANTI-COLLISION LIGHT GE16386-12-1 2167327 REF: AMM 33-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JUN-2013 3788.35 2663		
334333	LOWER ANTI-COLLISION LIGHT PN SN-UNKNOWN REF: AMM 33-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
335005	FWD ELS ACTIVATION ASSEMBLY (A81) MODULE 4533508501V5-001 A00440247 REF: AMM 33-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
336001	PILOT CHART HOLDER 10-62-01 4335 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
336002	COPILOT CHART HOLDER 10-62-01 4336 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
Y3310000 (s)	FLIGHT COMPARTMENT LIGHTING - PERFORM OPERATION OF THE FOLLOWING: A. MAP LIGHTS. B. INSTRUMENT PANEL FLUORESCENT LIGHTS. C. INSTRUMENT/INDICATOR LIGHTS. D. LIGHT DIMMING SWITCHES. E. CREW WARNING PANEL. F. PANEL OVERLAYS. PKG 1 REF: AMM 33-10-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			17-JUL-2020 4932.3		PKG

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y3340000 (s)	EXTERIOR LIGHTING SYSTEMS - PERFORM OPERATION OF THE FOLLOWING: A. TAXI LIGHTS. B. ANTI-COLLISION BEACONS. C. NAVIGATION LIGHTS. D. STROBE LIGHTS. E. LANDING/RECOGNITION LIGHTS. F. WING ICE INSPECTION LIGHTS. G. EMERGENCY DOOR EGRESS LIGHTS. PKG 2 REF: See Workcard	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			17-JUL-2020 4932.3		
Y3350003 (s)	EMERGENCY LIGHTING SYSTEM - PERFORM OPERATIONAL CHECK PKG 14 REF: AMM 33-50-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			23-NOV-2016 4476 3270		
CHAPTER 34	NAVIGATION								
341001	NO. 1 AIR DATA COMPUTER 7030700-71704 05010299 REF: AMM 34-17-01	MOS HRS/MSC AFL	O/C				06-APR-2017 4527.1 3323		
341001A	TEST/INSPECT NO. 1 AIR DATA COMPUTER 7030700-71704 05010299 REF: See Workcard	MOS HRS/MSC AFL	24				06-MAY-2019 06-MAY-2021		
341002	NO. 2 AIR DATA COMPUTER 7030700-71704 05010298 REF: AMM 34-17-01	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		03-APR-2005 0 0		
341002A	TEST/INSPECT NO. 2 AIR DATA COMPUTER 7030700-71704 05010298 REF: See Workcard	MOS HRS/MSC AFL	24				06-MAY-2019 06-MAY-2021		
341013	STANDBY AIRSPEED INDICATOR 26240-1129 282608 REF: AMM 34-18-01	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		03-APR-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341025	STANDBY ALTIMETER 7634208001-003 172239B REF: AMM 34-15-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			10-MAY-2019 4774.6 3558		
341025A	TEST/INSPECT STANDBY ALTIMETER 7634208001-003 172239B REF: See Workcard	MOS HRS/MSC AFL	24				09-MAY-2019	09-MAY-2021	
341037	LEFT PRIMARY PITOT/STATIC PROBE (P/N 0856TJ1 OR P/N 6634100000-001) 6634100000-001 227526 REF: AMM 34-11-01	MOS HRS/MSC AFL	15000	+25/-25 N:0 N:0			03-APR-2005 0 0	15000	15025
LIFE LIMIT									
341037A	TEST/INSPECT LEFT PRIMARY PITOT/STATIC PROBE (P/N 0856TJ1 OR P/N 6634100000-001) 6634100000-001 227526 REF: See Workcard	MOS HRS/MSC AFL	24				06-MAY-2019	06-MAY-2021	
341038	RIGHT PRIMARY PITOT/STATIC PROBE (P/N 0856TJ2 OR P/N 6634100000-003) 6634100000-003 228307 REF: AMM 34-11-01	MOS HRS/MSC AFL	15000	+25/-25 N:0 N:0			03-APR-2005 0 0	15000	15025
LIFE LIMIT									
341038A	TEST/INSPECT RIGHT PRIMARY PITOT/STATIC PROBE (P/N 0856TJ2 OR P/N 6634100000-003) 6634100000-003 228307 REF: See Workcard	MOS HRS/MSC AFL	24				06-MAY-2019	06-MAY-2021	
341049	STANDBY PITOT/STATIC PROBE 6634100000-005 227664 REF: AMM 34-11-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
+ 341049A	TEST/INSPECT STANDBY PITOT/STATIC PROBE REF: See Workcard	MOS HRS/MSC AFL	24				09-MAY-2019	09-MAY-2021	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341061	RADAR ALTIMETER RECEIVER 7001840-936 0412B726 REF: AMM 34-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
341073	FORWARD RADAR ALTIMETER ANTENNA S67-2002-4 11989 REF: AMM 34-14-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
341074	AFT RADAR ALTIMETER ANTENNA S67-2002-4 11886 REF: AMM 34-14-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
341901	(TAT) TOTAL AIR TEMPERATURE PROBE 102AU1AG A59630 REF: AMM 34-17-02	MOS HRS/MSC AFL	O/C				28-NOV-2005 460 321		
342001	(AHRS) NO. 1 ATTITUDE HEADING REFERENCE COMPUTER 145130-6000 5451 REF: AMM 34-26-01	MOS HRS/MSC AFL	O/C				16-DEC-2015 4379 3166		
342002	(AHRS) NO. 2 ATTITUDE HEADING REFERENCE COMPUTER 145130-6000 5455 REF: AMM 34-26-01	MOS HRS/MSC AFL	O/C				16-DEC-2015 4379 3166		
342003	(AHRS) NO. 1 ATTITUDE HEADING REFERENCE COMPUTER FAN 140691-0000 2674 REF: AMM 34-26-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
342004	(AHRS) NO. 2 ATTITUDE HEADING REFERENCE COMPUTER FAN 140691-0000 2685 REF: AMM 34-26-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342037	LEFT FLUX VALVE 7010133 04096521 REF: AMM 34-26-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
342038	RIGHT FLUX VALVE 7010133 04086498 REF: AMM 34-26-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
342103	STANDBY COMPASS PAI700-5V 54254 REF: AMM 34-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
342801	STANDBY ATTITUDE INDICATOR 501-1648-02 1411 REF: AMM 34-23-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
343005	MARKER BEACON ANTENNA DMN27-3/4534308006V1-001 14828 REF: AMM 34-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
343030	MARKER BEACON ANTENNA SPLITTER DMH21-1 30051 REF: AMM 34-30-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
344111	UPPER TCAS ANTENNA 7514081-913 ANE21198 REF: AMM 34-43-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
344112	LOWER TCAS ANTENNA 7514081-913 ANE20876 REF: AMM 34-43-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
344143	TCAS PROCESSOR 7517900-55012 20008028 REF: AMM 34-43-01	MOS HRS/MSC AFL	O/C					17-FEB-2015	
344205	WEATHER RADAR RECEIVER/TRANSMITTER/ANTENNA 7021450-801 04125330 REF: AMM 34-42-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				03-APR-2005 0 0	
344221	WEATHER RADAR CONTROLLER 7008471-667 04128088 REF: AMM 34-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				03-APR-2005 0 0	
345001	NO. 1 INTEGRATED NAVIGATION UNIT 7510100-631 0512A248 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:0				10-APR-2018	
345002	NO. 2 INTEGRATED NAVIGATION UNIT 7510100-633(C3450006-011) 04117777 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				03-APR-2005 0 0	
345013	NO. 1 ADF ANTENNA 7510300-901 04118784 REF: AMM 34-57-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				03-APR-2005 0 0	
345014	NO. 2 ADF ANTENNA 7510300-901 04118781 REF: AMM 34-57-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				03-APR-2005 0 0	
345025	ENHANCED GROUND PROXIMITY WARNING (EGPWS) COMPUTER 965-0976-040-208-208 20978 REF: AMM 34-45-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				03-APR-2005 0 0	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345037	FORWARD ATC ANTENNA DMN150-2-2 100803 REF: AMM 34-55-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
345038	AFT ATC ANTENNA DMN150-2-2 100825 REF: AMM 34-55-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
345049	AFT (NO. 1) DME ANTENNA DMN150-2-2 86104 REF: AMM 34-55-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
345050	FORWARD (NO. 2) DME ANTENNA DMN150-9-2 4004 REF: AMM 34-55-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
345083	LEFT VOR/LOCALIZER ANTENNA DMN4-17-1/N 22004 REF: AMM 34-51-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JUL-2018 4687.6 3479		
345084	RIGHT VOR/LOCALIZER ANTENNA DMN4-17-1/N 22026 REF: AMM 34-51-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JUL-2018 4687.6 3479		
345260	PHASING COUPLER DMN4-17-2 19029 REF: AMM 34-51-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
345605	LEFT UPPER MODE S ATC ANTENNA DMN150-2-2 100804 REF: AMM 34-55-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345606	RIGHT UPPER MODE S ATC ANTENNA DMN150-2-2 100832 REF: AMM 34-55-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
346001	PILOT FLIGHT MANAGEMENT CONTROL DISPLAY CDU 3017-41-201 1580 REF: AMM 34-60-01	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			13-DEC-2018 4734.4 3516		
346002	COPILOT FLIGHT MANAGEMENT CONTROL DISPLAY CDU 3017-41-221 777 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			13-DEC-2018 4734.4 3516		
346021	FMS DATA (DTU) TRANSFER UNIT 1406-01-1 2927 REF: AMM 34-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
347510	NO. 1 GPS ANTENNA 10706 9448 REF: AMM 34-53-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
347511	NO. 2 GPS ANTENNA 10706 9439 REF: AMM 34-53-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
5-19-02-RVSM-L3411062	DETAILED VISUAL INSPECTION OF PITOT-STATIC PROBES RVSM COMPLIANT AIRCRAFT(ZONE/ACCESS 220 IRN # L3411062)	MOS HRS/MSC AFL	24	+14d/-14d		-34	10-MAY-2019 4774.6 3558	06-APR-2021	20-APR-2021
RVSM	REF: AMM 34-11-01								

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-02-RVSM-M3411052	VERIFY PITCH, ROLL, AND YAW ALIGNMENT OF THE PRIMARY PITOT-STATIC PROBES RVSM COMPLIANT AIRCRAFT (IRN # M3411052)	MOS	24	+14d/-14d		-34	10-MAY-2019	06-APR-2021	20-APR-2021
RVSM	REF: AMM 34-11-01	HRS/MSC AFL					4774.6 3558		
5-19-02-RVSM-U3411060	PERFORM FUNCTIONAL TEST - AIR DATA SYSTEM (EFFECTIVE ON AIRCRAFT CERTIFIED & MAINTAINED FOR RVSM) (REFER TO 34-17-00) (IRN U3411060)	MOS	24	+14d/-14d		-34	10-MAY-2019	06-APR-2021	20-APR-2021
RVSM	REF: AMM 34-17-00	HRS/MSC AFL					4774.6 3558		
A3400000 (s)	** NAVIGATION SYSTEMS - PERFORM OPERATIONAL CHECK						PKG		
AIRWORTHINESS	REF: AMM 34-00-00	PKG 7	MOS	24	+14d/-14d		17-JUL-2020		
		HRS/MSC	600	+25/-25			4932.3		
V3420000 (s)	ATTITUDE HEADING REFERENCE UNIT (AHRU) MOUNTING TRAY FAN FILTER - PERFORM VISUAL INSPECTION. ENSURE FILTER IS FREE OF OBSTRUCTIONS.	MOS	24	+14d/-14d			PKG		
	REF: AMM 05-10-00	HRS/MSC	600	+25/-25			17-JUL-2020		
		AFL					4932.3		
Y3411000 (s)	PITOT-STATIC PROBE - PERFORM VISUAL INSPECTION. ENSURE DRAIN HOLES ARE CLEAR OF OBSTRUCTIONS	MOS	24	+14d/-14d			PKG		
	REF: See Workcard	HRS/MSC	600	+25/-25			17-JUL-2020		
		AFL					4932.3		
Y3440000 (s)	PERFORM RADOME STRUCTURE AND ANTENNA INSTALLATION - VISUAL INSPECTION	MOS	48	+14d/-14d			PKG		
	REF: AMM 05-10-00	HRS/MSC	1200	+25/-25			23-NOV-2016		
		AFL					4476 3270		
CHAPTER 35	OXYGEN								
350001	OXYGEN CYLINDER								
	806385-14	MOS	180	+14d/-14d			14-AUG-2019	01-SEP-2032	15-SEP-2032
LIFE LIMIT	REF: AMM 35-00-01	HRS/MSC			N:0		4829.3		
	Manufacture Date: 01-SEP-2017	AFL			N:0		3616		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
350001A	HYDROSTATIC TEST OXYGEN CYLINDER ** (IRN Q3510005 - STANDARD CAPACITY; Q3510018 - INCREASED CAPACITY) 806385-14 ALT280-6317 REF: GENERIC NO REF	MOS HRS/MSC AFL	60 5000	+14d/-14d +25/-25			01-AUG-2019	01-SEP-2024 M 9829.3 M	15-SEP-2024 9854.3
350001C	FUNCTIONAL TEST OXYGEN CYLINDER ** LOW PRESSURE RELIEF VALVE (IRN Q3510005 - STANDARD CAPACITY; Q3510018 - INCREASED CAPACITY) 806385-14 ALT280-6317 REF: GENERIC NO REF	MOS HRS/MSC AFL	60 5000	+14d/-14d +25/-25			14-AUG-2019 4829.3 3616	14-AUG-2024 9829.3	28-AUG-2024 9854.3
350201	TEMP/PRESSURE TRANSDUCER 10008789 20091811 REF: AMM 35-00-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			29-MAR-2010 2627.48 1831		
350225	OXYGEN FILL (POST SB 45-12-1) VALVE P21010 6278 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				16-APR-2012 3351.07 2355		
351001	PILOT OXYGEN MASK MC10-15-166 95457 REF: AMM 35-10-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			23-NOV-2016 4476 3270		
351001A	OVERHAUL PILOT OXYGEN MASK PER MANUFACTURER'S INSTRUCTIONS (IRN # L3510016/O3510006) MC10-15-166 95457 REF: GENERIC NO REF	MOS HRS/MSC AFL	72	+14d/-14d			23-NOV-2016 4476 3270	23-NOV-2022	07-DEC-2022
351002	COPILOT OXYGEN MASK MC10-15-166 SE54046 REF: AMM 35-10-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			23-NOV-2016 4476 3270		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
351002A	OVERHAUL COPILOT OXYGEN MASK PER MANUFACTURER'S INSTRUCTIONS (IRN # L3510016/O3510006) MC10-15-166 SE54046 REF: GENERIC NO REF	MOS HRS/MSC AFL	72	+14d/-14d			23-NOV-2016 4476 3270	23-NOV-2022	07-DEC-2022
352011	OXYGEN CONTROL VALVE 6635000000-025 0446 REF: AMM 35-20-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			26-FEB-2015 4228.8 3039		
352025	OXYGEN CYLINDER REGULATOR 806370-07 2423 REF: AMM NO REF	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			14-AUG-2019 4829.3 3616		
355111	OXYGEN PRESSURE INDICATOR P24071-3 336 REF: AMM 35-00-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
5-19-00-K3500021	** OXYGEN SYSTEM LOW PRESSURE SUPPLY HOSES - PERFORM OPERATIONAL CHECK. ENSURE THAT HOSES ARE FREE OF OBSTRUCTIONS. REF: AMM 35-00-00	MOS HRS/MSC AFL	N/A				03-APR-2005 0 0		
5-19-00-N3510013	PERFORM ** PERIODIC CHECK OF OXYGEN CYLINDER AND REMOTE OXYGEN FILL VALVES (IRN N3510013) REF: AMM 35-00-01	MOS HRS/MSC AFL	1500	+25/-25			23-SEP-2019 4841 3624	6341	6366
5-19-00-N3510019	PERFORM ** PERIODIC CHECK OF THE OXYGEN CYLINDER AND REMOTE FILL VALVES. EFFECTIVE ON AIRCRAFT EQUIPPED WITH INCREASED CAPACITY OXYGEN SYSTEM. (IRN N3510019) REF: AMM 35-00-01	MOS HRS/MSC AFL	N/A						

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-Q3510022	PERFORM OXYGEN CYLINDER REGULATOR - OVERHAUL	MOS	60	+14d/-14d			14-AUG-2019	14-AUG-2024	28-AUG-2024
	REF: AMM 35-00-01	HRS/MSC	5000	+25/-25			4829.3	9829.3	9854.3
		AFL					3616		
5-19-00-Q3510023	PERFORM OXYGEN CYLINDER REGULATOR - OVERHAUL (EFFECTIVE ON AIRCRAFT EQUIPPED WITH INCREASED CAPACITY OXYGEN SYSTEM)	MOS							
	REF: AMM 35-00-01	HRS/MSC	N/A						
		AFL							
O3510003 (s)	** CABIN LOW PRESSURE OXYGEN DISTRIBUTION FLEX HOSES - PERFORM FUNCTIONAL TEST.						PKG		
	PKG 7	MOS	24	+14d/-14d			17-JUL-2020		
	REF: AMM 35-20-00	HRS/MSC	600	+25/-25			4932.3		
	AIRWORTHINESS	AFL							
S3510014 (s)	** OXYGEN SYSTEM ALTITUDE COMPENSATING REGULATOR - PERFORM FUNCTIONAL TEST. (EFFECTIVE ON AIRCRAFT 45-170 AND SUBSEQUENT AND PRIOR AIRCRAFT MODIFIED BY SB 45-35-1)						PKG		
	PKG 7	MOS	24	+14d/-14d			17-JUL-2020		
	REF: AMM 35-20-00	HRS/MSC	600	+25/-25			4932.3		
	AIRWORTHINESS	AFL							
W3510002 (s)	** OXYGEN SYSTEM - PERFORM OPERATIONAL CHECK						PKG		
	PKG 7	MOS	24	+14d/-14d			17-JUL-2020		
	REF: AMM 35-00-00	HRS/MSC	600	+25/-25			4932.3		
	AIRWORTHINESS	AFL							
Y3510000 (s)	PERFORM OXYGEN CYLINDER INSTALLATION - VISUAL INSPECTION. CHECK PLUMBING FOR ROUTING, SECURITY, AND CONDITION						PKG		
	PKG 13	MOS	48	+14d/-14d			23-NOV-2016		
	REF: AMM 05-10-00	HRS/MSC	1200	+25/-25			4476		
		AFL					3270		
Y3510001 (s)	CREW SEAT OXYGEN HOSES - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO AREA WHERE OXYGEN HOSES ENTER CREW SEATS ABOVE COCKPIT FLOOR						PKG		
	PKG 1	MOS	12	+14d/-14d			17-JUL-2020		
	REF: AMM 05-10-00	HRS/MSC	300	+25/-25			4932.3		
		AFL							

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y3510017 (s)	OXYGEN CYLINDER INSTALLATION - PERFORM VISUAL INSPECTION, CHECK PLUMBING FOR ROUTING, SECURITY, AND CONDITION. (EFFECTIVE ON AIRCRAFT EQUIPPED WITH INCREASED CAPACITY OXYGEN SYSTEM.)						PKG		
	PKG 7	MOS	24	+14d/-14d			17-JUL-2020		
	REF: AMM 05-10-00	HRS/MSC	600	+25/-25			4932.3		
		AFL							
CHAPTER 36 PNEUMATIC									
361001	LEFT ASSEMBLY, HP TAILCONE OUTBOARD MANIFOLD								
	PN	MOS		N:0			03-APR-2005		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
361002	LEFT ASSEMBLY, ANTI-ICE OUTBOARD MANIFOLD								
	PN	MOS		N:0			03-APR-2005		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 30-10-07	AFL		N:0			0		
361004	LEFT INBOARD HPBA MANIFOLD ASSEMBLY								
	PN	MOS		N:0			03-APR-2005		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 36-10-07	AFL		N:0			0		
361005	RIGHT INBOARD HPBA MANIFOLD ASSEMBLY								
	PN	MOS		N:0			03-APR-2005		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 36-10-07	AFL		N:0			0		
361016	RIGHT ASSEMBLY, ANTI-ICE OUTBOARD MANIFOLD								
	PN	MOS		N:0			03-APR-2005		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 30-10-07	AFL		N:0			0		
361020	LEFT HP OVER-TEMP SWITCH								
	PN	MOS		N:0			03-APR-2005		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 36-20-03	AFL		N:0			0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361021	RIGHT HP OVER-TEMP SWITCH PN SN-UNKNOWN REF: AMM 36-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
361031	ECS CONTROLLER 6636108500-003 0019018 REF: AMM 36-10-01	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			12-FEB-2014 3959.52 2790		
361040	VALVE, APU BLEED AIR CHECK REPLACE 4011-14 0180 REF: AMM 36-10-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
361050	LOAD CONTROL (SHUTOFF (L5003) VALVE 3876322-1 0247 REF: AMM 36-10-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
361053	NO. 1 ECS SHUTOFF (L37) VALVE 6621000000-061 850 REF: AMM 36-10-03	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			23-DEC-2009 2548.02 1781		
361054	NO. 2 ECS SHUTOFF (L38) VALVE 6621000000-061 730 REF: AMM 36-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
361065	LEFT TAILCONE HIGH PRESSURE SHUT-OFF (L39) VALVE 3291216-3 623C REF: AMM 36-10-02	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			23-JAN-2012 3229.28 2261		
361066	RIGHT TAILCONE HIGH PRESSURE SHUT-OFF (L40) VALVE 6621000000-073 815 REF: AMM 36-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361120	NO. 1 PRESSURE (S79) SWITCH 642019-3 0773 REF: AMM 36-10-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
361121	NO. 2 PRESSURE (S88) SWITCH 642019-3 0783 REF: AMM 36-10-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
361125	LEFT PYLON LOW PRESSURE TEMPERATURE SENSOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
361126	RIGHT PYLON LOW PRESSURE TEMPERATURE SENSOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
361127	LEFT TAILCONE LOW PRESSURE (2.0 DIAMETER) CHECK VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
361128	RIGHT TAILCONE LOW PRESSURE (2.0 DIAMETER) CHECK VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
361215	ASSEMBLY, HP LEFT NACELLE BLEED AIR MANIFOLD LJ01212-001 041212-002 REF: AMM 36-10-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
361215A	BORESCOPE ASSEMBLY, HP LEFT NACELLE BLEED AIR MANIFOLD BRACKET LJ01212-001 041212-002 REF: AMM 36-10-07	MOS HRS/MSC AFL	O/C				03-APR-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361216	ASSEMBLY, HP RIGHT NACELLE BLEED AIR MANIFOLD LJ01212-002 191004-002 REF: AMM 36-10-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
361216A	BORESCOPE ASSEMBLY, HP RIGHT NACELLE BLEED AIR MANIFOLD BRACKET LJ01212-002 191004-002 REF: AMM 36-10-07	MOS HRS/MSC AFL	O/C				03-APR-2005 0 0		
361301	APU SERVO AIR CHECK VALVE. EFFECTIVE ON CHECK VALVE S/N 001 THRU 1486. (IRN # K3610013) REPLACE 6608295-3 2842 REF: AMM 36-15-02	MOS HRS/MSC AFL	O/C	N:0 N:0			08-JAN-2007 1197 816		
361302	LEFT ENGINE SERVO AIR CHECK - IRN K3610012 VALVE 6608295-3 4734 REF: AMM 36-15-02	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0		23.98	30-AUG-2019 4757.4 3558		
361303	RIGHT ENGINE SERVO AIR CHECK - IRN K3610012 VALVE 6608295-3 4767 REF: AMM 36-15-02	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0		18.58	30-AUG-2019 4762.8 3550		
362005	LEFT FORWARD PYLON OVERHEAT THERMOSTAT (S145) SWITCH PN SN-UNKNOWN REF: AMM 36-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
362006	LEFT AFT PYLON OVERHEAT THERMOSTAT (S146) SWITCH PN SN-UNKNOWN REF: AMM 36-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
362007	RIGHT FORWARD PYLON OVERHEAT THERMOSTAT (S147) SWITCH PN SN-UNKNOWN REF: AMM 36-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
362008	RIGHT AFT PYLON OVERHEAT THERMOSTAT (S148) SWITCH PN SN-UNKNOWN REF: AMM 36-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
5-19-00-D3610002	BORESCOPE INSPECTION HP BLEED AIR MANIFOLD ASSEMBLY ATTACH BRACKET ASSEMBLY FOR CRACKS AT WELD.(IRN D3610002) REF: AMM 36-10-07	MOS HRS/MSC AFL	N/A				03-APR-2005 0 0		
5-19-00-P3610048-LEFT	PERFORM VISUAL INSPECTION OF HP BLEED MANIFOLD ASSEMBLY (REFER TO 5-10-00.) EFFECTIVE ON AIRCRAFT 45-037 AND SUBSEQUENT, AND PREVIOUS AIRCRAFT MODIFIED PER SB 45-36-2, "PNEUMATIC-REPLACEMENT OF HIGH PRESSURE AIR MANIFOLD ASSEMBLY". REF: AMM 36-10-07	MOS HRS/MSC AFL	2500	+100/-100			17-JUL-2020 4932.3	7432.3	7532.3
5-19-00-P3610048-RIGHT	PERFORM VISUAL INSPECTION OF HP BLEED MANIFOLD ASSEMBLY (REFER TO 5-10-00.) EFFECTIVE ON AIRCRAFT 45-037 AND SUBSEQUENT, AND PREVIOUS AIRCRAFT MODIFIED PER SB 45-36-2, "PNEUMATIC-REPLACEMENT OF HIGH PRESSURE AIR MANIFOLD ASSEMBLY". REF: AMM 36-10-07	MOS HRS/MSC AFL	2500	+100/-100	-16.2		17-JUL-2020 4932.3	7416.1	7516.1
A3610000 (s)	** BLEED AIR SYSTEM - PERFORM FUNCTIONAL TEST PKG 7 REF: AMM 36-10-00	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
A3610001 (s)	** PYLON OVERHEAT THERMOSTAT AND ELECTRICAL SYSTEM - PERFORM FUNCTIONAL TEST PKG 8 REF: AMM 36-20-01	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
U3610075 (s)	BORESCOPE INSPECTION ECS BLEED AIR "Y" MANIFOLD (P/N 12945-054-019, 12945-054-025, 12945-054-031, 129-054-037, 12945-054V1-001, 12945-054V2-001, 12945-054V6-001, 4536102027-001) (EFFECTIVE ON AIRCRAFT 45-002 THRU 45-448) PKG 25 REF: AMM 36-10-00	MOS HRS/MSC AFL	4800	+25/-25			25-JUL-2018 4687.6 3479		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y3610061 (s)	HIGH PRESSURE BLEED AIR SHUT-OFF VALVE IN-LINE FILTER - PERFORM CLEANING PROCEDURES. PKG 8 REF: AMM 36-10-02	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
CHAPTER 38 WATER/WASTE									
383001	TOILET 6638303001-005 U2514 REF: AMM 38-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
383002	TOILET TIMER 7638303002-009/9600-12B T3679 REF: AMM 38-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
383005	WATER TANK ASSEMBLY H45WC-04001-9 0001 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
384051	TOILET MACERATOR 5300-1 M4115 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			08-AUG-2012 3486.57 2450		
CHAPTER 49 AIRBORNE AUXILIARY POWER									
491011	MAINTENANCE CONTROL, APU PANEL 7088001-2 DC175 REF: AMM 49-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
491020	APU, COCKPIT CONTROL PANEL 7088000-1 25866 REF: AMM 49-60-01	MOS HRS/MSC AFL	O/C	N:0 N:2349.4 N:1621			13-JAN-2009 2349.4 1621		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
494050	IGNITION, APU UNIT 9049300-2 040218051868 REF: AMM 49-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
495001	COOLING, TAILCONE APU (B31) FAN 011809 199303781 REF: AMM 49-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
49APU1 49.APU1	APU 3800726-1 P-297 REF: AMM NO REF	MOS HRS/MSC AFL	E/C						
5-19-01-AA4900039	APU FUEL LINE (P/N 4549058032-001) REPLACE 4549058032-005 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-OCT-2019 4865.4		
H4900011 (s) AIRWORTHINESS	PERFORM **APU GENERATOR - OVERVOLTAGE PROTECTION CHECK. PKG 13 REF: AMM 49-40-01	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 23-NOV-2016 4476 3270		
Y4900000 (s)	AUXILIARY POWER UNIT - PERFORM VISUAL INSPECTION OF EXTERNAL FIREBOX INSTALLATION AND ATTACHING COMPONENTS PKG 2 REF: AMM 05-10-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
Y4900002 (s)	AUXILIARY POWER UNIT - FIRE EXTINGUISHER CONTAINER - PERFORM FUNCTIONAL TEST OF WIRING. PKG 7 REF: AMM 26-22-00	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
Y4900010 (s)	APU ENGINE FIRE EXTINGUISHER CONTAINER - CHECK CONTAINER PRESSURE GAUGE FOR PROPER PRESSURE. PKG 2 REF: AMM 26-22-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y4900012 (s)	APU INLET SCREEN AND OPENING - PERFORM VISUAL INSPECTION PKG 2 REF: AMM 05-10-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
Y4900013 (s)	APU EXHAUST DUCT AREA, INCLUDING FORWARD AND AFT APU EXHAUST FAIRINGS - PERFORM VISUAL INSPECTION PKG 2 REF: AMM 05-10-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
APU Model : RE100 (CIMMS) Serial # P-297 Part # 3800726-1									
492001	APU - APU COMPRESSOR ROTOR. (P/N 3822523-2 - IRN H4900019) (P/N 3822523-003 - IRN H4900020) ROTOR 3822523-003 040350104760 REF: AMM 49-10-01	MOS HRS/MSC APUS					28-DEC-2004 0 0		12000
LIFE LIMIT			12000						
492005	APU - APU TURBINE ROTOR (P/N 3842340 - IRN H4900018) CHANGE 3842340-2 040134512720 REF: AMM 49-10-01	MOS HRS/MSC APUS					28-DEC-2004 0 0		4000
LIFE LIMIT			4000						
493071	APU - APU ASSEMBLY, FUEL CONTROL 3883900-1 0400640 REF: AMM 49-30-04	MOS HRS/MSC APUS					28-DEC-2004 0 0		
494021	APU - APU LOW VOLTAGE IGNITER PLUG PN SN-UNKNOWN REF: AMM 49-40-02	MOS HRS/MSC APUS					28-DEC-2004 0 0		
496001	APU - APU REMOTELY LOCATED (ECU) CONTROLLER 2119560-3 104-G0115 REF: AMM 49-60-04	MOS HRS/MSC APUS					28-DEC-2004 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
499025	APU - APU ASSEMBLY, LUBE OIL-PUMP 3881825-1 P-705 REF: AMM 49-90-03	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			28-DEC-2004 0 0		
5-19-00-O4900008	APU - INSPECT APU CHIP DETECTOR - FOR CONTAMINATION. (ZONE/ACCESS 310JL, 310RR IRN # O4900008) REF: AMM 49-90-05	MOS HRS/MSC APUS	750				11-OCT-2019 1497.37 3338	2247.37	
5-19-00-P4900009	APU - CHANGE APU OIL. (ZONE/ACCESS 310JL, 310RR). (IRN # P4900009). (REFER TO 12-10-10.) NOTE: THIS REQUIREMENT IS NOT APPLICABLE FOR OPERATORS ENROLLED IN THE SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) SYSTEM PER HONEYWELL SIL# APU-49). REF: AMM 12-10-10	MOS HRS/MSC APUS	750				11-OCT-2019 1497.37 3338	2247.37	
5-19-01-K4900005	APU - REPLACE APU ENGINE FUEL FILTER. IRN # K4900005 REF: AMM 49-30-03	MOS HRS/MSC APUS	750				11-OCT-2019 1497.37 3338	2247.37	
5-19-01-T4900004	APU - REPLACE APU OIL FILTER. THIS REQUIREMENT IS NOT APPLICABLE FOR OPERATORS ENROLLED IN THE SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) SYSTEM PER HONEYWELL SIL# APU-49 (ZONE/ACCESS 310JR, 310QR) (IRN # T4900004) REF: AMM 49-90-04	MOS HRS/MSC APUS	750				28-MAY-2015 1166.65	1916.65	
CHAPTER 52 DOORS									
5-19-02-RVSM-M5240004	INSPECT AVIONIC ACCESS DOOR GAP AND MISMATCH FOR RVSM COMPLIANT AIRCRAFT (IRN # M5240004) RVSM REF: AMM 52-40-01	MOS HRS/MSC AFL	24	+14d/-14d		-34	10-MAY-2019 4774.6 3558	06-APR-2021	20-APR-2021
521001	UPPER CABIN DOOR 4552101000-003 W293 REF: AMM 52-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
521002	LOWER CABIN DOOR 4552100300-001 W279 REF: AMM 52-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
+ 5210053	CABIN DOOR HANDLE - REPLACE REF: GENERIC NO REF	MOS HRS/MSC AFL	36 1200	+14d/-14d +25/-25			(EBT) 4707	30-APR-2021 4732	14-MAY-2021
522001	EMERGENCY EXIT DOOR ASSEMBLY 4552200076V36-001 L0268 REF: AMM 52-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
523001	TAILCONE BAGGAGE DOOR ASSEMBLY 12045-557V1-001 0313 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
524001	TAILCONE ACCESS DOOR 4552405151-005 0313 REF: AMM 52-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
524010	SPPR DOOR ASSY 4553448001-801 SN-UNKNOWN REF: AMM 52-40-03	MOS HRS/MSC AFL	O/C						
A5210009 (s)	PERFORM * EMERGENCY EXIT DOOR RETAINERS - VISUAL INSPECTION. INSPECT DOOR STOP FITTINGS ON EMERGENCY EXIT DOOR FRAMES IN FLANGE RADII. (FS 374 AND 394) PKG 26 REF: GENERIC NO REF	MOS HRS/MSC AFL	9600				03-APR-2005 0 0		
AIRWORTHINESS									

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A5210012 (s)	PERFORM * LOWER PASSENGER DOOR HINGE - VISUAL INSPECTION. INSPECT PIANO HINGE LUGS AND FASTENERS						PKG		
	PKG 26	MOS					03-APR-2005		
		HRS/MSC	9600				0		
AIRWORTHINESS	REF: GENERIC NO REF	AFL					0		
A5210014 (s)	PERFORM * UPPER PASSENGER DOOR TENSION FITTINGS - VISUAL INSPECTION. INSPECT THE FOLLOWING: A. TENSION STUDS AT RETAINING FLANGES. B. RADII AROUND FLANGE PERIPHERY.						PKG		
	PKG 26	MOS					03-APR-2005		
		HRS/MSC	9600				0		
AIRWORTHINESS	REF: GENERIC NO REF	AFL					0		
+ AA5210055 (s)	CABIN DOOR HANDLE RAMP ROLLER WHEEL - LUBRICATION						PKG		
	PKG 18	MOS	48	+14d/-14d			03-APR-2005		
		HRS/MSC	1200	+25/-25			0		
	REF: AMM 12-21-02	AFL					0		
D5210015 (s)	PERFORM * EMERGENCY EXIT DOOR - VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO FLANGES AND FASTENER HOLES OF DOOR STOP FITTINGS.						PKG		
	PKG 25	MOS					25-JUL-2018		
		HRS/MSC	4800				4687.6		
AIRWORTHINESS	REF: GENERIC NO REF	AFL					3479		
E5210013 (s)	PERFORM * UPPER AND LOWER PASSENGER DOOR LATCH ARMS AND DOOR ATTACHMENTS - VISUAL INSPECTION.						PKG		
	PKG 25	MOS					25-JUL-2018		
		HRS/MSC	4800				4687.6		
AIRWORTHINESS	REF: GENERIC NO REF	AFL					3479		
F5210016 (s)	PERFORM * UPPER PASSENGER DOOR HINGE - VISUAL INSPECTION. INSPECT UPPER SURFACE OF HINGE FINGERS AT BASE OF LUG.						PKG		
	PKG 26	MOS					03-APR-2005		
		HRS/MSC	9600				0		
AIRWORTHINESS	REF: GENERIC NO REF	AFL					0		
N5210010 (s)	PERFORM * LOWER PASSENGER DOOR TENSION BOLTS, BOLT RETAINERS, TENSION FITTINGS, AND DOOR ATTACHMENTS - VISUAL INSPECTION.						PKG		
	PKG 24	MOS	96				23-NOV-2016		
		HRS/MSC	2400				4476		
AIRWORTHINESS	REF:	AFL					3270		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
N5210011 (s)	PERFORM * UPPER AND LOWER PASSENGER DOOR LATCH PINS - VISUAL INSPECTION. INSPECT BOLTS AND DOOR END RIB STRUCTURE AT LOCK PINS.						PKG		
	PKG 24	MOS	96					23-NOV-2016	
AIRWORTHINESS	REF:	HRS/MSC	2400					4476	
		AFL						3270	
N5210017 (s)	PERFORM * UPPER PASSENGER DOOR TENSION BOLTS, BOLT RETAINERS, TENSION FITTINGS, AND DOOR ATTACHMENTS - VISUAL INSPECTION.						PKG		
	PKG 24	MOS	96					23-NOV-2016	
AIRWORTHINESS	REF:	HRS/MSC	2400					4476	
		AFL						3270	
T5210003 (s)	PERFORM EXTERNAL LOWER PASSENGER/CREW DOOR CABLES - VISUAL INSPECTION OF VISIBLE PORTION OF CABLES AND HANDLE AREA						PKG		
	PKG 18	MOS	48	+14d/-14d				23-NOV-2016	
		HRS/MSC	1200	+25/-25				4476	
	REF: AMM 05-10-00	AFL						3270	
Y5210000 (s)	PERFORM AVIONICS COMPARTMENT ACCESS DOORS AND SEALS - VISUAL INSPECTION						PKG		
	PKG 13	MOS	48	+14d/-14d				23-NOV-2016	
		HRS/MSC	1200	+25/-25				4476	
	REF: AMM 05-10-00	AFL						3270	
Y5210001 (s)	TAILCONE ACCESS DOOR AND SEAL - PERFORM VISUAL INSPECTION OF DOOR, SEALS, AND LATCHES						PKG		
	PKG 12	MOS	24	+14d/-14d				17-JUL-2020	
		HRS/MSC	600	+25/-25				4932.3	
	REF: AMM 05-10-00	AFL							
Y5210002 (s)	BAGGAGE COMPARTMENT DOOR - PERFORM VISUAL INSPECTION OF DOORS, SEALS, AND LATCHES						PKG		
	PKG 12	MOS	24	+14d/-14d				17-JUL-2020	
		HRS/MSC	600	+25/-25				4932.3	
	REF: AMM 05-10-00	AFL							
Y5210004 (s)	PERFORM UPPER AND LOWER PASSENGER/CREW DOOR - VISUAL INSPECTION OF DOOR STRUCTURE, TENSION FITTINGS, AND HINGE AREA FOR CRACKS AND CORROSION						PKG		
	PKG 18	MOS	48	+14d/-14d				23-NOV-2016	
		HRS/MSC	1200	+25/-25				4476	
	REF: AMM 05-10-00	AFL						3270	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y5210005 (s)	PERFORM INTERNAL LOWER PASSENGER/CREW DOOR CABLES - VISUAL INSPECTION. REMOVE STEP SKIN TO GAIN ACCESS TO CABLES						PKG		
	PKG 18	MOS	48	+14d/-14d				23-NOV-2016	
		HRS/MSC	1200	+25/-25				4476	
	REF: AMM 05-10-00	AFL						3270	
Y5210006 (s)	UPPER PASSENGER/CREW DOOR VENT DOOR SPRINGS - PERFORM VISUAL INSPECTION						PKG		
	PKG 12	MOS	24	+14d/-14d				17-JUL-2020	
		HRS/MSC	600	+25/-25				4932.3	
	REF: AMM 05-10-00	AFL							
Y5210008 (s)	EMERGENCY EXIT DOOR INTERNAL AND EXTERNAL HANDLE LATCHING MECHANISM - PERFORM OPERATIONAL CHECK						PKG		
	PKG 12	MOS	24	+14d/-14d				17-JUL-2020	
		HRS/MSC	600	+25/-25				4932.3	
	REF: AMM 52-20-07	AFL							
Y5240000 (s)	PERFORM OXYGEN SYSTEM SERVICING DOOR AND LATCHES - VISUAL INSPECTION FOR CONDITION AND SECURITY. CHECK DECAL FOR CONDITION AND LEGIBILITY						PKG		
	PKG 13	MOS	48	+14d/-14d				23-NOV-2016	
		HRS/MSC	1200	+25/-25				4476	
	REF: AMM 05-10-00	AFL						3270	
Y5240003 (s)	PERFORM SINGLE POINT REFUELING ACCESS DOOR - VISUAL INSPECTION.						PKG		
	PKG 14	MOS	48	+14d/-14d				23-NOV-2016	
		HRS/MSC	1200	+25/-25				4476	
	REF: AMM 05-10-00	AFL						3270	

CHAPTER 53	FUSELAGE								
5-19-00-H5323032	* EXTERIOR CABIN WINDOW COAMINGS (UNPAINTED) - PERFORM EDDY CURRENT INSPECTION (IRN H5323032)								
		MOS	24					05-MAY-2019	05-MAY-2021
		HRS/MSC	2400					4789.6	7189.6
AIRWORTHINESS	REF: NDT PART 6/56-20-01	AFL						3579	
5-19-00-H5323092	* EXTERIOR CABIN WINDOW COAMINGS (PAINTED) - PERFORM EDDY CURRENT INSPECTION (IRN H5323092)								
		MOS	96			-9		12-APR-2013	03-APR-2021
		HRS/MSC	4800					3715.78	8515.78
AIRWORTHINESS	REF: NDT PART 6/56-20-01	AFL						2610	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-T5323166	PERFORM * EXTERNAL SKIN CUT-OUTS/PENETRATIONS (PRESSURE CABIN) - PERFORM DETAILED VISUAL INSPECTION. INSPECT SKIN AND DOUBLERS AT ANTENNAS, ELECTRICAL COMPONENTS, AND ACCESS PANELS (EXCLUDING PITOT/STATIC PROBES, AOA STALL VANES AND WING INSPECTION LIGHT. (REFER TO 5-10-00.) IRN T5323166	MOS	144				05-MAY-2017	05-MAY-2029	
MANDATORY	REF: GENERIC NO REF	HRS/MSC	9600				4531.3	14131.3	
		AFL					3329		
5-19-00-V5323168	EDDY CURRENT INSPECTION * LOWER COUPE RAIL RADIUS/WINDSCREEN RETAINER ATTACH (P/N'S 4553130001-802 THRU 4553130001-809)	MOS					03-APR-2005		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	5000				0	5000	
		AFL					0		
5-19-01-U5323167-LEFT	* REPLACE LEFT COUPE RAIL (P/N 4553002003V7000-001, 4553002003V7001-002) (IRN U5323167) ASSEMBLY	MOS		N:0			(EBT)		
NOT APPLICABLE	PN	HRS/MSC	N/A	N:0					
	SN-UNKNOWN	AFL		N:0					
	REF: AMM 53-10-04			N:0					
5-19-01-U5323167-RIGHT	* REPLACE RIGHT COUPE RAIL (4553002003V7000-001, 4553002003V7001-002) (IRN U5323167) ASSEMBLY	MOS		N:0			(EBT)		
NOT APPLICABLE	PN	HRS/MSC	N/A	N:0					
	SN-UNKNOWN	AFL		N:0					
	REF: AMM 53-10-04			N:0					
5-19-02-RVSM-M5313001	PERFORM PITOT-STATIC PROBE ZONE SKIN CONTOUR CHECK OF THE FORWARD FUSELAGE SKIN FOR RVSM COMPLIANT AIRCRAFT (IRN # M5313001)	MOS	24	+14d/-14d		-34	10-MAY-2019	06-APR-2021	20-APR-2021
RVSM	REF: AMM 53-00-01	HRS/MSC					4774.6		
		AFL					3558		
530001	FUSELAGE ASSEMBLY	MOS		N:0			03-APR-2005		
	4553000010-001	HRS/MSC	O/C	N:0			0		
	L0267	AFL		N:0			0		
	REF: GENERIC NO REF			N:0					
535001	RADOME	MOS		N:92			11-DEC-2012		
	6634408000-003	HRS/MSC	O/C	N:3615.6			3615.55		
	0335	AFL					2542		
	REF: AMM 53-50-01								

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
535002 (s)	BOOT, EROSION, RADOME REPLACE PM-112 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			08-FEB-2016 4383.7 3170		
CUSTOMER CODE									
535601	LEFT DELTA FIN 4555501000-015 S7549/A0068 REF: AMM 53-56-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
535602	RIGHT DELTA FIN 4555501000-016 S7549/A0068 REF: AMM 53-56-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
A5310005 (s)	PERFORM * FUSELAGE FUEL CELL CANTED BULKHEAD (FS 495) - VISUAL INSPECTION, PAYING PARTICULAR ATTENTION TO MAIN CROSSMEMBER. INSPECT FLANGES AND ATTACHMENTS FOR CRACKING. PKG 25 REF: GENERIC NO REF	MOS HRS/MSC AFL	4800				25-JUL-2018 4687.6 3479		
A5310007 (s)	PERFORM * AFT PRESSURE BULKHEAD BOTTOM SHEAR DIAPHRAGM - DETAILED VISUAL INSPECTION. INSPECT BULKHEAD POST ATTACHMENT FASTENER HOLES AND CONTROL CABLE SLOT. PKG 26 REF: GENERIC NO REF	MOS HRS/MSC AFL	9600				03-APR-2005 0 0		
A5323022 (s)	PERFORM * NOSE LANDING GEAR AFT WHEELBOX CLOSING STRUCTURE (FS 150 TO FS 162) - VISUAL INSPECTION. INSPECT THE FOLLOWING: A. PANEL B. CHANNEL STIFFENERS. C. SUPPORT ANGLE. D. ANGLE STIFFENER. E. ZEE STIFFENER. PKG 26 REF: GENERIC NO REF	MOS HRS/MSC AFL	9600				03-APR-2005 0 0		
A5323023 (s)	PERFORM * DRAG LINK ATTACHMENT LUG - VISUAL INSPECTION. PKG 25 REF: GENERIC NO REF	MOS HRS/MSC AFL	4800				25-JUL-2018 4687.6 3479		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A5360001 (s)	PERFORM DELTA FINS - WITH DELTA FINS REMOVED, VISUALLY INSPECT THE FOLLOWING: A. DELTA FIN AFT SPAR. B. DELTA FIN SUPPORT ANGLE. C. INSPECT STIFFENERS CONNECTING TO ATTACH FITTINGS.						PKG		
	PKG 26	MOS						03-APR-2005	
		HRS/MSC	9600	+25/-25				0	
	REF: AMM 05-10-00	AFL						0	
D5323039 (s)	PERFORM * MACHINED FUSELAGE FRAME AT FS 466 - DETAILED VISUAL INSPECTION BETWEEN STRINGER 13 LEFT AND RIGHT, PAYING PARTICULAR ATTENTION TO THE BL 10 SPLICES. CONFIRM ANY CRACK INDICATIONS WITH THE EDDY CURRENT PROCEDURES						PKG		
	PKG 25	MOS						25-JUL-2018	
		HRS/MSC	4800					4687.6	
AIRWORTHINESS	REF: GENERIC NO REF	AFL						3479	
E5310001 (s)	PERFORM * LONGERON, INTERNAL (BETWEEN FS 384 AND FS 433) - VISUAL INSPECTION.						PKG		
	PKG 26	MOS						03-APR-2005	
		HRS/MSC	9600					0	
AIRWORTHINESS	REF: GENERIC NO REF	AFL						0	
E5310002 (s)	PERFORM * FLIGHT DECK LONGERON (FS 149 - FS 196) - VISUAL INSPECTION. INSPECT FLIGHT DECK LONGERON STIFFENERS, WEBS, AND CUTOUTS.						PKG		
	PKG 26	MOS						03-APR-2005	
		HRS/MSC	9600					0	
AIRWORTHINESS	REF: GENERIC NO REF	AFL						0	
E5310017 (s)	PERFORM * AFT PRESSURE BULKHEAD BOTTOM CROSSMEMBER (FS 457) - DETAILED VISUAL INSPECTION. INSPECT TEE-SECTION AT FS 457 FLANGE AT ATTACHMENT TO PRESSURE FLOOR.						PKG		
	PKG 26	MOS						03-APR-2005	
		HRS/MSC	9600					0	
AIRWORTHINESS	REF: GENERIC NO REF	AFL						0	
E5310018 (s)	PERFORM * AFT PRESSURE BULKHEAD PANEL FACING SHEETS (FS 457) - VISUAL INSPECTION. INSPECT BOTH FRONT AND AFT OF FACING SHEETS.						PKG		
	PKG 26	MOS						03-APR-2005	
		HRS/MSC	9600					0	
AIRWORTHINESS	REF: GENERIC NO REF	AFL						0	
E5323025 (s)	PERFORM * FORWARD/AFT WHEELBOX JOINT (FS 150) - VISUAL INSPECTION. INSPECT SPLICE STRAP AFT OF FORWARD PRESSURE BULKHEAD AT INTERSECTION OF ATTACHMENT ANGLE AND FLIGHT DECK LONGERON.						PKG		
	PKG 26	MOS						03-APR-2005	
		HRS/MSC	9600					0	
AIRWORTHINESS	REF: GENERIC NO REF	AFL						0	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E5323050 (s)	PERFORM * AFT POST/WINDSHIELD RETAINER ATTACHMENT - WITH HEADLINER REMOVED, EDDY CURRENT INSPECTION						PKG		
	PKG 25	MOS					25-JUL-2018		
AIRWORTHINESS	REF: NDT PART 6/53-30-04	HRS/MSC	4800				4687.6		
		AFL					3479		
E5323053 (s)	PERFORM * FRAME ATTACHMENTS TO UPPER AND LOWER COUPE RAILS (FS 171 TO FS 204) - VISUAL INSPECTION. INSPECT THE FOLLOWING: A. FRAME ATTACHMENTS TO LOWER COUPE RAILS AT FS 171, FS 182, FS 196, AND FS 204. B. FRAME ATTACHMENTS TO UPPER COUPE RAILS AT FS 196 AND FS 204. C. GUSSETS AT FASTENER HOLES.						PKG		
	PKG 26	MOS					03-APR-2005		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	9600				0		
		AFL					0		
E5323054 (s)	PERFORM * TIE-ROD ASSEMBLY (FS 162) (ALUMINUM ENDS) - VISUAL INSPECTION. INSPECT TIE-ROD ENDS, TIE-ROD TUBES, AND TIE-ROD BOLTS.						PKG		
	PKG 25	MOS					25-JUL-2018		
AIRWORTHINESS	REF:	HRS/MSC	4800				4687.6		
		AFL					3479		
E5323055 (s)	PERFORM * TIE-ROD ASSEMBLY (FS 162) (TITANIUM ENDS) - VISUAL INSPECTION. INSPECT TIE-ROD ENDS, TIE-ROD TUBES, AND TIE-ROD BOLTS.						PKG		
	PKG 26	MOS					03-APR-2005		
AIRWORTHINESS	REF: AMM 53-10-04	HRS/MSC	9600				0		
		AFL					0		
E5323068 (s)	PERFORM * STRINGER 1 RH BETWEEN FS 533 AND FS 543 - VISUAL INSPECTION. INSPECT STRINGER 1 FLANGE AND SKIN ALONG STRINGER 1 BETWEEN FS 533 AND FS 543.						PKG		
	PKG 26	MOS					03-APR-2005		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	9600				0		
		AFL					0		
E5323073 (s)	PERFORM * FUSELAGE BOTTOM SKIN PANEL - VISUAL INSPECTION. INSPECT CORNER RADIUS AT JUNCTION OF EXTERNAL LONGERON AND MID SPAR FRAME (FS 435)						PKG		
	PKG 26	MOS					03-APR-2005		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	9600				0		
		AFL					0		
E5323074 (s)	PERFORM * AUXILIARY SKIN PANEL - VISUAL INSPECTION. INSPECT CORNER RADIUS AT JUNCTION OF KEEL BEAM AND REAR SPAR FRAME (FS 466).						PKG		
	PKG 26	MOS					03-APR-2005		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	9600				0		
		AFL					0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E5350000 (s)	PERFORM * BOTTOM KEELBEAM END PADS (FS 384 - FS 486) - VISUAL INSPECTION. INSPECT END PADS AROUND BOLT HOLES AND IN RADII AT FS 433.						PKG		
	PKG 26	MOS						03-APR-2005	
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	9600					0	
		AFL						0	
F5323056 (s)	PERFORM * TIE-ROD FORK ENDS (ALUMINUM) - FLOURESCENT PENETRANT INSPECTION. (EFFECTIVE ON AIRCRAFT 45-001 THRU 45-058)						PKG		
	PKG 25	MOS						25-JUL-2018	
AIRWORTHINESS	REF:	HRS/MSC	4800					4687.6	
		AFL						3479	
F5323081 (s)	PERFORM * TIE-ROD FORK ENDS (TITANIUM, P/N R24889) - FLUORESCENT PENETRANT INSPECTION. (EFFECTIVE ON AIRCRAFT 45-059 AND SUBSEQUENT AND PRIOR AIRCRAFT WITH TITANIUM ROD ASSEMBLY INSTALLED.)						PKG		
	PKG 26	MOS						03-APR-2005	
AIRWORTHINESS	REF: NDT PART 8/53-10-01	HRS/MSC	9600					0	
		AFL						0	
F5331021 (s)	PERFORM * FORWARD CANTED BULKHEAD (FS 630) - VISUAL INSPECTION. INSPECT AT FRONT SPAR ATTACHMENT FASTENERS.						PKG		
	PKG 25	MOS						25-JUL-2018	
AIRWORTHINESS	REF: AMM NO REF	HRS/MSC	4800					4687.6	
		AFL						3479	
F5331022 (s)	PERFORM * MID CANTED BULKHEAD (FS 657) - VISUAL INSPECTION AT MID SPAR UPPER ATTACHMENT FASTENERS.						PKG		
	PKG 26	MOS						03-APR-2005	
AIRWORTHINESS	REF: AMM NO REF	HRS/MSC	9600					0	
		AFL						0	
F5331023 (s)	PERFORM * AFT CANTED BULKHEAD (FS 682) - VISUAL INSPECTION. INSPECT AT REAR SPAR ATTACHMENT FASTENERS.						PKG		
	PKG 26	MOS						03-APR-2005	
AIRWORTHINESS	REF: AMM NO REF	HRS/MSC	9600					0	
		AFL						0	
F5331024 (s)	PERFORM * VERTICAL STABILIZER FRONT ROOT BULKHEAD ATTACHMENT (FS 630) - VISUAL INSPECTION. INSPECT FRONT SPAR ROOT BULKHEAD ATTACHMENT AT FASTENER HOLES.						PKG		
	PKG 26	MOS						03-APR-2005	
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	9600					0	
		AFL						0	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
F5331025 (s)	PERFORM * VERTICAL STABILIZER MID SPAR ROOT BULKHEAD ATTACHMENT (FS 657) - VISUAL INSPECTION. INSPECT MID SPAR ROOT BULKHEAD ATTACHMENT AT FASTENER HOLES.						PKG		
	PKG 26	MOS						03-APR-2005	
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	9600					0	
		AFL						0	
F5331026 (s)	PERFORM * VERTICAL STABILIZER REAR SPAR ROOT BULKHEAD ATTACHMENT (FS 682) - VISUAL INSPECTION. INSPECT REAR SPAR ROOT BULKHEAD ATTACHMENT AT FASTENER HOLES.						PKG		
	PKG 26	MOS						03-APR-2005	
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	9600					0	
		AFL						0	
L5311002 (s)	PERFORM * NOSE LANDING GEAR ACTUATOR ATTACHMENT ON FORWARD PRESSURE BULKHEAD - EDDY CURRENT INSPECTION. INSPECT ACTUATOR ATTACHMENT BRACKET LUGS, RADII, AND FASTENER HOLES.						PKG		
	PKG 27	MOS						03-APR-2005	
AIRWORTHINESS	REF: NDT PART 6/32-12-00	HRS/MSC						0	
		AFL	10000					0	
L5311004 (s)	PERFORM * NOSE LANDING GEAR TRUNNION FITTINGS - VISUAL INSPECTION OF THE TRUNNION FITTINGS AND ATTACHMENT BOLTS.						PKG		
	PKG 27	MOS						03-APR-2005	
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC						0	
		AFL	10000					0	
L5311005 (s)	PERFORM * NOSE LANDING GEAR TRUNNION FITTINGS AND SUPPORT STRUCTURE - EDDY CURRENT INSPECTION OF THE TRUNNION SUPPORT STRUCTURE AT THE FORWARD PRESSURE BULKHEAD FLANGE.						PKG		
	PKG 27	MOS						03-APR-2005	
AIRWORTHINESS	REF: NDT PART 6/32-12-05	HRS/MSC						0	
		AFL	10000					0	
M5323021 (s)	PERFORM * EXTERNAL LONGERON, FASTENER LOCATIONS, AND AREA AROUND WING ATTACHMENTS - VISUAL INSPECTION. INSPECT LONGERON BETWEEN FS 398 AND FS 486, STRINGER 13 LHS & RHS.						PKG		
	PKG 26	MOS						03-APR-2005	
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	9600					0	
		AFL						0	
M5323034 (s)	PERFORM * UPPER AND LOWER COUPE RAIL AND CENTER POST/ WINDSHIELD RETAINER ATTACHMENT - EDDY CURRENT INSPECTION.						PKG		
	PKG 26	MOS						03-APR-2005	
AIRWORTHINESS	REF: NDT PART 6/53-30-03	HRS/MSC	9600					0	
		AFL						0	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
N5314000 (s)	PERFORM * EMERGENCY EXIT DOOR SKIN CUTOUT CORNERS AND DOUBLERS (FS 370 TO FS 398) - PERFORM EDDY CURRENT INSPECTION.						PKG		
	PKG 19	MOS	96					23-NOV-2016	
		HRS/MSC	2400					4476	
AIRWORTHINESS	REF: NDT PART 6/53-30-01	AFL						3270	
N5323026 (s)	PERFORM * UPPER AND LOWER PASSENGER/CREW DOOR SKIN CUTOUT CORNERS (F.S. 224 - F.S. 256) -EDDY CURRENT INSPECTION. INSPECT SKIN AT CORNERS OF PASSENGER/CREW DOOR CUTOUT						PKG		
	PKG 19	MOS	96					23-NOV-2016	
		HRS/MSC	2400					4476	
AIRWORTHINESS	REF: NDT PART 6/53-30-02	AFL						3270	
P5310003 (s)	PERFORM * AFT PRESSURE BULKHEAD SUPPORT POST (FS 457) - EDDY CURRENT INSPECTION.						PKG		
	PKG 26	MOS						03-APR-2005	
		HRS/MSC	9600					0	
AIRWORTHINESS	REF: NDT PART 6/53-30-18	AFL						0	
P5310004 (s)	PERFORM * AFT PRESSURE BULKHEAD FRAME PERIPHERY - EDDY CURRENT INSPECTION.						PKG		
	PKG 25	MOS						25-JUL-2018	
		HRS/MSC	4800					4687.6	
AIRWORTHINESS	REF: NDT PART 6/53-30-21	AFL						3479	
P5310006 (s)	PERFORM * FORWARD PRESSURE BULKHEAD - EDDY CURRENT INSPECTION.						PKG		
	PKG 26	MOS						03-APR-2005	
		HRS/MSC	9600					0	
AIRWORTHINESS	REF: NDT PART 6/53-30-07	AFL						0	
P5320001 (s)	PERFORM * FUSELAGE PRESSURE FLOOR STEP (FS 433 - FS 457) - EDDY CURRENT INSPECTION.						PKG		
	PKG 26	MOS						03-APR-2005	
		HRS/MSC	9600					0	
AIRWORTHINESS	REF: NDT PART 6/53-20-01	AFL						0	
P5323024 (s)	PERFORM * FUSELAGE SKIN CUT-OUTS ABOVE FUEL CELL - EDDY CURRENT INSPECTION.						PKG		
	PKG 25	MOS						25-JUL-2018	
		HRS/MSC	4800					4687.6	
AIRWORTHINESS	REF: NDT PART 6/53-30-12	AFL						3479	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P5323027 (s)	PERFORM * FUSELAGE FRAME AT FS 412 - EDDY CURRENT INSPECTION. PKG 25	MOS					PKG	25-JUL-2018	
AIRWORTHINESS	REF: NDT PART 6/53-30-20	HRS/MSC AFL	4800				4687.6 3479		
P5323029 (s)	PERFORM * MACHINED SPAR FRAMES SYSTEMS CUTOUTS (FS 398, FS 412, FS 432, FS 466) - EDDY CURRENT INSPECTION PKG 25	MOS					PKG	25-JUL-2018	
AIRWORTHINESS	REF: NDT PART 6/53-30-15	HRS/MSC AFL	4800				4687.6 3479		
P5323033 (s)	PERFORM * FUSELAGE SKIN AT EMERGENCY DOOR EGRESS-LIGHT AND WING INSPECTION LIGHT - EDDY CURRENT INSPECTION. PKG 26	MOS					PKG	03-APR-2005	
AIRWORTHINESS	REF: NDT PART 6/53-40-02	HRS/MSC AFL	9600				0 0		
P5323037 (s)	PERFORM * WINDSHIELD COUPE RAIL TIE ROD BRACKET - EDDY CURRENT INSPECTION. PKG 26	MOS					PKG	03-APR-2005	
AIRWORTHINESS	REF: NDT PART 6/53-30-09	HRS/MSC AFL	9600				0 0		
P5323038 (s)	PERFORM * WINDSHIELD CENTERPOST TO UPPER COUPE RAIL JOINT ATTACHMENT - EDDY CURRENT INSPECTION PKG 25	MOS					PKG	25-JUL-2018	
AIRWORTHINESS	REF: NDT PART 6/53-30-22	HRS/MSC AFL	4800				4687.6 3479		
P5323047 (s)	PERFORM * PRESSURE CABIN FUSELAGE CROWN SKIN - PERFORM EDDY CURRENT INSPECTION. PKG 19	MOS					PKG	23-NOV-2016	
AIRWORTHINESS	REF: NDT PART 6/53-10-04	HRS/MSC AFL	2400				4476 3270		
P5323049 (s)	PERFORM * FUSELAGE SKIN AT UPPER AND LOWER COUPE RAIL RUN-OUT JOINTS - EDDY CURRENT INSPECTION. PKG 26	MOS					PKG	03-APR-2005	
AIRWORTHINESS	REF: NDT PART 6/53-30-11	HRS/MSC AFL	9600				0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P5323057 (s)	PERFORM * PRESSURE CABIN SKIN AT FUSELAGE STATION 451 - EDDY CURRENT INSPECTION. PKG 19	MOS	96				PKG	23-NOV-2016	
AIRWORTHINESS	REF: NDT PART 6/53-30-06	HRS/MSC AFL	2400				4476 3270		
P5323058 (s)	PERFORM * FUSELAGE SKIN AT F.S. 504 - EDDY CURRENT INSPECTION. PKG 25	MOS					PKG	25-JUL-2018	
AIRWORTHINESS	REF: NDT PART 6/53-30-13	HRS/MSC AFL	4800				4687.6 3479		
P5323069 (s)	PERFORM * CIRCUMFERENTIAL SKIN JOINT AT FORWARD PRESSURE BULKHEAD - EDDY CURRENT INSPECTION. PKG 26	MOS					PKG	03-APR-2005	
AIRWORTHINESS	REF: NDT PART 6/53-30-08	HRS/MSC AFL	9600				0 0		
P5323164 (s)	PERFORM * FUSELAGE SKIN AND DOUBLER AROUND ECS DUCT CUTOUT - EDDY CURRENT INSPECTION. PKG 26	MOS					PKG	03-APR-2005	
AIRWORTHINESS	REF: NDT PART 6/53-40-01	HRS/MSC AFL	9600				0 0		
P5323165 (s)	PERFORM * WINDSHIELD CENTER POST TO LOWER COUPE RAIL JOINT ATTACHMENT - EDDY CURRENT INSPECTION. PKG 26	MOS					PKG	03-APR-2005	
AIRWORTHINESS	REF: NDT PART 6/53-30-10	HRS/MSC AFL	9600				0 0		
P5360006 (s)	PERFORM DELTA FIN ATTACH BOLT - LIQUID PENETRANT INSPECTION. PKG 26	MOS					PKG	03-APR-2005	
AIRWORTHINESS	REF: NDT PART 8/53-10-02	HRS/MSC AFL	9600	+25/-25			0 0		
Q5310023 (s)	PERFORM FORWARD AND AFT FUEL CELL BAY STRUCTURE, ANGLE REINFORCEMENT, STRINGER 1, LH & RH - DETAILED VISUAL INSPECTION OF HI-LITE COLLARS PKG 26	MOS					PKG	03-APR-2005	
AIRWORTHINESS	REF:	HRS/MSC AFL	9600	+25/-25			0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Q5310025 (s)	PERFORM AFT FUSELAGE KEELBEAM LONGERON (LH & RH, BL 5.15, FS 466.30 - 495.12) AND AFT FUSELAGE KEELBEAM LOWER FRAME (FS 466.30, BL 9.55 LH THRU BL 9.55 RH) - DETAILED VISUAL INSPECTION OF HI-LITE COLLARS						PKG		
	PKG 26	MOS						03-APR-2005	
		HRS/MSC	9600	+25/-25				0	
	REF:	AFL						0	
Q5323048 (s)	PERFORM * FUSELAGE (PRESSURE CABIN) - EDDY CURRENT INSPECTION. INSPECT PRESSURE CABIN SKIN (LONGITUDINAL SKIN CRACKING)						PKG		
	PKG 25	MOS						25-JUL-2018	
		HRS/MSC	4800					4687.6	
AIRWORTHINESS	REF: NDT PART 6/53-30-05	AFL						3479	
Q5323051 (s)	PERFORM * LONGITUDINAL JOINTS INSIDE PRESSURE CABIN (FS 220- FS 457) AND SKIN WITHIN ONE STRINGER BAY OF JOINT - EDDY CURRENT INSPECTION. INSPECT SKIN FASTENER HOLES ALONG JOINTS AT STRINGER 10 LH AND RH AND STRINGER 2 RH AND STRINGER 18 RH.						PKG		
	PKG 25	MOS						25-JUL-2018	
		HRS/MSC	4800					4687.6	
AIRWORTHINESS	REF: GENERIC NO REF	AFL						3479	
Q5323059 (s)	PERFORM * STRINGER TO FRAME JOINTS (FS 162 TO FS 213) - EDDY CURRENT INSPECTION. INSPECT SKIN, STRINGERS, AND FRAMES AT JOINTS.						PKG		
	PKG 26	MOS						03-APR-2005	
		HRS/MSC	9600					0	
AIRWORTHINESS	REF: GENERIC NO REF	AFL						0	
T5310027 (s)	PERFORM * AFT PRESSURE BULKHEAD TOP MOUNTING STRUCTURE - EDDY CURRENT INSPECTION						PKG		
	PKG 26	MOS						03-APR-2005	
		HRS/MSC	9600					0	
AIRWORTHINESS	REF: NDT PART 6/53-30-17	AFL						0	
T5321089 (s)	SEAT RAILS - PERFORM DETAILED INSPECTION OF SEAT RAIL (TRACK) SHEAR WEBS FOR CRACKING						PKG		
	PKG 7	MOS	24	+14d/-14d				17-JUL-2020	
		HRS/MSC	600	+25/-25				4932.3	
	REF: AMM 53-20-01	AFL							
T5323028 (s)	PERFORM * FUSELAGE TO WING ATTACH FITTINGS - EDDY CURRENT INSPECTION						PKG		
	PKG 25	MOS						25-JUL-2018	
		HRS/MSC	4800					4687.6	
AIRWORTHINESS	REF: NDT PART 6/53-30-16	AFL						3479	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y5311001 (s)	PERFORM NOSE LANDING GEAR ACTUATOR ATTACH FITTING AND SURROUNDING STRUCTURE - VISUAL INSPECTION						PKG		
	PKG 17	MOS	48	+14d/-14d			23-NOV-2016		
		HRS/MSC	1200	+25/-25			4476		
	REF: AMM 05-10-00	AFL					3270		
Y5311003 (s)	PERFORM NOSE LANDING GEAR TRUNNION FITTING AND SURROUNDING STRUCTURE - VISUAL INSPECTION						PKG		
	PKG 17	MOS	48	+14d/-14d			23-NOV-2016		
		HRS/MSC	1200	+25/-25			4476		
	REF: AMM 05-10-00	AFL					3270		
Y5320000 (s)	CENTER PEDESTAL - PERFORM VISUAL INSPECTION						PKG		
	PKG 1	MOS	12	+14d/-14d			17-JUL-2020		
		HRS/MSC	300	+25/-25			4932.3		
	REF: AMM 05-10-00	AFL							
Y5321010 (s)	FLOORBOARDS AROUND GALLEY, LAVATORY, AND WATER TANK - PERFORM VISUAL INSPECTION						PKG		
	PKG 1	MOS	12	+14d/-14d			17-JUL-2020		
		HRS/MSC	300	+25/-25			4932.3		
	REF: AMM 53-20-01	AFL							
Y5321011 (s)	TAILCONE BAGGAGE COMPARTMENT - PERFORM VISUAL INSPECTION						PKG		
	PKG 8	MOS	24	+14d/-14d			17-JUL-2020		
		HRS/MSC	600	+25/-25			4932.3		
	REF: AMM 05-10-00	AFL							
Y5321088 (s)	PERFORM SEAT RAILS - REMOVE FLOORBOARD 230AL AND PERFORM VISUAL INSPECTION OF SEAT RAILS. IF CORROSION IS DETECTED, REMOVE ALL FLOORBOARDS AND INSPECT ALL SEAT RAILS.						PKG		
	PKG 13	MOS	48	+14d/-14d			23-NOV-2016		
		HRS/MSC	1200	+25/-25			4476		
	REF: AMM NO REF	AFL					3270		
Y5323020 (s)	PERFORM EXTERNAL FUSELAGE (PRESSURE CABIN) - VISUAL INSPECTION OF ALL CABIN SKINS FROM F.S. 100 TO F.S.458. PAY PARTICULAR ATTENTION TO ALL CUTOUTS AND SKIN JOINTS. NO FAIRING ACCESS REQUIRED.						PKG		
	PKG 13	MOS	48	+14d/-14d			23-NOV-2016		
		HRS/MSC	1200	+25/-25			4476		
	REF: AMM 05-10-00	AFL					3270		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y5323031 (s)	PERFORM EXTERIOR CABIN WINDOW COAMINGS AND SURROUNDING FUSELAGE SKIN - VISUAL INSPECTION USING 10X MAGNIFICATION AND ADEQUATE LIGHTING						PKG		
	PKG 13	MOS	48	+14d/-14d				23-NOV-2016	
	REF: AMM 05-10-00	HRS/MSC	1200	+25/-25				4476	
		AFL						3270	
Y5340007 (s)	PERFORM WING ATTACH FITTINGS - VISUAL INSPECTION						PKG		
	PKG 19	MOS	96	+14d/-14d				23-NOV-2016	
	REF: AMM 05-10-00	HRS/MSC	2400	+25/-25				4476	
		AFL						3270	
Y5360000 (s)	DELTA FINS - PERFORM VISUAL INSPECTION						PKG		
	PKG 8	MOS	24	+14d/-14d				17-JUL-2020	
	REF: AMM 05-10-00	HRS/MSC	600	+25/-25				4932.3	
		AFL							
Z5323172 (s)	*SKIN CUT-OUT FOR IRIIDIUM ANTENNAS FS283.88 TO FS308.39 - PERFORM EDDY CURRENT INSPECTION						PKG		
	PKG 25	MOS						25-JUL-2018	
	AIRWORTHINESS	HRS/MSC	N/A					4687.6	
	REF: AMM NO REF	AFL						3479	
CHAPTER 54	NACELLES/PYLONS								
5-19-00-Q5450013-LEFT	FORWARD LEFT ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE								
		MOS						03-APR-2005	
	REF:	HRS/MSC	N/A					0	
		AFL						0	
5-19-00-Q5450013-RIGHT	RIGHT FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE.								
		MOS						03-APR-2005	
	REF:	HRS/MSC	N/A					0	
		AFL						0	
5-19-01-A5450028	REPLACE AFT ENGINE BEAM ASSEMBLY END FITTINGS (P/N 4553500201-001/-002)								
		MOS						03-APR-2005	
	N/A BY SERIAL NUMBER	HRS/MSC	N/A					0	
	REF: AMM 53-40-02	AFL						0	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-01-M5450027	REPLACE FORWARD ENGINE BEAM ASSEMBLY END FITTINGS (P/N 4553500101-003/4)	MOS							
	REF: AMM 53-40-02	HRS/MSC N/A							
		AFL							
5450054	LEFT FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE.	MOS					03-APR-2005		
	REF: AMM 05-10-00	HRS/MSC 6000	+100/-100				0	6000	6100
		AFL					0		
5450054	RIGHT FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE.	MOS					03-APR-2005		
	REF: AMM 05-10-00	HRS/MSC 6000	+100/-100				0	6000	6100
		AFL					0		
545019	* REPLACE LEFT AFT ENGINE BEAM TO FRAME ATTACHMENT (IRN P5450020) BOLT	MOS		N:0			03-APR-2005		
	PN	HRS/MSC 9600		N:0			0	9600	
	SN-UNKNOWN	AFL		N:0			0		
LIFE LIMIT	REF: NDT PART 8/54-30-01								
545020	* REPLACE RIGHT AFT ENGINE BEAM TO FRAME ATTACHMENT (IRN P5450020) BOLT	MOS		N:0			03-APR-2005		
	PN	HRS/MSC 9600		N:0			0	9600	
	SN-UNKNOWN	AFL		N:0			0		
LIFE LIMIT	REF: NDT PART 8/54-30-01								
545021	* REPLACE LEFT AFT ENGINE MOUNT TO END FITTING ATTACH (IRN A5450022) BOLT	MOS		N:0			03-APR-2005		
	PN	HRS/MSC 9600		N:0			0	9600	
	SN-UNKNOWN	AFL		N:0			0		
LIFE LIMIT	REF: GENERIC NO REF								
545022	* REPLACE RIGHT AFT ENGINE MOUNT TO END FITTING ATTACH (IRN A5450022) BOLT	MOS		N:0			03-APR-2005		
	PN	HRS/MSC 9600		N:0			0	9600	
	SN-UNKNOWN	AFL		N:0			0		
LIFE LIMIT	REF: GENERIC NO REF								

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
545023	* REPLACE LEFT ENGINE TO AFT ENGINE MOUNT ATTACH (IRN P5450023) BOLT PN SN-UNKNOWN REF: NDT PART 8/54-30-02	MOS HRS/MSC AFL	9600	N:0 N:0 N:0			03-APR-2005 0 0	9600	
545024	*REPLACE RIGHT ENGINE TO AFT ENGINE MOUNT ATTACH (IRN P5450023) BOLT PN SN-UNKNOWN REF: NDT PART 8/54-30-02	MOS HRS/MSC AFL	9600	N:0 N:0 N:0			03-APR-2005 0 0	9600	
A5450026 (s)	PERFORM * ENGINE DRAG STRUT - EDDY CURRENT INSPECTION PKG 25 REF: NDT PART 6/54-50-01	MOS HRS/MSC AFL	4800				PKG 25-JUL-2018 4687.6 3479		
E5450029 (s)	PERFORM * AFT ENGINE BEAM - VISUAL INSPECTION. INSPECT UPPER CAPPING PLATE, AROUND FASTENER HOLES IN THE CAPPING PLATE, AND CHANNEL FLANGE. PKG 25 REF: GENERIC NO REF	MOS HRS/MSC AFL	4800				PKG 25-JUL-2018 4687.6 3479		
F5450019 (s)	PERFORM * AFT ENGINE BEAM ATTACHMENT TO FRAMES - VISUAL INSPECTION. INSPECT AFT ENGINE BEAM ATTACHMENT TO FRAMES. PKG 25 REF: GENERIC NO REF	MOS HRS/MSC AFL	4800				PKG 25-JUL-2018 4687.6 3479		
H5450012 (s)	PERFORM * FRAMES 39/40 (FS 512/518) AT ENGINE BEAM ATTACHMENT - EDDY CURRENT INSPECTION. INSPECT OUTER FLANGE AND FRAME WEB AT ENGINE BEAM ATTACHMENT. PKG 25 REF: NDT PART 6/54-50-03	MOS HRS/MSC AFL	4800				PKG 25-JUL-2018 4687.6 3479		
M5450015 (s)	PERFORM * FORWARD ENGINE BEAM, SPAR CAP, AND WEB - EDDY CURRENT INSPECTION PKG 25 REF: NDT PART 6/54-50-05	MOS HRS/MSC AFL	4800				PKG 25-JUL-2018 4687.6 3479		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
M5450018 (s)	PERFORM * FORWARD ENGINE MOUNT ATTACHMENT BOLTS - FLUORESCENT LIQUID PENETRANT INSPECTION. PKG 25	MOS					PKG	25-JUL-2018	
AIRWORTHINESS	REF: NDT PART 8/71-20-01	HRS/MSC AFL	4800				4687.6 3479		
P5450011 (s)	PERFORM * DRAG STRUT ATTACHMENT FITTINGS - EDDY CURRENT INSPECTION. PKG 25	MOS					PKG	25-JUL-2018	
AIRWORTHINESS	REF: NDT PART 6/53-10-03	HRS/MSC AFL	4800				4687.6 3479		
P5450016 (s)	PERFORM * FORWARD ENGINE BEAM END FITTING - EDDY CURRENT INSPECTION. PKG 25	MOS					PKG	25-JUL-2018	
AIRWORTHINESS	REF: NDT PART 6/54-50-02	HRS/MSC AFL	4800				4687.6 3479		
P5450017 (s)	PERFORM * FORWARD ENGINE BEAM TO FRAME ATTACH BOLTS - LIQUID PENETRANT INSPECTION. PKG 25	MOS					PKG	25-JUL-2018	
AIRWORTHINESS	REF: NDT PART 8/53-40-01	HRS/MSC AFL	4800				4687.6 3479		
P5450021 (s)	PERFORM * ENGINE AFT ISOLATOR MOUNT FITTINGS - LIQUID PENETRANT INSPECTION. PKG 25	MOS					PKG	25-JUL-2018	
AIRWORTHINESS	REF: NDT PART 8/71-20-03	HRS/MSC AFL	4800				4687.6 3479		
P5450024 (s)	PERFORM * FUSELAGE FRAMES AT FS 543.55 AND 546.15 TO AFT BEAM ATTACHMENT - EDDY CURRENT INSPECTION. PKG 25	MOS					PKG	25-JUL-2018	
AIRWORTHINESS	REF: NDT PART 6/53-30-14	HRS/MSC AFL	4800				4687.6 3479		
P5450025 (s)	PERFORM * FORWARD ENGINE BEAM AND FRAMES AT ATTACH HOLES - EDDY CURRENT INSPECTION PKG 25	MOS					PKG	25-JUL-2018	
AIRWORTHINESS	REF: NDT PART 6/54-50-03	HRS/MSC AFL	4800				4687.6 3479		
P5450030 (s)	PERFORM * AFT ENGINE BEAM END FITTING - EDDY CURRENT INSPECTION. PKG 25	MOS					PKG	25-JUL-2018	
AIRWORTHINESS	REF: NDT PART 6/54-50-04	HRS/MSC AFL	4800				4687.6 3479		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y5410002 (s)	PERFORM PYLONS - VISUAL INSPECTION. INSPECT HILITE COLLARS COMMON TO MAIN ENGINE BEAM EXTERNAL TO FUSELAGE						PKG		
	PKG 14	MOS	48	+14d/-14d			23-NOV-2016		
		HRS/MSC	1200	+25/-25			4476		
	REF: AMM 54-00-01	AFL					3270		
CHAPTER 55 STABILIZERS									
5-19-00-M5510010	EDDY CURRENT INSPECTION * HORIZONTAL STABILIZER AFT ROOT RIB. INSPECT AFT ROOT RIB INTERNAL BETWEEN MID SPAR AND AFT SPAR AND UPPER AND LOWER SKINS EXTERNAL AT ATTACHMENT FASTENERS. (REFER TO NDI MANUAL {NDI-104}, PART 6, 55-10-03.)								
		MOS					22-NOV-2019		
		HRS/MSC	1200				4865.4		6065.4
AIRWORTHINESS	REF: NDT PART 6/55-10-03	AFL					3649		
5-19-00-W5510091	PERFORM * HORIZONTAL STABILIZER HINGE PRIMARY AND SECONDARY PIVOT PIN INSTALLATION AND ATTACHING HARDWARE - PERFORM DETAILED VISUAL INSPECTION. (REFER TO 55-10-00.)								
		MOS					17-JUL-2020		
		HRS/MSC	625				4932.3		5557.3
MANDATORY	REF: AMM 55-10-00	AFL							
+ 5510034	HORIZONTAL STABILIZER PRIMARY AND SECONDARY BOLTS AND BUSHINGS - PERFORM DETAILED INSPECTION								
		MOS					25-JUL-2018		
		HRS/MSC	4800	+25/-25			4687.6		9487.6
	REF: AMM 55-10-00	AFL					3479		9512.6
551005	HORIZONTAL STABILIZER ASSEMBLY								
	4555101002-027	MOS					03-APR-2005		
	A0054	HRS/MSC	O/C		N:0		0		
	REF: AMM 27-40-01	AFL			N:0		0		
552031	LEFT ELEVATOR ASSEMBLY								
	4555201001V7003-001	MOS					03-APR-2005		
	A0058	HRS/MSC	O/C		N:0		0		
	REF: AMM 27-30-01	AFL			N:0		0		
552032	RIGHT ELEVATOR ASSEMBLY								
	4555201001V7003-002	MOS					03-APR-2005		
	A0058	HRS/MSC	O/C		N:0		0		
	REF: AMM 27-30-01	AFL			N:0		0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
553000	TAILCONE/VERTICAL STABILIZER ASSEMBLY 4555301001-001 A0053 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
554005	RUDDER ASSEMBLY 4555401000-017 A0061 REF: AMM 27-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
A5510014 (s)	PERFORM * VERTICAL STABILIZER PIVOT FITTING BOTTOM PLATE - DETAILED VISUAL INSPECTION. INSPECT AFT PORTION OF BOTTOM PLATE THROUGH LIGHTENING HOLE IN TOP PLATE, FORWARD PORTION OF BOTTOM PLATE THROUGH TOP PLATE CUTOUTS, AND BOTTOM OF OUTSIDE EXPOSED SURFACE OF PIVOT FITTING. PKG 26 REF: GENERIC NO REF	MOS HRS/MSC AFL	9600				03-APR-2005 0 0		
A5510021 (s)	PERFORM * HORIZONTAL MID SPAR FROM CANTED RIB #2 TO CANTED RIB #3 - DETAILED VISUAL INSPECTION. PKG 26 REF: GENERIC NO REF	MOS HRS/MSC AFL	9600				03-APR-2005 0 0		
A5540000 (s)	PERFORM * RUDDER ROOT RIB CAP (FS 698) - VISUAL INSPECTION. INSPECT AROUND FASTENER HOLES AND LIGHTENING HOLES. PKG 26 REF: GENERIC NO REF	MOS HRS/MSC AFL	9600				03-APR-2005 0 0		
E5510074 (s)	PERFORM * HORIZONTAL STABILIZER REAR SPAR FROM CANTED RIB #2 TO CANTED RIB #3 - VISUAL INSPECTION. INSPECT REAR SPAR CAP AND FASTENERS. PKG 26 REF: GENERIC NO REF	MOS HRS/MSC AFL	9600				03-APR-2005 0 0		
E5510075 (s)	PERFORM * HORIZONTAL STABILIZER OUTBOARD SPARS AND SKINS OUTBOARD OF CANTED RIB #3 - VISUAL INSPECTION. INSPECT SPAR CAPS AND FASTENERS. PKG 26 REF: GENERIC NO REF	MOS HRS/MSC AFL	9600				03-APR-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E5510076 (s)	PERFORM * HORIZONTAL STABILIZER FRONT SPAR FROM CANTED RIB #2 TO CANTED RIB #3 - VISUAL INSPECTION. INSPECT FRONT SPAR CAP AND FASTENERS.						PKG		
	PKG 26	MOS						03-APR-2005	
		HRS/MSC	9600					0	
AIRWORTHINESS	REF: GENERIC NO REF	AFL						0	
E5520003 (s)	PERFORM * ELEVATOR FRONT SPAR - VISUAL INSPECTION. INSPECT SPAR CAP AT FASTENER HOLES.						PKG		
	PKG 26	MOS						03-APR-2005	
		HRS/MSC	9600					0	
AIRWORTHINESS	REF: GENERIC NO REF	AFL						0	
E5520004 (s)	PERFORM * ELEVATOR RIB #1 CAP - VISUAL INSPECTION OF RIB #1 CAP CROSS SECTION AND RIB CAP FLANGES AT TORQUE TUBE.						PKG		
	PKG 26	MOS						03-APR-2005	
		HRS/MSC	9600					0	
AIRWORTHINESS	REF: GENERIC NO REF	AFL						0	
G5510000 (s)	PERFORM * HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTINGS - EDDY CURRENT INSPECTION.						PKG		
	PKG 25	MOS						25-JUL-2018	
		HRS/MSC	4800					4687.6	
AIRWORTHINESS	REF: NDT PART 6/55-10-01	AFL						3479	
G5510023 (s)	PERFORM * HORIZONTAL STABILIZER ACTUATOR VERTICAL TAIL ATTACHMENT - EDDY CURRENT INSPECTION.						PKG		
	PKG 25	MOS						25-JUL-2018	
		HRS/MSC	4800					4687.6	
AIRWORTHINESS	REF: NDT PART 6/55-30-01	AFL						3479	
H5510033 (s)	PERFORM * HORIZONTAL STABILIZER ACTUATOR ATTACHMENT BOLTS - LIQUID PENETRANT INSPECTION.						PKG		
	PKG 25	MOS						25-JUL-2018	
		HRS/MSC	4800					4687.6	
AIRWORTHINESS	REF: NDT PART 8/27-40-01	AFL						3479	
N5510005 (s)	PERFORM * HORIZONTAL STABILIZER REAR SPAR CAP - EDDY CURRENT INSPECTION. INSPECT REAR SPAR CAP AND WEB AT CENTER SPLICE.						PKG		
	PKG 20	MOS	96					23-NOV-2016	
		HRS/MSC	2400					4476	
AIRWORTHINESS	REF: NDT PART 6/55-10-05	AFL						3270	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
N5510015 (s)	PERFORM * VERTICAL STABILIZER PIVOT FITTING TOP PLATE - EDDY CURRENT INSPECTION. PKG 20	MOS	96				PKG	23-NOV-2016	
AIRWORTHINESS	REF: NDT PART 6/55-30-02	HRS/MSC AFL	2400				4476 3270		
N5510016 (s)	PERFORM * VERTICAL STABILIZER PIVOT FITTING TOWER SECTION FORWARD RADIUS - EDDY CURRENT INSPECTION. INSPECT PIVOT FITTING AT TOWER SECTION RADIUS, PIVOT FITTING AND TOP PLATE AROUND ADJACENT FASTENERS, AND PIVOT FITTING SIDES AT TOWER SECTION RADIUS PKG 20	MOS	96				PKG	23-NOV-2016	
AIRWORTHINESS	REF: NDT PART 6/55-30-03	HRS/MSC AFL	2400				4476 3270		
N5510069 (s)	PERFORM * HORIZONTAL STABILIZER MID SPAR FLANGE ROOT RIB ATTACHMENT - EDDY CURRENT INSPECTION PKG 20	MOS	96				PKG	23-NOV-2016	
AIRWORTHINESS	REF: NDT PART 6/55-10-02	HRS/MSC AFL	2400				4476 3270		
N5510082 (s)	PERFORM * HORIZONTAL STABILIZER REAR SPAR FLANGE ROOT RIB ATTACHMENT - EDDY CURRENT INSPECTION PKG 20	MOS	96				PKG	23-NOV-2016	
AIRWORTHINESS	REF: NDT PART 6/55-10-04	HRS/MSC AFL	2400				4476 3270		
P5510006 (s)	PERFORM * VERTICAL STABILIZER FRONT SPAR AND MID SPAR - RADIOGRAPHIC INSPECTION. PKG 26	MOS					PKG	03-APR-2005	
AIRWORTHINESS	REF: NDT PART 2/55-30-01	HRS/MSC AFL	9600				0 0		
P5510008 (s)	PERFORM * HORIZONTAL STABILIZER PRIMARY AND SECONDARY ATTACH BOLTS - MAGNETIC PARTICLE INSPECTION. PKG 26	MOS					PKG	03-APR-2005	
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	9600				0 0		
P5510009 (s)	PERFORM * HORIZONTAL STABILIZER MID SPAR CAP B.L. 0.0 TO B.L. 4.0 - X-RAY INSPECTION. PKG 20	MOS	96				PKG	23-NOV-2016	
AIRWORTHINESS	REF: NDT PART 2/55-10-03	HRS/MSC AFL	2400				4476 3270		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P5510011 (s)	PERFORM * HORIZONTAL STABILIZER MID-SPAR AND REAR-SPAR UPPER FLANGE AT ROOT RIB - RADIOGRAPHIC INSPECTION. PKG 26	MOS					PKG	03-APR-2005	
AIRWORTHINESS	REF: NDT PART 2/55-10-01	HRS/MSC AFL	9600				0	0	
P5510017 (s)	PERFORM * VERTICAL STABILIZER PIVOT FITTING TOWER SECTION - EDDY CURRENT INSPECTION PKG 20	MOS	96				PKG	23-NOV-2016	
AIRWORTHINESS	REF: NDT PART 6/55-30-05	HRS/MSC AFL	2400				4476	3270	
P5510018 (s)	PERFORM * VERTICAL STABILIZER PIVOT FITTING LUGS - EDDY CURRENT INSPECTION. PKG 26	MOS					PKG	03-APR-2005	
AIRWORTHINESS	REF: NDT PART 6/55-30-04	HRS/MSC AFL	9600				0	0	
P5510019 (s)	PERFORM * ELEVATOR HINGES ON HORIZONTAL STABILIZER - EDDY CURRENT INSPECTION. PKG 26	MOS					PKG	03-APR-2005	
AIRWORTHINESS	REF: NDT PART 6/55-20-02	HRS/MSC AFL	9600				0	0	
P5510020 (s)	PERFORM * HORIZONTAL MID-SPAR UPPER CAP - EDDY CURRENT INSPECTION. PKG 26	MOS					PKG	03-APR-2005	
AIRWORTHINESS	REF: NDT PART 6/55-10-07	HRS/MSC AFL	9600				0	0	
P5510024 (s)	PERFORM * ELEVATOR CONTROL HORN - EDDY CURRENT INSPECTION. PKG 26	MOS					PKG	03-APR-2005	
AIRWORTHINESS	REF: NDT PART 6/55-20-01	HRS/MSC AFL	9600				0	0	
P5510070 (s)	PERFORM * HORIZONTAL STABILIZER FRONT SPAR - RADIOGRAPHIC INSPECTION. PKG 26	MOS					PKG	03-APR-2005	
AIRWORTHINESS	REF: NDT PART 2/55-10-02	HRS/MSC AFL	9600				0	0	
P5510073 (s)	PERFORM * HORIZONTAL REAR SPAR UPPER CAP - EDDY CURRENT INSPECTION. PKG 26	MOS					PKG	03-APR-2005	
AIRWORTHINESS	REF: NDT PART 6/55-10-07	HRS/MSC AFL	9600				0	0	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P5510092 (s)	PERFORM * HORIZONTAL STABILIZER UPPER-SPAR-SPLICE DOUBLER - EDDY CURRENT INSPECTION. PKG 20	MOS	96				PKG	23-NOV-2016	
AIRWORTHINESS	REF: NDT PART 6/55-10-06	HRS/MSC AFL	2400				4476 3270		
P5520001 (s)	PERFORM * ELEVATOR HINGE ATTACH BOLT - MAGNETIC PARTICLE INSPECTION. PKG 26	MOS					PKG	03-APR-2005	
AIRWORTHINESS	REF: NDT PART 7/27-30-01	HRS/MSC AFL	9600				0 0		
P5520002 (s)	PERFORM * ELEVATOR HINGE PIN - LIQUID PENETRANT INSPECTION. (EFFECTIVE ON AIRCRAFT 45-001 THRU 45-014) PKG 26	MOS					PKG	03-APR-2005	
AIRWORTHINESS	REF: NDT PART 8/55-30-01	HRS/MSC AFL	9600				0 0		
P5520021 (s)	PERFORM * ELEVATOR HINGE FITTINGS - EDDY CURRENT INSPECTION. (EFFECTIVE ON AIRCRAFT 45-015 AND SUBSEQUENT.) PKG 26	MOS					PKG	03-APR-2005	
AIRWORTHINESS	REF: NDT PART 6/55-30-07	HRS/MSC AFL	9600				0 0		
P5520022 (s)	PERFORM * ELEVATOR HINGE PRIMARY AND SECONDARY ATTACH BOLTS - LIQUID PENETRANT INSPECTION. PKG 26	MOS					PKG	03-APR-2005	
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	9600				0 0		
P5540001 (s)	PERFORM * RUDDER SPAR - DETAILED VISUAL INSPECTION. INSPECT SPAR CAPS AND FASTENERS. PKG 26	MOS					PKG	03-APR-2005	
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC AFL	9600				0 0		
P5540002 (s)	PERFORM * RUDDER ATTACH BOLT - LIQUID PENETRANT INSPECTION. PKG 26	MOS					PKG	03-APR-2005	
AIRWORTHINESS	REF: NDT PART 8/55-30-02	HRS/MSC AFL	9600				0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Q5510007 (s)	PERFORM * VERTICAL STABILIZER SKIN AND LOWER AFT SPAR CAP - EDDY CURRENT INSPECTION. PKG 26	MOS					PKG	03-APR-2005	
AIRWORTHINESS	REF: NDT PART 6/55-30-06	HRS/MSC AFL	9600				0 0		
Q5530011 (s)	PERFORM * VERTICAL STABILIZER SKIN AND UPPER AFT SPAR CAP - EDDY CURRENT INSPECTION. PKG 20	MOS	96				PKG	23-NOV-2016	
AIRWORTHINESS	REF: NDT PART 6/55-30-06	HRS/MSC AFL	2400				4476 3270		
T5510004 (s)	PERFORM * RUDDER HINGE FITTINGS - VISUAL INSPECTION. CONTROL SURFACE REMOVAL NOT REQUIRED. PKG 26	MOS					PKG	03-APR-2005	
AIRWORTHINESS	REF:	HRS/MSC AFL	9600				0 0		
Y5510001 (s)	PERFORM HORIZONTAL STABILIZER - EXTERNAL VISUAL INSPECTION PKG 14	MOS	48	+14d/-14d			PKG	23-NOV-2016	
	REF: AMM 05-10-00	HRS/MSC AFL	1200	+25/-25			4476 3270		
Y5510002 (s)	PERFORM ELEVATOR HINGES ON HORIZONTAL STABILIZER - VISUAL INSPECTION. INSPECT HINGE LUGS ON HORIZONTAL TAIL SIDE OF JOINT. INSPECT HILITE COLLARS AT BL 0.0 AND OUTBOARD ELEVATOR HINGE PKG 14	MOS	48	+14d/-14d			PKG	23-NOV-2016	
	REF: AMM 55-10-01	HRS/MSC AFL	1200	+25/-25			4476 3270		
Y5510003 (s)	PERFORM VERTICAL STABILIZER PIVOT FITTING - VISUAL INSPECTION. INSPECT HILITE COLLARS COMMON TO THE PIVOT FITTING (MID SPAR, AFT SPAR, TOP PLATE, AND UP/DOWN SPRING BRACKET). PKG 14	MOS	48	+14d/-14d			PKG	23-NOV-2016	
	REF: AMM 55-00-01	HRS/MSC AFL	1200	+25/-25			4476 3270		
Y5510093 (s)	PERFORM HORIZONTAL STABILIZER - VISUAL INSPECTION OF HILITE COLLARS IN THE FOLLOWING AREAS:- FORWARD SPAR TO BL 0.0 RIB.- CENTER SPAR TO BL 0.0 RIB.- CENTER SPAR SPLICE PLATE.- AFT SPAR SPLICE PLATE.- ROOT RIBS AT BL 3.70 (RIGHT AND LEFT).- UPPER DOUBLER SPAR SPLICE, BL 0.0.- HSTA UPPER ATTACH FITTING STRUCTURE PKG 14	MOS	48	+14d/-14d			PKG	23-NOV-2016	
	REF: AMM 55-00-01	HRS/MSC AFL	1200	+25/-25			4476 3270		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y5510094 (s)	PERFORM LOWER BRACKET, HORIZONTAL STABILIZER TRIM ACTUATOR - BORESCOPE INSPECTION OF HILITE COLLARS COMMON TO RIB # 6 AND MID SPAR PKG 14 REF: AMM 55-10-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			23-NOV-2016 4476 3270		
Y5540012 (s)	RUDDER TORQUE TUBE - LOOSEN TORQUE TUBE BONDING CLAMP AND PERFORM DETAILED VISUAL INSPECTION OF AREA AROUND BONDING CLAMP FOR CORROSION. NOTE: PERFORM BONDING CHECK OF CLAMP AND BONDING JUMPERS AFTER REINSTALLATION OF CLAMP. PKG 2 REF: AMM 27-20-01	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			17-JUL-2020 4932.3		
CHAPTER 56 WINDOWS									
5-19-00-W5600002	** WINDSHIELD - PERFORM RAIN REMOVAL COATING EFFECTIVENESS TEST (IRN W5600002)	MOS HRS/MSC AFL	12	+14d/-14d		-60	01-MAR-2020 4900.9 3686	31-DEC-2020	14-JAN-2021
AIRWORTHINESS	REF: See Workcard								
561001	LEFT WINDSHIELD ASSEMBLY 173600-23 3645 REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0		11-OCT-2017 4589.5 3375		
+ 561001A	ULTRASONIC-INSPECTION LEFT WINDSHIELD ASSEMBLY STRUCTURAL PLYS (IRN N5600003)	MOS HRS/MSC AFL	4800				11-OCT-2017 4589.5 3375	9389.5	
AIRWORTHINESS	REF: NDT PART 4/56-10-01								
561001B	PERFORM INSPECTION LEFT WINDSHIELD ASSEMBLY BOLT HOLES (IRN N5600012)	MOS HRS/MSC AFL	N/A				11-OCT-2017 4589.5 3375		
AIRWORTHINESS	REF: AMM 56-10-01								
561002	RIGHT WINDSHIELD ASSEMBLY 173600-24 2132 REF: See Workcard	MOS HRS/MSC AFL	O/C				24-AUG-2018 4698.7 3487		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 561002A	ULTRASONIC-INSPECTION RIGHT WINDSHIELD ASSEMBLY STRUCTURAL PLIES (IRN N5600003)	MOS					24-AUG-2018		
AIRWORTHINESS	REF: NDT PART 4/56-10-01	HRS/MSC AFL	4800				4698.7 3487	9498.7	
561002B	PERFORM INSPECTION RIGHT WINDSHIELD ASSEMBLY BOLT HOLE (IRN N5600012)	MOS					24-AUG-2018		
AIRWORTHINESS	REF: AMM 56-10-01	HRS/MSC AFL	N/A				4698.7 3487		
L5600010 (s)	PERFORM * CABIN WINDOWS (INCLUDING THE EMERGENCY EXIT WINDOW) - DETAILED VISUAL INSPECTION	MOS					25-JUL-2018		
AIRWORTHINESS	PKG 25 REF: GENERIC NO REF	HRS/MSC AFL	4800				4687.6 3479		
Y5600000 (s)	WINDSHIELDS - PERFORM VISUAL INSPECTION (INTERIOR AND EXTERIOR)	MOS	12	+14d/-14d			17-JUL-2020		
	PKG 1	HRS/MSC AFL	300	+25/-25			4932.3		
	REF: AMM 05-10-00								
Y5600001 (s)	CABIN WINDOWS - PERFORM VISUAL INSPECTION	MOS	24	+14d/-14d			17-JUL-2020		
	PKG 7	HRS/MSC AFL	600	+25/-25			4932.3		
	REF: AMM 05-10-00								
Y5600013 (s)	WINDSHIELDS - PERFORM VISUAL INSPECTION OF THE AERODYNAMIC SEAL. IF REPAIRS TO THE SEAL ARE NEEDED, REFER TO 56-10-01.	MOS	12	+14d/-14d			17-JUL-2020		
	PKG 1	HRS/MSC AFL	300	+25/-25			4932.3		
	REF: See Workcard								
CHAPTER 57 WINGS									
5-19-00-E5750051	VISUALLY INSPECT * FLAP MAIN TRACK ROLLERS WITH FLAPS REMOVED (IRN E5750051)	MOS					03-APR-2005		
AIRWORTHINESS	REF: AMM 05-10-00	HRS/MSC AFL	10000				0 0	10000	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-E5750052	VISUALLY INSPECT * FLAP NOSE ROLLERS WITH FLAPS REMOVED (IRN E5750052)	MOS					03-APR-2005		
AIRWORTHINESS	REF: AMM 05-10-00	HRS/MSC AFL	7200				0 0	7200	
5-19-00-N5710002	VISUALLY INSPECT * WING BOX MID SPAR LOWER CAP, OUTBOARD OF JOINT AT WS 137 BETWEEN RIBS 7 AND 8. N5710002 (PRE SB 45-11-5)	MOS							
AIRWORTHINESS	REF: AMM 05-10-00	HRS/MSC AFL	9600					9600	
5-19-00-N5710008	NON DESTRUCTIVE INSPECT * WING BOX SPAR LOWER CAP - PERFORM NDI INSPECTION. N5710008 (PRE SB 45-11-5)	MOS							
AIRWORTHINESS	REF: NDT PART 4/57-30-03	HRS/MSC AFL	9600					9600	
5-19-00-N5710009	NON DESTRUCTIVE TEST * WING BOX MID SPAR LOWER CAP JOINT AT WS 137 - PERFORM NDI INSPECTION. N5710009 (PRE SB 45-11-5)	MOS							
AIRWORTHINESS	REF: NDT PART 2/57-10-02	HRS/MSC AFL	9600					9600	
5-19-00-N5710010	NON DESTRUCTIVE INSPECT * WING BOX REAR SPAR LOWER CAP INBOARD OF JOINT WS 81 - PERFORM NDI INSPECTION. N5710010 (PRE SB 45-11-5)	MOS					03-APR-2005		
AIRWORTHINESS	REF: NDT PART 4/57-30-01	HRS/MSC AFL	9600				0 0	9600	
5-19-00-N5710012	* WING BOX REAR SPAR LOWER CAP OUTBOARD OF JOINT AT WS 81 TO RIB #6 - PERFORM DETAILED VISUAL INSPECTION. INSPECT OUTER REAR SPAR LOWER CAP AND AFT LOWER SKIN PANEL OUTBOARD OF REAR SPLICE AT WS 90. (REFER TO 5-10-00.) (EFFECTIVE ON AIRCRAFT NOT MODIFIED BY SB 45-11-5, "INCREASE MAXIMUM ZERO FUEL WEIGHT (16,500 POUNDS).")	MOS					03-APR-2005		
AIRWORTHINESS	REF: AMM 05-10-00	HRS/MSC AFL	9600				0 0	9600	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-N5710013	NON DESTRUCTIVE INSPECT * WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM NDI INSPECTION. N5710013 (PRE SB 45-11-5)	MOS					03-APR-2005		
AIRWORTHINESS	REF: NDT PART 6/57-20-04	HRS/MSC AFL	10000				0 0	10000	
5-19-00-N5710026	NON DESTRUCTIVE INSPECT * WING BOX SPAR LOWER CAP - PERFORM NDI INSPECTION. INSPECT MID SPAR LOWER CAP OUTBOARD OF ROOT RIB AT WS 33 TO WS 99. N5710026 (PRE SB 45-11-5)	MOS							
AIRWORTHINESS	REF: NDT PART 4/57-30-03	HRS/MSC AFL	10000					10000	
5-19-00-N5710123	EDDY CURRENT INSPECT * WING BOX MID SPAR LOWER CAP AT TRUNNION FITTING - PERFORM EDDY CURRENT INSPECTION AT TRUNNION FITTING. N5710123 (PRE SB 45-11-5)	MOS					03-APR-2005		
AIRWORTHINESS	REF: NDT PART 6/57-10-01	HRS/MSC AFL	9600				0 0	9600	
5-19-00-N5710148	EDDY CURRENT INSPECTION * WING CENTER SECTION REAR SPAR - PERFORM EDDY CURRENT INSPECTION, INSPECT REAR SPAR LOWER CAP FROM CENTERLINE TO WS 33 N5710148 (POST SB 45-11-5)	MOS					03-APR-2005		
	REF: NDT PART 6/57-20-02	HRS/MSC AFL	N/A				0 0		
5-19-00-N5710149	EDDY CURRENT INSPECTION * WING CENTER SECTION FORWARD AND AFT RIBS AT WS6 AND FORWARD RIBS AT WS 17 - PERFORM EDDY CURRENT INSPECTION. N5710149 (POST SB 45-11-5)	MOS					03-APR-2005		
	REF: NDT PART 6/57-10-06	HRS/MSC AFL	N/A				0 0		
5-19-00-N5710150	ULTRASONIC-INSPECTION * WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION, INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS BETWEEN WS99 AND WS137. N5710150 (POST SB 45-11-5)	MOS					03-APR-2005		
	REF: NDT PART 4/57-30-03	HRS/MSC AFL	N/A				0 0		
5-19-00-N5710151	X-RAY INSPECTION * WING BOX MID SPAR LOWER CAP JOINT AT WS137 - PERFORM X-RAY INSPECTION. INSPECT MID SPAR CENTER/OUTER JOINT. N5710151 (POST SB 45-11-5)	MOS					03-APR-2005		
	REF: NDT PART 2/57-10-02	HRS/MSC AFL	N/A				0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-N5710152	ULTRASONIC-INSPECTION * WING BOX REAR SPAR LOWER CAP INBOARD OF JOINT AT WS81 - PERFORM ULTRASONIC INSPECTION, INSPECT REAR SPAR LOWER CAP BETWEEN SKIN TERMINATION AT WS 48 CLOSING RIB AT WS 60. N5710152 (POST SB 45-11-5)	MOS					03-APR-2005		
	REF: NDT PART 4/57-30-01	HRS/MSC	N/A				0		
		AFL					0		
5-19-00-N5710153	X-RAY INSPECTION * WING BOX REAR SPAR LOWER CAP JOINT AT WS 81 - PERFORM X-RAY INSPECTION. INSPECT CENTER AND OUTER REAR SPARS, LOWER SPLICE PLATE, AND LOWER SKIN BETWEEN WS 60 AND WS 90. N5710153 (POST SB 45-11-5)	MOS					03-APR-2005		
	REF: NDT PART 2/57-10-03	HRS/MSC	N/A				0		
		AFL					0		
5-19-00-N5710155	EDDY CURRENT INSPECTION * WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS33 AND WS 48. N5710155 (POST SB 45-11-5)	MOS					03-APR-2005		
	REF: NDT PART 6/57-20-04	HRS/MSC	N/A				0		
		AFL					0		
5-19-00-N5710158	EDDY CURRENT INSPECTION * CENTER SECTION FRONT SPAR LOWER CAP - PEFORM EDDY CURRENT INSPECTION. INSPECT CENTER WING FRONT SPAR LOWER CAP BETWEEN SKIN TERMINATIONS (WS31 LEFT TO WS31 RIGHT) N5710158 (POST SB 45-11-5)	MOS					03-APR-2005		
	REF: NDT PART 6/57-10-03	HRS/MSC	N/A				0		
		AFL					0		
5-19-00-N5710159	ULTRASONIC-INSPECTION * WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION. INSPECT MID SPAR LOWER CAP OUTBOARD OF ROOT RIB AT WS 33 TO WS 99. N5710159 (POST SB 45-11-5)	MOS					03-APR-2005		
	REF: NDT PART 4/57-30-03	HRS/MSC	N/A				0		
		AFL					0		
5-19-00-N5710160	EDDY CURRENT INSPECTION * WING BOX MID SPAR LOWER CAP, SKIN TERMINATION AT WS 33 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION. INSPECT MID SPAR LOWER CAP UNDERNEATH ROOT RIB (WS 33) AT POINT OF SKIN TERMINATION. N5710160 (POST SB 45-11-5)	MOS					03-APR-2005		
	REF: NDT PART 6/57-10-11	HRS/MSC	N/A				0		
		AFL					0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-N5710163	EDDY CURRENT INSPECTION * CENTER SECTION MID SPAR CENTERLINE JOINT - PERFORM EDDY CURRENT INSPECTION. INSPECT CENTER MID SPAR (CENTERLINE TO WS 17), LOWER SPLICE PLATE, AND CENTER MID SPAR JOINT FITTING LOWER CAP. N5710163 (POST SB 45-11-5)	MOS						03-APR-2005	
NOT APPLICABLE	REF: See Workcard	HRS/MSC	N/A					0	
		AFL						0	
5-19-00-N5710164	EDDY CURRENT INSPECTION * CENTER SECTION MID SPAR LOWER CAP - PEFORM EDDY CURRENT INSPECTION. INSPECT MID SPAR FROM CENTERLINE SPLICE PLATE TO SKIN TERMINATION AT MS 33. N5710164 (POST SB 45-11-5)	MOS						03-APR-2005	
	REF: NDT PART 6/57-10-02	HRS/MSC	N/A					0	
		AFL						0	
5-19-00-N5710165	EDDY CURRENT INSPECTION * WING BOX REAR SPAR FLAP TRACK CUT-OUTS - PERFORM EDDY CURRENT INSPECTION. INSPECT FLAP TRACK CUT-OUTS AT WS65, WS 126 AND WS184 ON REAR SPAR. N5710165 (POST SB 45-11-5)	MOS						03-APR-2005	
	REF: NDT PART 6/57-20-01	HRS/MSC	N/A					0	
		AFL						0	
5-19-00-N5710168	EDDY CURRENT INSPECTION * WING BOX MID SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION AT TRUNNION FITTING. N5710168 (POST SB 45-11-5)	MOS						03-APR-2005	
	REF: NDT PART 6/57-10-01	HRS/MSC	N/A					0	
		AFL						0	
5-19-00-N5710169	EDDY CURRENT INSPECTION * MID SPAR AT RIB #2 NEAR WS48 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION. N5710169 (POST SB 45-11-5)	MOS						03-APR-2005	
	REF: NDT PART 6/57-10-11	HRS/MSC	N/A					0	
		AFL						0	
5-19-00-N5710170	EDDY CURRENT INSPECTION * MID SPAR AT RIB #3 NEAR WS60 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION. N5710170 (POST SB 45-11-5)	MOS						03-APR-2005	
	REF: NDT PART 6/57-10-11	HRS/MSC	N/A					0	
		AFL						0	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-N5710171	EDDY CURRENT INSPECTION * FORWARD FLANGE FASTENERS AT REAR SPAR BETWEEN WS 52 AND WS 60 - PEROFRM BOLT HOLE EDDY CURRENT INSPECTION. N5710171 (POST SB 45-11-5)	MOS HRS/MSC AFL	N/A				03-APR-2005 0 0		
	REF: NDT PART 6/57-20-03								
5-19-00-N5710172	ULTRASONIC-INSPECTION * WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION AT TRUNNION FITTING. N5710172 (PRE SB 45-11-5)	MOS HRS/MSC AFL	9600				0	9600	
	REF: NDT PART 4/57-10-00								
5-19-00-N5710173	ULTRASONIC-INSPECTION * WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION AT TRUNNION FITTING. N5710173 (POST SB 45-11-5)	MOS HRS/MSC AFL	N/A				03-APR-2005 0 0		
	REF: NDT PART 4/57-10-00								
5-19-00-N5710174	ULTRASONIC-INSPECTION * WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT WS 48 - PEFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48. N5710174 (PRE SB 45-11-5)	MOS HRS/MSC AFL	10000					10000	
	REF: NDT PART 4/57-30-04								
5-19-00-N5710175	ULTRASONIC-INSPECTION * WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48. N5710175 (POST SB 45-11-5)	MOS HRS/MSC AFL	N/A				03-APR-2005 0 0		
	REF: NDT PART 4/57-30-04								
5-19-00-N5710177	ULTRASONIC-INSPECTION * WING MID SPAR (CENTER SECTION) LOWER CAP AND CENTER JOINT FITTING - PERFORM ULTRASONIC INSPECTION. N5710177 (POST SB 45-11-5)	MOS HRS/MSC AFL	N/A				03-APR-2005 0 0		
	REF: NDT PART 4/57-30-05								
571001	WING ASSEMBLY	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
	4557000004-001 676091600293 REF: AMM 57-10-00								

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 5710190	LEFT WING CENTER SECTION (PANELS 510AC, 510BC, 510BL AND 610BR REMOVED AND PANELS 510AL, 610AR, 720BL, AND 730BR LOWERED) - PERFORM VISUAL INSPECTION. INSPECT STRUCTURE FOR CORROSION OR DETERIORATION OF PROTECTIVE TREATMENT.	MOS HRS/MSC AFL	96	+14d/-14d			30-MAR-2020 4909.4 3693	30-MAR-2028	13-APR-2028
	REF: GENERIC NO REF								
+ 5710190	RIGHT WING CENTER SECTION (PANELS 510AC, 510BC, 510BL AND 610BR REMOVED AND PANELS 510AL, 610AR, 720BL, AND 730BR LOWERED) - PERFORM VISUAL INSPECTION. INSPECT STRUCTURE FOR CORROSION OR DETERIORATION OF PROTECTIVE TREATMENT.	MOS HRS/MSC AFL	96	+14d/-14d			30-MAR-2020 4909.4 3693	30-MAR-2028	13-APR-2028
	REF: GENERIC NO REF								
573090	LEFT WING WINGLET 4557300006-001/00 675844800293 REF: AMM 57-30-01	MOS HRS/MSC AFL			N:0 N:0 N:0		03-APR-2005 0 0		
573092	RIGHT WING WINGLET 4557300006-002/00 675847100293 REF: AMM 57-30-01	MOS HRS/MSC AFL			N:0 N:0 N:0		03-APR-2005 0 0		
574005	LEFT INBOARD LEADING EDGE 4557400005-013 223914400293 REF: AMM 57-40-01	MOS HRS/MSC AFL			N:0 N:0 N:0		03-APR-2005 0 0		
574007	RIGHT INBOARD LEADING EDGE 4557400005-014 221932300293 REF: AMM 57-40-01	MOS HRS/MSC AFL			N:0 N:0 N:0		03-APR-2005 0 0		
574011	LEFT INBOARD LEADING EDGE ACCESS SECTION 4557400005-031 291282600293 REF: AMM 57-40-01	MOS HRS/MSC AFL			N:0 N:0 N:0		03-APR-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
574013	RIGHT INBOARD LEADING EDGE ACCESS SECTION 4557400005-032 277553000293 REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
574033	LEFT CENTER LEADING EDGE 4557400005-033V0968 629737200300 REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
574035	RIGHT CENTER LEADING EDGE 4557400005-034V0972 666976000301 REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
574039	LEFT OUTBOARD LEADING EDGE ACCESS SECTION 4557400005-045 551214100293 REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
574041	RIGHT OUTBOARD LEADING EDGE ACCESS SECTION 4557400005-044 220286900293 REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
574050	LEFT OUTBOARD LEADING EDGE 4557400005-043 473401700293 REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
574051	RIGHT OUTBOARD LEADING EDGE 4557400005-046 219955900293 REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
575001	LEFT FLAP ASSEMBLY 4557500006-007 6760081400293 REF: AMM 27-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
575002	RIGHT FLAP ASSEMBLY 4557500006-008 735643400309 REF: AMM 27-50-01	MOS HRS/MSC AFL	O/C				19-FEB-2010 2597.47 1810		
576001	LEFTAILERON 4557600003-001 PMF676094000293 REF: AMM 27-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
576002	RIGHTAILERON 4557600003-002 PMF676096500293 REF: AMM 27-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
+ 576037	REPLACE LEFTAILERON (ZONE/ACCESS 540/640 *IRN # A5760004) BOLTS PN SN-UNKNOWN REF: AMM 27-10-02	MOS HRS/MSC AFL	9600	N:0 N:0 N:0			03-APR-2005 0 0	9600	
+ 576038	REPLACE RIGHTAILERON (ZONE/ACCESS 540/640 *IRN # A5760004) BOLTS PN SN-UNKNOWN REF: AMM 27-10-02	MOS HRS/MSC AFL	9600	N:0 N:0 N:0			03-APR-2005 0 0	9600	
577001	LEFTSPOILER 4557700003-021 0340 REF: AMM 27-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
577002	RIGHTSPOILER 4557700003-022 0347 REF: AMM 27-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
E5710005 (s)	PERFORM * WING CENTER SECTION SPAR UPPER CAPS - VISUAL INSPECTION. INSPECT FRONT, MID, AND REAR SPAR UPPER CAPS FROM CENTERLINE TO SKIN TERMINATION AT WS 33. PKG 26 REF: GENERIC NO REF	MOS HRS/MSC AFL	9600				03-APR-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E5710019 (s)	PERFORM * WING BOX, UPPER SKIN, SKIN/STRINGER AND SPAR CAPS - VISUAL INSPECTION. INSPECT UPPER WING SPAR CAPS, SKIN PANEL, AND STRINGERS OF OUTER WING						PKG		
	PKG 26	MOS					03-APR-2005		
		HRS/MSC	9600				0		
AIRWORTHINESS	REF: GENERIC NO REF	AFL					0		
E5710020 (s)	PERFORM * WING BOX RIBS - VISUAL INSPECTION. INSPECT ALL WING BOX RIBS EXCEPT CLOSING RIB BETWEEN FRONT AND MID SPARS AND CLOSING RIB BETWEEN MID AND REAR SPAR.						PKG		
	PKG 26	MOS					03-APR-2005		
		HRS/MSC	9600				0		
AIRWORTHINESS	REF: GENERIC NO REF	AFL					0		
E5760006 (s)	PERFORM * AILERON BASIC STRUCTURE - VISUAL INSPECTION						PKG		
	PKG 26	MOS					03-APR-2005		
		HRS/MSC	9600				0		
AIRWORTHINESS	REF: GENERIC NO REF	AFL					0		
L5710124 (s)	PERFORM * AILERON DRIVE SUPPORT - ULTRASONIC INSPECTION.						PKG		
	PKG 25	MOS					25-JUL-2018		
		HRS/MSC	4800				4687.6		
AIRWORTHINESS	REF: NDT PART 4/27-10-01	AFL					3479		
N5710004 (s)	PERFORM * WING CENTER SECTION REAR SPAR - EDDY CURRENT INSPECTION. INSPECT REAR SPAR LOWER CAP FROM CENTERLINE TO WS 33. (PRE SB 45-11-5)						PKG		
	PKG 25	MOS					25-JUL-2018		
		HRS/MSC	4800				4687.6		
AIRWORTHINESS	REF: NDT PART 6/57-20-02	AFL					3479		
N5710006 (s)	PERFORM * WING CENTER SECTION FORWARD AND AFT RIBS AT WS 6 AND FORWARD RIBS AT WS 17 - EDDY CURRENT INSPECTION. (PRE SB 45-11-5)						PKG		
	PKG 25	MOS					25-JUL-2018		
		HRS/MSC	4800				4687.6		
AIRWORTHINESS	REF: NDT PART 6/57-10-06	AFL					3479		
N5710011 (s)	PERFORM * WING BOX REAR SPAR LOWER CAP JOINT AT WS 81 - X-RAY INSPECTION. INSPECT CENTER AND OUTER REAR SPARS, LOWER SPLICE PLATE, AND LOWER SKIN BETWEEN WS 60 AND WS 90. (PRE SB 45-11-5)						PKG		
	PKG 22	MOS	96				23-NOV-2016		
		HRS/MSC	2400				4476		
AIRWORTHINESS	REF: NDT PART 2/57-10-03	AFL					3270		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
N5710014 (s)	PERFORM * WING BOX REAR SPAR FLAP TRACK CUTOUTS - EDDY CURRENT INSPECTION. INSPECT FLAP TRACK CUTOUTS AT WS 65, WS 126, AND WS 184 ON REAR SPAR. (PRE SB 45-11-5)						PKG		
	PKG 25	MOS						25-JUL-2018	
AIRWORTHINESS	REF: NDT PART 6/57-20-01	HRS/MSC	4800					4687.6	
		AFL						3479	
N5710016 (s)	PERFORM * WING BOX BASIC SKIN/STRINGER, LOWER SKIN - VISUAL INSPECTION. INSPECT OUTBOARD WING FORWARD AND AFT LOWER SKIN PANELS AND STRINGERS. (PRE SB 45-11-5)						PKG		
	PKG 25	MOS						25-JUL-2018	
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	4800					4687.6	
		AFL						3479	
N5710017 (s)	PERFORM * WING BOX BASIC SKIN/STRINGER AT STRINGER RUN-OUT, LOWER SKIN - VISUAL INSPECTION. INSPECT STRINGER RUN-OUTS IN FORWARD AND AFT LOWER SKIN PANELS. (PRE SB 45-11-5)						PKG		
	PKG 26	MOS						03-APR-2005	
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	9600					0	
		AFL						0	
N5710021 (s)	PERFORM * CENTER SECTION MID SPAR LOWER CAP - EDDY CURRENT INSPECTION. INSPECT MID SPAR FROM CENTERLINE SPLICE PLATE TO SKIN TERMINATION AT MS 33 (PRE SB 45-11-5)						PKG		
	PKG 22	MOS	96					23-NOV-2016	
AIRWORTHINESS	REF: NDT PART 6/57-10-02	HRS/MSC	2400					4476	
		AFL						3270	
N5710022 (s)	PERFORM * CENTER SECTION MID SPAR CENTERLINE JOINT - EDDY CURRENT INSPECTION. INSPECT CENTER MID SPAR (CENTERLINE TO WS 17), LOWER SPLICE PLATE, AND CENTER MID SPAR JOINT FITTING LOWER CAP. (PRE SB 45-11-5)						PKG		
	PKG 22	MOS	96					23-NOV-2016	
AIRWORTHINESS	REF: See Workcard	HRS/MSC	2400					4476	
		AFL						3270	
N5710023 (s)	PERFORM * CENTER SECTION FRONT SPAR LOWER CAP - EDDY CURRENT INSPECTION. INSPECT CENTER WING FRONT SPAR LOWER CAP BETWEEN SKIN TERMINATIONS(WWS 31 LEFT TO WS 31 RIGHT). (PRE SB 45-11-5)						PKG		
	PKG 22	MOS	96					23-NOV-2016	
AIRWORTHINESS	REF: NDT PART 6/57-10-03	HRS/MSC	2400					4476	
		AFL						3270	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
N5710028 (s)	PERFORM * WING BOX MID SPAR LOWER CAP, SKIN TERMINATION AT WS 33 - BOLT HOLE EDDY CURRENT INSPECTION. INSPECT MID SPAR LOWER CAP UNDERNEATH ROOT RIB (WS 33) AT POINT OF SKIN TERMINATION. (PRE SB 45-11-5)						PKG		
	PKG 25	MOS						25-JUL-2018	
AIRWORTHINESS	REF: NDT PART 6/57-10-11	HRS/MSC	4800					4687.6	
		AFL						3479	
N5710031 (s)	PERFORM * WING BOX SKIN ACCESS COVER HOLES - EDDY CURRENT INSPECTION. INSPECT ACCESS HOLES IN FORWARD AND AFT LOWER SKIN PANELS. (PRE SB 45-11-5)						PKG		
	PKG 25	MOS						25-JUL-2018	
AIRWORTHINESS	REF: NDT PART 6/57-30-01	HRS/MSC	4800					4687.6	
		AFL						3479	
N5710037 (s)	PERFORM * WING BOX FRONT SPAR LOWER CAP - VISUAL INSPECTION. INSPECT FRONT SPAR LOWER CAP AND LOWER FORWARD SKIN OUTBOARD OF MID-SPAR STATION(MS) 55. (PRE SB 45-11-5)						PKG		
	PKG 22	MOS	96					23-NOV-2016	
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	2400					4476	
		AFL						3270	
N5710084 (s)	PERFORM SPOILER, CENTER HINGE SPOILER SIDE - NDI INSPECTION.						PKG		
	PKG 22	MOS	96	+14d/-14d				23-NOV-2016	
		HRS/MSC	2400	+25/-25				4476	
	REF: NDT PART 6/57-40-01	AFL						3270	
N5710121 (s)	PERFORM * WING BOX MID SPAR, OUTBOARD OF RIB #8 - VISUAL INSPECTION AT WS 156 AND OUTBOARD TO WS 260. (PRE SB 45-11-5)						PKG		
	PKG 25	MOS						25-JUL-2018	
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	4800					4687.6	
		AFL						3479	
N5710122 (s)	PERFORM * WING BOX REAR SPAR, OUTBOARD OF RIB #6 - VISUAL INSPECTION AT WS 118 AND OUTBOARD TO WS 260. (PRE SB 45-11-5)						PKG		
	PKG 25	MOS						25-JUL-2018	
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	4800					4687.6	
		AFL						3479	
N5710137 (s)	PERFORM * MID SPAR AT RIB #2 NEAR WS 48 - BOLT HOLE EDDY CURRENT INSPECTION. (PRE SB 45-11-5)						PKG		
	PKG 25	MOS						25-JUL-2018	
AIRWORTHINESS	REF: NDT PART 6/57-10-11	HRS/MSC	4800					4687.6	
		AFL						3479	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
N5710138 (s)	PERFORM * MID SPAR AT RIB #3 NEAR WS 60 - BOLT HOLE EDDY CURRENT INSPECTION. (PRE SB 45-11-5)						PKG		
	PKG 25	MOS						25-JUL-2018	
AIRWORTHINESS	REF: NDT PART 6/57-10-11	HRS/MSC	4800					4687.6	
		AFL						3479	
N5710139 (s)	PERFORM * FORWARD FLANGE FASTENERS AT REAR SPAR BETWEEN WS 52 AND WS 60 - BOLT HOLE EDDY CURRENT INSPECTION. (PRE SB 45-11-5)						PKG		
	PKG 22	MOS	96					23-NOV-2016	
AIRWORTHINESS	REF: NDT PART 6/57-20-03	HRS/MSC	2400					4476	
		AFL						3270	
N5710157 (s)	PERFORM * WING BOX BASIC SKIN/STRINGER AT STRINGER RUN-OUT, LOWER SKIN - VISUAL INSPECTION. INSPECT STRINGER RUN-OUTS IN FORWARD AND AFT LOWER SKIN PANELS. (POST SB 45-11-5)						PKG		
	PKG 25	MOS						25-JUL-2018	
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	4800					4687.6	
		AFL						3479	
N5710161 (s)	PERFORM *WING BOX SKIN ACCESS COVER HOLES - EDDY CURRENT INSPECTION. INSPECT ACCESS HOLES IN FORWARD AND AFT LOWER SKIN PANELS. (POST SB 45-11-5)						PKG		
	PKG 22	MOS	96					23-NOV-2016	
AIRWORTHINESS	REF: NDT PART 6/57-30-01	HRS/MSC	2400					4476	
		AFL						3270	
N5710176 (s)	PERFORM * WING MID-SPAR (CENTER SECTION) LOWER CAP AND CENTER-JOINT FITTING - ULTRASONIC INSPECTION. (PRE SB 45-11-5)						PKG		
	PKG 22	MOS	96					23-NOV-2016	
AIRWORTHINESS	REF: NDT PART 4/57-30-05	HRS/MSC	2400					4476	
		AFL						3270	
N5750005 (s)	PERFORM * FLAP MAIN TRACK HINGE FITTINGS, TRACK, AND FLAP BOX SIDES - VISUAL INSPECTION. INSPECT MAIN TRACK HINGE FITTINGS ON TRACK AND FLAP BOX SIDES.						PKG		
	PKG 22	MOS	96					23-NOV-2016	
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	2400					4476	
		AFL						3270	
P5710001 (s)	PERFORM * WING DRAG LINK ATTACH FITTING - MAGNETIC PARTICLE INSPECTION						PKG		
	PKG 22	MOS	96					23-NOV-2016	
AIRWORTHINESS	REF: NDT PART 7/57-30-02	HRS/MSC	2400					4476	
		AFL						3270	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P5710007 (s)	PERFORM * WING TO FUSELAGE ATTACH FITTINGS AND LINKS - EDDY CURRENT INSPECTION						PKG		
	PKG 25	MOS					25-JUL-2018		
AIRWORTHINESS	REF: NDT PART 6/57-10-12	HRS/MSC	4800				4687.6		3479
		AFL					3479		
P5710015 (s)	PERFORM * WING REAR SPAR ATAILERON HINGE - EDDY CURRENT INSPECTION.						PKG		
	PKG 25	MOS					25-JUL-2018		
AIRWORTHINESS	REF: NDT PART 6/57-10-20	HRS/MSC	4800				4687.6		3479
		AFL					3479		
P5710018 (s)	PERFORM * WING LOWER SKIN AT MID-SPAR SPAN-WISE JOINT - EDDY CURRENT INSPECTION.						PKG		
	PKG 26	MOS					03-APR-2005		
AIRWORTHINESS	REF: NDT PART 6/57-10-09	HRS/MSC	9600				0		0
		AFL					0		
P5710024 (s)	PERFORM * WING REAR-SPAR SIDE-STAY-FITTING SUPPORT STRUCTURE - EDDY CURRENT INSPECTION						PKG		
	PKG 25	MOS					25-JUL-2018		
AIRWORTHINESS	REF: NDT PART 6/57-20-06	HRS/MSC	4800				4687.6		3479
		AFL					3479		
P5710025 (s)	PERFORM * WING FRONT SPAR LOWER CAP FROM WS 33.0 TO WS 60.0 - RADIOGRAPHIC INSPECTION.						PKG		
	PKG 22	MOS	96				23-NOV-2016		
AIRWORTHINESS	REF: NDT PART 2/57-10-01	HRS/MSC	2400				4476		3270
		AFL					3270		
P5710029 (s)	PERFORM * WING MID-SPAR VERTICAL WEB - EDDY CURRENT INSPECTION.						PKG		
	PKG 26	MOS					03-APR-2005		
AIRWORTHINESS	REF: NDT PART 6/57-10-07	HRS/MSC	9600				0		0
		AFL					0		
P5710030 (s)	PERFORM * WING REAR SPAR VERTICAL WEB - EDDY CURRENT INSPECTION.						PKG		
	PKG 26	MOS					03-APR-2005		
AIRWORTHINESS	REF: NDT PART 6/57-20-05	HRS/MSC	9600				0		0
		AFL					0		
P5710032 (s)	PERFORM * WING RIB UPPER-AFT-FLANGE FILLET RADIUS AT WS 33.0 - ULTRASONIC INSPECTION						PKG		
	PKG 25	MOS					25-JUL-2018		
AIRWORTHINESS	REF: NDT PART 4/57-30-02	HRS/MSC	4800				4687.6		3479
		AFL					3479		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P5710033 (s)	PERFORM * WING ACCESS HOLE IN CLOSING RIB BETWEEN MID SPAR AND REAR SPAR - EDDY CURRENT INSPECTION. PKG 25	MOS					PKG	25-JUL-2018	
AIRWORTHINESS	REF: NDT PART 6/57-10-05	HRS/MSC AFL	4800					4687.6 3479	
P5710034 (s)	PERFORM * WING BOX JOINT TO WINGLET - EDDY CURRENT INSPECTION. PKG 25	MOS					PKG	25-JUL-2018	
AIRWORTHINESS	REF: NDT PART 6/57-10-13	HRS/MSC AFL	4800					4687.6 3479	
P5710035 (s)	PERFORM * WING LOWER SKIN AT DRAIN HOLE - EDDY CURRENT INSPECTION. PKG 25	MOS					PKG	25-JUL-2018	
AIRWORTHINESS	REF: NDT PART 6/57-30-02	HRS/MSC AFL	4800					4687.6 3479	
P5710083 (s)	PERFORM * FLAP BOX BASIC STRUCTURE - EDDY CURRENT INSPECTION. PKG 25	MOS					PKG	25-JUL-2018	
AIRWORTHINESS	REF: NDT PART 6/57-40-02	HRS/MSC AFL	4800					4687.6 3479	
P5710085 (s)	PERFORM SPOILER UPPER SKIN - EDDY CURRENT INSPECTION. PKG 25	MOS					PKG	25-JUL-2018	
AIRWORTHINESS	REF: NDT PART 6/57-10-16	HRS/MSC AFL	4800	+25/-25				4687.6 3479	
P5710086 (s)	PERFORM SPOILER BOLTS AND HINGE PINS - MAGNETIC PARTICLE INSPECTION. PKG 25	MOS					PKG	25-JUL-2018	
AIRWORTHINESS	REF: NDT PART 7/27-10-01	HRS/MSC AFL	4800	+25/-25				4687.6 3479	
P5710181 (s)	PERFORM * WING DRAG LINK TUBE - MAGNETIC PARTICLE INSPECTION. PKG 22	MOS	96				PKG	23-NOV-2016	
AIRWORTHINESS	REF: NDT PART 7/57-30-01	HRS/MSC AFL	2400					4476 3270	
P5710182 (s)	PERFORM * WING DRAG LINK ATTACH BOLTS - LIQUID PENETRANT INSPECTION PKG 22	MOS	96				PKG	23-NOV-2016	
AIRWORTHINESS	REF: NDT PART 8/57-10-01	HRS/MSC AFL	2400					4476 3270	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P5710183 (s)	PERFORM * WING DRAG-LINK CLEVIS - MAGNETIC PARTICLE INSPECTION. PKG 22	MOS	96				PKG	23-NOV-2016	
AIRWORTHINESS	REF: NDT PART 7/57-10-01	HRS/MSC AFL	2400				4476 3270		
P5710184 (s)	PERFORM * WING ATTACH BOLTS - FLUORESCENT PENETRANT INSPECTION. PKG 25	MOS					PKG	25-JUL-2018	
AIRWORTHINESS	REF: NDT PART 8/57-10-02	HRS/MSC AFL	4800				4687.6 3479		
P5710185 (s)	PERFORM * WING ATTACH LINKS - MAGNETIC PARTICLE INSPECTION. PKG 25	MOS					PKG	25-JUL-2018	
AIRWORTHINESS	REF: NDT PART 7/57-10-03	HRS/MSC AFL	4800				4687.6 3479		
P5710186 (s)	PERFORM * WING ATTACH FITTINGS AT MID SPAR AND REAR SPAR - MAGNETIC PARTICLE INSPECTION PKG 25	MOS					PKG	25-JUL-2018	
AIRWORTHINESS	REF: NDT PART 7/57-10-02	HRS/MSC AFL	4800				4687.6 3479		
P5750002 (s)	PERFORM * FLAP FRONT-SPAR CUTOUTS - EDDY CURRENT INSPECTION. PKG 22	MOS	96				PKG	23-NOV-2016	
AIRWORTHINESS	REF: NDT PART 6/57-10-15	HRS/MSC AFL	2400				4476 3270		
P5750003 (s)	PERFORM * FLAP NOSE-ROLLER RIBS - EDDY CURRENT INSPECTION. PKG 25	MOS					PKG	25-JUL-2018	
AIRWORTHINESS	REF: NDT PART 6/57-10-14	HRS/MSC AFL	4800				4687.6 3479		
P5750004 (s)	PERFORM * FLAP ACTUATOR SUPPORT RIBS - EDDY CURRENT INSPECTION. PKG 26	MOS					PKG	03-APR-2005	
AIRWORTHINESS	REF: NDT PART 6/57-10-21	HRS/MSC AFL	9600				0 0		
P5750048 (s)	PERFORM * FLAP TRACKS - MAGNETIC PARTICLE INSPECTION. PKG 26	MOS					PKG	03-APR-2005	
AIRWORTHINESS	REF: NDT PART 7/57-71-01	HRS/MSC AFL	9600				0 0		



Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P5750049 (s)	PERFORM * FLAP NOSE ROLLER TRACKS - MAGNETIC PARTICLE INSPECTION WITH FLAPS REMOVED. PKG 26	MOS					PKG	03-APR-2005	
AIRWORTHINESS	REF: NDT PART 7/57-10-04	HRS/MSC AFL	9600				0 0		
P5750053 (s)	PERFORM * FLAP TRACK SUPPORT RIBS - EDDY CURRENT INSPECTION. PKG 26	MOS					PKG	03-APR-2005	
AIRWORTHINESS	REF: NDT PART 6/57-10-17	HRS/MSC AFL	9600				0 0		
P5750068 (s)	PERFORM * FLAP FRONT-SPAR RIB SUPPORT STRUCTURE - EDDY CURRENT INSPECTION PKG 25	MOS					PKG	25-JUL-2018	
AIRWORTHINESS	REF: NDT PART 6/57-10-26	HRS/MSC AFL	4800				4687.6 3479		
P5760000 (s)	PERFORM * AILERON ACTUATOR HINGE FITTING - EDDY CURRENT INSPECTION. PKG 26	MOS					PKG	03-APR-2005	
AIRWORTHINESS	REF: NDT PART 6/57-10-25	HRS/MSC AFL	9600				0 0		
P5760001 (s)	PERFORM * AILERON SKIN - EDDY CURRENT INSPECTION PKG 26	MOS					PKG	03-APR-2005	
AIRWORTHINESS	REF: NDT PART 6/57-10-19	HRS/MSC AFL	9600				0 0		
P5760002 (s)	PERFORM * AILERON BALANCE TAB HINGE FITTINGS - EDDY CURRENT INSPECTION PKG 22	MOS	96				PKG	23-NOV-2016	
AIRWORTHINESS	REF: NDT PART 6/57-60-01	HRS/MSC AFL	2400				4476 3270		
P5760003 (s)	PERFORM * AILERON TRIM AND BALANCE TAB FRONT SPARS - RADIOGRAPHIC INSPECTION PKG 25	MOS					PKG	25-JUL-2018	
AIRWORTHINESS	REF: NDT PART 2/57-60-01	HRS/MSC AFL	4800				4687.6 3479		
P5760005 (s)	PERFORM * AILERON HINGE LUGS AND FITTINGS - EDDY CURRENT INSPECTION PKG 26	MOS					PKG	03-APR-2005	
AIRWORTHINESS	REF: NDT PART 6/57-10-24	HRS/MSC AFL	9600				0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P5760014 (s)	PERFORM * AILERON HINGE SUPPORT STRUCTURE - EDDY CURRENT INSPECTION						PKG		
	PKG 26	MOS					03-APR-2005		
AIRWORTHINESS	REF: NDT PART 6/57-10-23	HRS/MSC	9600				0		
		AFL					0		
P5770000 (s)	PERFORM SPOILER HINGE ASSEMBLIES AND ACTUATOR FITTING - EDDY CURRENT INSPECTION.						PKG		
	PKG 25	MOS					25-JUL-2018		
	REF: NDT PART 6/57-10-22	HRS/MSC	4800	+25/-25			4687.6		
		AFL					3479		
Q5710156 (s)	PERFORM * WING BOX BASIC SKIN/STRINGER, LOWER SKIN - VISUAL INSPECTION. INSPECT OUTBOARD WING FORWARD AND AFT LOWER SKIN PANELS AND STRINGERS. (POST SB 45-11-5)						PKG		
	PKG 22	MOS					23-NOV-2016		
	REF: GENERIC NO REF	HRS/MSC	N/A				4476		
		AFL					3270		
Q5710162 (s)	PERFORM * WING BOX FRONT SPAR LOWER CAP - VISUAL INSPECTION. INSPECT FRONT SPAR LOWER CAP AND LOWER FORWARD SKIN OUTBOARD OF MID-SPAR STATION (MS) 55. (POST SB 45-11-5)						PKG		
	PKG 22	MOS					23-NOV-2016		
NOT APPLICABLE	REF: AMM 05-10-00	HRS/MSC	N/A				4476		
		AFL					3270		
Q5710166 (s)	PERFORM * WING BOX MID SPAR, OUTBOARD OF RIB #8 - VISUAL INSPECTION AT WS 156 AND OUTBOARD TO WS 260. (POST SB 45-11-5)						PKG		
	PKG 22	MOS					23-NOV-2016		
NOT APPLICABLE	REF: AMM 05-10-00	HRS/MSC	N/A				4476		
		AFL					3270		
Q5710167 (s)	PERFORM * WING BOX REAR SPAR, OUTBOARD OF RIB #6 - VISUAL INSPECTION AT WS 118 AND OUTBOARD TO WS 260. (POST SB 45-11-5)						PKG		
	PKG 22	MOS					23-NOV-2016		
NOT APPLICABLE	REF: AMM 05-10-00	HRS/MSC	N/A				4476		
		AFL					3270		
U5710147 (s)	* WING BOX MID SPAR LOWER CAP, OUTBOARD OF JOINT AT WS 137 BETWEEN RIB #7 AND #8 - PERFORM DETAILED VISUAL INSPECTION. INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS. (POST SB 45-11-5)						PKG		
	PKG 10	MOS	24				17-JUL-2020		
AIRWORTHINESS	REF:	HRS/MSC	600				4932.3		
		AFL							

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
U5710154 (s)	* WING BOX REAR SPAR LOWER CAP, OUTBOARD OF JOINT AT WS 81 TO RIB #6 - PERFORM DETAILED VISUAL INSPECTION. INSPECT OUTER REAR SPAR LOWER CAP AND AFT LOWER SKIN PANEL OUTBOARD OF REAR SPLICE AT WS 90. (POST SB 45-11-5)						PKG		
	PKG 10	MOS	24				17-JUL-2020	4932.3	
AIRWORTHINESS	REF:	HRS/MSC	600						
		AFL							
V5710039 (s)	PERFORM WINGLET SKIN - EDDY CURRENT INSPECTION						PKG		
	PKG 25	MOS					25-JUL-2018	4687.6	
	REF: NDT PART 6/57-10-18	HRS/MSC	4800	+25/-25			3479		
		AFL							
Y5700001 (s)	WINGLET - PERFORM VISUAL INSPECTION						PKG		
	PKG 4	MOS	12	+14d/-14d			17-JUL-2020	4932.3	
	REF: AMM 05-10-00	HRS/MSC	300	+25/-25					
		AFL							
Y5700002 (s)	FLUX VALVE BRACKET - VISUALLY INSPECT FOR CRACKS. (EFFECTIVE ON AIRCRAFT 45-006 THRU 45-131 PRE SB 45-57-4)						PKG		
	PKG 4	MOS	12	+14d/-14d			17-JUL-2020	4932.3	
	REF: GENERIC NO REF	HRS/MSC	300	+25/-25					
		AFL							
Y5710000 (s)	PERFORM WING - EXTERNAL VISUAL INSPECTION FROM BL 0.00 TO WS 260						PKG		
	PKG 16	MOS	48	+14d/-14d			23-NOV-2016	4476	
	REF: AMM 05-10-00	HRS/MSC	1200	+25/-25			3270		
		AFL							
Y5710180 (s)	EXTERNAL LOWER WING SKIN - PERFORM VISUAL INSPECTION.						PKG		
	PKG 10	MOS	24	+14d/-14d			17-JUL-2020	4932.3	
	REF: AMM 05-10-00	HRS/MSC	600	+25/-25					
		AFL							
Y5730013 (s)	AILERON BRUSH SEALS - PERFORM DETAILED INSPECTION.						PKG		
	PKG 4	MOS	12	+14d/-14d			17-JUL-2020	4932.3	
	REF: AMM 57-60-01	HRS/MSC	300	+25/-25					
		AFL							

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y5750067 (s)	PERFORM FLAP BRACKETS (P/N A159019-1 AND A159022-1) - DETAILED VISUAL INSPECTION. PKG 22	MOS	96	+14d/-14d			PKG	23-NOV-2016	
	REF: AMM 05-10-00	HRS/MSC AFL	2400	+25/-25			4476 3270		
Y5750069 (s)	FLAPS - PERFORM VISUAL INSPECTION OF FLAP NOSE ROLLERS, FLAP TRACKS, FLAP NOSE ROLLER TRACKS, AND FLAP MAIN TRACK ROLLERS. PKG 4	MOS	12	+14d/-14d			PKG	17-JUL-2020	
	REF: AMM 05-10-00	HRS/MSC AFL	300	+25/-25			4932.3		
Y5750071 (s)	PERFORM FLAPS - WITH FLAPS REMOVED, DETAILED VISUAL INSPECTION OF FLAP NOSE ROLLERS, FLAP TRACKS, FLAP NOSE ROLLER TRACKS, AND FLAP MAIN TRACK ROLLERS. PKG 16	MOS	48	+14d/-14d			PKG	23-NOV-2016	
	REF: AMM 05-10-00	HRS/MSC AFL	1200	+25/-25			4476 3270		
CHAPTER 71 POWER PLANT									
5-19-00-Q7110004-LEFT	TAP TEST NO. 1 ENGINE NACELLE INLET (ZONE/ACCESS 430/440 IRN Q7110004). (REFER TO 71-10-01.)	MOS						02-JUN-2011	
	REF: AMM 71-10-01	HRS/MSC AFL	3000	+100/-100			2942.4 2046	5942.4	6042.4
5-19-00-Q7110004-RIGHT	TAP TEST NO. 2 ENGINE NACELLE INLET (ZONE/ACCESS 430/440 IRN Q7110004). (REFER TO 71-10-01.)	MOS						24-JUL-2009	
	REF: AMM 71-10-01	HRS/MSC AFL	3000	+100/-100			2416.1 1669	5416.1	5516.1
5-19-00-R7100032	L/H ENGINE NACELLE TUBES - PERFORM DETAILED VISUAL INSPECTION.	MOS						06-MAR-2012	
NOT APPLICABLE	REF: AMM 71-10-03	HRS/MSC AFL	N/A				3285.12 2304		
5-19-01-V7120074L	LEFT ENGINE *REPLACE AFT ENGINE MOUNT BOLT (P/N 4571408525-001) (REFER TO 71-00-01.)	MOS						03-APR-2005	
AIRWORTHINESS	REF: AMM 71-20-00	PN SN-UNKNOWN AFL	E/C		N:0 N:0 N:0		0 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-01-V7120074R	RIGHT ENGINE *REPLACE AFT ENGINE MOUNT BOLT (P/N 4571408525-001) (REFER TO 71-00-01.)								
	PN	MOS		N:0				03-APR-2005	
	SN-UNKNOWN	HRS/MSC	E/C	N:0				0	
AIRWORTHINESS	REF: AMM 71-20-00	AFL		N:0				0	
+ 7120002 (s)	NO. 1 ENGINE AFT ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								
		MOS						03-APR-2005	
		HRS/MSC	5000	+100/-100				0	
	REF: AMM 71-20-00	AFL						0	
7120002	NO. 1 ENGINE ALL ISOLATORS - PERFORM INSPECTION OF ISOLATORS AND ASSOCIATED PARTS								
		MOS						03-APR-2005	
		HRS/MSC	N/A					0	
	REF: AMM 71-20-00	AFL						0	
+ 7120002 (s)	NO. 1 ENGINE FORWARD LOWER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								
		MOS						03-APR-2005	
		HRS/MSC	5000	+100/-100				0	
	REF: AMM 71-20-00	AFL						0	
+ 7120002 (s)	NO. 1 ENGINE FORWARD UPPER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								
		MOS						03-APR-2005	
		HRS/MSC	5000	+100/-100				0	
	REF: AMM 71-20-00	AFL						0	
+ 7120002 (s)	NO. 2 ENGINE AFT ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								
		MOS						03-APR-2005	
		HRS/MSC	5000	+100/-100				0	
	REF: AMM 71-20-00	AFL						0	
7120002	NO. 2 ENGINE ALL ISOLATORS - PERFORM INSPECTION OF ISOLATORS AND ASSOCIATED PARTS								
		MOS						03-APR-2005	
		HRS/MSC	N/A					0	
	REF: AMM 71-20-00	AFL						0	
+ 7120002 (s)	NO. 2 ENGINE FORWARD LOWER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								
		MOS						03-APR-2005	
		HRS/MSC	5000	+100/-100				0	
	REF: AMM 71-20-00	AFL						0	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 7120002 (s)	NO. 2 ENGINE FORWARD UPPER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS	MOS						03-APR-2005	
	REF: AMM 71-20-00	HRS/MSC AFL	5000	+100/-100			0 0		
7120004	REPLACE ALL FORWARD AND AFT ENGINE MOUNT ISOLATOR HOUSINGS	MOS						03-APR-2005	
LIFE LIMIT	REF: AMM 71-20-00	HRS/MSC AFL	15000	+25/-25			0 0	15000	15025
+ 7120004 (s)	REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR HOUSING	MOS						03-APR-2005	
	PN	HRS/MSC	15000	N:0			0		
LIFE LIMIT	REF: AMM 71-20-00	AFL		N:0			0		
+ 7120004 (s)	REPLACE NO. 1 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR HOUSING	MOS						03-APR-2005	
	PN	HRS/MSC	15000	N:0			0		
LIFE LIMIT	REF: AMM 71-20-00	AFL		N:0			0		
+ 7120004 (s)	REPLACE NO. 1 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR HOUSING	MOS						03-APR-2005	
	PN	HRS/MSC	15000	N:0			0		
LIFE LIMIT	REF: AMM 71-20-00	AFL		N:0			0		
+ 7120004 (s)	REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR HOUSING	MOS						03-APR-2005	
	PN	HRS/MSC	15000	N:0			0		
LIFE LIMIT	REF: AMM 71-20-00	AFL		N:0			0		
+ 7120004 (s)	REPLACE NO. 2 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR HOUSING	MOS						03-APR-2005	
	PN	HRS/MSC	15000	N:0			0		
LIFE LIMIT	REF: AMM 71-20-00	AFL		N:0			0		
+ 7120004 (s)	REPLACE NO. 2 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR HOUSING	MOS						03-APR-2005	
	PN	HRS/MSC	15000	N:0			0		
LIFE LIMIT	REF: AMM 71-20-00	AFL		N:0			0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 7120005 (s)	REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR METAL MESH ELEMENTS								
	PN	MOS		N:0			03-APR-2005		
	SN-UNKNOWN	HRS/MSC	5000	+100/-100	N:0		0		
LIFE LIMIT	REF: AMM 71-20-00	AFL		N:0			0		
7120005	REPLACE NO. 1 ENGINE ALL ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS								
		MOS					03-APR-2005		
		HRS/MSC	N/A				0		
	REF: AMM 71-20-00	AFL					0		
+ 7120005 (s)	REPLACE NO. 1 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS								
	PN	MOS		N:0			03-APR-2005		
	SN-UNKNOWN	HRS/MSC	5000	+100/-100	N:0		0		
LIFE LIMIT	REF: AMM 71-20-00	AFL		N:0			0		
+ 7120005 (s)	REPLACE NO. 1 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS								
	PN	MOS		N:0			03-APR-2005		
	SN-UNKNOWN	HRS/MSC	5000		N:0		0		
LIFE LIMIT	REF: AMM 71-20-00	AFL		N:0			0		
+ 7120005 (s)	REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR METAL MESH ELEMENTS								
	PN	MOS		N:0			03-APR-2005		
	SN-UNKNOWN	HRS/MSC	5000	+100/-100	N:0		0		
LIFE LIMIT	REF: AMM 71-20-00	AFL		N:0			0		
7120005	REPLACE NO. 2 ENGINE ALL ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS								
		MOS							
		HRS/MSC	N/A						
	REF: AMM 71-20-00	AFL							
+ 7120005 (s)	REPLACE NO. 2 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS								
	PN	MOS		N:0			03-APR-2005		
	SN-UNKNOWN	HRS/MSC	5000	+100/-100	N:0		0		
LIFE LIMIT	REF: AMM 71-20-00	AFL		N:0			0		
+ 7120005 (s)	REPLACE NO. 2 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS								
	PN	MOS		N:0			03-APR-2005		
	SN-UNKNOWN	HRS/MSC	5000		N:0		0		
LIFE LIMIT	REF: AMM 71-20-00	AFL		N:0			0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 7120006	REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR METAL MESH ELEMENTS PN SN-UNKNOWN REF: AMM 71-20-00	MOS HRS/MSC AFL	N/A	N:0 N:0 N:0			03-APR-2005 0 0		
+ 7120006	REPLACE NO. 1 ENGINE ALL ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING AND AFT MOUNT METAL MESH ELEMENTS PN SN-UNKNOWN REF: AMM 71-20-00	MOS HRS/MSC AFL	N/A	N:0 N:0 N:0			03-APR-2005 0 0		
+ 7120006	REPLACE NO. 1 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS PN SN-UNKNOWN REF: AMM 71-20-00	MOS HRS/MSC AFL	N/A	N:0 N:0 N:0			03-APR-2005 0 0		
+ 7120006	REPLACE NO. 1 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS PN SN-UNKNOWN REF: AMM 71-20-00	MOS HRS/MSC AFL	N/A	N:0 N:0 N:0			03-APR-2005 0 0		
+ 7120006	REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR METAL MESH ELEMENTS PN SN-UNKNOWN REF: AMM 71-20-00	MOS HRS/MSC AFL	N/A	N:0 N:0 N:0			03-APR-2005 0 0		
+ 7120006	REPLACE NO. 2 ENGINE ALL ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING AND AFT MOUNT METAL MESH ELEMENTS PN SN-UNKNOWN REF: AMM 71-20-00	MOS HRS/MSC AFL	N/A	N:0 N:0 N:0			03-APR-2005 0 0		
+ 7120006	REPLACE NO. 2 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS PN SN-UNKNOWN REF: AMM 71-20-00	MOS HRS/MSC AFL	N/A	N:0 N:0 N:0			03-APR-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 712006	REPLACE NO. 2 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS								
	PN	MOS		N:0			03-APR-2005		
	SN-UNKNOWN	HRS/MSC	N/A	N:0			0		
	REF: AMM 71-20-00	AFL		N:0			0		
712005	NO. 1 ENGINE AFT MOUNT ISOLATOR ASSEMBLY								
	LM-833-SA18	MOS		N:0			03-APR-2005		
	LK0951	HRS/MSC	O/C	N:0			0		
	REF: AMM 71-20-00	AFL		N:0			0		
712006	NO. 2 ENGINE AFT MOUNT ISOLATOR ASSEMBLY								
	LM-833-SA18	MOS		N:0			03-APR-2005		
	LK0948	HRS/MSC	O/C	N:0			0		
	REF: AMM 71-20-00	AFL		N:0			0		
+ 7120069 (s)	NO. 1 ENGINE AFT ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								
		MOS					03-APR-2005		
		HRS/MSC	2500	+100/-100			0		
	REF: AMM 71-20-00	AFL					0		
7120069	NO. 1 ENGINE ALL ISOLATORS - PERFORM VISUAL INSPECTION OF ISOLATORS AND ASSOCIATED PARTS								
		MOS					01-APR-2011		
		HRS/MSC	3000	+100/-100			2867.6	5867.6	5967.6
	REF: AMM 71-20-00	AFL					1988		
+ 7120069 (s)	NO. 1 ENGINE FORWARD LOWER ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								
		MOS					03-APR-2005		
		HRS/MSC	2500	+100/-100			0		
	REF: AMM 71-20-00	AFL					0		
+ 7120069 (s)	NO. 1 ENGINE FORWARD UPPER ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								
		MOS					03-APR-2005		
		HRS/MSC	2500	+100/-100			0		
	REF: AMM 71-20-00	AFL					0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 7120069 (s)	NO. 2 ENGINE AFT ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS	MOS					03-APR-2005		
	REF: AMM 71-20-00	HRS/MSC AFL	2500	+100/-100			0 0		
7120069	NO. 2 ENGINE ALL ISOLATORS - PERFORM VISUAL INSPECTION OF ISOLATORS AND ASSOCIATED PARTS	MOS					24-JUL-2009		
	REF: AMM 71-20-00	HRS/MSC AFL	3000	+100/-100			2416.1 1669	5416.1	5516.1
+ 7120069 (s)	NO. 2 ENGINE FORWARD LOWER ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS	MOS					03-APR-2005		
	REF: AMM 71-20-00	HRS/MSC AFL	2500	+100/-100			0 0		
+ 7120069 (s)	NO. 2 ENGINE FORWARD UPPER ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS	MOS					03-APR-2005		
	REF: AMM 71-20-00	HRS/MSC AFL	2500	+100/-100			0 0		
+ 7120070 (s)	REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR METAL MESH ELEMENTS	MOS					03-APR-2005		
	PN	HRS/MSC	6000	+100/-100	N:0		0		
	SN-UNKNOWN	AFL			N:0		0		
LIFE LIMIT	REF: AMM 71-20-00				N:0		0		
7120070	REPLACE NO. 1 ENGINE ALL ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS	MOS					03-APR-2005		
	REF: AMM 71-20-00	HRS/MSC AFL	6000	+100/-100			0 0	6000	6100
LIFE LIMIT									
+ 7120070 (s)	REPLACE NO. 1 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS	MOS					03-APR-2005		
	PN	HRS/MSC	6000	+100/-100	N:0		0		
	SN-UNKNOWN	AFL			N:0		0		
LIFE LIMIT	REF: AMM 71-20-00				N:0		0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 7120070 (s)	REPLACE NO. 1 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS								
	PN	MOS		N:0			03-APR-2005		
	SN-UNKNOWN	HRS/MSC	6000	+100/-100	N:0		0		
LIFE LIMIT	REF: AMM 71-20-00	AFL		N:0			0		
+ 7120070 (s)	REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR METAL MESH ELEMENTS								
	PN	MOS		N:0			03-APR-2005		
	SN-UNKNOWN	HRS/MSC	6000	+100/-100	N:0		0		
LIFE LIMIT	REF: AMM 71-20-00	AFL		N:0			0		
7120070	REPLACE NO. 2 ENGINE ALL ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS								
		MOS					03-APR-2005		
		HRS/MSC	6000	+100/-100			0	6000	6100
LIFE LIMIT	REF: AMM 71-20-00	AFL					0		
+ 7120070 (s)	REPLACE NO. 2 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS								
	PN	MOS		N:0			03-APR-2005		
	SN-UNKNOWN	HRS/MSC	6000	+100/-100	N:0		0		
LIFE LIMIT	REF: AMM 71-20-00	AFL		N:0			0		
+ 7120070 (s)	REPLACE NO. 2 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS								
	PN	MOS		N:0			03-APR-2005		
	SN-UNKNOWN	HRS/MSC	6000	+100/-100	N:0		0		
LIFE LIMIT	REF: AMM 71-20-00	AFL		N:0			0		
+ 7120073 (s)	NO. 1 ENGINE AFT ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								
		MOS					03-APR-2005		
		HRS/MSC	6000	+100/-100			0		
	REF: AMM 71-20-00	AFL					0		
7120073	NO. 1 ENGINE ALL ISOLATORS - PERFORM INSPECTION OF ISOLATORS AND ASSOCIATED PARTS								
		MOS					03-APR-2005		
		HRS/MSC	6000	+100/-100			0	6000	6100
	REF: AMM 71-20-00	AFL					0		
+ 7120073 (s)	NO. 1 ENGINE FORWARD LOWER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								
		MOS					03-APR-2005		
		HRS/MSC	6000	+100/-100			0		
	REF: AMM 71-20-00	AFL					0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
7120073 (s)	NO. 1 ENGINE FORWARD UPPER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS	MOS						03-APR-2005	
	REF: AMM 71-20-00	HRS/MSC	6000	+100/-100				0	
		AFL						0	
+ 7120073 (s)	NO. 2 ENGINE AFT ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS	MOS						03-APR-2005	
	REF: AMM 71-20-00	HRS/MSC	6000	+100/-100				0	
		AFL						0	
7120073	NO. 2 ENGINE ALL ISOLATORS - PERFORM INSPECTION OF ISOLATORS AND ASSOCIATED PARTS	MOS						03-APR-2005	
	REF: AMM 71-20-00	HRS/MSC	6000	+100/-100				0	6000 6100
		AFL						0	
+ 7120073 (s)	NO. 2 ENGINE FORWARD LOWER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS	MOS						03-APR-2005	
	REF: AMM 71-20-00	HRS/MSC	6000	+100/-100				0	
		AFL						0	
7120073 (s)	NO. 2 ENGINE FORWARD UPPER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS	MOS						03-APR-2005	
	REF: AMM 71-20-00	HRS/MSC	6000	+100/-100				0	
		AFL						0	
712045	NO. 1 ENGINE AFT MOUNT	MOS						03-APR-2005	
	4571200011-003	HRS/MSC	O/C		N:0			0	
	CDF685	AFL			N:0			0	
	REF: AMM 71-20-00				N:0			0	
712046	NO. 2 ENGINE AFT MOUNT	MOS						03-APR-2005	
	4571200011-003	HRS/MSC	O/C		N:0			0	
	CDF682	AFL			N:0			0	
	REF: AMM 71-20-00				N:0			0	
71EN1	NO. 1 ENGINE	MOS							
	3060082-6	HRS/MSC	E/C						
	P-116593	AFL							
	71.EN1								
	REF: AMM 71-00-01								

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71EN2	NO. 2 ENGINE								
71.EN2	3060082-6 P-116590 REF: AMM 71-00-01	MOS HRS/MSC AFL	E/C	N:4048.88			10-OCT-2014 4118 2932		
P7120001 (s)	PERFORM * FORWARD ENGINE MOUNT - EDDY CURRENT INSPECTION. PKG 25	MOS HRS/MSC AFL	4800				PKG 25-JUL-2018 4687.6 3479		
AIRWORTHINESS	REF: NDT PART 6/71-10-01								
Y7100002 (s)	LOWER ENGINE COWLING - VISUALLY INSPECT LATCH CHANNELS FOR CHAFING. PKG 9	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
REF: AMM 05-10-00									
Y7110000 (s)	ENGINE NACELLE - PERFORM VISUAL INSPECTION. INSPECT INLET BULKHEAD, STRUCTURE, PLUMBING, SKIN SPOT WELDS, ANTI-ICE OUTLET SCREEN, AND FASTENERS FOR SECURITY, CRACKS, AND GENERAL CONDITION. PKG 9	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
REF: AMM 05-10-00									
Y7110001 (s)	ENGINE INLET LIP AND DUCT - PERFORM VISUAL INSPECTION. PKG 9	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
REF: AMM 05-10-00									
Y7110002 (s)	ENGINE STARTER/GENERATOR INLET AND EXHAUST DUCT AND SEALS - PERFORM VISUAL INSPECTION. PKG 9	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
REF: AMM 05-10-00									
Y7110003 (s)	ENGINE ALTERNATOR EXHAUST DUCT AND SEALS - PERFORM VISUAL INSPECTION. PKG 9	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
REF: AMM 05-10-00									
Y7120000 (s)	FORWARD ENGINE MOUNTS - PERFORM VISUAL INSPECTION. PKG 3	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 17-JUL-2020 4932.3		
REF: AMM 05-10-00									

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
ENGINE NO. 1 Model : TFE731-20BR-1B Serial # P-116593 Part # 3060084-2									
+ 710130 (s)	NO. 1 ENGINE - INSPECT TAILPIPE/LPT3 ROTOR ASSEMBLY-VISUALLY INSPECT FOR FOREIGN OBJECT DAMAGE, THERMAL DISTRESS, AND LEAKS.	MOS						09-MAY-2017	
		HRS/MSC	800	+50/-300				4456.5	
	REF: LMM 72-00-00	ENC						3267	
+ 710140 (s)	NO. 1 ENGINE - INSPECT INLET/FAN AREA - INSPECT FOR FOREIGN OBJECT DAMAGE AND LEAKAGE (REFER TO PARAGRAPH 4.B)	MOS						09-MAY-2017	
		HRS/MSC	800	+50/-300				4456.5	
	REF: See Workcard	ENC						3267	
+ 714010 (s)	NO. 1 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY AND DAMAGE	MOS						09-MAY-2017	
		HRS/MSC	800	+50/-300				4456.5	
	REF: LMM 72-00-00	ENC						3267	
+ 715010 (s)	NO. 1 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY, LOOSE OR BROKEN CLAMPS OR BRACKETS, LEAKS, CRACKS, CUTS, OR RUBBING	MOS						09-MAY-2017	
		HRS/MSC	800	+50/-300				4456.5	
	REF: LMM 72-00-00	ENC						3267	
ENGINE NO. 2 Model : TFE731-20BR-1B Serial # P-116590 Part # 3060084-2									
+ 710130 (s)	NO. 2 ENGINE - INSPECT TAILPIPE/LPT3 ROTOR ASSEMBLY-VISUALLY INSPECT FOR FOREIGN OBJECT DAMAGE, THERMAL DISTRESS, AND LEAKS.	MOS						21-NOV-2019	
		HRS/MSC	800	+50/-300				4796	
	REF: LMM 72-00-00	ENC						3581	
+ 710140 (s)	NO. 2 ENGINE - INSPECT INLET/FAN AREA - INSPECT FOR FOREIGN OBJECT DAMAGE AND LEAKAGE (REFER TO PARAGRAPH 4.B)	MOS						21-NOV-2019	
		HRS/MSC	800	+50/-300				4796	
	REF: See Workcard	ENC						3581	
+ 714010 (s)	NO. 2 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY AND DAMAGE	MOS						21-NOV-2019	
		HRS/MSC	800	+50/-300				4796	
	REF: LMM 72-00-00	ENC						3581	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 715010 (s)	NO. 2 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY, LOOSE OR BROKEN CLAMPS OR BRACKETS, LEAKS, CRACKS, CUTS, OR RUBBING	MOS HRS/MSC ENC	800	+50/-300			21-NOV-2019 4796 3581		
	REF: LMM 72-00-00								
CHAPTER 72 ENGINE									
ENGINE NO. 1	Model : TFE731-20BR-1B	Serial # P-116593	Part # 3060084-2						
72-AS-720005	NO. 1 ENGINE - INSPECT MAJOR PERIODIC PER MANUFACTURERS INSTRUCTIONS	MOS HRS/MSC ENC	3000	+100			14-APR-2011 2867.6 1988	(5867.6) 5942.4	5967.6
	REF: LMM 72-00-00								
72-AS-720006 (s)	NO. 1 ENGINE - INSPECT COMB CHAMBER PLENUM CASE INSP PER MANUFACTURERS INSTRUCTIONS	MOS HRS/MSC ENC	3000	+100/-100			14-APR-2011 2867.6 1988		
	REF: GENERIC NO REF								
72-AS-720007	NO. 1 ENGINE - INSPECT COMPRESSOR ZONE PER MANUFACTURERS INSTRUCTIONS	MOS HRS/MSC ENC	6000	+200			17-JAN-2005 0 0	(6000) 6074.8	6200
	REF: LMM 72-00-00								
72-AS-720008 (s)	NO. 1 ENGINE - INSPECT AGB PER MANUFACTURERS INSTRUCTIONS	MOS HRS/MSC ENC	6000	+200/-200			17-JAN-2005 0 0		
	REF: See Workcard								
72-AS-720010	NO. 1 ENGINE - ANALYSIS OIL AND FILTER (BASELINE/SPECIAL REQUIREMENT) (SOAP)	MOS HRS/MSC ENC	A/R				01-MAY-2005 10.4 9		
	REF: LMM 72-00-00								
72-AS-720011	NO. 1 ENGINE - REPLACE FUEL FILTER ELEMENT (25-HR INITIAL)	MOS HRS/MSC ENC	A/R				01-MAY-2005 10.4 9		
	REF: LMM 73-21-02								

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720110	NO. 1 ENGINE - ACCESSORY GEARBOX 3060827-2 S-2043 REF: LMM 72-60-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			17-JAN-2005 0 0		
+ 723010 (s)	NO. 1 ENGINE - CHECK CARBON SEAL HEALTH REF: LMM 72-00-00	MOS HRS/MSC ENC	1600	+50/-100			09-MAY-2017 4456.5 3267		
725007 72.500	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) NOZZLE ASSEMBLY PN SN-UNKNOWN REF: LMM 72-50-07	MOS HRS/MSC ENC	A/R	N:0 N:0 N:0			17-JAN-2005 0 0		
725010 LIFE LIMIT	NO. 1 ENGINE - 1ST-STAGE LOW PRESSURE TURBINE (LPT) DISC 3060625-1 040322900680 REF: LMM 72-50-04	MOS HRS/MSC ENC	12000	N:0 N:0 N:0			17-JAN-2005 0 0	(12000) 12060	
725020 LIFE LIMIT	NO. 1 ENGINE - 2ND-STAGE LOW PRESSURE TURBINE (LPT) DISC 3060611-1 040322901498 REF: LMM 72-50-04	MOS HRS/MSC ENC	12000	N:0 N:0 N:0			17-JAN-2005 0 0	(12000) 12060	
725030 LIFE LIMIT	NO. 1 ENGINE - 3RD-STAGE LOW PRESSURE TURBINE (LPT) DISC 3060671-2 040322900928 REF: LMM 72-50-04	MOS HRS/MSC ENC	12000	N:0 N:0 N:0			17-JAN-2005 0 0	(12000) 12060	
725040 LIFE LIMIT	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) DISC 3060841-1 041217200404 REF: LMM 72-50-07	MOS HRS/MSC ENC	10000	N:0 N:0 N:0			17-JAN-2005 0 0	(10000) 10060	
725045	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) ASSY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			17-JAN-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725050	NO. 1 ENGINE - FAN DISC 3060287-2 040322900811	MOS HRS/MSC		N:0 N:0			17-JAN-2005 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	20000	N:0			0	(20000) 20060	
725060	NO. 1 ENGINE - 1ST-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC 3060372-1 040316002625	MOS HRS/MSC		N:0 N:0			17-JAN-2005 0		
LIFE LIMIT	REF: LMM 72-30-04	ENC	10000	N:0			0	(10000) 10060	
725070	NO. 1 ENGINE - 2ND-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC 3060373-1 040316002575	MOS HRS/MSC		N:0 N:0			17-JAN-2005 0		
LIFE LIMIT	REF: LMM 72-30-04	ENC	10000	N:0			0	(10000) 10060	
725080	NO. 1 ENGINE - 3RD-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC 3060374-1 040316002222	MOS HRS/MSC		N:0 N:0			17-JAN-2005 0		
LIFE LIMIT	REF: LMM 72-30-04	ENC	20000	N:0			0	(20000) 20060	
725090	NO. 1 ENGINE - 4TH-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC 3075326-5 040350107645	MOS HRS/MSC		N:0 N:0			17-JAN-2005 0		
LIFE LIMIT	REF: LMM 72-30-04	ENC	20000	N:0			0	(20000) 20060	
725110	NO. 1 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD 3074744-1 04P21970	MOS HRS/MSC	O/C	N:0 N:0			17-JAN-2005 0		
	REF: See Workcard	ENC		N:0			0		
725120	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR IMPELLER 3060371-1 040322901342	MOS HRS/MSC		N:0 N:0			17-JAN-2005 0		
LIFE LIMIT	REF: LMM 72-50-06	ENC	8000	N:0			0	(8000) 8060	
725130	NO. 1 ENGINE - FAN SPINNER 3060156-2 042784300289	MOS HRS/MSC		N:0 N:0			17-JAN-2005 0		
LIFE LIMIT	REF: LMM 72-70-01	ENC	20000	N:0			0	(20000) 20060	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725140	NO. 1 ENGINE - FAN DRIVE SHAFT 3060180-2 041366303683 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			17-JAN-2005 0 0		
725160	NO. 1 ENGINE - FORWARD ROTOR HIGH PRESSURE SEAL 3060698-1 040350107314 REF: LMM 72-70-03	MOS HRS/MSC ENC	7000	N:0 N:0 N:0			17-JAN-2005 0 0	(7000) 7060	
725170	NO. 1 ENGINE - HIGH PRESSURE SHOULDERED SHAFT 3060366-3 04P25138 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			17-JAN-2005 0 0		
725180	NO. 1 ENGINE - COMBUSTION PLENUM CASE 3060534-4 04P24228 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			17-JAN-2005 0 0		
725210	NO. 1 ENGINE - HIGH PRESSURE TURBINE FORWARD SEAL PLATE 3060514-1 040322903207 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	N:0 N:0 N:0			17-JAN-2005 0 0	(10000) 10060	
725220	NO. 1 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT 3060694-6 04P20437 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			17-JAN-2005 0 0		
725230	NO. 1 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE SEAL SUPPORT 3060693-1 04P23672 REF: LMM 72-50-04	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			17-JAN-2005 0 0		
725240	NO. 1 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE ASSEMBLY 3060666-7 04P25306 REF: LMM 72-50-04	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			17-JAN-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725250	NO. 1 ENGINE - FORWARD SHAFT HIGH PRESSURE TURBINE (HPT) COUPLING 3060502-2 04P25401 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			17-JAN-2005 0 0		
725260	NO. 1 ENGINE - AFT HIGH PRESSURE TURBINE (HPT) SHAFT COUPLING 3060599-2 04P25406 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			17-JAN-2005 0 0		
725270	NO. 1 ENGINE - NOZZLE LOW PRESSURE TURBINE (LPT) (A5) SEAL 3073765-12 04P22501 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			17-JAN-2005 0 0		
727006	NO. 1 ENGINE - LOWER FAN DUCT ASSEMBLY PN SN-UNKNOWN REF: LMM 72-70-05	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			17-JAN-2005 0 0		
727010 (s)	NO. 1 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY. REF: See Workcard	MOS HRS/MSC ENC	1200	+100/-200			21-NOV-2019 4790.6 3589		
ENGINE NO. 2 Model : TFE731-20BR-1B Serial # P-116590 Part # 3060084-2									
72-AS-720005	NO. 2 ENGINE - INSPECT MAJOR PERIODIC PER MANUFACTURERS INSTRUCTIONS REF: LMM 72-00-00	MOS HRS/MSC ENC	3000	+100			29-JUN-2009 2398.4 1655	(5398.4) 5467.8	5498.4
72-AS-720006 (s)	NO. 2 ENGINE - INSPECT COMB CHAMBER PLENUM CASE INSP PER MANUFACTURERS INSTRUCTIONS REF: GENERIC NO REF	MOS HRS/MSC ENC	3000	+100/-100			29-JUN-2009 2398.4 1655		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-AS-720007	NO. 2 ENGINE - INSPECT COMPRESSOR ZONE PER MANUFACTURERS INSTRUCTIONS REF: LMM 72-00-00	MOS HRS/MSC ENC	6000	+200			17-JAN-2005 0 0	(6000) 6069.4	6200
72-AS-720008 (s)	NO. 2 ENGINE - INSPECT AGB PER MANUFACTURERS INSTRUCTIONS REF: See Workcard	MOS HRS/MSC ENC	6000	+200/-200			17-JAN-2005 0 0		
72-AS-720010	NO. 2 ENGINE - ANALYSIS OIL AND FILTER (BASELINE/SPECIAL REQUIREMENT) (SOAP) REF: LMM 72-00-00	MOS HRS/MSC ENC	A/R				25-NOV-2014 4082 2904		
72-AS-720011	NO. 2 ENGINE - REPLACE FUEL FILTER ELEMENT (25-HR INITIAL) REF: LMM 73-21-02	MOS HRS/MSC ENC	A/R				01-MAY-2005 10.4 9		
720110	NO. 2 ENGINE - ACCESSORY GEARBOX 3060827-2 S-2056 REF: LMM 72-60-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			17-JAN-2005 0 0		
720244	NO. 2 ENGINE - NO. 6 CARBON SEAL ASSEMBLY 3071383-2 08-03650-01391 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				29-JUN-2009 2398.4 1655		
+ 723010 (s)	NO. 2 ENGINE - CHECK CARBON SEAL HEALTH REF: LMM 72-00-00	MOS HRS/MSC ENC	1600	+50/-100			07-OCT-2014 4048.8 2866		
725007	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) NOZZLE ASSEMBLY PN 72.500 SN-UNKNOWN REF: LMM 72-50-07	MOS HRS/MSC ENC	A/R	N:0 N:0 N:0			17-JAN-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - 1ST-STAGE LOW PRESSURE TURBINE (LPT) DISC 3060610-3 070322903029	MOS HRS/MSC					29-JUN-2009 2398.4		
LIFE LIMIT	REF: LMM 72-50-04	ENC	12000	N:0			1655	(13655) 13723	
725020	NO. 2 ENGINE - 2ND-STAGE LOW PRESSURE TURBINE (LPT) DISC 3060611-1 040322901465	MOS HRS/MSC		N:0 N:0			17-JAN-2005 0		
LIFE LIMIT	REF: LMM 72-50-04	ENC	12000	N:0			0	(12000) 12068	
725022	NO. 2 ENGINE - 2ND-STAGE LPT NOZZLE SHROUD 3060695-4 SN-UNKNOWN	MOS HRS/MSC	O/C				29-JUN-2009 2398.4		
CUSTOMER CODE	REF: LMM 72-50-04	ENC					1655		
725030	NO. 2 ENGINE - 3RD-STAGE LOW PRESSURE TURBINE (LPT) DISC 3060671-2 040322900930	MOS HRS/MSC		N:0 N:0			17-JAN-2005 0		
LIFE LIMIT	REF: LMM 72-50-04	ENC	12000	N:0			0	(12000) 12068	
725031	NO. 2 ENGINE - 3RD-STAGE LTP BLADES 3060788-1 NA	MOS HRS/MSC	O/C				29-JUN-2009 2398.4		
CUSTOMER CODE	REF: LMM 72-50-04	ENC					1655		
725040	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) DISC 3060841-1 041217200357	MOS HRS/MSC		N:0 N:0			17-JAN-2005 0		
LIFE LIMIT	REF: LMM 72-50-07	ENC	10000	N:0			0	(10000) 10068	
725045	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) ASSY PN SN-UNKNOWN	MOS HRS/MSC	O/C	N:0 N:0			17-JAN-2005 0		
	REF:	ENC		N:0			0		
725050	NO. 2 ENGINE - FAN DISC 3060287-2 040322900809	MOS HRS/MSC		N:0 N:0			17-JAN-2005 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	20000	N:0			0	(20000) 20068	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725060	NO. 2 ENGINE - 1ST-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC 3060372-1 040316002628	MOS HRS/MSC		N:0 N:0			17-JAN-2005 0		
LIFE LIMIT	REF: LMM 72-30-04	ENC	10000	N:0			0	(10000) 10068	
725070	NO. 2 ENGINE - 2ND-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC 3060373-1 040316002565	MOS HRS/MSC		N:0 N:0			17-JAN-2005 0		
LIFE LIMIT	REF: LMM 72-30-04	ENC	10000	N:0			0	(10000) 10068	
725080	NO. 2 ENGINE - 3RD-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC 3060374-1 040316003292	MOS HRS/MSC		N:0 N:0			17-JAN-2005 0		
LIFE LIMIT	REF: LMM 72-30-04	ENC	20000	N:0			0	(20000) 20068	
725090	NO. 2 ENGINE - 4TH-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC 3075326-5 040350106954	MOS HRS/MSC		N:0 N:0			17-JAN-2005 0		
LIFE LIMIT	REF: LMM 72-30-04	ENC	20000	N:0			0	(20000) 20068	
725110	NO. 2 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD 3074744-1 04P21965	MOS HRS/MSC	O/C	N:0 N:0			17-JAN-2005 0		
	REF: See Workcard	ENC		N:0			0		
725120	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR IMPELLER 3060371-1 040322901346	MOS HRS/MSC		N:0 N:0			17-JAN-2005 0		
LIFE LIMIT	REF: LMM 72-50-06	ENC	8000	N:0			0	(8000) 8068	
725130	NO. 2 ENGINE - FAN SPINNER 3060156-2 042784300284	MOS HRS/MSC		N:0 N:0			17-JAN-2005 0		
LIFE LIMIT	REF: LMM 72-70-01	ENC	20000	N:0			0	(20000) 20068	
725140	NO. 2 ENGINE - FAN DRIVE SHAFT 3060180-2 041366303617	MOS HRS/MSC	O/C	N:0 N:0			17-JAN-2005 0		
	REF: GENERIC NO REF	ENC		N:0			0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725160	NO. 2 ENGINE - FORWARD ROTOR HIGH PRESSURE SEAL 3060698-1 040350107299	MOS HRS/MSC		N:0 N:0			17-JAN-2005 0		
LIFE LIMIT	REF: LMM 72-70-03	ENC	7000	N:0			0	(7000) 7068	
725170	NO. 2 ENGINE - HIGH PRESSURE SHOULDERED SHAFT 3060366-3 04P25136	MOS HRS/MSC	O/C	N:0 N:0			17-JAN-2005 0		
	REF: GENERIC NO REF	ENC		N:0			0		
725180	NO. 2 ENGINE - COMBUSTION PLENUM CASE 3060534-4 04P22660	MOS HRS/MSC	O/C	N:0 N:0			17-JAN-2005 0		
	REF: See Workcard	ENC		N:0			0		
725210	NO. 2 ENGINE - HIGH PRESSURE TURBINE FORWARD SEAL PLATE 3060514-1 040322901591	MOS HRS/MSC		N:0 N:0			17-JAN-2005 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	10000	N:0			0	(10000) 10068	
725220	NO. 2 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT 3060694-6 04P20441	MOS HRS/MSC	O/C	N:0 N:0			17-JAN-2005 0		
	REF: GENERIC NO REF	ENC		N:0			0		
725230	NO. 2 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE SEAL SUPPORT 3060693-1 04P24271	MOS HRS/MSC	O/C	N:0 N:0			17-JAN-2005 0		
	REF: LMM 72-50-04	ENC		N:0			0		
725240	NO. 2 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE ASSEMBLY 3060666-7 04P25299	MOS HRS/MSC	O/C	N:0 N:0			17-JAN-2005 0		
	REF: LMM 72-50-04	ENC		N:0			0		
725250	NO. 2 ENGINE - FORWARD SHAFT HIGH PRESSURE TURBINE (HPT) COUPLING 3060502-2 04P24284	MOS HRS/MSC	O/C	N:0 N:0			17-JAN-2005 0		
	REF: GENERIC NO REF	ENC		N:0			0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725260	NO. 2 ENGINE - AFT HIGH PRESSURE TURBINE (HPT) SHAFT COUPLING 3060599-2 04P23871 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			17-JAN-2005 0 0		
725270	NO. 2 ENGINE - NOZZLE LOW PRESSURE TURBINE (LPT) (A5) SEAL 3073765-12 04P24515 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			17-JAN-2005 0 0		
727006	NO. 2 ENGINE - LOWER FAN DUCT ASSEMBLY PN SN-UNKNOWN REF: LMM 72-70-05	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			17-JAN-2005 0 0		
727010 (s)	NO. 2 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY. REF: See Workcard	MOS HRS/MSC ENC	1200	+100/-200			17-JUL-2020 4862.9 3646		
727101	NO. 2 ENGINE - NO. 1 CARBON SEAL ASSEMBLY 3060457-1 08-5158-16186 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				29-JUN-2009 2398.4 1655		
CHAPTER 73 ENGINE FUEL AND CONTROL									
733001	NO. 1 ENGINE FUEL FLOW TRANSDUCER 7600021-1 518532 REF: AMM 73-31-01	MOS HRS/MSC AFL	O/C				26-MAR-2013 3715.78 2610		
733002	NO. 2 ENGINE FUEL FLOW TRANSDUCER 7600021-1 207325 REF: AMM 73-31-01	MOS HRS/MSC AFL	O/C	O:4 O:0 O:0			28-MAR-2013 3715.78 2610		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
733013	DUAL FUEL FLOW (DFFC) CONVERTER 6673308500-003 05040896 REF: AMM 73-31-02	MOS HRS/MSC AFL	O/C				09-JUL-2008 2215 1537		
733031	LEFT ENGINE FUEL TEMPERATURE BULB MS28034-3 H8989 REF: AMM 73-31-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
733032	RIGHT ENGINE FUEL TEMPERATURE BULB MS28034-3 H6380 REF: AMM 73-31-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
ENGINE NO. 1 Model : TFE731-20BR-1B Serial # P-116593 Part # 3060084-2									
730110	NO. 1 ENGINE - FUEL CONTROL UNIT 3070800-47 15258 REF: LMM 73-20-01	MOS HRS/MSC ENC	O/C	R:0 R:0 R:0			15-JAN-2014 3870.53 2710		
730120 (s)	NO. 1 ENGINE - REPLACE FUEL FILTER ELEMENT REF: See Workcard	MOS HRS/MSC ENC	600				11-OCT-2019 4766.2 3564		
730130	NO. 1 ENGINE - ENGINE FUEL PUMP ASSEMBLY 3060760-4 1663 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			17-JAN-2005 0 0		
731001	NO. 1 ENGINE - MOTIVE FLOW FUEL PUMP ASSEMBLY 3060759-1 SN-UNKNOWN REF: LMM 73-21-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			17-JAN-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
732120 (s)	NO. 1 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE	MOS						11-OCT-2019	
		HRS/MSC	600	+50/-100				4766.2	
	REF: See Workcard	ENC						3564	
ENGINE NO. 2 Model : TFE731-20BR-1B Serial # P-116590 Part # 3060084-2									
730110	NO. 2 ENGINE - FUEL CONTROL UNIT	MOS						09-APR-2015	
	3070800-47	HRS/MSC	O/C		R:0			4180.8	
	18358	ENC			R:0			2988	
	REF: LMM 73-20-01				R:0				
730120 (s)	NO. 2 ENGINE - REPLACE FUEL FILTER ELEMENT	MOS						17-JUL-2020	
		HRS/MSC	600					4862.9	
	REF: See Workcard	ENC						3646	
730130	NO. 2 ENGINE - ENGINE FUEL PUMP ASSEMBLY	MOS						17-JAN-2005	
	3060760-4	HRS/MSC	O/C		N:0			0	
	1661	ENC			N:0			0	
	REF: See Workcard				N:0			0	
731001	NO. 2 ENGINE - MOTIVE FLOW FUEL PUMP ASSEMBLY	MOS						17-JAN-2005	
	3060759-1	HRS/MSC	O/C		N:0			0	
	SN-UNKNOWN	ENC			N:0			0	
	REF: LMM 73-21-02				N:0				
731005-1	NO. 2 ENGINE - NO. 1 FUEL MANIFOLD NOZZLE ASSEMBLY	MOS						29-JUN-2009	
	3060540-2	HRS/MSC	O/C					2398.4	
	97-01371-576	ENC						1655	
	REF: LMM 73-10-01								
731005-10	NO. 2 ENGINE - NO. 10 FUEL MANIFOLD NOZZLE ASSEMBLY	MOS						29-JUN-2009	
	3060540-2	HRS/MSC	O/C					2398.4	
	94-01371-160	ENC						1655	
	REF: LMM 73-10-01								

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731005-11	NO. 2 ENGINE - NO. 11 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 97-01371-414 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C					29-JUN-2009 2398.4 1655	
731005-12	NO. 2 ENGINE - NO. 12 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 97-01371-412 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C					29-JUN-2009 2398.4 1655	
731005-2	NO. 2 ENGINE - NO. 2 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 94-01371-209 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C					29-JUN-2009 2398.4 1655	
731005-3	NO. 2 ENGINE - NO. 3 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 94-01371-148 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C					29-JUN-2009 2398.4 1655	
731005-4	NO. 2 ENGINE - NO. 4 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 94-01371-174 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C					29-JUN-2009 2398.4 1655	
731005-5	NO. 2 ENGINE - NO. 5 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 94-01371-666 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C					29-JUN-2009 2398.4 1655	
731005-6	NO. 2 ENGINE - NO. 6 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 94-01371-213 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C					29-JUN-2009 2398.4 1655	
731005-7	NO. 2 ENGINE - NO. 7 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 97-01371-578 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C					29-JUN-2009 2398.4 1655	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731005-8	NO. 2 ENGINE - NO. 8 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 97-01371-554 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C				29-JUN-2009 2398.4 1655		
731005-9	NO. 2 ENGINE - NO. 9 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 94-01371-167 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C				29-JUN-2009 2398.4 1655		
732120 (s)	NO. 2 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE REF: See Workcard	MOS HRS/MSC ENC	600	+50/-100			17-JUL-2020 4862.9 3646		

CHAPTER 74 IGNITION

ENGINE NO. 1	Model : TFE731-20BR-1B	Serial # P-116593	Part # 3060084-2		
740130	NO. 1 ENGINE - 5 O'CLOCK IGNITER (#1 POSITION) PLUG 3074541-4 SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0	09-MAY-2017 4456.5 3267
+ 740140 (s)	NO. 1 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD REF: See Workcard	MOS HRS/MSC ENC	1600	+50/-100	09-MAY-2017 4456.5 3267
740150	NO. 1 ENGINE - 7 O'CLOCK IGNITER (#2 POSITION) PLUG 3074541-4 SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0	09-MAY-2017 4456.5 3267
+ 740160 (s)	NO. 1 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD REF: LMM 74-00-01	MOS HRS/MSC ENC	1600	+50/-100	09-MAY-2017 4456.5 3267

ENGINE NO. 2 Model : TFE731-20BR-1B Serial # P-116590 Part # 3060084-2

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
740130	NO. 2 ENGINE - 5 O'CLOCK IGNITER (#1 POSITION) PLUG 3074541-4 NA REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C				29-JUN-2009 2398.4 1655		
+ 740140 (s)	NO. 2 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD REF: See Workcard	MOS HRS/MSC ENC	1600	+50/-100			07-OCT-2014 4048.8 2866		
740150	NO. 2 ENGINE - 7 O'CLOCK IGNITER (#2 POSITION) PLUG 3074541-4 NA REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C				29-JUN-2009 2398.4 1655		
+ 740160 (s)	NO. 2 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD REF: LMM 74-00-01	MOS HRS/MSC ENC	1600	+50/-100			07-OCT-2014 4048.8 2866		
742011	NO. 2 ENGINE - NO. 1 IGNITION (IPC 20 REFERENCE) LEAD 9043913 NA REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C				29-JUN-2009 2398.4 1655		
742012	NO. 2 ENGINE - NO. 2 IGNITION (IPC 25 REFERENCE) LEAD 9043913 NA REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C				29-JUN-2009 2398.4 1655		
CHAPTER 76	ENGINE CONTROLS								
761013	THROTTLE CONTROL MODULE 69011-17 472 REF: AMM 76-10-02	MOS HRS/MSC AFL	O/C				14-JUL-2014 4046.1 2866		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y7600000 (s)	PERFORM ENGINE DEEC WIRE HARNESS SHIELD OVERBRAIDS AND SHIELD TERMINATIONS - VISUAL INSPECTION PKG 15 REF: AMM 05-10-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 23-NOV-2016 4476 3270		
Y7600001 (s)	PERFORM THRUST LEVER CONTROL MODULE - FUNCTIONAL TEST PKG 13 REF: AMM 76-10-02	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 23-NOV-2016 4476 3270		
Y7610007 (s)	PERFORM ENGINE CONTROL CABLES - VISUAL INSPECTION OF FORWARD AND AFT CABLE CONNECTION. PKG 14 REF: AMM 05-10-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 23-NOV-2016 4476 3270		

ENGINE NO. 1 Model : TFE731-20BR-1B Serial # P-116593 Part # 3060084-2

761330	NO. 1 ENGINE - ENGINE (DEEC) COMPUTER 2118882-1008 25-AW0068 REF: See Workcard	MOS HRS/MSC ENC	O/C				01-AUG-2019 4749.7 3553		
761330A	NO. 1 ENGINE - DOWNLOAD ENGINE (DEEC) COMPUTER ECTM 2118882-1008 25-AW0068 REF: See Workcard	MOS HRS/MSC ENC	A/R						

ENGINE NO. 2 Model : TFE731-20BR-1B Serial # P-116590 Part # 3060084-2

761330	NO. 2 ENGINE - ENGINE (DEEC) COMPUTER 2118882-1008 117-U0035 REF: See Workcard	MOS HRS/MSC ENC	O/C				28-FEB-2018		
761330A	NO. 2 ENGINE - DOWNLOAD ENGINE (DEEC) COMPUTER ECTM 2118882-1008 117-U0035 REF: See Workcard	MOS HRS/MSC ENC	A/R				28-FEB-2018		

CHAPTER 77 ENGINE INDICATING

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
774001	ENGINE VIBRATION MONITOR BOX 241-241-000-501 AB06807 REF: AMM 77-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
Y7741000 (s)	PERFORM ENGINE VIBRATION MONITORING SYSTEM - FUNCTIONAL TEST. PKG 21 REF: AMM 77-41-00	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 23-NOV-2016 4476 3270		
CHAPTER 78 EXHAUST									
5-19-00-R7830007	PERFORM - THRUST REVERSER - PERFORM CONDUCTIVITY CHECK OF RH THRUST REVERSER DOOR SKIN AND COWL ADJACENT TO APU EXHAUST REF: NDT PART 6/78-30-01	MOS HRS/MSC AFL APH	1200	+25/-25		19.48	26-MAR-2009 2381.38 1642 580.52	1800	1825
783001	LEFT THRUST REVERSER LJ7830101-5 A30040303 REF: AMM 78-31-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
783001A	- ONE TIME VISUAL INSPECTION TO ENSURE NO CRACKS ARE PRESENT ON REPAIRED LEFT LOWER THRUST REVERSER DOOR BLENDED CHAFFING AT SEAL AREA IAW LEARJET REQUEST FOR ENGINEERING DISPOSITION #45267ICT4838 REF:	MOS HRS/MSC AFL	-			-56.67	26-FEB-2015 4228.8 3039		
783002	RIGHT THRUST REVERSER LJ7830101-6 A30040303 REF: AMM 78-31-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
783002A	- ONE TIME VISUAL INSPECTION TO ENSURE NO CRACKS ARE PRESENT ON REPAIRED RIGHT LOWER THRUST REVERSER DOOR BLENDED CHAFFING AT SEAL AREA IAW LEARJET REQUEST FOR ENGINEERING DISPOSITION #45267ICT4839 REF:	MOS HRS/MSC AFL	-			-56.67	26-FEB-2015 4228.8 3039		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783051	LEFT OUTBOARD THRUST REVERSER ACTUATOR PN SN-UNKNOWN REF: AMM 78-32-20	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
783052	LEFT INBOARD THRUST REVERSER ACTUATOR PN SN-UNKNOWN REF: AMM 78-32-20	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
783053	RIGHT INBOARD THRUST REVERSER ACTUATOR PN SN-UNKNOWN REF: AMM 78-32-20	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
783054	RIGHT OUTBOARD THRUST REVERSER ACTUATOR LJ7833100-4 A30040489 REF: AMM 78-32-20	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			27-MAY-2014 4022.13 2841		
783061	NO. 1 CONTROL, THRUST REVERSER HYDRAULIC VALVE 6678300000-003 OBTE30812 REF: AMM 78-32-10	MOS HRS/MSC AFL	O/C				03-JUL-2007 1578.1 1085		
783062	NO. 2 CONTROL, THRUST REVERSER HYDRAULIC VALVE 6678300000-003 OBTE30666 REF: AMM 78-32-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		
783101	LEFT THRUST REVERSER HYDRAULIC ISOLATION VALVE LJ7835200-5 0116 REF: AMM 78-30-02	MOS HRS/MSC AFL	O/C				29-JUL-2009 2420.2 1673		
783102	RIGHT THRUST REVERSER HYDRAULIC ISOLATION VALVE R-9045-9 0711 REF: AMM 78-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2005 0 0		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
D7830078 (s)	PERFORM ** THRUST REVERSER SYSTEM THROTTLE RETARD ACTUATOR - OPERATIONAL CHECK PKG 21	MOS	96	+14d/-14d			PKG	23-NOV-2016	
AIRWORTHINESS	REF: AMM 78-32-40	HRS/MSC AFL	2400	+25/-25			4476 3270		
H7830081 (s)	PERFORM THRUST REVERSERS - REMOVE LINK ROD ASSEMBLIES AND PERFORM MAGNETIC PARTICLE INSPECTION. PKG 21	MOS	96	+14d/-14d			PKG	23-NOV-2016	
	REF: NDT PART 7/78-30-01	HRS/MSC AFL	2400	+25/-25			4476 3270		
H7830082 (s)	PERFORM THRUST REVERSERS - REMOVE THRUST REVERSER DOOR ASSEMBLIES AND PERFORM EDDY CURRENT INSPECTION OF PIVOT FITTING AND DOOR HINGES. PKG 21	MOS	96	+14d/-14d			PKG	23-NOV-2016	
	REF: See Workcard	HRS/MSC AFL	2400	+25/-25			4476 3270		
Y7830000 (s)	PERFORM EXHAUST NOZZLE - VISUAL INSPECTION PKG 21	MOS	96	+14d/-14d			PKG	23-NOV-2016	
	REF: AMM 05-10-00	HRS/MSC AFL	2400	+25/-25			4476 3270		
Y7830001 (s)	PERFORM THRUST REVERSER INNER FAN DUCT ASSEMBLY - VISUAL INSPECTION. INSPECT FROM EXHAUST END ONLY PKG 15	MOS	48	+14d/-14d			PKG	23-NOV-2016	
	REF: AMM 05-10-00	HRS/MSC AFL	1200	+25/-25			4476 3270		
Y7830002 (s)	PERFORM THRUST REVERSER DOOR AND HINGE FITTINGS - VISUAL INSPECTION PKG 15	MOS	48	+14d/-14d			PKG	23-NOV-2016	
	REF: AMM 05-10-00	HRS/MSC AFL	1200	+25/-25			4476 3270		
Y7830003 (s)	PERFORM THRUST REVERSER PRIMARY ACTUATOR AND LATCH ASSEMBLY - VISUAL INSPECTION PKG 15	MOS	48	+14d/-14d			PKG	23-NOV-2016	
	REF: AMM 05-10-00	HRS/MSC AFL	1200	+25/-25			4476 3270		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y7830004 (s)	PERFORM THRUST REVERSER HYDRAULIC CONTROL VALVE (HCV), THROTTLE RETARD ACTUATOR, AND ASSOCIATED PLUMBING - VISUAL INSPECTION						PKG		
	PKG 15	MOS	48	+14d/-14d				23-NOV-2016	
		HRS/MSC	1200	+25/-25				4476	
	REF: AMM 05-10-00	AFL						3270	
Y7830005 (s)	PERFORM THRUST REVERSER DOOR SEALS AND RETAINERS - VISUAL INSPECTION						PKG		
	PKG 15	MOS	48	+14d/-14d				23-NOV-2016	
		HRS/MSC	1200	+25/-25				4476	
	REF: AMM 05-10-00	AFL						3270	
Y7830006 (s)	PERFORM THRUST REVERSER WIRE HARNESS - VISUAL INSPECTION.						PKG		
	PKG 15	MOS	48	+14d/-14d				23-NOV-2016	
		HRS/MSC	1200	+25/-25				4476	
	REF: AMM 05-10-00	AFL						3270	
CHAPTER 79 OIL									
793011	LEFT TEMPERATURE OIL BULB								
	MS28034-3	MOS						03-APR-2005	
	H9156	HRS/MSC	O/C					0	
	REF: AMM 79-30-03	AFL						0	
793012	RIGHT TEMPERATURE OIL BULB								
	MS28034-3	MOS						03-APR-2005	
	H9169	HRS/MSC	O/C					0	
	REF: AMM 79-30-03	AFL						0	
ENGINE NO. 1 Model : TFE731-20BR-1B Serial # P-116593 Part # 3060084-2									
790110	NO. 1 ENGINE - OIL PUMP								
	3060785-2	MOS						17-JAN-2005	
	041405700785	HRS/MSC	O/C					0	
	REF: LMM 79-20-03	ENC						0	
790130 (s)	NO. 1 ENGINE - ANALYSIS OIL AND FILTER (SOAP)								
		MOS						21-NOV-2019	
		HRS/MSC	150	+100				4790.6	
	REF: LMM 72-00-00	ENC						3589	

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
790140 (s)	NO. 1 ENGINE - PERFORM OIL CHANGE REF: LMM 72-00-00	MOS HRS/MSC ENC	1200	+100/-200			21-NOV-2019 4790.6 3589		
790150 (s)	NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM RESISTANCE CHECK REF: See Workcard	MOS HRS/MSC ENC	600	+50/-100			11-OCT-2019 4766.2 3564		
790160 (s)	NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION REF: See Workcard	MOS HRS/MSC ENC	150	+100			21-NOV-2019 4790.6 3589		
+ 793315 (s)	NO. 1 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH REF: LMM 79-30-01	MOS HRS/MSC ENC	1200	+100/-200			21-NOV-2019 4790.6 3589		
ENGINE NO. 2 Model : TFE731-20BR-1B Serial # P-116590 Part # 3060084-2									
790110	NO. 2 ENGINE - OIL PUMP 3060785-2 041405700784 REF: LMM 79-20-03	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		17-JAN-2005 0 0		
790130 (s)	NO. 2 ENGINE - ANALYSIS OIL AND FILTER (SOAP) REF: LMM 72-00-00	MOS HRS/MSC ENC	150	+100			21-NOV-2019 4796 3581		
790140 (s)	NO. 2 ENGINE - PERFORM OIL CHANGE REF: LMM 72-00-00	MOS HRS/MSC ENC	1200	+100/-200			17-JUL-2020 4862.9 3646		

Status Report

LEARJET 45 S/N 45-267 (N219JL): 4932.3 HRS, 3714 AFL as of 17-Jul-2020

Owner: CDJ ASSETS, LLC Operator: CHAMPAIR AVIATION, LLC

Report Date: 03-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
790150 (s)	NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM RESISTANCE CHECK REF: See Workcard	MOS HRS/MSC ENC	600	+50/-100				17-JUL-2020 4862.9 3646	
790160 (s)	NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION REF: See Workcard	MOS HRS/MSC ENC	150	+100				21-NOV-2019 4796 3581	
793310	NO. 2 ENGINE - OIL FILTER BYPASS VALVE 3060782-2 NA REF: LMM 79-30-01	MOS HRS/MSC ENC	O/C					29-JUN-2009 2398.4 1655	
+ 793315 (s)	NO. 2 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH REF: LMM 79-30-01	MOS HRS/MSC ENC	1200	+100/-200				17-JUL-2020 4862.9 3646	