



CBSCOM

Maintenance Transaction Record

MTR ID # 2031750

Page 1 of 3

CAMP Systems International
8200 E. 34TH STREET
BULDING 1600, SUITE 1607
MICHIA, KS 67226
Phone: 316-462-2267/ Fax: 316-462-0791

This Maintenance Report is To Be Used Solely For (Check One)

Airframe Entries

Eng. #1 Serial No. _____

Eng. #2 Serial No. _____

APU Serial No. _____

Aircraft Identification and Status

| A/C Serial # | A/C Unit # | A/C Registration # | Date | City ID | Total A/C Hours | Total A/C Landings | Engine 1 Total Hrs | Engine 2 Total Hrs | Engine 1 Ttl Cycles | Engine 2 Ttl Cycles | APU Hrs | APU Events | Freon Hrs |
|--------------|------------|--------------------|-------------|---------|-----------------|--------------------|--------------------|--------------------|---------------------|---------------------|---------|------------|-----------|
| 560-0248 | 0248 | N749TT | 01-Aug-2012 | EFD | 4275.1 | 3187 | 4275.1 | 4275.1 | 3184 | 3184 | | | 0 |

Component Changes, Inspections, Service Bulletins or Airworthiness Directives Accomplished

| Item | Transaction No. Type | Item Name | Position | Part Number / Alternate Part | Mod Level | Part Serial | Removal Reason | Installed Part Status | Material Costs | Man Hours |
|---|----------------------|-----------|----------|------------------------------|-----------|-------------|----------------|-----------------------|----------------|-----------|
| 5-12-05 051205 | 1 2 | PHASE 5 | | | | | | | | |
| Comments: COMPLIED WITH PHASE 5 IAW MODEL 560 MAINTENANCE MANUAL (REV 29) 5-12-05 (REV 29). | | | | | | | | | | |
| 5-12-11 051211 | 2 2 | PHASE 11 | | | | | | | | |
| Comments: COMPLIED WITH PHASE 11 IAW MODEL 560 MAINTENANCE MANUAL (REV 29) 5-12-11 (REV 28). PERFORMED PERIODIC CHECK IAW TASK 34-21-12-761 | | | | | | | | | | |
| 5-12-18 051218 | 3 2 | PHASE 18 | | | | | | | | |
| Comments: COMPLIED WITH PHASE 18 IAW MODEL 560 MAINTENANCE MANUAL (REV 29) 5-12-18 (REV 28). PERIODIC CHECK PS-895 EMERGENCY POWER SUPPLY ACCOMPLISHED BY UNITED BATTERIES AND ACCESSORIES, INC FAA CRS # U9BR618Y AS PER W/O 22281 DATED 7/16/2012. | | | | | | | | | | |
| 5-12-49 051249 | 4 2 | PHASE 49 | | | | | | | | |
| Comments: COMPLIED WITH PHASE 49 IAW MODEL 560 MAINTENANCE MANUAL (REV 29) 5-12-49 (REV 27). | | | | | | | | | | |
| 5-12-50 051250 | 5 2 | PHASE 50 | | | | | | | | |
| Comments: COMPLIED WITH PHASE 50 IAW MODEL 560 MAINTENANCE MANUAL (REV 29) 5-12-50 (REV 28). | | | | | | | | | | |
| 5-12-55 | 6 2 | PHASE 55 | | | | | | | | |
| Comments: COMPLIED WITH PHASE 55 IAW MODEL 560 MAINTENANCE MANUAL (REV 29) 5-12-55 (REV 28). INSPECT MAIN SHIP BATTERY LEAD ACID BATTERY ACCOMPLISHED BY UNITED BATTERIES AND ACCESSORIES, INC FAA CRS # U9BR618Y AS PER W/O 22288 DATED 7/19/2012. | | | | | | | | | | |

Trans. Type: 1 - Component, 2 - Inspection, 3 - SB, 4 - AD, - - Misc.

Removal Reason: WO - Work to Limit, SC - Scheduled, UN - Unscheduled, CO - Convenience, N - Other (note in comments)

Installed Part Status: N - New, R - Replaced/Rebuilt, S - Serviceable, O - Overhauled

Repair Facility: HARCO AVIATION LLC Certified Repair Station Number: 9HCR378B Work Order No. 1858-07-2012

Work Performed By: HARCO AVIATION LLC Certificate No. 9HCR378B Date 01-Aug-2012

I certify that the above stated maintenance and/or inspection was performed in accordance with the current regulations of the Federal Aviation Administration Other (Specify) _____ and _____

THE AIRCRAFT IDENTIFIED ABOVE IS PRESENTLY APPROVED FOR RETURN TO SERVICE ONLY WITH RESPECT TO THE WORK ACCOMPLISHED.

Work Inspected By: WILLIAM B. VICE III *William B Vice III* Certificate No. 9HCR378B Date 01-Aug-2012

Pertinent details of this maintenance are on file at our facility under the above Work/Service Order Number as applicable.

| |
|-----------------|
| Maintenance Log |
| Section |
| Page |



CBS/COM

Maintenance Transaction Record

This Maintenance Report is To Be Used Solely For (Check One)

Airframe Entries

Eng. #1 Serial No. _____

Eng. #2 Serial No. _____

APU Serial No. _____

MTR ID # 2031750

Page 2 of 3

CAMP Systems International
8200 E. 34TH STREET
BUILDING 1600, SUITE 1607
Wichita, KS 67226
Phone: 316-462-2677 Fax: 316-462-0791

Aircraft Identification and Status

| A/C Serial # | A/C Unit # | A/C Registration # | Date | City ID | Total A/C Hours | Total A/C Landings | Engine 1 Total Hrs | Engine 2 Total Hrs | Engine 1 TII Cycles | Engine 2 TII Cycles | APU Hrs | APU Events | Freon Hrs |
|--------------|------------|--------------------|-------------|---------|-----------------|--------------------|--------------------|--------------------|---------------------|---------------------|---------|------------|-----------|
| 560-0248 | 0248 | N749TT | 01-Aug-2012 | EFD | 4275.1 | 3187 | 4275.1 | 4275.1 | 3184 | 3184 | | | 0 |

Component Changes - Inspections, Service Bulletins or Airworthiness Directives Accomplished

| Item | Transaction No. Type | Item Name | Position | Part Number / Alternate Part | Mod Level | Part Serial | Removal Reason | Installed Part Status | TSN/TSO/TSR | Material Costs | Man Hours |
|--|----------------------|--|----------|------------------------------|-----------|----------------|----------------|-----------------------|-------------|----------------|-----------|
| 5-12-56 051256 | 7 2 | PHASE 56 | | | | | | | | | |
| Comments: COMPILED WITH PHASE 56 I/A/W MODEL 560 MAINTENANCE MANUAL (REV 29) 5-12-56 (REV 26). | | | | | | | | | | | |
| 256003 | 8 1 | EMERGENCY LOCATOR TRANSMITTER BEACON BATTERY | | 2020 | | 2020BATT RY | NONE | SC | N | 0 MTH | |
| Expiration Date: 31-May-2014 Comments: REMOVED P/N 2020 BATTERY AND INSTALLED NEW BATTERY P/N 2020 | | | | | | | | | | | |
| 212004 | 9 1 | OVERHEAD CABIN FAN | | BC61A901-2 | 9912323-2 | 2837A | SC | O | | | |
| Comments: REMOVED OVERHEAD CABIN FAN P/N BC61A901-2 S/N 522A AND INSTALLED O/H BLOWER P/N BC61A901-2 S/N 2837A. UNIT O/H BY AMETEK ADVANCED INDUSTRIES, INC. FAA CRS # 002R064L AS PER W/O V016606-00 DATED 5/16/2012. | | | | | | | | | | | |
| 212010 | 10 1 | AVONICS BAY VANE AXIAL BLOWER | | 19A827 | | | NONE | UN | N | 0 MTH 0 HRS | |
| Comments: REMOVED AVONICS BAY VANE AXIAL BLOWER P/N 19A827 S/N UNKNOWN AND INSTALLED NEW UNIT P/N 19A827 S/N NONE. | | | | | | | | | | | |
| 2031750011 | 11 1 | CONTROL CABLE | | | | | NONE | WO | N | 0 MTH 0 HRS | |
| Comments: INSTALLED NEW CONTROL CABLE P/N 5565550-202 | | | | | | | | | | | |
| 2031750 | 12 1 | CONTROL CABLE | | | | | NONE | WO | N | 0 MTH 0 HRS | |
| Comments: INSTALLED NEW CONTROL CABLE P/N 5565550-34CR | | | | | | | | | | | |
| 2031750 | 13 1 | CONTROL CABLE | | | | | NONE | WO | N | 0 MTH 0 HRS | |
| Comments: INSTALLED NEW CONTROL CABLE P/N 5565550-37CR | | | | | | | | | | | |
| 2031750014 | 14 1 | CONTROL CABLE | | | | | NONE | WO | N | 0 MTH 0 HRS | |
| Comments: INSTALLED NEW CONTROL CABLE P/N 6565120-37. | | | | | | | | | | | |

Trans. Type 1 - Component, 2 - Inspection, 3 - SB, 4 - AD, 5 - Misc.

Removal Reasons: WO - Worn to Limits, SC - Scheduled, UN - Unscheduled, CO - Convenience, N - Other (note in comments)

Installed Part Status: N - New, R - Repaired/Rebuilt, S - Serviceable, O - Overhauled

Repair Facility: HARCO AVIATION LLC Station Number: 9HCR378B Work Order No. 1858-07-2012

Work Performed By: HARCO AVIATION LLC Certificate No. 9HCR378B Date 01-Aug-2012

Federal Aviation Administration Other (Specify) _____

I certify that the above stated maintenance and/or inspection was performed in accordance with the current regulations of the _____ and _____

THE AIRCRAFT IDENTIFIED ABOVE IS PRESENTLY APPROVED FOR RETURN TO SERVICE ONLY WITH RESPECT TO THE WORK ACCOMPLISHED.

Work Inspected By: WILLIAM B. VICE III *William B. Vice III* Certificate No. 9HCR378B Date 01-Aug-2012

Permittal details of this maintenance are on file at our facility under the above Work/Service Order Number as applicable.

| | | |
|-----------------|---------|------|
| Maintenance Log | Section | Page |
|-----------------|---------|------|



CBSCOM

MTR ID # 2031750

Page 3 of 3

CAMP Systems International
8200 E. 34TH STREET
BUILDING 1600, SUITE 1607
Wichita, KS 67226
Phone: 316-462-2267 / Fax: 316-462-0791

This Maintenance Report is To Be Used Solely For (Check One)

Airframe Entries

Eng. #1 Serial No. _____

Eng. #2 Serial No. _____

APU Serial No. _____

Aircraft Identification and Status

| A/C Serial # | A/C Unit # | A/C Registration # | Date | City ID | Total A/C Hours | Total A/C Landings | Engine 1 Total Hrs | Engine 2 Total Hrs | Engine 1 Ttl Cycles | Engine 2 Ttl Cycles | APU Hrs | APU Events | Freon Hrs |
|--------------|------------|--------------------|-------------|---------|-----------------|--------------------|--------------------|--------------------|---------------------|---------------------|---------|------------|-----------|
| 560-0248 | 0248 | N749TT | 01-Aug-2012 | EFD | 4275.1 | 3187 | 4275.1 | 4275.1 | 3184 | 3184 | | | 0 |

Component Changes Inspections Service Bulletins or Airworthiness Directives Accomplished

| Item No. | Transaction No. | Type | Item Name | Position | Part Number / Alternate Part | Mod Level | Part Serial | Removal Reason | Status | Installed Part | Material Costs | Man Hours |
|----------|-----------------|------|-----------|----------|------------------------------|-----------|-------------|----------------|--------|----------------|----------------|-----------|
|----------|-----------------|------|-----------|----------|------------------------------|-----------|-------------|----------------|--------|----------------|----------------|-----------|

345007 : F
 15 1 FORWARD DME ANTENNA FORWARD DMNISO-2-2 85226 UNK UNK 0 MTH 0 HRS
 Comments: Removed part no. DMNISO-2-2 Removed serial no. 119307. INSTALLED NEW FORWARD DME ANTENNA P/N DMNISO-2-2 S/N NONE.

2031750016 16 - ALERON TRIM RIGGING
 Comments: ALERON TRIM TAB RIGGED IAW CESSNA CITATION 560 MAINTENANCE MANUAL CH 27-00-00. OPS CHECKED PROPERLY AFTER RIGGING.

2031750017 17 1 AFT COMM ANTENNA AFT VFS10-90-7 1572 UN N 0 MTH 0 HRS
 Comments: REMOVED LOWER AFT COMM ANT P/N VFS10-90-7 S/N 3003 AND INSTALLED NEW LOWER AFT COMM ANT P/N VFS10-90-7 S/N 1572.

2031750018 18 - BONDING STRAPS
 Comments: REPLACED LH /B FLAP BELLCRANK BONDING STRAP AND LH /B FLAP ARM BONDING STRAP WITH NEW STRAPS. REPLACED NOSE GEAR BONDING STRAP WITH NEW ONE P/N RD18 (NOTE TWO BLOTS FROZEN IN BEARINGS OF ASSY). REPLACED HYD VENT BONDING UNDER SERVICE DOOR WITH NEW STRAP. REPLACED BONDING STRAP FOR LH SPEED BRAKE WITH NEW ONE.

2031750020 19 1 SWIVEL FITTING / HOSE LH LSAS6-56DAS / 24K001-4CLO140 UN N 0 MTH 0 HRS
 Comments: INSTALLED NEW LH MAIN LANDING GEAR ACTUATOR LOWER HYDRAULIC HOSE P/N 124K001-4CLO140 AND SWIVEL FITTING P/N LSAS6-56DAS.

2031750021 20 - STATIC WICKS 15330 / 15340 UN N 0 MTH 0 HRS
 Comments: REMOVED AND INSTALLED NEW STATIC WICKS ON RIGHT WING AND ON TOP OF RUDDER P/N 15330 & P/N 15340.

Taxs. Type 1 - Component, 2 - Inspection, 3 - SB, 4 - AD, - - Misc. Removal Reasons: WC - Work to Limits, SC - Scheduled, UN - Unchecked, CO - Convenience, N - Other (note in comments) Installed Part Status: N - New, R - Repaired/Rebuilt, S - Serviceable, O - Overhauled

Repair Facility: HARCO AVIATION LLC
 Certified Repair Station Number: 9HCR3788
 Work Order No.: 1858-07-2012
 Date: 01-Aug-2012

Work Performed By: HARCO AVIATION LLC
 Certificate No.: 9HCR3788
 I certify that the above stated maintenance and/or inspection was performed in accordance with the current regulations of the _____ and _____
 Federal Aviation Administration Other (Specify) _____

THE AIRCRAFT IDENTIFIED ABOVE IS PRESENTLY APPROVED FOR RETURN TO SERVICE ONLY WITH RESPECT TO THE WORK ACCOMPLISHED.

Work Inspected By: WILLIAM B. VICE III
 Certificate No.: 9HCR3788
 Date: 01-Aug-2012
 Permit details of this maintenance are on file at our facility under the above Work/Service Order Number as applicable.

| | |
|-----------------|------|
| Maintenance Log | Page |
| Section | |